LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd. From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

50 Raffles Place

#05-01/06, Singapore Land Tower Paya Ubi Industrial Park Singapore 048623 Singapore 408933

Melvin Ye Date: 26 Apr 2019 Attn:

Preliminary Advice

Insured Vehicle No : SKR9336Y

TP Vehicle No : 22/04/2019 : SHB5369Z Accident Date Make : TOYOTA PRIUS Assignment Date : 24/04/2019

Date of Inspection :4 : 25/4/2019 Est. Duration of Repair

:SMRT AUTOMOTIVE SERVICES PTE LTD Inspection At

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 14,877.43 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 3,705.40 |
| Check Items (Estimated) | :S\$ | 2,655.05 |
| Total | :S\$ | 6,360.45 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us |
|---|---|--|
| | | have your authorisation. |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: The above survey was conducted on a 'Without Prejudice' basis.