

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 25 Apr 2019

**Preliminary Advice**

Vehicle No	: GBD4747H	Accident Date	: 09/04/2019
Make	: NISSAN CABSTAR	Policy No.	: D18MTPCVE003542
Assignment Date	: 23/04/2019	Excess	: S\$500.00
		Additional Excess	: S\$2,000.00
Date of Inspection	: 25/04/2019	Est. Duration of Repair	: 12 days
Inspection At	: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,293.50
Revised Amount	:S\$	10,812.50
Check Items (Estimated)	:S\$	2,073.50
Total	:S\$	12,886.00
 Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38,000.00
COE / PARF Rebate	:S\$	18,976.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,024.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer is asking part by part basis because no second hand part.