LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd. From:

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

GNOH PAU LOONG Date: 30 Apr 2019 Attn:

Preliminary Advice

Insured Vehicle No : GBD5629J

TP Vehicle No : SBP3868K Accident Date : 18/04/2019 Make : TOYOTA COROLLA ALTIS Assignment Date : 25/04/2019

Date of Inspection :29/4/2019 Est. Duration of Repair :5

Inspection At :AUTOMOTIVE REPAIR CENTRE PTE LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,680.00
Revised Amount	:S\$	3,500.00
Check Items (Estimated)	:S\$	1,100.00
Total	:S\$	4,600.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$:S\$ Margin for Repair

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
		have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: The above survey was conducted on a 'Without Prejudice' basis.