

ASS. REC. BY:

REF: CS / SM019007289 / Jrd3n2

Special Instruction:

Survivor: Hwee Jie**ASSIGNMENT (Office)**

MURMAN

From (Person): Gniah Pau Loong of SMO Date/Time: 25.4.19 11:50a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBP 3868K Insured: GBD 5629Jat Workshop m/s Automotive Repair Tel: 64688834of 38 Woodlands Industrial Park E1 #05-18Policy No: D19M7HCVE000181 Claim No: CMTD1901956

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18.4.2019
(Client's Record) "wp" 29/4/19 (Before repair)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 25.4.17 1:11 p.m Person Contacted: Raymond Vehicle IN/OUT: (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SBP 3868K - NJA/INC10006525/y1 D.O.A - 04/04/2010
	GBD 5629J - X
<u>30/4/19</u>	<u>Send preli revised via merimen</u>

Surrogate Huse Jie


REF: SMO

ASSIGNMENT

From: _____ Date: 29.4.2019
 Estimated Cost: _____
 OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SBP 3868K
 at Workshop m/s Automotive Repair
 of 38 woodlands Industrial Park El # 05-18
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: Before 1.00pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS *rup''*

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SBP 3868K Yr Regn: 13 Aug 2009
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota Altis C.C. 1898
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 161734 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: MROS3ZEE106151967
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / STD / STD A/Rim or

Tyre Size: F: 195/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	18/4/19	D.O.I.	29/4/19

Survey held at ARC
 Des. of Damages: Frt / Rear / O/S ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NUV - \$17500
	PR - \$9379
	NUV - \$8121
15/5/19	Confirmed L/S \$2600/- 5 days of repair. (Real 2080, 445)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 20/5 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

250
10
160

Report Format: merimen

Lump Sum / I.B.I. (\$) 2600p

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: GNOH PAU LOONG	Date: 30 Apr 2019
Preliminary Advice	

Insured Vehicle No	: GBD5629J	Accident Date	: 18/04/2019
TP Vehicle No	: SBP3868K	Assignment Date	: 25/04/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5
Date of Inspection	: 29/4/2019		
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,680.00
Revised Amount	:S\$	3,500.00
Check Items (Estimated)	:S\$	1,100.00
Total	:S\$	4,600.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
☐	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
☒	Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Apr 2019		25 Apr 2019 11:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H								
Main Claimant:	ONG TAT LEONG, ID: S6849501F								
Vehicle Reg. No.:	SBP3868K	Date of Loss:	18/04/2019 00:00 - :59						
Claim Type:	TP / CMTD1901956	Policy/Cover Note No.:	D19MTHCVE000181 (Third Party Only)						
Vehicle Reg. No. (Insured):	GBD5629J	Policy No. (Claimant):							
		Excess:							
Repairer:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2019]								
Adj Asg. Remarks:	WS: RAYMOND 64688834 PLS ARRANGE SURVEY ON MON 29/4 AM								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[-> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9501F
Vehicle Details	
Vehicle No.:	SBP3868K
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	3ZZ4920057
Chassis No.:	MR053ZEE106151967
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	13 Aug 2009
First Registration Date:	13 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$453.00
Total Rebate Amount:	\$9,379.00

The information contained herein is correct as at 18 Apr 2019

OK

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1904-037

DATE : 18-Apr-2019

POLICY NO. : MSIG A27145107QMY

VEHICLE REG. NO. : SBP3868K

VEHICLE MAKE : TOYOTA COROLLA ALTIS 1.6

TO Motor Claim Department
 Sompo Insurance Singapore Pte Ltd
 50 Raffles Place
 #05-01/06 Singapore Land Tower
 Tel: 6221 2211, Fax: 6221 3147

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Door LH <i>BUC ✓</i>	1	\$ 1,080.00	\$ 1,080.00
2	Rear Door Lock LH <i>Jam ✓</i>	1	\$ 380.00	\$ 380.00
3	Rear Door Regulator LH <i>BT ✓</i>	1	\$ 240.00	\$ 240.00
4	Rear Door Regulator Motor LH <i>nn x</i>	1	\$ 580.00	\$ 580.00
5	Rear Door Inner Rubber Seal <i>nn x</i>	1	\$ 280.00	\$ 280.00
6	Rear Door Protector LH <i>hec ✓</i>	1	\$ 120.00	\$ 120.00
7	Rear Door Protector Chrome Strip LH <i>hec ✓</i>	1	\$ 40.00	\$ 40.00
8	Rear Door LH Upper Frame Sticker Rear <i>hec ✓</i>	1	\$ 40.00	\$ 40.00
9	Rear Door LH Upper Frame Sticker Front <i>nn x</i>	1	\$ 40.00	\$ 40.00
<i>25% Discount on parts</i> Total Spare Parts				\$ 2,800.00
SPECIAL NETT				
10	Rear Rim LH <i>SCR ✓</i>	1	\$ 300.00	\$ 300.00
Total Special Nett				\$ 300.00
LABOUR				
11	Spray Paint Rear Bumper, Fender RH, Door RH and Side Skirt	1	\$ 800.00	\$ 800.00 ✓
12	Labour for Remove, Refit and Repair Affected Accident Parts	1	\$ 600.00	\$ 600.00 ✓
13	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00 50 ✓
14	Computerized Wheel Alignment	1	\$ 70.00	\$ 70.00 60 ✓
15	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 ✓

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 1,580.00
Amount Before Excess	\$ 4,680.00
Add GST @ 7%	327.60
Total Amount Payable	\$ 5,007.60

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Page 1 of 1

Hwee Jie - LKK
 29/4/19
 L/s Sdags
[Signature]

Total - \$2600

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007289/JVD3N2

Date: 23/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTHCVE000181
Claimant Vehicle No :	SBP3868K	Insured Vehicle No :	GBD5629J
Date of Loss:	18/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1901956

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBP3868K	Engine No:	3ZZ4920057
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106151967
Reg. Date:	13/08/2009 (Man. Year: 2009)	Odometer:	161734 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,100.00	1,725.00	1,375.00	44.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,540.00	40.00	2.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,680.00	3,265.00	1,415.00	30.24
Approved Total (Overridden) (\$\$)		2,600.00		
(\$\$)	4,680.00	2,600.00	2,080.00	44.44
+ GST 7.00/7.00% (\$\$)	327.60	182.00	145.60	44.44
Nett Amount (\$\$)	5,007.60	2,782.00	2,225.60	44.44

INSPECTION

Date of Assignment:	25/04/2019	
Date Inspected:	29/04/2019 Inspected At:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18 Singapore 757700

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBP3868K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Buckled	1,080.00 F	*1,080.00 FL
2	1		*REAR DOOR LOCK LH	Jammed	380.00 F	*380.00 FL
3	1		*REAR DOOR REGULATOR LH	Bent	240.00 F	*240.00 FL
4	1		*REAR DOOR REGULATOR MOTOR LH	Not Necessary	580.00 F	*- FL
5	1		*REAR DOOR INNER RUBBER SEAL	Not Necessary	280.00 F	*- FL
6	1		*REAR DOOR PROTECTOR LH	Necessary	120.00 F	*120.00 FL
7	1		*REAR DOOR PROTECTOR CHROME STRIP LH	Necessary	40.00 F	*40.00 FL
8	1		*REAR DOOR LH UPPER FRAME STICKER REAR	Necessary	40.00 F	*40.00 FL
9	1		*REAR DOOR LH UPPER FRAME STICKER FRONT	Not Necessary	40.00 F	*- FL
10	1		*REAR RIM LH	Scratched	300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,100.00	2,200.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	475.00
Total Parts (S\$)	3,100.00	1,725.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT REAR BUMPER,FENDER RH,DOOR RH AND SIDE SKIRT	New	800.00	800.00
2	LABOUR FOR REMOVE,REFIT AND REPAIR AFFECTED ACCIDENT PARTS	New	600.00	600.00
3	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR	New	80.00	50.00
4	COMPUTERIZED WHEEL ALIGNMENT	New	70.00	60.00
5	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00
Gross Labour Cost (S\$)			1,580.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >