

ASS. REC. BY:

REF: CS/SMD190072901K9d3⁵²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

MUTIMUN

From (Person): Melvin YE of SMO Date/Time: 25.4.19 11:40 a.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 93364 Insured:

at Workshop m/s Ah Lim Motor Tel: 64831244

of 10 Amk Industrial Park 2A #01-09

Policy No: DIA MTPV01002671 Claim No: CMTD1907022

Sum Insured: Excess: 100 + 600 = 700

Make of Veh: D.O.A. 22.4.2019

(Client's Record) 26.4.19 10.00 a.m.

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 25.4.2019 11:45 a.m. Person Contacted: Gilan Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate.
	SKR 93364 - CS/SMD190072901Jvd3 D.O.A - 22/04/2019
29/4/19 @ 12:14pm	revert to Melvin via Messenger.
29/4/19 @ 1:40pm	Bernard Han informed via Messenger.
29/4/19 @ 1:48pm	informed Alex C/A B ex to 100 by email.
29/4/19 @ 3:35pm	informed Eileen the excess should be 670 instead of 8100 by email.

REF: SMO

ASSIGNMENT

From: Date: 26.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 93364

at Workshop m/s Ah Lim Motor
of 10 Amk Industrial Park 2A

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 10-00 9-M

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$106k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "wup"

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKR 93364 Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Japva A, XF c.c. 1999

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 2472 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SATA.C05.M3F4 86689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F: 245/45R18

R: —————

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 5 mm

L/Bal. 6 mm

L/Bal. 5 mm

D.O.A. 22/4/19

D.O.I. 26/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/7 @ 7343.50 Confirmed (Red @ 2874.80, 28%)

RECEIVED 12 JUL 2019

Date/Time, File Pass to?

12/7 12:00

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$) 7343.50

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: 350

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

11

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2019 Sendback Est	25 Apr 2019 11:27 S\$10,218.30	25 Apr 2019 11:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	SEAH LENG WAH, ID: S1633611D, Tel: +6596185670, Email: SEAH LW@HOTMAIL.SG		
Vehicle Reg. No.:	SKR9336Y	Date of Loss:	22/04/2019 18:00 - :59 [49 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1902022	Policy/Cover Note No.:	D19MTPV01002671 (Comprehensive)
	Excess:		
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2019]		
Driver/Custodian:	SEAH LENG WAH (54 / Male), NRIC: S1633611D, Tel: +6596185670 Email: SEAH LW@HOTMAIL.SG		
Adj Asg. Remarks:	FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER PLS CONTACT EILEEN FOR SURVEY ARRANGEMENT		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 29 April 2019 3:35 PM
To: ahlimmc@singnet.com.sg
Cc: SUR
Subject: RE: OD VEHICLE SKR 9336Y (DOA: 22/04/2019)

Dear Eileen,

Please be informed that the excess should be \$700 instead of \$100.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 29 April 2019 1:48 PM
To: ahlimmc@singnet.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: OD VEHICLE SKR 9336Y (DOA: 22/04/2019)

Dear Eileen,

As instructed by our client, please proceed to repair the insured vehicle **SKR 9336Y (Excess \$100/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 29 April 2019 1:48 PM
To: ahlimmc@singnet.com.sg
Cc: SUR
Subject: OD VEHICLE SKR 9336Y (DOA: 22/04/2019)

Dear Eileen,

As instructed by our client, please proceed to repair the insured vehicle **SKR 9336Y (Excess \$100/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	23 Apr 2019 17:17	Clim Veh Model Changed		[] Merimen Administrator
2	23 Apr 2019 17:17	Clim Created	Reg No: SKR9336Y, Policy No: D19MTPV01002671, Acct Date: 2019/04/22, Claim Type: SC, Insurer: Sompo Insurance Singapore Pte, Ltd. (HQ), Ins.Status => Notification, Created from SAS:MALM19052635	[I] Merimen Administrator
3	24 Apr 2019 11:17	Clim Registration Modified	Acct Time:18:15:00->18:00:00.	[I] Lim Sze Hwee
4	25 Apr 2019 11:21	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] Eileen Chua
5	25 Apr 2019 11:21	Clim Veh Model Changed	(204423) JAGUAR XF 2.0 P TSS (A).	[R] Eileen Chua
6	25 Apr 2019 11:27	Clim Submitted	10218.30.	[R] Eileen Chua
7	25 Apr 2019 11:40	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER PLS CONTACT EILEEN FOR SURVEY ARRANGEMENT	[I] GRACE TEO
8	25 Apr 2019 11:40	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2019/05/07	[I] GRACE TEO
9	25 Apr 2019 11:40	Adj Mandate Set	Approved:0.00.	[I] GRACE TEO
10	25 Apr 2019 11:43	Assignment 1st Accessed		[A] LEE SU THING
11	25 Apr 2019 13:42	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] LEE SU THING
12	29 Apr 2019 11:19	Clim Registration Modified	Excess: -> 100.00, Excess Waived: -> 1000.00, 2F: -> 600.00.	[I] Melvin Ye
13	29 Apr 2019 12:09	Adj Rpt Initiated		[A] SHIAU CHAN
14	29 Apr 2019 12:11	Adj Im. Advice Submitted	Next Rpt:Final Rpt, Due Date:2019/05/07	[A] SHIAU CHAN
15	29 Apr 2019 12:14	Adj Mandate Request	Cur.Req:8774.80:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY CONFIRM THE EXCESS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	29 Apr 2019 13:40	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2019/05/07	[I] HAN CHEUNG YONG BERNARD
17	29 Apr 2019 13:40	Adj Mandate Set	Approved:8774.80.Reinsp:Adj decides.	[I] HAN CHEUNG YONG BERNARD

Date From Date To Audit Type

ACTIVITY

[25/04/2019 13:42] LEE SU THING:

Please be informed vehicle not in the workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2124718	23/04/2019 17:17	Motor	Sompo Insurance Singapore Pte, Ltd. (HQ)	Sompo Insurance Singapore Pte, Ltd. (HQ)	SKR9336Y	SEAH LENG WAH	xx.xx
2126619	25/04/2019 11:21	Motor	Ah Lim Motor Company (AMK)	Ah Lim Motor Company (AMK)	SKR9336Y		xx.xx
2129715	29/04/2019 12:09	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKR9336Y		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye

Date: 29 Apr 2019

Preliminary Advice

Vehicle No	: SKR9336Y	Accident Date	: 22/04/2019
Make	: JAGUAR XF	Policy No.	: D19MTPV01002671
Assignment Date	: 25/04/2019	Excess	: S\$100.00
		Additional Excess	: S\$600.00
Date of Inspection	: 26/04/2019	Est. Duration of Repair	: 5.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,218.30
Revised Amount	:S\$	6,217.10
Check Items (Estimated)	:S\$	2,557.70
Total	:S\$	8,774.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	106,000.00
COE / PARF Rebate	:S\$	88,063.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,937.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY CONFIRM THE EXCESS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2019 16:04
Date Of Accident	22/04/2019 18:15
Exact Location Of Accident	JUNCTION OF AMK CENTRAL RD 2 & AMK AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR9336Y
Insured/Policyholder	
Name Of Registered Owner	SEAH LENG WAH
NRIC No	S1633611D
Email Address	SEAH LW@HOTMAIL.SG
Mobile Phone No	(LOCAL) +65-96185670
Alternative Phone No	OTHERS-96185670

Vehicle Particulars

Manufacturer	JAGUAR
Model	XF 2.0P TSS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01002671
Cover Note Number	18/03/2019 - 17/03/2020


Driver

Name of Driver	SEAH LENG WAH
NRIC No	S1633611D
Date Of Birth	30/05/1964
Occupation	INDOOR
Date Of Driving Pass	17/10/1985
Driving Experience	33 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96185670
Fax Number	
Contact Number	OTHERS-96185670
Email Address	SEAH LW@HOTMAIL.SG

Sketch Plan Pg. 1

Date of accident: 23 April 19 Time: 1815 Location: Junction of Amk Central Rd 2 & Amk Ave 6
 My Vehicle A: SKR 9336 Y Vehicle B: SHB 5369 Z Vehicle C: —

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Taxi SHB5369Z was at the junction of the above stated location, I was distracted by a vehicle and carelessly bumped onto the taxi at its back.

Veh B: Chan Han Hwee / S1177230 G.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

23 April 19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



AH LIM MOTOR COMPANY

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3611D

Vehicle Details

Vehicle No.: SKR9336Y
Vehicle to be Exported: Yes
Intended Deregistration Date: 23 Apr 2019
Vehicle Make: JAGUAR
Vehicle Model: XF 2.0P TSS
Primary Colour: Red
Manufacturing Year: 2015
Engine No.: 091214212852204PT
Chassis No.: SAJAC05M3FPU66689
Maximum Power Output: 177.0 kW (237 bhp)
Open Market Value: \$50,808.00
Original Registration Date: 18 Mar 2015
First Registration Date: 18 Mar 2015
Transfer Count: 0
Actual ARF Paid: \$63,455.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Mar 2025
PARF Rebate Amount: \$47,591.00

Intended COE Rebate Details

COE Expiry Date: 17 Mar 2025
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$68,668.00
COE Rebate Amount: \$40,472.00
Total Rebate Amount: \$88,063.00

The information contained herein is correct as at 23 Apr 2019

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man with glasses.

Licence Number: **S1633611D**
 Name: **SEAH LENG WAH**

Birth Date: **30 May 1964**
 Issue Date: **17 Jun 2003**

Barcode: 000573379G

Hp: 9618 5670

Email: seahlw@hotmail.sg

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	17 Oct 1985

NP 428A



dry
 inf. No
 Ca. No
 Total: 1.

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6555 : Fax: 6221 3302 : Website: www.sompo.com.sg
Co. Reg. No. 198905490E : GST Reg. No. M200903196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D19MTPV01002671
Insured : SEAH LENG WAH
Motor Car (Registration No.) : SKR9336Y
Cover : Comprehensive - ExcelDrive GOLDPLUS
Policy Commencement Date : 18 MARCH 2019 00:00
Policy Expiry Date : 17 MARCH 2020 23:59
Maximum Liability (Section I) : Market value at time of loss - Excl. COE
Excess* : \$1100 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : Buy Up : \$600 - Section I
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured,
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

(We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27)

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 01 FEBRUARY 2019 10:26

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car.
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11A14307 & ACCORD INSURANCE AGENCY - AUTO SECURE CI Code: 22A FRJDSZ14R0RBDKJA

UPP = 26/4/19
10:15 am

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlmmc@singnet.com.sg
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/SOMPO
Policy No:	D19MTPV01002671	Date of Loss:	22/04/2019
Vehicle Reg. No.:	SKR9336Y	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SEAH LENG WAH	Contact No:	+6596185670
Driver:	SEAH LENG WAH		
Make/Model:	JAGUAR XF, 2.0 P TSS (A)	Vehicle Reg. Date:	18/03/2015
Vehicle Colour:	RED		
Engine No:	091214212852204PT	Chassis No:	SAJAC05M3FPU66689
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 5 days		
Description of Accident/Loss	REFER TO THE ATTACHED SKETCH PLAN BY DRIVER. <i>Ex: 62564315</i>		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

FAULS

*Not Authorized
Return By paint*

COST OF CLAIMS	Amount
Parts	8,308.30
Miscellaneous Items	0.00
Labour	1,910.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	10,218.30
+ GST 7.00% (\$)	715.28
Nett Amount (\$)	10,933.58

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 25 Apr 2019)
Parts: 143 **JAGUAR XF 2.0 P TSS (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	Bz	0.00	0.00	*1,600.00 F ✓
2	1		*FRONT BONNET INNER LOCK		0.00	0.00	*60.00 F X
3	10		*FRONT BONNET INSULATOR CLIPS		0.00	0.00	*35.00 F X
4	1		*FRONT GRILLE WITH CHROME MOULDING	Sn	0.00	0.00	*620.00 F X
5	1		*FRONT GRILLE EMBLEM	Sn	0.00	0.00	*65.00 F X
6	1		*HEADLAMP LH	CNT	0.00	0.00	*1,520.00 F ✓
7	1		*HEADLAMP BALLAST MODULE	Sn	0.00	0.00	*400.00 F X
8	1		*HEADLAMP WASHER NOZZLE LH	CNT	0.00	0.00	*138.00 F ✓
9	1		*HEADLAMP WASHER NOZZLE COVER LH	mis	0.00	0.00	*45.00 F ✓
10	1		*FRONT BUMPER	Bz	0.00	0.00	*1,100.00 F ✓
11	2		*FRONT BUMPER SIDE RETAINERS LH & RH	0/5 0/5 mis Dir	0.00	0.00	*80.00 F 4
12	15		*FRONT BUMPER CLIPS	Sn	0.00	0.00	*60.00 F ✓
13	1		*FRONT BUMPER LOWER AIR GRILLE	Sn	0.00	0.00	*170.00 F X
14	1		*FRONT BUMPER REINFORCEMENT	Bz	0.00	0.00	*480.00 F ✓
15	1		*FRONT BUMPER SPONGE	Sn	0.00	0.00	*290.00 F X
16	1		*FRONT BUMPER PARKING SENSOR INNER LH	Shot	0.00	0.00	*175.00 F ✓
17	1		*FRONT BUMPER PARKING SENSOR OUTER LH	Shot	0.00	0.00	*175.00 F ✓
18	4		*FRONT BUMPER PARKING SENSOR BRACKET	Src	0.00	0.00	*144.00 F X
19	1		*FOGLAMP COVER LH	Dir	0.00	0.00	*172.00 F ✓
20	1		*FOGLAMP COVER CHROME LH	Sn	0.00	0.00	*224.00 F ✓

F=Franchise part.

Sub Total (S\$) **7,553.00**
+ Margin on L,N Items 10.00% (S\$) **755.30**
Total Parts (S\$) 8,308.30

Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 20/
2	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	New	120.00 60/
3	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	350.00 X

Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
4	TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR RADIATOR SUPPORT PANEL;FRONT FENDER LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New 800	600.00 <i>400</i>
5	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH; RADIATOR SUPPORT PANEL	New 800	800.00 <i>500</i>
Gross Labour Cost (\$\$)			1,910.00

Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey & resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 22/04/2019

Claim No: **MC1900332**
Ref No: **MF1900417**
Date: 09 Jul 2019
Policy No: D19MTPV01002671
Veh Reg No: **SKR9336Y**
Make/Model: JAGUAR XF 2.0P TSS

Amendment
Repair Cost to Vehicle No (For Finalization):SKR9336Y

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET		1 PC	1,600.00	
2 HEADLAMP LH		1 PC	1,520.00	
3 HEADLAMP WASHER NOZZLE LH		1 PC	138.00	
4 HEADLAMP WASHER NOZZLE COVER LH		1 PC	45.00	
5 FRONT BUMPER		1 PC	1,100.00	
6 FRONT BUMPER SIDE RETAINERS LH & RH		2 PC	96.00	
7 FRONT BUMPER CLIPS		15 PC	60.00	
8 FRONT BUMPER REINFORCEMENT		1 PC	480.00	
9 FRONT BUMPER PARKING SENSOR INNER LH		1 PC	175.00	
10 FRONT BUMPER PARKING SENSOR OUTER LH		1 PC	175.00	
11 FOGLAMP COVER LH		1 PC	172.00	
12 FOGLAMP COVER CHROME LH		1 PC	224.00	
			5,785.00	
	Add 10%		578.50	6,363.50
LABOUR				
13 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
14 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		1 PC	60.00	
15 TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR RADIATOR SUPPORT PANEL,FRONT FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	400.00	
16 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, RADIATOR SUPPORT PANEL		1 PC	500.00	
				980.00

Amendment
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 22/04/2019

Claim No: MC1900332
Ref No: MF1900417
Date: 09 Jul 2019
Policy No: D19MTPV01002671
Veh Reg No: SKR9336Y
Make/Model: JAGUAR XF 2.0P TSS

Repair Cost to Vehicle No (For Finalization):SKR9336Y

Amount Before Excess	S\$ 7,343.50
Less Excess	S\$ 700.00
Amount Before GST	S\$ 6,643.50
Add GST @ 7%	465.05
Total Amount payable	<u>S\$ 7,108.55</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND ONE HUNDRED AND EIGHT AND CENTS FIFTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 26/04/2019

For AH LIM MOTOR COMPANY

~~AH LIM MOTOR COMPANY~~
No. 10 Ang Mo Kio Industrial Park 2A
#01-09
AUTHORISED SIGNATURE

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Apr 2019)
 Parts: 143 JAGUAR XF 2.0 P TSS (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	B1	0.00	0.00	*1,600.00F ✓
2	1		*FRONT BONNET INNER LOCK		0.00	0.00	*60.00F X
3	10		*FRONT BONNET INSULATOR CLIPS		0.00	0.00	*35.00F ?
4	1		*FRONT GRILLE WITH CHROME MOULDING	B1	0.00	0.00	*620.00F X
5	1		*FRONT GRILLE EMBLEM	B1	0.00	0.00	*65.00F X
6	1		*HEADLAMP LH	C14	0.00	0.00	*1,520.00F ✓
7	1		*HEADLAMP BALLAST MODULE		0.00	0.00	*400.00F ✓
8	1		*HEADLAMP WASHER NOZZLE LH		0.00	0.00	*138.00F ? Photo
9	1		*HEADLAMP WASHER NOZZLE COVER LH	M15	0.00	0.00	*45.00F ✓
10	1		*FRONT BUMPER	B1	0.00	0.00	*1,100.00F ✓
11	2		*FRONT BUMPER SIDE RETAINERS LH & RH	M15 DIV	0.00	0.00	*80.00F ✓ photo
12	15		*FRONT BUMPER CLIPS	M1	0.00	0.00	*60.00F ✓
13	1		*FRONT BUMPER LOWER AIR GRILLE		0.00	0.00	*170.00F ?
14	1		*FRONT BUMPER REINFORCEMENT		0.00	0.00	*480.00F ? Photo
15	1		*FRONT BUMPER SPONGE		0.00	0.00	*290.00F ?
16	1		*FRONT BUMPER PARKING SENSOR INNER LH		0.00	0.00	*175.00F ? Photo
17	1		*FRONT BUMPER PARKING SENSOR OUTER LH		0.00	0.00	*175.00F ? Photo
18	4		*FRONT BUMPER PARKING SENSOR BRACKET		0.00	0.00	*144.00F ?
19	1		*FOGLAMP COVER LH	D11	0.00	0.00	*172.00F ✓
20	1		*FOGLAMP COVER CHROME LH	SUN	0.00	0.00	*224.00F ✓

F=Franchise part.

Sub Total (S\$) 7,553.00
 + Margin on L,N Items 10.00% (S\$) 755.30
Total Parts (S\$) 8,308.30

Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	New	120.00
3	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	350.00

Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
4	TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR RADIATOR SUPPORT PANEL;FRONT FENDER LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	600.00 4001
5	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH; RADIATOR SUPPORT PANEL	New	800.00 5001
Gross Labour Cost (S\$)			1,910.00

Ah Lim Motor Company/SKR9336Y/25/04/2019 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

實利基機件(私人)有限公司 SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s Ah Lim Motor Co

Tax Invoice ^(P1)

SSP No. 43396

Order No.

Date: 2/5/19 20

Item	Quantity	Description	Unit Price	Amount
1	1/2	C22 29968 Front lower		1600 00 ✓
2	1/2	C22 31446 Head Lamp		1520 00 ✓
3	1/2	C22 13208XXX Front Bumper		1100 00 ✓
4	2/	C22 16531/C22 16532 bumper Retainer	48/-	96 00 ✓
5	1/2	C25 9354 bumper cap	4/-	60 00 ✓
6	1/2	C22 18083 bumper Reinforcement		480 00 ✓
7	2/	C22 22820 Parking sensor	175/-	350 00 ✓
8	1/2	C22 13454 Fog Lamp Core		172 00 ✓
9	1/2	C22 13455 LH Fog Lamp Chrome		224 00 ✓
10	1/2	C22 16548 Nozzle core		45 00 ✓
11				
12				
13				
14				

Sub Total

5649 00

Add GST @ 7%

395 29

Total Amount

6042 29

Delivered by Received by

N. B. Goods are not returnable after two days.

E. & O. E.

實利基機件(私人)有限公司
SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s Ah Lim Motor Co

Tax Invoice (P2)

SSP No. 43428

Order No.

Date:

20

Item	Quantity	Description	Unit Price	Amount
1	1	C22 13782 Lf nozzle		138.00
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				

Sub Total

138.00

Add GST @ 7%

9.66

Total Amount

147.66

Delivered by Received by

N. B. Goods are not returnable after two days.

E. & O. E.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2019 Sendback Est	25 Apr 2019 11:27 S\$10,218.30	25 Apr 2019 11:40 Edit Adj Rpt	S\$7,343.50 Edit Estimates	S\$7,343.50 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SEAH LENG WAH , ID: S1633611D, Tel: +6596185670, Email: SEAH LW@HOTMAIL.SG		
Vehicle Reg. No.:	SKR9336Y	Date of Loss:	22/04/2019 18:00 - :59 [49 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1902022	Policy/Cover Note No.:	D19MTPV01002671 (Comprehensive)
		Excess:	S\$100.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/05/2019]		
Driver/Custodian:	SEAH LENG WAH (54 / Male), NRIC: S1633611D, Tel: +6596185670 Email: SEAH LW@HOTMAIL.SG		
Adj Asg. Remarks:	FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER PLS CONTACT EILEEN FOR SURVEY ARRANGEMENT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- SOMPO_SG (29/04/2019): Alert - Adj Mandate Approved (S\$8774.80) - SKR9336Y - Claim Handler: Melvin Ye

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKR9336Y (CMTD1902022)

OD

Apr 22 2019 6:00PM

[SEAH LENG WAH]

Ah Lim Motor Company

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Assessment Reports				
			1 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)		
1	25/04/19 11:27	Repairer Estimates		Thumbnail Print
				Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	29/04/19 12:11	Adjuster Immediate Advice		Thumbnail Print
				Load HTM
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
2	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
3	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
4	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
5	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
6	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
7	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
8	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
9	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
10	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
11	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
12	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
13	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
14	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
15	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
16	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
17	29/04/19 12:13	Odometer Reading		Thumbnail Print
				Load JPG
18	29/04/19 12:13	Chassis Number		Thumbnail Print
				Load JPG
19	29/04/19 12:13	Chassis Number		Thumbnail Print
				Load JPG
20	29/04/19 12:13	General View		Thumbnail Print
				Load JPG
21	12/07/19 14:49	Reinspection Photo		Thumbnail Print
				Load JPG
22	12/07/19 14:49	Reinspection Photo		Thumbnail Print
				Load JPG
23	12/07/19 14:49	Reinspection Photo		Thumbnail Print
				Load JPG
24	12/07/19 14:49	Reinspection Photo		Thumbnail Print
				Load JPG
25	12/07/19 14:49	Reinspection Photo		Thumbnail Print
				Load JPG
26	12/07/19 14:49	Reinspection Photo		Thumbnail Print
				Load JPG
27	12/07/19 14:49	Reinspection Photo		Thumbnail Print
				Load JPG
Documentation				
			1 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)		
1	25/04/19 11:26	Log card (if available)		Thumbnail Print
				Load PDF
2	25/04/19 11:26	Certificate of Insurance		Thumbnail Print
				Load PDF
3	25/04/19 11:26	Driver's Driving License		Thumbnail Print
				Load PDF

Assessment Reports			1 per page ▾	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 14:44	PARTS INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▾	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	23/04/19 17:17	Accident Statement	Load HTM	
Photos/Images			3 per page ▾	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	23/04/19 16:46	Accident Photo	Load JPG	☒
2	23/04/19 16:46	Accident Photo	Load JPG	☒
3	23/04/19 16:46	Accident Photo	Load JPG	☒
4	23/04/19 16:46	Accident Photo	Load JPG	☒
5	23/04/19 16:46	Accident Photo	Load JPG	☒
6	23/04/19 16:46	Accident Photo	Load JPG	☒
7	23/04/19 16:46	Accident Photo	Load JPG	☒
8	23/04/19 16:46	Accident Photo	Load JPG	☒
9	23/04/19 16:46	Accident Photo	Load JPG	☒
10	23/04/19 16:46	Accident Photo	Load JPG	☒
11	23/04/19 16:46	Accident Photo	Load JPG	☒
12	23/04/19 16:46	Accident Photo	Load JPG	☒
13	23/04/19 16:46	Accident Photo	Load JPG	☒
14	23/04/19 16:46	Accident Photo	Load JPG	☒
15	23/04/19 16:46	Accident Photo	Load JPG	☒
16	23/04/19 16:46	Accident Photo	Load JPG	☒
17	23/04/19 16:46	Accident Photo	Load JPG	☒
18	23/04/19 16:46	Accident Photo	Load JPG	☒
Documentation			1 per page ▾	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	23/04/19 17:16	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19007290/KQD3S2

Date: 15/07/2019

REFERENCE

Insured/Claimant: SEAH LENG WAH Policy No: D19MTPV01002671
Date of Loss: 22/04/2019 Nature of Claim: OD Claim No: CMTD1902022

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR9336Y**
Make & Model: JAGUAR XF, 2.0 P TSS (A) Engine No: 091214212852204PT
Reg. Date: 18/03/2015 (Man. Year: 2015) Chassis No: SAJAC05M3FPU66689
Colour: Metallic Maroon Odometer: 2472 km
Engine Capacity: 1999 cc
Market Value/New Car Price: S\$106,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,308.30	6,363.50	1,944.80	23.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	980.00	930.00	48.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,218.30	7,343.50	2,874.80	28.13
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	10,218.30	6,643.50	3,574.80	34.98
+ GST 7.00/7.00% (S\$)	715.28	465.05	250.23	34.98
Nett Amount (S\$)	10,933.58	7,108.55	3,825.03	34.98

INSPECTION

Date of Assignment: 25/04/2019 Present Location: Ah Lim Motor Company (AMK)
Ah Lim Motor Company (AMK)
Date Inspected: 26/04/2019 Inspected At: 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

7/15/2019

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2019)
Parts: 143	JAGUAR XF 2.0 P TSS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKR9336Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Bent	1,600.00 F	*1,600.00 F
2	1		*FRONT BONNET INNER LOCK (WCP)	Repair	60.00 F	*- F
3	10		*FRONT BONNET INSULATOR CLIPS (WCP)	Not Necessary	35.00 F	*- F
4	1		*FRONT GRILLE WITH CHROME MOULDING (WCP)	Serviceable	620.00 F	*- F
5	1		*FRONT GRILLE EMBLEM (WCP)	Serviceable	65.00 F	*- F
6	1		*HEADLAMP LH (WCP)	Cracked	1,520.00 F	*1,520.00 F
7	1		*HEADLAMP BALLAST MODULE (WCP)	Serviceable	400.00 F	*- F
8	1		*HEADLAMP WASHER NOZZLE LH (WCP)	Cracked	138.00 F	*138.00 F
9	1		*HEADLAMP WASHER NOZZLE COVER LH (WCP)	Missing	45.00 F	*45.00 F
10	1		*FRONT BUMPER (WCP)	Bent	1,100.00 F	*1,100.00 F
11	2		*FRONT BUMPER SIDE RETAINERS LH & RH (WCP)	Distorted	80.00 F	*96.00 F
12	15		*FRONT BUMPER CLIPS (WCP)	Necessary	60.00 F	*60.00 F
13	1		*FRONT BUMPER LOWER AIR GRILLE (WCP)	Serviceable	170.00 F	*- F
14	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	480.00 F	*480.00 F
15	1		*FRONT BUMPER SPONGE (WCP)	Serviceable	290.00 F	*- F
16	1		*FRONT BUMPER PARKING SENSOR INNER LH (WCP)	Shorted	175.00 F	*175.00 F
17	1		*FRONT BUMPER PARKING SENSOR OUTER LH (WCP)	Shorted	175.00 F	*175.00 F
18	4		*FRONT BUMPER PARKING SENSOR BRACKET (WCP)	Serviceable	144.00 F	*- F
19	1		*FOGLAMP COVER LH (WCP)	Distorted	172.00 F	*172.00 F
20	1		*FOGLAMP COVER CHROME LH (WCP)	Scratched	224.00 F	*224.00 F

F=Franchise part.

Sub Total (\$\$)	7,553.00	5,785.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	755.30	578.50
Total Parts (\$\$)	8,308.30	6,363.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	New	120.00	60.00
3	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	350.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR RADIATOR SUPPORT PANEL;FRONT FENDER LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	600.00	400.00
5	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH; RADIATOR SUPPORT PANEL	New	800.00	500.00
Gross Labour Cost (\$\$)			1,910.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >