

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5209S**AAD1904-143***Not Notarized**Reserve 34 point**84594.93*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5209S

JTDKB3FU103076646

TOYOTA

PRIUS

13.4.2019

III

15/11/2018

PART**LIST**

1	1 REAR BUMPER	\$	Bu	458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	Bu	318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	Sn	14.70	✓
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	Real Bu	552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	Sn	112.70	X
6	1 REAR BUMPER SIDE RETAINER RH	\$	Sn	112.70	X
7	1 REAR TAILGATE	\$	Bu	1,547.27	✓
8	1 REAR TAILGATE OUTER GARNISH	\$	Sn	905.10	} X
9	1 COVER, REAR COMBINATION LAMP, RH	\$	Sn	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	Sn	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	Sn	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	Sn	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	Sn	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	Sn	51.20	} X
15	1 REAR TAILGATE WEATHERSTRIP	\$	Sn	365.20	
16	1 REAR END PANEL	\$	Bu	602.10	
17	1 TAILLAMP LOWER RH	\$	Sn	548.40	
18	1 TAILLAMP UPPER RH	\$	Sn	557.90	
19	1 REAR BUMPER SIDE RH	\$	Sn	232.00	} X
20	1 REAR BUMPER SIDE LH	\$	Sn	232.00	
21	1 TAILLAMP LOWER LH	\$	Sn	548.40	
22	1 TAILLAMP UPPER LH	\$	Sn	557.90	
23	1 PAN, REAR FLOOR	\$	N	572.10	
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	N	77.00	
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	N	192.90	
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	N	77.00	
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	N	192.90	
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	N	290.50	

Trans-cab Auto Services Pte Ltd

AAD1904-143

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5209S

29	1 REAR FENDER LH	\$	<i>R</i> 817.50 <i>X</i>
30	1 REAR FENDER RH	\$	<i>R</i> 817.50 <i>X</i>
		\$	11,305.97
25%		\$	2,826.49
		\$	8,479.48

Special Nett

1	1SET PARKING AID	\$	<i>P</i> 700.00 <i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>me</i> 22.00 <i>✓</i>
3	2 REAR WINDSCREEN SELANT	\$	<i>me</i> 80.00 <i>4000</i>
4	1 WINDSCREEN MOULDING	\$	<i>me</i> 100.00 <i>✓</i>
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>me</i> 100.00 <i>3000</i>
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>me</i> 47.00 <i>✓</i>
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>me</i> 52.90 <i>✓</i>
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>me</i> 53.50 <i>✓</i>
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>me</i> 80.00 <i>3000</i>
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>me</i> 80.00 <i>3000</i>
11	1 REAR BUMPER PROTECTOR	\$	<i>me</i> 100.00 <i>X</i>

TOTAL \$ 1,415.40**TOTAL PARTS \$ 9,894.88****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>6601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 <i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>301</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>501</i>

Trans-cab Auto Services Pte Ltd**AAD1904-143**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5209S

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X

TOTAL \$ 7,750.00**Over All Total \$ 26,124.36****(PART-BY-PART) Repair Days****14 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: