



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunus Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SJX7211S

Model : Volkswagen SCIROCCO

Damaged Area: (Front Right Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

1	Front Right Wing Mirror	\$ 11	695.00	X
2	Front Right Wing Mirror Garnish	\$ 17	107.00	X
3	Front Right Wing Mirror Signal Lamp	\$ 17	175.00	X
4	Front Right Wing Mirror Sponge Based	\$ 17	57.00	X
5	Front Right Door	17	Repair	X
6	Front Right Door Glass Outer Moulding	\$ 17	175.00	X
Parts :		\$	1,209.00	
Less Parts 5% :		\$	60.45	
Total Parts :		\$	1,148.55	

Special Net Items :

Front Right Door Inner Trimboard Clips

	\$ 17	48.00	X
Total S/N Parts :	\$	48.00	

Labour :

To Remove, Repair & Renew Affected Accident Areas

To Putty, Spray Paint on Affected Accident Areas

To Check & Re-Connect all electrical wiring

To Conduct Diagnostic & Reset Engine Mangement

	\$	400.00	} 180
	\$	400.00	
	\$ 17	50.00	X
	\$ 17	450.00	X
Total Labour :	\$	1,300.00	

TOTAL PARTS :	\$	1,148.55
TOTAL SPECIAL NET ITEM :	\$	48.00
TOTAL LABOUR :	\$	1,300.00
TOTAL REPAIR COST :	\$	2,496.55

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

not Authorized
Lhr
p/p \$ 180
2 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: