

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0532/2019/DY/TF
Date : 24-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SHC 8122 T

India International Insurance Pte Ltd

64 Cecil Street

#04-00/05-00 IOB Building

Singapore 049711

Attn: Motor Claims Dept

Tel: 6347 6100 Fax: 6224 4174

Owner's Name : Mr. Lee Ching Huat
Address : 53 Hume Avenue
#06-06
Singapore 598751
Telephone : HP 90030482
Type of Claim : Third Party Claims
Policy No. : 1800053510
Vehicle No : **SGM 5660 K**
Model Code : Audi A6 1.8 TFSI S tronic
Model / Year : May-18
Engine No : CYG 022614
Chassis No : WAUZZZ4G9JN027725
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Apr-19
Place of Accident : Slip Rd entrance to 150C Paya Lebar Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGM 5660 K

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer lhs front door's multi lock systems and power window devices. Inspect for damages and renew if necessary.	s/n	\$ 280.00	
2	To dismantle and renew lhs front door and lhs wing mirror assy. Re-organise crash management components. Reinstall all parts removed.		\$ 1,400.00	
3	To respray lhs front door, door handle and lhs wing mirror cover.		\$ 1,500.00	
4	To carry out diagnostic checks.	s/n	\$ 192.00	
TOTAL LABOUR CHARGES		:	<u>\$ 3,372.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGM 5660 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - LH	\$ 3,374.00	
2	FRONT DOOR STONE GUARD FILM - LH	\$ 110.00	
3	FRONT DOOR ATTACHMENT PARTS	\$ 173.00	
4	FRONT DOOR OUTER SEAL - LH	\$ 212.00	
5	BONDING AGENT	\$ 45.00	
6	CLEANING SOLUTION	\$ 65.00	
7	APPLICATOR	\$ 7.00	
8	FRONT DOOR CATCH - LH	\$ 109.00	
9	FRONT DOOR HANDLE - LH	\$ 537.00	
10	FRONT DOOR HANDLE CAP - LH	\$ 102.00	
11	FRONT DOOR HANDLE CAP HOUSING - LH	\$ 7.00	
12	FRONT DOOR HANDLE SENSOR - LH	\$ 237.00	
13	FRONT DOOR SLOT SEAL CHROME TRIM	\$ 310.00	
14	FRONT WIND MIRROR MOUNTING - LH	\$ 1,291.00	
15	FRONT WIND MIRROR COVER - LH	\$ 195.00	
16	FRONT WIND MIRROR TURN SIGNAL - LH	\$ 116.00	
17	FRONT WIND MIRROR WARNING DISPLAY - LH	\$ 189.00	
18	FRONT WIND MIRROR GLASS - LH	\$ 1,132.00	
19	SUNDRIES	\$ 500.00	
TOTAL SPARE PARTS CHARGES		\$ 8,711.00	
TOTAL LABOUR CHARGES		\$ 3,372.00	
GRAND TOTAL		\$ 12,083.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant