

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0513/2019/DY/TF
Date : 18-Apr-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle no. : SJQ 5681 T

ERGO INSURANCE PTE LTD

Motor Claims Dept

5 Temasek Boulevard

#04-01 Sunteck Tower Five

Singapore 038985

Attn: Motor Claims Dept

Tel: 6829 9199

Owner's Name : Mr. Ramasamy Silvam
Address : Blk 359 Admiralty Drive
#12-192
Singapore 750359
Telephone : 9700908
Type of Claim : Third party Claims
Policy No. : 1800109904
Vehicle No : **SME 2015 P**
Model Code : Audi A4 Sedan TFSI 8W
Model / Year : Sep-18
Engine No : CVK 068899
Chassis No : WAUZZZF46JA232963
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Apr-19
Place of Accident : PIE (Changi) before Lornie Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 2015 P

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	s/n \$ 360.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 600
3	To respray rear bumper.	\$ 800.00 600
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 2,252.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2015 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Repis</i>	\$ 2,015.00	X
2	REAR BUMPER FIXING PARTS	\$ 66.00	X
3	REAR BUMPER SECURING STRIP	\$ 203.00	X
4	REAR BUMPER SPOILER	\$ 227.00	X
5	REAR BUMPER REFLECTOR - RH	\$ 38.00	X
6	REAR BUMPER CARRIER	\$ 819.00	X
7	REAR BUMPER CARRIER SEAL	2 \$ 25.00	X
8	REAR BUMPER TOP GUIDE SECTION - RH	\$ 20.00	X
9	REAR BUMPER TOP GUIDE SECTION PIN	\$ 3.00	X
10	REAR BUMPER SENSOR	2 \$ 462.00	X
11	REAR BUMPER SENSOR SEAL	4 \$ 12.00	X
12	SUNDRIES	\$ 400.00	X
GRAND TOTAL SPARE PARTS		: \$ 4,290.00	
TOTAL LABOUR CHARGES		: \$ 2,252.00	
GRAND TOTAL		: \$ 6,542.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 26/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant