

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A**AAD1904-224***Not Authored
Resony B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 81A

VF1ABL15AUC283395

RENAULT

LATITUDE

23.4.2019

CHINA TAIPING

24/7/2017

PART**LIST**

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	RADIATOR GRILLE
15	1	RADIATOR GRILLE BADGE 'RENAULT'
16	1	RADIATOR GRILLE FRAME
17	1	FRAME FULL SUPPORT PANEL
18	1	FRAME FULL SUPPORT BRACKET
19	1	FRONT BRACE PANEL
20	1	HORN
21	1	HORN BRACKET
22	1	HEADLAMP LH
22	1	HEADLAMP HARNESS
22	1	HEADLAMP RH
22	1	HEADLAMP HARNESS
22	1	HEADLAMP PANEL FRT LH
25	1	HEADLAMP PANEL FRT RH
26	1	BONNET

\$	<i>BA/CM</i>	1,259.42	✓
\$	<i>Sm</i>	181.75	X
\$	<i>CM</i>	394.68	✓
\$	<i>CM</i>	151.41	✓
\$	<i>Sm</i>	123.88	X
\$	<i>Sm</i>	150.77	X
\$	<i>Sm</i>	123.88	X
\$	<i>CM</i>	472.83	✓
\$	<i>Sm</i>	266.80	X
\$	<i>Mr</i>	207.21	✓
\$	<i>Sm</i>	207.21	X
\$	<i>R</i>	914.08	✓
\$	<i>Sm</i>	28.61	X
\$	<i>Sm</i>	1,707.78	X
\$	<i>Sm</i>	225.36	X
\$	<i>CM</i>	1,353.75	✓
\$	<i>CM</i>	615.90	✓
\$	<i>R</i>	89.79	X
\$	<i>R</i>	177.22	X
\$	<i>Sm</i>	314.17	X
\$	<i>R</i>	40.45	X
\$	<i>Bu</i>	1,184.43	✓
\$	<i>Sm</i>	928.29	✓
\$	<i>mb CM</i>	1,184.43	✓
\$	<i>Sm</i>	928.29	X
\$	<i>Mr</i>	152.15	✓
\$	<i>R</i>	152.15	X
\$	<i>R</i>	1,941.63	✓

Trans-cab Auto Services Pte Ltd**AAD1904-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

27	1	BONNET INSULATOR	\$	SL	405.73	X
28	1	BONNET STRUT LH	\$	SL	88.61	X
29	1	BONNET STRUT RH	\$	SL	88.61	Λ
30	1	BONNET HINGE LH	\$	BZ	348.31	✓
31	1	BONNET HINGE RH	\$	DIT	348.31	✓
32	1	BONNET LOCK	\$	R	305.48	X
33	1	BONNET CABLE	\$	SL	119.19	X
34	1	BONNET CABLE COVER	\$	SL	161.03	X
35	1	BONNET SEAL OUTER	\$	SL	92.36	X
36	1	BONNET SEAL INNER	\$	SL	157.28	X
37	1	FENDER PANEL FRT LH	\$	BZ	783.83	✓
38	1	WHEELARCH FRT LH	\$	CM	278.84	✓
39	1	FENDER BRACKET LOWER LH	\$	DIT	15.79	✓
40	1	FENDER INSULATOR LH	\$	SL	130.84	X
41	1	FENDER PANEL INNER FRT RH L70Y	\$	BZ	1,654.50	✓
42	1	FENDER PANEL SUPPORT FRT RH L70Y	\$		1,095.24	?
43	1	FENDER PANEL BRACKET FRT RH L70Y	\$		209.97	?
44	1	FENDER PANEL BRACKET FRT RH L70Y	\$		143.27	?
45	1	WHEEL HOUSING PANEL FRT RH L70Y	\$		4,682.09	?
46	1	WIPER RESERVOIR	\$	SL	348.25	X
47	1	WIPER RESERVOIR NECK	\$	SL	136.11	X
48	1	WIPER RESERVOIR MOTOR	\$	SL	270.06	X
49	1	AIR CLEANER LOWER	\$	SL	271.26	X
50	1	AIR CLEANER HOSE	\$	SL	76.14	X
51	1	AIR CLEANER BOX	\$		464.20	?
52	1	TURBO DUCT	\$		1,027.80	?
53	1	A/C HEATER VALVE	\$		484.50	?
54	1	SUBFRAME OUTER FRT	\$	BZ	2,652.45	✓
55	1	SUBFRAME BRACKET OUTER LH	\$	DIT	92.36	✓
56	1	SUBFRAME BRACKET OUTER RH	\$	R	92.36	✓
57	1	ENGINE UNDERTRAY	\$		564.98	?
58	1	A/C CONDENSER	\$	SL	2,020.37	} X
59	1	A/C CONDENSER GARNISH LH UPPER	\$	SL	39.67	
60	1	A/C CONDENSER GARNISH RH UPPER	\$	SL	39.67	
61	1	A/C CONDENSER GARNISH LH	\$	SL	58.81	
62	1	A/C CONDENSER GARNISH RH	\$	SL	59.60	
63	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SL	208.39	}
64	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SL	658.72	

Trans-cab Auto Services Pte Ltd**AAD1904-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

74	1	A/C PIPE COMPRESSOR	\$	SL	334.29	
75	1	A/C PIPE	\$	SL	658.72	
76	1	A/C COMPRESSOR	\$	SL	2,684.61	
77	1	AIR COOLER	\$	SL	792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	SL	1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	SL	375.14	
80	1	TRANSMISSION COOLER	\$	SL	1,219.30	
81	1	TRANSMISSION COOLER PAD	\$	SL	17.96	
82	1	RADIATOR	\$	SL	1,202.20	
83	2	RADIATOR STUD UPPER	\$	SL	14.41	
84	2	RADIATOR BUSH UPPER	\$	SL	50.12	
85	2	RADIATOR MTG LOWER	\$	SL	55.85	
86	1	RADIATOR FAN COWLING	\$	SL	820.54	
87	1	RADIATOR FAN MOTOR LH	\$	SL	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	SL	1,479.46	
89	1	RADIATOR TANK	\$	SL	324.62	
90	1	RADIATOR HOSE UPPER	\$	SL	240.56	
91	1	RADIATOR HOSE LOWER	\$	SL	491.18	
92	1	RADIATOR TANK HOSE	\$	SL	61.18	
93	1	AUTO COMPUTER	\$	CM	5,032.17	✓
94	1	INJECTION COMPUTER	\$		4,706.30	?
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	BL/SL	5,154.52	✓
96	1	STEERING PUMP ELECTRIC	\$	R	2,306.90	✓
97	1	STEERING PINION RACK	\$	NIP	4,413.11	X
98	1	SEATBELT LH L70Y	\$	T	2,937.80	✓
99	1	SEATBELT RH L70Y	\$	T	2,925.37	✓
100	1	SEATBELT BUCKLE LH L70Y	\$		984.13	?
101	1	SEATBELT BUCKLE RH L70Y	\$		949.80	?
102	1	PASSENGER AIRBAG L70Y	\$	Aug	3,412.40	✓
103	1	STEERING AIRBAG L70Y	\$	L	2,525.75	✓
104	1	AIRBAG COMPUTER L70Y	\$	L	1,259.82	✓
105	1	AIRBAG SENSOR L70Y	\$	L	724.63	✓
106	1	AIRBAG SENSOR L70Y	\$	L	289.30	✓
107	1	DASHBOARD L70Y	\$	T	4,900.54	✓
108	1	WINDSCREEN FRT L70Y	\$	CM	1,364.06	✓
109	1	AIRBAG COMPUTER L70Y	\$	Revised	1,259.82	X
110	1	AIRBAG SENSOR L70Y	\$	L	724.63	X
111	1	AIRBAG SENSOR L70Y	\$	L	289.30	X

Trans-cab Auto Services Pte Ltd**AAD1904-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

112	1	LOWER ARM LH	\$	B ₁	685.76	—
113	1	KUNCKLE ARM LH	\$	B ₁	846.98	—
114	1	ABSORBER FRT LH	\$	B ₁	360.54	—
115	1	STABILIZER BAR FRT	\$		604.65	?
116	1	DRIVESHAFT LH	\$		1,747.45	?
117	1	LOWER ARM LH L70Y	\$	Agnew	685.76	X
118	1	KUNCKLE ARM LH L70Y	\$	h	846.98	X
119	1	ABSORBER FRT LH L70Y	\$	h	360.54	X

TOTAL	\$	101,256.53
10%	\$	10,125.65
	\$	91,130.88

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00	—
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	na	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
21	1	Windscreen moulding	\$	na	100.00	—
22	1SET	Front licence plate with holder	\$	na	80.00	X
23	1	DOOR CHECK BOLT	\$	na	22.69	
24	1	DOOR GUIDE SCREW	\$	na	10.85	
25	1	DOOR HINGE BOLT	\$	na	10.85	
26	1	DOOR HINGE NUT RH	\$	na	14.60	
27	1	DOOR CHECK BOLT	\$	na	22.69	
28	1	DOOR CHECK NUT	\$	na	3.75	
29	1	DOOR LOCK SCREW L70Y	\$	na	6.12	

Trans-cab Auto Services Pte Ltd

AAD1904-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

30	1	DOOR CATCH SCREW L70Y	\$	Sn	10.06
31	1	WINDSCREEN SEALANT	\$	nn	253.80 401n
32	1	FRONT LEFT TYRE	\$	nn	300.00 802n
33	1	FRONT LEFT TYRE RIM	\$	Bj	380.00 ✓

TOTAL	\$	1,597.93
--------------	-----------	-----------------

TOTAL PARTS	\$	92,728.80
--------------------	-----------	------------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	1200	6,000.00
Towing Fees.	\$	120.00	501
To apply paint protection system (PPS) maintain and enhancement	\$	nn	380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00	13201
To rust-proofing of the affected areas.	\$	170.00	1201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To check steering geometry and computer wheel alignment	\$	220.00	601
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 2501
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To lift-up engine with gear box and refit.	\$	440.00	2801

Trans-cab Auto Services Pte Ltd**AAD1904-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 1001
To remove and refit air bag system and reset.	\$	480.00 2201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 1001
To replace, refix and top up coolant for radiator	\$	170.00 501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 1201
To remove and renew engine and gear box mounting.	\$	nn 380.00 X
To dismantle and refit engine cross-member and engine mounting.	\$	nn 380.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

To remove and refit ABS pump relay to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>201</i>

TOTAL	\$	19,130.00
--------------	-----------	------------------

Over All Total	\$	111,858.80
-----------------------	-----------	-------------------

Repair Days (Lump Sum)**~~30~~ DAYS***24 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: