



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19007315/Aea3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-05-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGM 3231D	Veh. Inspected	SJW 7043R
Policy No.	DMPCSN1634471802	Coverage (\$)	0.00
Claim No.	SNM19D201819C02/1	Excess (\$)	0.00
Assign From		Assign Date	24/04/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHMRB38509C201906	Colour	BLACK
Odometer	149491	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DAVANTI	6 mm
L/H Front Tyre	215/55 R17	DAVANTI	6 mm
R/H Rear Tyre	215/55 R17	DAVANTI	6 mm
L/H Rear Tyre	215/55 R17	DAVANTI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/04/2019	Inspection Date	24/04/2019
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------