

S M SPRAY PAINTING PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KB Singapore 417800

Tel: 6384 1755/1766

Fax: 6384 1744

TP LongPac.
Ashes.

25th APRIL 2019

LIM KAY YIT
Bk 25 Kaki Bukit Rd 4
08-30 SYNERGY @KB
Singapore 417800

Accident date: 16th March 2019 SJY3113M.
Estimated repair cost for vehicle no: SJ3113M AUDI A4 2.0TFSI '09

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,850.00 ✓
2	1	Rear boot lid center Emblem logo <i>new</i>		\$78.00 ✓
3	1	Rear boot lid A4 Logo		\$44.00 ✓
4	1	Rear Boot lid 2.0T logo		\$52.00 ✓
5	2	Rear Boot Lid side reflector <i>could</i>	\$748.00	\$1,496.00 ✓
6	1	Rear Boot lid Inner lock <i>new</i>		\$325.00 ✓
7	1	Rear boot lid inner rubber		\$225.00 ✓
8	1	Rear Boot Lid Inner Trim board		\$485.00 ✓
9	10	Rear Boot Lid Inner Trim board clips	\$6.50	\$65.00 ✓
10	2	Rear tail Lamp <i>new</i>	\$775.00	\$1,550.00 ✓
11	4	Rear tail lamp clips	\$6.50	\$26.00 ✓
12	1	Rear Bumper <i>Debond</i>		\$1,255.00 ✓
13	10	Rear Bumper Clips <i>new</i>	\$6.50	\$65.00 ✓
14	2	Rear Bumper Side Bracket <i>new</i>	\$85.00	\$170.00 ✓
15	4	Rear Bumper Reverse Sensor <i>new</i>	\$245.00	\$980.00 ✓

Subtotal :- \$8,666.00

4975

4477.50

Labour charges

To remove & refix cushion

~~\$150.00~~ 40

To remove & re-fix reverse sensor

~~\$100.00~~ 60

To remove & refix rear exhaust

~~\$0.00~~ X

To check wiring

~~\$60.00~~ 30

Tuff kote

~~\$120.00~~ X

Panel beating

~~\$800.00~~ 400

Spray painting

~~\$800.00~~ 400

Subtotal :- \$2,030.00

Total:- \$10,696.00

total: 5407.50

H/S: 4K

(Nett Value)

04 Days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: