

Surveyor:

DOI:

Date / Time:

Registered in Marimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

JRJ 7838 - X

SLC 8030 C-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call CI:

After call ltr to CI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to CI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lin.:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

120.00 (\$ 30 x 4 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

6020.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6020.00

Name 1:

AE Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Non-Report/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

24/4/19

HAW-W

ASS. REC. BY:

REF: EQ1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s AE Auto

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4.5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1 / File pass to
Est not ready

US\$ 5900 Cred \$ 2078 by JHY

15/20/2019

Veh No: JR J 7838 Yr Regn: 02, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or Pick upMake: Mit Triton VGT cc 2477Colour: M. Black A/C: Insured / Std / Nil / NASp. Reading: 155879 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: NMBJYK2 30614020123Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 265/70R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HankookFront 8 mmR/Bal. 6 mmL/Bal. 6 mmD.O.A. 17/4/19 D.O.I. 24/4/19Survey held at 24Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS - SI

Pumps

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQ119007319/Kca3

Date: 30/04/2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

JRJ 7838


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/04/2019 at the premises of M/s AE Auto Pte Ltd - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	13,878.80
Revised Estimate Amount	: S\$	7,500.90
"Check" Items Amount	: S\$	2,962.80
Total (Including Check Items)	: S\$	10,463.70
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4-5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

KP

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
11 May 859006
Resurvey After Paint
4 days

Date : 24/04/2019

QUOTATION - THIRD PARTY CLAIM

EQ INSURANCE COMPANY LIMITED

Attn: Motor Claim Department, Officer In Charge

Accident on : 17/04/2019

Claim : Third Party Claim
Veh. No : JRJ 7838
Model : MITSUBISHI TRITON
Insured Ins: ETIOA TAKAFUL

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SLC 8030 C		
1	TAILGATE <i>Re</i>	\$ 2,850.00	✓
1	TAILGATE CENTER LOGO <i>Re</i>	\$ 78.00	—
1	TAILGATE TRITON EMBLEM <i>Re</i>	\$ 68.00	—
1	TAILGATE VGT EMBLEM <i>Re</i>	\$ 68.00	—
1	TAILGATE COMMON RAIL EMBLEM <i>Re</i>	\$ 68.00	—
1	TAILGATE DHD EMBLEM <i>Re</i>	\$ 68.00	—
1	TAILGATE LOCK	\$ 385.00	X
1	TAILGATE LATCH	\$ 78.00	X
1	TAILGATE TRIM BOARD	\$ 580.00	2
1	END PANEL	\$ 480.00	X
1	FLOOR PANEL	REPAIR	X
2	REAR No.PLATE LAMPS <i>CRS</i>	\$ 442.00	✓
2	TAILLAMPS <i>offered</i>	\$ 960.00	✓ X
2	TAILLAMP PANELS	\$ 440.00	X
2	REAR SIDE PANELS	REPAIR	✓
1	REAR BUMPER <i>Re</i>	\$ 1,685.00	✓
2	REAR BUMPER SENSORS <i>Shoy</i>	\$ 420.00	2000
1	REAR BUMPER TOP STEP PAD	\$ 480.00	✓
1	REAR CENTER STEP PANEL	\$ 580.00	X
2	REAR SIDE STEP PAD <i>342</i> <i>MSDIT</i>	\$ 664.00	✓
1	REAR BUMPER INNER BRACKET	\$ 580.00	✓
1	REAR BUMPER REINFORCEMENT	\$ 650.00	X
2	REAR BUMPER BRACKETS <i>MSDIT</i> <i>MS Re</i>	\$ 448.00	✓
2	REAR BUMPER BRACKET HOLDERS <i>Re</i>	\$ 580.00	X
		\$ 12,632.00	
	Less 10%	\$ 1,263.20	
		\$ 11,368.80	
	S/NETT PARTS		
1	REAR No.PLATE <i>(Com Type)</i> <i>Re</i>	\$ 50.00	2000
	TOTAL S/NETT	\$ 50.00	
	TOTAL PARTS :	\$ 11,418.80	

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #05-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 11,418.80	
	Labour charges to replace, repair accident affected area	\$ 900.00	6001
	Labour to remove refix trim board, side trims, rear floor panel board etc	\$ 200.00	801
	To transfer tailgate parts to another tailgate	\$ 80.00	301
	Check wiring system, sensor etc	\$ 180.00	701
	Anti rust	\$ 100.00	301
	To do sealant, seal gap, water proofing on rear accident area	\$ in 200.00	X
	To do spray painting on affected area	\$ 800.00	6001
	Total Labour :	\$ 2,460.00	
	Total Parts & Labour :	\$ 13,878.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
11 Days 8?
Resurvey After Paint
4-5 days

Date : 24/04/2019

QUOTATION -THIRD PARTY CLAIM

EQ INSURANCE COMPANY LIMITED

Attn: Motor Claim Department - Officer In Charge

Claim : Third Party Claim
Veh. No : JRJ 7838
Model : MITSUBISHI TRITON
Insured Ins: ETIQA TAKAFUL

Accident on : 17/04/2019

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SLC 8030 C		
1	TAILGATE <i>Re</i>	\$ 2,850.00	✓
1	TAILGATE CENTER LOGO <i>Re</i>	\$ 78.00	✓
1	TAILGATE TRITON EMBLEM <i>Re</i>	\$ 68.00	✓
1	TAILGATE VGT EMBLEM <i>Re</i>	\$ 68.00	✓
1	TAILGATE COMMON RAIL EMBLEM <i>Re</i>	\$ 68.00	✓
1	TAILGATE DHD EMBLEM <i>Re</i>	\$ 68.00	✓
1	TAILGATE LOCK	\$ <i>Re</i> 385.00	X
1	TAILGATE LATCH	\$ <i>Re</i> 78.00	X
1	TAILGATE TRIM BOARD	\$ 580.00	?
1	END PANEL	\$ 480.00	?
1	FLOOR PANEL	REPAIR	
2	REAR No.PLATE LAMPS	\$ 442.00	?
2	TAILLAMPS <i>offered</i>	\$ <i>Ins</i> 960.00	<i>4X</i>
2	TAILLAMP PANELS	\$ <i>Re</i> 440.00	X
2	REAR SIDE PANELS	REPAIR	
1	REAR BUMPER <i>Re</i>	\$ 1,685.00	✓
2	REAR BUMPER SENSORS <i>Shoy</i>	\$ 420.00	<i>20012</i>
1	REAR BUMPER TOP STEP PAD	\$ <i>Re</i> 480.00	✓
1	REAR CENTER STEP PANEL	\$ 580.00	?
2	REAR SIDE STEP PAD <i>MJNIT</i>	\$ 664.00	<i>LP</i>
1	REAR BUMPER INNER BRACKET	\$ <i>Re</i> 580.00	✓
1	REAR BUMPER REINFORCEMENT	\$ 650.00	?
2	REAR BUMPER BRACKETS <i>MS Re</i>	\$ 448.00	<i>LP</i>
2	REAR BUMPER BRACKET HOLDERS	\$ 560.00	?
		\$ 12,632.00	
	Less 10%	\$ 1,263.20	
		\$ 11,368.80	
	<u>S/NETT PARTS</u>		
1	REAR No.PLATE <i>(Gen Type)</i> <i>Re</i>	\$ 50.00	<i>20012</i>
	TOTAL S/NETT	\$ 50.00	
	TOTAL PARTS :	\$ 11,418.80	

AE AUTO PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-01
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64591698

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 11,418.80	
	Labour charges to replace, repair accident affected area	\$ 900.00	6001
	Labour to remove refix trim board, side trims, rear floor panel board etc	\$ 200.00	801
	To transfer tailgate parts to another tailgate	\$ 80.00	501
	Check wiring system, sensor etc	\$ 180.00	701
	Anti rust	\$ 100.00	301
	To do sealant, seal gap, water proofing on rear accident area	\$ in 200.00	X
	To do spray painting on affected area	\$ 800.00	6001
	Total Labour :	\$ 2,460.00	
	Total Parts & Labour :	\$ 13,878.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before enter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hsiao Tong (LKKAUTO)

From: Autoexcel Engineering <aeexcel@singnet.com.sg>
Sent: Wednesday, 21 August 2019 12:47 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: JRJ7838 *Our Ref: CC6/EQI19007319/Kpa3 [ACCIDENT INVOLVING SLC 8030C(EQ) AND JRJ 7838 ON 17/04/2019]

Dear Hsiao Tong,

Accept the offer at \$6020.00

Please forward us DV.

Thank you

Best Regards
Ryan Soh
93825367

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, August 17, 2019 12:35 PM
To: Autoexcel (aeexcel@singnet.com.sg) <aeexcel@singnet.com.sg>
Subject: Your Ref: JRJ7838 *Our Ref: CC6/EQI19007319/Kpa3 [ACCIDENT INVOLVING SLC 8030C(EQ) AND JRJ 7838 ON 17/04/2019]

Your Ref: **JRJ7838** **Without Prejudice**
Our Ref: CC6/EQI19007319/Kpa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLC 8030C(EQ) AND JRJ 7838 ON 17/04/2019

We refer to the above matter.

We propose settlement at a global sum of \$6,020.00(all-in).

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Mei Kwan (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 24 May, 2019 3:25 PM
To: Mei Kwan (LKKAuto)
Cc: Asher Sng (LKKAuto); CS A Team; Admin A
Subject: FW: Direct Settlement - Accident Involving SLC8030C (OI : EQI - DM19HO01106/JT) and JRJ7838 (TP : LKK REF - CC6/EQI19007319/Kea3) on 17/04/2019
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf; MSIA LOG CARD.pdf; TP CL.pdf; TP POLICE REPORT.pdf; SAS2587154.PDF

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan

OI report as attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 a member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify th.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Friday, May 3, 2019 1:13 PM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Cc: Janet Tan <janet.tan@eqinsurance.com.sg>; Joel Goh <joel.goh@eqinsurance.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLC8030C (OI : EQI - TBA) and JRJ7838 (TP : LKK REF - CC6/EQI19007319/Kea3) on 17/04/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/ Madam,

We refer to the above matter.

AE AUTO PTE LTD

160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Email: alee.kai@singnet.com.sg

(N5100 Tony)

ATTN: MOTOR CLAIM DEPARTMENT (T.P)

WITHOUT PREJUDICE

ADDRESS: EQ INSURANCE COMPANY LTD

Dear Sir/ Mdm :

Accident involving our vehicle No: ORJ 7838 & your insure vehicle SLC 8030C

Date Of Accident 17/04/19 Along / At Malaysia

Refer to the matter . The accident was caused solely by the negligence of your insured and as a result the following costs and losses had incurred.:

AMOUNT

1	FINAL REPAIR BILL INCLUDE GST	S\$	<u>\$5900/-</u>
2	SURVEYOR REPORT FEE	S\$	<u>LKK</u>
3	RENTAL BILL : L.O.U. <u>4 days x \$80 =</u>	S\$	<u>\$320/-</u>
4	T.P INSURANCE SEARCH : <u>-</u>	S\$	<u>-</u>
5	OTHER DOCUMENT.: <u>-</u>	S\$	<u>-</u>
TOTAL :		S\$	<u>\$6220/-</u>

Please kindly let us have your confirmation to settle our claim within **30 days**.
Kindly contact Ryan Soh regarding the above matter.

Ryan Soh
Hp : 93825367
Tel : 64535654

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 5 August 2019 9:02 AM
To: GALLENCYF@YAHOO.COM.SG
Subject: ACCIDENT INVOLVING SLC 8030C(EQ) AND JRJ 7838 ALONG/ AT KSL CITY VIA TUAS SECOND LINK ON 17/04/2019

05 Aug 2019

MR CHAN YONG FU

Dear Sir/ Mdm

OUR REF : CC6/EQI19007319/Kpa3
YOUR REF : SLC 8030C
ACCIDENT INVOLVING SLC 8030C(EQ) AND JRJ 7838 ALONG/ AT KSL CITY VIA TUAS SECOND LINK ON 17/04/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from JRJ 7838 against your insurance policy.

Based on the accident report and accident scenario, liability is not in your driver's favour as it is a head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORITY & INDEMNITY

To: **AUTOEXCEL ENGINEERING PTE LTD ("AUTOEXCEL")**

ACCIDENT INVOLVING VEHICLE NO. JRJ 7838 AND SLC 8030C
ON 17/04/19

1. I/We, the owner of vehicle no. JRJ 7838 hereby instruct and authorise AUTOEXCEL to commence repairs to the said vehicle.
2. You are authorised to submit my/our claim on my/our behalf, to the Insurers of the third party driver to recover the repair cost, loss of use or rental fees as the case may be, survey report fee and any other expenses which are recoverable.
3. AUTOEXCEL is further authorised to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment is made and instructions are given by me/us with respect to the conduct of my/our claim against the third party driver and/or his/her Insurers including if necessary, to commence legal proceedings in Court in my/our name against the third party.
4. AUTOEXCEL have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his Insurers on such terms as AUTOEXCEL deem fit. Upon settlement of my/our claim, AUTOEXCEL is authorised to sign any Discharge Voucher or any document to confirm my/our acceptance of the settlement as full and final discharge of my/our claim, on my/our behalf.
5. Upon resolving my/our claim, AUTOEXCEL is authorised to agree with my/our solicitors on the amount of their professional costs and disbursements for acting for me/us and to receive payment of the balance of the settlement sum on my/our behalf directly into your account.
6. In the event that I/we and/or the driver of my/our vehicle are required to attend at my/our solicitors' office or to attend Court in connection with my/our claim, I/we shall render full co-operation.
7. Subject to Clause 8 hereinafter, in the event that my/our claim against the 3rd party is not successful, AUTOEXCEL will write off the repair cost.
8. While my/our vehicle is undergoing repairs, AUTOEXCEL will on my /our behalf rent a vehicle for my/our use and recover the rental fees from the 3rd party driver. If no vehicle is rented for my/our use, AUTOEXCEL will on my/our behalf recover damages for loss of use of vehicle and remit the sum recovered to me/us upon successful recovery.
9. I/we agree to pay AUTOEXCEL the repair cost, rental fees (if applicable), survey report fees and legal costs and disbursements in the event that my/our claim is not successful for any one or more of the following reasons :-
 - a. If the driver of my/our vehicle had committed a traffic offence or driving related offence in the above captioned accident and is convicted in a court of law or is served a traffic summons and has accepted and paid the composition fine stated therein.

- b. If I/we and/or the driver of my/our vehicle fails to render full co-operation to sign or make any court documents and/or to attend court in connection with my/our claim.
- c. If the third party driver is uninsured or fails to report the accident to his or her insurers or fails to co-operate with his/her insurers or commits a breach of policy conditions (including but not limited to drunken driving in respect of the accident) resulting in his or her insurers refusing to entertain my/our claim.
- d. If the driver of my/our vehicle had falsely reported the circumstances of the accident or misled AUTOEXCEL in respect of the circumstances of the accident including but not limited to the identity of the driver of my/our vehicle.

Dated : 24 Month : 4 Year : 19

Signed : X 

Name: Mohadzir b. Cho Mai

NRIC No. 620925-02-6171

Contact No./ Email : 013-7723494 / 019-7234493



AE AUTO PTE LTD

160, Sin Ming Drive, Sin Ming Auto City,
#06-01 Singapore 575722
Tel: 6453 5654, 6459 1630 Fax: 6459 1698
Email: aeexcel@singnet.com.sg

PRO FORMA

Reg. No. 201535575N

01/08/2019

INVOICE NO : TP 1524

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK, MND COMPLEX
SINGAPORE 069110

JRJ 7838

MITSUBISHI
TRITON

S/N	DESCRIPTION	AMOUNT S\$
-----	-------------	------------

Accident Date: 17/04/2019

Lump Sum Repair, Supply Parts &
Labour \$ 5,900.00

Sub - Total : \$ 5,900.00

\$ 5,900.00

NOTE : All cheques must be crossed and make
payable to AE Auto Pte Ltd

RECEIVED VEHICLE IN GOOD ORDER

for AE Auto Pte Ltd



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 18/09/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLC 8030C (Insd Veh)	Your Ref. No. : DM19HO01106/JT
	JRJ 7838 (TP Veh)	Our Ref. No. : CC6/EQI19007319/Kpa3q2
Date of Accident	17/4/2019	

Liability	100%	
Final Repair Cost	: \$ 5,900.00	
Loss of Use	: \$ 120.00	4 days
Rental (If any)	: \$	days
Others:	: \$	
	: \$	
	6,020.00	
Final Settlement Sum	: \$ 6,020.00	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1	AE AUTO PTE LTD	: \$ 6,020.00
		: \$

JOANNE LEE


LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ19007319/Kpa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 18-09-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLC 8030C	Veh. Inspected	JRJ 7838
Policy No.	DMPPHQ19-000263	Coverage (\$)	0.00
Claim No.	DM19HO01106/JT	Excess (\$)	0.00
Assign From		Assign Date	24/04/2019
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI TRITON VGT (A)	c.c	2477
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MMBJYKL30GH020123	Colour	METALLIC BLACK
Odometer	155679	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	265/70 R16	HANKOOK	6 mm
L/H Front Tyre	265/70 R16	HANKOOK	6 mm
R/H Rear Tyre	265/70 R16	HANKOOK	6 mm
L/H Rear Tyre	265/70 R16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/04/2019	Inspection Date	24/04/2019
Survey held at	AE AUTO PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRJ 7838

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	2,850.00	2,850.00
1	TAILGATE CENTER LOGO	NECESSARY	78.00	78.00
1	TAILGATE TRITON EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE VGT EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE COMMON RAIL EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE DHD EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	385.00	-
1	TAILGATE LATCH	TO REPAIR SEE LABOUR	78.00	-
1	TAILGATE TRIM BOARD	SERVICEABLE	580.00	-
1	END PANEL	TO REPAIR SEE LABOUR	480.00	-
1	FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
2	REAR NO.PLATE LAMPS	CRACKED	442.00	442.00
2	TAILLAMPS	SERVICEABLE	960.00	-
2	TAILLAMP PANELS	TO REPAIR SEE LABOUR	440.00	-
2	REAR SIDE PANELS (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER	BENT	1,685.00	1,685.00
1	REAR BUMPER TOP STEP PAD	DENTED	480.00	480.00
1	REAR CENTER STEP PANEL	TO REPAIR SEE LABOUR	580.00	-
2	REAR SIDE STEP PAD	N/S DISTORTED	664.00	332.00
1	REAR BUMPER INNER BRACKET	BENT	580.00	580.00
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	650.00	-
2	REAR BUMPER BRACKETS	O/S DISTORTED / N/S BENT	448.00	448.00
2	REAR BUMPER BRACKET HOLDERS	SERVICEABLE	560.00	-
	LESS 10% DISCOUNT		-1,221.20	-716.70
			10,990.80	6,450.30

Report Ref No. CC6/EQ119007319/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER SENSORS (SN)	SHORTED	420.00	200.00
	LESS 10% DISCOUNT		-42.00	-
			378.00	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NO.PLATE (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPLACE ,REPAIR ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK,TAILGATE LATCH,END PANEL,FLOOR PANEL,TAILLAMP PANELS,REAR SIDE PANELS AND REAR CENTER STEP PANEL.		900.00	600.00
	LABOUR TO REMOVE REFIX TRIM BOARD ,SIDE TRIMS ,REAR FLOOR PANEL BOARD ETC.		200.00	80.00
	TO TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE.		80.00	50.00
	CHECK WIRING SYSTEM ,SENSOR ETC.		180.00	70.00
	ANTI RUST.		100.00	30.00
	TO DO SEALANT ,SEAL GAP ,WATER PROOFING ON REAR ACCIDENT AREA.	NOT NECESSARY	200.00	-
	TO DO SPRAY PAINTING ON AFFECTED AREA.		800.00	600.00
			2,460.00	1,430.00
GRAND TOTAL			13,878.80	8,100.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,900.00

Report Ref No. CC6/EQ119007319/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.