

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
11 Lmp 8 ?
Assuming After Paint
4-5 days

Date : 24/04/2019

QUOTATION -THIRD PARTY CLAIM

EQ INSURANCE COMPANY LIMITED

Attn: Motor Claim Department . Officer In Charge

Accident on : 17/04/2019

Claim : Third Party Claim
Veh. No : JRJ 7838
Model : MITSUBISHI TRITON
Insured Ins: ETIQA TAKAFUL

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SLC 8030 C		
1	TAILGATE <i>RM</i>	\$ 2,850.00	✓
1	TAILGATE CENTER LOGO <i>RM</i>	\$ 78.00	✓
1	TAILGATE TRITON EMBLEM <i>RM</i>	\$ 68.00	✓
1	TAILGATE VGT EMBLEM <i>RM</i>	\$ 68.00	✓
1	TAILGATE COMMON RAIL EMBLEM <i>RM</i>	\$ 68.00	✓
1	TAILGATE DHD EMBLEM <i>RM</i>	\$ 68.00	✓
1	TAILGATE LOCK	\$ <i>RM</i> 385.00	X
1	TAILGATE LATCH	\$ <i>RM</i> 78.00	X
1	TAILGATE TRIM BOARD	\$ 580.00	?
1	END PANEL	\$ 480.00	?
1	FLOOR PANEL	REPAIR	
2	REAR No.PLATE LAMPS	\$ 442.00	?
2	TAILLAMPS <i>other AA</i>	\$ <i>RM</i> 960.00	✓ X
2	TAILLAMP PANELS	\$ <i>RM</i> 440.00	X
2	REAR SIDE PANELS	REPAIR	
1	REAR BUMPER <i>RM</i>	\$ 1,685.00	✓
2	REAR BUMPER SENSORS <i>shop</i>	\$ 420.00	20052
1	REAR BUMPER TOP STEP PAD	\$ <i>RM</i> 480.00	✓
1	REAR CENTER STEP PANEL	\$ 580.00	?
2	REAR SIDE STEP PAD <i>MSDIT</i>	\$ 664.00	✓
1	REAR BUMPER INNER BRACKET	\$ <i>RM</i> 580.00	✓
1	REAR BUMPER REINFORCEMENT	\$ 650.00	?
2	REAR BUMPER BRACKETS <i>MS RM</i>	\$ 448.00	✓
2	REAR BUMPER BRACKET HOLDERS	\$ 560.00	?
		\$ 12,632.00	
	Less 10%	\$ 1,263.20	
		\$ 11,368.80	
	<u>S/NETT PARTS</u>		
1	REAR No.PLATE <i>(Cum Type)</i> <i>RM</i>	\$ 50.00	20052
	TOTAL S/NETT	\$ 50.00	
	TOTAL PARTS :	\$ 11,418.80	

AE AUTO PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-01
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64591698

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 11,418.80	
	Labour charges to replace, repair accident affected area	\$ 900.00	6001
	Labour to remove refix trim board, side trims, rear floor panel board etc	\$ 200.00	801
	To transfer tailgate parts to another tailgate	\$ 80.00	501
	Check wiring system, sensor etc	\$ 180.00	701
	Anti rust	\$ 100.00	301
	To do sealant, seal gap, water proofing on rear accident area	\$ in 200.00	X
	To do spray painting on affected area	\$ 800.00	6001
	Total Labour :	\$ 2,460.00	
	Total Parts & Labour :	\$ 13,878.80	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: