

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AXA Insurance Singapore Pte Ltd
8 Shenton Way B1-01 AXA Tower
Singapore 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Estimate : TP19-055

Date : 24/04/2019
Vehicle Num. : GBG1348C
Make/Model : Toyota Dyna-2016
Chassis/Eng# : JTFAT35YXOK207583/1KD2686330
Accident Date : 11/04/2019
Claim No. :
Reference : SKH833R
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-------|---|--------|-----------------|
| 1. | 2 pcs | LIST ITEMS : Rear Lamp Assy L/R <i>LH cancelled</i> | 413.45 | 826.90 |
| 2. | 2 pcs | Rear No. Plate Lamp <i>on</i> | 217.55 | 435.10 <i>x</i> |
| 3. | 1 pc | Rear Bumper <i>missing</i> | | 577.35 <i>x</i> |
| 4. | 2 pcs | Rear Bumper Bracket L/R <i>not new</i> | 218.90 | 437.80 <i>x</i> |
| 5. | 1 pc | Rear Spare Tyre Hanger <i>not new</i> | | 53.70 |
| 6. | 1 pc | Rear Reinforcement <i>new</i> | | 438.80 <i>x</i> |
| 7. | 2 pcs | Rear Floor Panel Rubber Upholstery <i>at</i> | 75.43 | 150.86 <i>x</i> |
| 8. | 1 pc | Rear Chassis Frame <i>Repair</i> | | 581.80 <i>x</i> |

List Total S\$:
25.00% Discount S\$:

285.50
413.45
217.55
218.90
75.43
3,502.41
875.60
2,626.81

- | | | | | |
|----|-------|--|--|-------------------|
| 1. | 1 set | SPECIAL NETT ITEMS : Reverse Sensor <i>not</i> | | 250.00 <i>200</i> |
| 2. | 1 pc | Rear No Plate <i>But</i> | | 25.00 <i>x</i> |
| 3. | 1 pc | Rear Spare Tyre <i>new</i> | | 250.00 <i>x</i> |

Special Nett Total S\$:

LABOUR :
To remove, rearrange electrical wirings, check lighting

To remove, repair and replaced damaged bodyparts,
realign bodyworks & where consistent to the accident

To putty and respray painting on affected area.

Labour Total S\$:

225
250.00 *200*
25.00 *x*
250.00 *x*
525.00

80.00 *30*
1,500.00 *40*
800.00 *25*
2,380.00

Total S\$: 5,531.81

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin Lj total: 1665.28
L/S 02/05/19. 4/5: 1.31c
0489p.