

Kp

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0022085
Soon Chin Poh

Page 1 of 1
Your ref: TP-SHA 2461P India
Job No: 70442
Our ref: 19.04.37
Payment
Date: 24/4/2019

Attn:

Vehicle No: SGV 8080S
Vehicle Model: Toyota Harrier
Accident on: 23/4/2019

Not attached

McBunny B4 paint

52480.83 ✓ 2 days

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts					
1.00	Pc	Rear bumper	1,712.60	10.00	1,541.34 ✓
1.00	Pc	Rear bumper lower spoiler	466.10	10.00	419.49 ✓
1.00	Pc	Rear bumper sponge	137.83	10.00	124.05 X
4.00	Pcs	Rear bumper lower clips	3.50	10.00	12.60 X
Labour & Misc.					
1.00		To transfer rear parking sensor	40.00		40.00 ✓
1.00		To remove and renew above parts	250.00	22%	250.00
1.00		To spray paint (include blend of parking sensor)	300.00	26%	300.00

Sub-Total 2,887.43
GST 7.00% 188.12
Total S\$ 2,875.60

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."