

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

25, APR 2019

AXA Insurance PL
143 Cecil Street
#01-01 GB Building
S 069542

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SLJ4954B
Accident involving vehicle no: SCQ23J/SLJ4954B
DOA: 23/03/2019 AT Dunearn Rd twds Steven Rd

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SCQ23J
To supply—

Description	Qty	Amount
Rear bumper	1 <i>R</i>	1,078.50 ✓
Rear bumper retainer, Rh	1	26.70 ✓
Taillamp Rh	1 <i>R</i>	258.00 X
Parts		1,363.20
Parts less 20%		272.64
		1,090.56

To remove damaged parts and attachments.
Repair/reshape tailgate, rear fender, end panel.
Replace/align above parts into position.
To spray paint

700.00 *4000*
850.00 *4000*

2,640.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts noted subject to confirmation
- Third party claims on a "Without Prejudice" basis
- No cash payment(s) is allowed
- Surveys must be resurveyed and approved by Insurance Company

Approved by Repairer

Not Authorised

11 Sep 8 13501

*Resurvey After Repair
3 days*