

INSURANCE

INS. CASE OWNER:

LYNN

CC 4 ASM AXA1900 7720, JMBZ

LKK IDAC:

Surveyor:

OHS

DOI:

ASSIGNMENT 26/04/19

Date / Time:

25/4/19

Registered in Meritex:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMD 6210E

Claim No.:

S9M02L62/112627

Name of Insured:

OMY VE PMI PATRICK

Policy No.:

P270103

Insured Tel No.:

HP:

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A.:

15/4/19

Place of Accident:

MURRAY TOWN HALL RD

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SMD 6210E

→ SJK 9981P →

→ SLH 5820P →



INSRS: WSP: Tel: Liability: RMKS: 01



INSRS: WSP: Tel: Liability: RMKS: Y.Tee TP



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date / Time

26-6-19 @ 247 PM w/ OI PATRICK

of S9M02L62/112627

3 VC ; OI LAST.

A GREEED & HE SAID HE HAS PROPECTOR.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI

204 26-6-19

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: LG

\$5 1800.00

( 4 days) Reduction: 86 %

Email  Call

FINAL SETTLEMENT

Date/Time: 12/7/19

Confirm with: SHAWN

Email  Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Li: 100

Repair Cost: GST

\$5 1,926.00

Loss of Rental (LOR): GST

\$5 535.00 ( 5 days) 100

Loss of Use (LOU):

\$5 15 x days)

Loss of Income (LOI):

\$5 15 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

\$5 2.00

Medical:

\$5 28 x ✓

Disbursement:

\$5 (e.g. Tow/ Independent)

Legal Cost:

\$5

1) Claim status: N  /Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

Total:

\$5 2,491.00 Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email  Call

Payee 1:

\$5 2,491.00

Name 1:

YEW TEE AUTOMOBILE TECH PTE LTD

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

-

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

-

COPY SENT

REF: ASM(AXA)

REF: ASM(AXA)

### ASSIGNMENT

From: \_\_\_\_\_ Date: 26/4/19

Estimated Cost: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJK 9581D

at Workshop n/s Yew Tee Automobile

of Blk 6 Woodlands Rd 399F Yew Tee

Insured: Ind. Est.

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 10CM

Veh No: SJK 9581D Yr Regn: 11 NOV 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_

Make: Honda Fit c.c. 1339

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 151655 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GE6110497

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Bim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 175/65 R14  
R: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Imp

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>18/4/19</u>		D.O.I. <u>26/4/19</u>	

Survey held at Yew tee Auto

Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - \$27500
	PV - \$13,449
	NV - \$14,051
	22-5-19 L/S 1,800. x x
	CR600: \$11,797.60 (66%)

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$) )  
 Interview (\$) )  
 Tech. Invs (\$) )  
 Weekend (\$) )

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. \$

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL \_\_\_\_\_

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8963A
Vehicle Details	
Vehicle No.:	SJK9581D
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	L13A4122428
Chassis No.:	GE61110497
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,195.00
Original Registration Date:	11 Nov 2008
First Registration Date:	11 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$9,705.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$13,449.00
<b>Total Rebate Amount:</b>	<b>\$13,449.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Apr 2019

OK

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

**INSURER : AXA INSURANCE SINGAPORE PTE LTD****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1904/016
Policy No:	5107630825	Date of Loss:	18/04/2019
Vehicle Reg. No.:	<b>SJK9581D</b>	Driveable?	no
Driver Age:	19/04/1989	Third Party Vehicle No.:	SMD6210X, SLU5820P
Any Injuries?	no	Contact No:	94241355
Insured/Claimant:	SENIN BIN HASSAN	Driver:	MUHAMMAD SYAHMI BIN SENIN

Make/Model:	Honda, FIT 1.3G A	Vehicle Reg. Date:	18/04/2019
Vehicle Colour:	BLUE	Engine Number:	L13A4122428
Chassis No:	GE61110497	Odometer:	
Total Loss?	<b>NO</b>	Est. Duration of Repair(Day)	

Description of Accident/loss: CHAIN COLLISION  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

**COST OF CLAIMS**

	Amount
Parts	8,309.40
Miscellaneous Items	1,133.00
Labour	2,190.00
Paintwork Labour	1,965.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>13,597.40</b>
<b>GST 7.00%(S\$):</b>	<b>951.82</b>
<b>Nett Amount(S\$):</b>	<b>14,549.22</b>

This claim is handled by: Sky Toh T C

## REPAIR DETAILS

## Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE BUC ✓	0.00	260.00	+10.00	286.00
2	1	REAR TAILGATE LOCK SVC X	0.00	78.00	+10.00	85.80
3	1	REAR TAILGATE LOCK CATCH nux	0.00	30.00	+10.00	33.00
4	1	REAR TAILGATE RUBBER DEF ✓	0.00	50.00	+10.00	55.00
5	1	REAR TAILGATE INNER BOARD !	0.00	70.00	+10.00	77.00
6	1	REAR TAILGATE HINGE RH nux	0.00	30.00	+10.00	33.00
7	1	REAR TAILGATE HINGE LH nux	0.00	30.00	+10.00	33.00
8	1	REAR TAILGATE OUTER GARNISH !	0.00	70.00	+10.00	77.00
9	2	REAR NUMBER PLATE LAMP nux	0.00	80.00	+10.00	88.00
10	1	REAR BUMPER <del>DEF</del> * DEF ✓	0.00	160.00	+10.00	176.00
11	1	REAR BUMPER SIDE RETAINER LH ?	0.00	15.00	+10.00	16.50
12	1	REAR BUMPER SIDE RETAINER RH ?	0.00	15.00	+10.00	16.50
13	1	REAR BUMPER BRACKET RH nux	0.00	13.00	+10.00	14.30
14	1	REAR BUMPER BRACKET LH nux	0.00	13.00	+10.00	14.30
15	1	REAR BUMPER STAY RH nux	0.00	25.00	+10.00	27.50
16	1	REAR BUMPER STAY LH nux	0.00	25.00	+10.00	27.50
17	1	REAR BUMPER REINFORCEMENT ?	0.00	180.00	+10.00	198.00
18	1	REAR BUMPER TOWING COVER SCR ✓	0.00	13.00	+10.00	14.30
19	1	REAR TAILLAMP LH ?	0.00	130.00	+10.00	143.00
20	1	REAR TAILLAMP RH ?	0.00	130.00	+10.00	143.00
21	1	REAR TAILLAMP LOWER BRACKET RH nux	0.00	28.00	+10.00	30.80
22	1	REAR TAILLAMP LOWER BRACKET LH nux	0.00	28.00	+10.00	30.80
23	1	REAR END PANEL ?	0.00	220.00	+10.00	242.00
24	1	REAR END PANEL INNER GARNISH ?	0.00	60.00	+10.00	66.00
25	1	REAR SPARE TYRE PANEL nux	0.00	370.00	+10.00	407.00
26	1	REAR SPARE TYRE BOARD nux	0.00	130.00	+10.00	143.00
27	1	FRONT BUMPER Repair X	0.00	230.00	+10.00	253.00
28	1	FRONT BUMPER SIDE RETAINER RH nux	0.00	18.00	+10.00	19.80
29	1	FRONT BUMPER SIDE RETAINER LH nux	0.00	18.00	+10.00	19.80
30	1	FRONT BUMPER LOWER GRILLE nux	0.00	300.00	+10.00	330.00
31	1	FRONT GRILLE nux	0.00	85.00	+10.00	93.50
32	1	FRONT GRILLE LOGO nux	0.00	30.00	+10.00	33.00
33	1	FRONT HEADLAMP RH nux	0.00	400.00	+10.00	440.00
34	1	FRONT HEADLAMP LH nux	0.00	400.00	+10.00	440.00
35	1	FRONT HEADLAMP PANEL RH nux	0.00	22.00	+10.00	24.20
36	1	FRONT HEADLAMP PANEL LH nux	0.00	22.00	+10.00	24.20
37	1	BONNET nux	0.00	270.00	+10.00	297.00
38	1	BONNET HINGE RH nux	0.00	35.00	+10.00	38.50
39	1	BONNET HINGE LH nux	0.00	35.00	+10.00	38.50
40	1	BONNET HINGE LOCK nux	0.00	75.00	+10.00	82.50
41	1	BONNET HINGE LOCK CATCH nux	0.00	120.00	+10.00	132.00
42	1	FRONT SUPPORT PANEL nux	0.00	200.00	+10.00	220.00
43	1	AIRCON CONDENSER nux	0.00	300.00	+10.00	330.00
44	2	AIRCON CONDENSER AIR GUIDE nux	0.00	52.00	+10.00	57.20
45	1	AIRCON CONDENSER FAN COWLING nux	0.00	78.00	+10.00	85.80
46	1	AIRCON CONDENSER FAN MOTOR nux	0.00	110.00	+10.00	121.00
47	1	AIRCON CONDENSER FAN BLADE nux	0.00	95.00	+10.00	104.50
48	1	REAR FENDER RH nux	0.00	400.00	+10.00	440.00
49	1	REAR FENDER LH nux	0.00	400.00	+10.00	440.00
50	1	REAR FENDER INNER TRIM BOARD RH nux	0.00	170.00	+10.00	187.00
51	1	REAR FENDER INNER TRIM BOARD LH nux	0.00	170.00	+10.00	187.00
52	1	REAR FENDER INNER SHIELD RH nux	0.00	57.00	+10.00	62.70
53	1	REAR FENDER INNER SHIELD LH nux	0.00	57.00	+10.00	62.70

**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	RADIATOR <i>nm x</i>	0.00	300.00	+10.00	330.00
55	1	RADIATOR FAN COWLING <i>nm x</i>	0.00	60.00	+10.00	66.00
56	1	RADIATOR FAN MOTOR <i>nm x</i>	0.00	200.00	+10.00	220.00
57	1	RADIATOR FAN BLADE <i>nm x</i>	0.00	70.00	+10.00	77.00
58	1	AIR CON SUCTION PIPE <i>nm x</i>	0.00	170.00	+10.00	187.00
59	1	AIR CON RETURN PIPE <i>nm x</i>	0.00	172.00	+10.00	189.20
60	1	AIR CON DISCHARGE PIPE <i>nm x</i>	0.00	180.00	+10.00	198.00

**Total Parts (\$\$)** 8,309.40

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE INNER BOARD CLIPS ?	0.00	30.00	0.00	30.00
2	1	REAR NUMBER PLATE <i>nm x</i>	0.00	35.00	0.00	35.00
3	1	REAR BUMPER CLIPS <i>rec /</i>	0.00	35.00	0.00	35.00
4	1	FRONT BUMPER CLIPS <i>nm x</i>	0.00	30.00	0.00	30.00
5	1	FRONT NUMBER PLATE <i>nm x</i>	0.00	35.00	0.00	35.00
6	1	REAR BUMPER LOWER SKIRT (SPORTS) <i>nm x</i>	0.00	350.00	0.00	350.00
7	1	FRONT BUMPER LOWER SKIRT (SPORTS) <i>nm x</i>	0.00	350.00	0.00	350.00
8	1	REAR WINDSCREEN SEALANT <i>rec /</i>	0.00	48.00	0.00	48.00
9	1	REAR BUMPER SENSORS (1 SET) <i>shorted</i>	0.00	220.00	0.00	<del>220.00</del>

**Sub Total (\$\$)** 1,133.00

**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	<del>80.00</del> 30
2	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 x
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	<del>80.00</del> 50
4	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	0.00	180.00 x
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
6	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 ✓
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,600.00	1,600.00	0.00	<del>1,600.00</del> 600

**Gross Labour Cost (\$\$)** 2,190.00

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 x
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 x
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	<del>80.00</del> 20
4	1	To Spray painting on the Replaced and Repair	1,800.00	1,800.00	0.00	<del>1,800.00</del> 650

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.				

Gross Labour Cost (S\$) 1,965.00

< END OF ESTIMATES >

Hwa Jia - LKK

26/4/19

L/S 4 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## REPAIR DETAILS

## Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE <i>BUZ</i>	0.00	260.00	+10.00	286.00
2	1	REAR TAILGATE LOCK <i>SVC X</i>	0.00	78.00	+10.00	85.80
3	1	REAR TAILGATE LOCK CATCH <i>nx</i>	0.00	30.00	+10.00	33.00
4	1	REAR TAILGATE RUBBER <i>DEF</i>	0.00	50.00	+10.00	55.00
5	1	REAR TAILGATE INNER BOARD <i>! nx</i>	0.00	70.00	+10.00	77.00
6	1	REAR TAILGATE HINGE RH <i>nx</i>	0.00	30.00	+10.00	33.00
7	1	REAR TAILGATE HINGE LH <i>nx</i>	0.00	30.00	+10.00	33.00
8	1	REAR TAILGATE OUTER GARNISH <i>! nx</i>	0.00	70.00	+10.00	77.00
9	2	REAR NUMBER PLATE LAMP <i>nx</i>	0.00	80.00	+10.00	88.00
10	1	REAR BUMPER <i>Repair x DEF</i>	0.00	160.00	+10.00	176.00
11	1	REAR BUMPER SIDE RETAINER LH <i>! nx</i>	0.00	15.00	+10.00	16.50
12	1	REAR BUMPER SIDE RETAINER RH <i>! nx</i>	0.00	15.00	+10.00	16.50
13	1	REAR BUMPER BRACKET RH <i>nx</i>	0.00	13.00	+10.00	14.30
14	1	REAR BUMPER BRACKET LH <i>nx</i>	0.00	13.00	+10.00	14.30
15	1	REAR BUMPER STAY RH <i>nx</i>	0.00	25.00	+10.00	27.50
16	1	REAR BUMPER STAY LH <i>nx</i>	0.00	25.00	+10.00	27.50
17	1	REAR BUMPER REINFORCEMENT <i>! nx</i>	0.00	180.00	+10.00	198.00
18	1	REAR BUMPER TOWING COVER <i>SCR</i>	0.00	13.00	+10.00	14.30
19	1	REAR TAILLAMP LH <i>! nx</i>	0.00	130.00	+10.00	143.00
20	1	REAR TAILLAMP RH <i>! nx</i>	0.00	130.00	+10.00	143.00
21	1	REAR TAILLAMP LOWER BRACKET RH <i>nx</i>	0.00	28.00	+10.00	30.80
22	1	REAR TAILLAMP LOWER BRACKET LH <i>nx</i>	0.00	28.00	+10.00	30.80
23	1	REAR END PANEL <i>! nx</i>	0.00	220.00	+10.00	242.00
24	1	REAR END PANEL INNER GARNISH <i>! nx</i>	0.00	60.00	+10.00	66.00
25	1	REAR SPARE TYRE PANEL <i>nx</i>	0.00	370.00	+10.00	407.00
26	1	REAR SPARE TYRE BOARD <i>nx</i>	0.00	130.00	+10.00	143.00
27	1	FRONT BUMPER <i>Repair x</i>	0.00	230.00	+10.00	253.00
28	1	FRONT BUMPER SIDE RETAINER RH <i>nx</i>	0.00	18.00	+10.00	19.80
29	1	FRONT BUMPER SIDE RETAINER LH <i>nx</i>	0.00	18.00	+10.00	19.80
30	1	FRONT BUMPER LOWER GRILLE <i>nx</i>	0.00	300.00	+10.00	330.00
31	1	FRONT GRILLE <i>nx</i>	0.00	85.00	+10.00	93.50
32	1	FRONT GRILLE LOGO <i>nx</i>	0.00	30.00	+10.00	33.00
33	1	FRONT HEADLAMP RH <i>nx</i>	0.00	400.00	+10.00	440.00
34	1	FRONT HEADLAMP LH <i>nx</i>	0.00	400.00	+10.00	440.00
35	1	FRONT HEADLAMP PANEL RH <i>nx</i>	0.00	22.00	+10.00	24.20
36	1	FRONT HEADLAMP PANEL LH <i>nx</i>	0.00	22.00	+10.00	24.20
37	1	BONNET <i>nx</i>	0.00	270.00	+10.00	297.00
38	1	BONNET HINGE RH <i>nx</i>	0.00	35.00	+10.00	38.50
39	1	BONNET HINGE LH <i>nx</i>	0.00	35.00	+10.00	38.50
40	1	BONNET HINGE LOCK <i>nx</i>	0.00	75.00	+10.00	82.50
41	1	BONNET HINGE LOCK CATCH <i>nx</i>	0.00	120.00	+10.00	132.00
42	1	FRONT SUPPORT PANEL <i>nx</i>	0.00	200.00	+10.00	220.00
43	1	AIRCON CONDENSER <i>nx</i>	0.00	300.00	+10.00	330.00
44	2	AIRCON CONDENSER AIR GUIDE <i>nx</i>	0.00	52.00	+10.00	57.20
45	1	AIRCON CONDENSER FAN COWLING <i>nx</i>	0.00	78.00	+10.00	85.80
46	1	AIRCON CONDENSER FAN MOTOR <i>nx</i>	0.00	110.00	+10.00	121.00
47	1	AIRCON CONDENSER FAN BLADE <i>nx</i>	0.00	95.00	+10.00	104.50
48	1	REAR FENDER RH <i>nx</i>	0.00	400.00	+10.00	440.00
49	1	REAR FENDER LH <i>nx</i>	0.00	400.00	+10.00	440.00
50	1	REAR FENDER INNER TRIM BOARD RH <i>nx</i>	0.00	170.00	+10.00	187.00
51	1	REAR FENDER INNER TRIM BOARD LH <i>nx</i>	0.00	170.00	+10.00	187.00
52	1	REAR FENDER INNER SHIELD RH <i>nx</i>	0.00	57.00	+10.00	62.70
53	1	REAR FENDER INNER SHIELD LH <i>nx</i>	0.00	57.00	+10.00	62.70

**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	RADIATOR <i>nmv</i>	0.00	300.00	+10.00	330.00
55	1	RADIATOR FAN COWLING <i>nmv</i>	0.00	60.00	+10.00	66.00
56	1	RADIATOR FAN MOTOR <i>nmv</i>	0.00	200.00	+10.00	220.00
57	1	RADIATOR FAN BLADE <i>nmv</i>	0.00	70.00	+10.00	77.00
58	1	AIR CON SUCTION PIPE <i>nmv</i>	0.00	170.00	+10.00	187.00
59	1	AIR CON RETURN PIPE <i>nmv</i>	0.00	172.00	+10.00	189.20
60	1	AIR CON DISCHARGE PIPE <i>nmv</i>	0.00	180.00	+10.00	198.00

*20% Discount on parts*

**Total Parts (\$\$)** 8,309.40

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE INNER BOARD CLIPS <i>nmv</i>	0.00	30.00	0.00	30.00
2	1	REAR NUMBER PLATE <i>nmv</i>	0.00	35.00	0.00	35.00
3	1	REAR BUMPER CLIPS <i>nmv</i>	0.00	35.00	0.00	35.00
4	1	FRONT BUMPER CLIPS <i>nmv</i>	0.00	30.00	0.00	30.00
5	1	FRONT NUMBER PLATE <i>nmv</i>	0.00	35.00	0.00	35.00
6	1	REAR BUMPER LOWER SKIRT (SPORTS) <i>nmv</i>	0.00	350.00	0.00	350.00
7	1	FRONT BUMPER LOWER SKIRT (SPORTS) <i>nmv</i>	0.00	350.00	0.00	350.00
8	1	REAR WINDSCREEN SEALANT <i>nmv</i>	0.00	48.00	0.00	48.00
9	1	REAR BUMPER SENSORS (1 SET) <i>short seal</i>	0.00	220.00	0.00	<del>220.00</del>

**Sub Total (\$\$)** 1,133.00

**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	<del>80.00</del> 30
2	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 X
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	<del>80.00</del> 50
4	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	0.00	180.00 X
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
6	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 ✓
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,600.00	1,600.00	0.00	<del>1,600.00</del> 600

**Gross Labour Cost (\$\$)** 2,190.00

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 X
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	<del>80.00</del> 20
4	1	To Spray painting on the Replaced and Repair	1,800.00	1,800.00	0.00	<del>1,800.00</del> 650 700

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.				

Gross Labour Cost (\$\$) 1,965.00

< END OF ESTIMATES >

Here Iia -LKK

26/4/19

L/S 4days

*ey*

Total - \$1800/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

**INSURER : AXA INSURANCE SINGAPORE PTE LTD**

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTHQ/TP/1904/016
Policy No:	5107630825	Date of Loss:	18/04/2019
Vehicle Reg. No.:	SJK9581D	Driveable?	no
Driver Age:	19/04/1989	Third Party Vehicle No.:	SMD6210X, SLU5820P
Any Injuries?	no	Contact No:	94241355
Insured/Claimant:	SENIN BIN HASSAN	Driver:	MUHAMMAD SYAHMI BIN SENIN

Make/Model:	Honda, FIT 1.3G A	Vehicle Reg. Date:	18/04/2019
Vehicle Colour:	BLUE	Engine Number:	L13A4122428
Chassis No:	GE61110497	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: CHAIN COLLISION  
 Remarks:  
 Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS	Amount
Parts	8,309.40
Miscellaneous Items	1,133.00
Labour	2,190.00
Paintwork Labour	1,965.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>13,597.40</b>
<b>GST 7.00%(S\$):</b>	<b>951.82</b>
<b>Nett Amount(S\$):</b>	<b>14,549.22</b>

This claim is handled by: Sky Toh T C

Joy

c/s \$1800/- 4 days of repair.

◀ Re:RE: MANDATE IA - ( YEW TEE - SJK 9581D)

Type

🗨 Question

Message

Proceed as proposed. Thanks

Reply

⏪ **Re:RE: MANDATE IA - ( YEW TEE - SJK 9581D)**

Type

🗨 Question

Message

Kindly use the DV instead of the settlement form as BI claim is inclusive. Thanks

Reply

⏪ **Re:RE: MANDATE IA - ( YEW TEE - SJK 9581D)**

Type

🗨 Question

Message

Proceed as proposed. Thanks

Reply



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 29/04/2019

### Survey Details:

Date of loss	18-Apr-19
Date of appointment	25-Apr-19
Date of survey	26-Apr-19
Location of survey	YEW TEE AUTOMOBILE TECH PL (HQ)

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SJK 9581D
Make and Model	HONDA FIT 1.3G A
Date of registration	11/11/2008
Excess	
Market Value	\$27,500
Parf Rebate	\$13,449
Nett Loss	\$14,051

### Repair details:

Initial Estimate	\$ 13,597.40
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 814.30
Check items (estimate)	
Labour	\$ 1,480.00
<b>Total</b>	<b>\$ 2,294.30</b>
Lump Sum(if applicable)	\$ 1,800.00

Number of days for repair	4 DAYS
---------------------------	--------



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

3 VEH CHAIN ; INSURED LAST VEHICLE. BOLA 28.

**Mandate:**

Liability(TP)		100%	
Proposed repair cost	\$	1,926.00	GST
Loss of rental GST	\$	535.00	\$100 x 5 days
Medical Fee	\$	28.00	
LTA search fees	\$	2.00	
<b>Proposed Total</b>	<b>\$</b>	<b>2,491.00</b>	

**Certificate of Insurance**

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 5107630825 **Cover :** drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SIK9581D**  
Chassis Number : GE61110497
2. Name of Policyholder : SENIN BIN HASSAN
3. Effective Date of Insurance : 23 Feb 2019
4. Expiry Date of Insurance : 22 Feb 2020
5. Persons or Classes of Persons entitled to drive#  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#  
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

**This Policy does not cover**

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: SENIN BIN HASSAN
NAMED DRIVER (1)	: MUHAMMAD SYAHMI BIN SENIN
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TECK WEI CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

德威信贷私人有限公司  
**TECK WEI CREDIT PTE LTD**  
Co. Reg. No. 200512300K  
210 Turf Club Road, The Grandstand  
Lot A8 Singapore 287995  
Tel: 6465 0020 Fax: 6465 0017  
Email: info@teckwei.com.sg

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)


Agency : TECK WEI CREDIT PTE. LTD. (00000572499)  
Date of Issue : 22 Feb 2019 11:55 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive



**Yew Tee Automobile Tech Pte Ltd**

Blk 6 Woodlands Road 399F Yew Tee Ind. Est.

Singapore 678006

Tel: 67653373 Fax: 67604895

25.05.2019

AXA Insurance Singapore  
143 Cecil Street  
#01-01 GB Building  
Singapore 069542

**Attn: Motor Claims Department**

Dear Sirs,

**ACCIDENT INVOLVING VEHICLE: SJK9581D & SMD6210X & SLU5820P on 18/04/2019**

We are the authorized repair workshop for the owner of motor vehicle no: SJK9581D which was involved in the captioned accident with your insured vehicle: SMD6210X. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Lump Sum Repair	\$	1,800.00
02)	TP search fee	\$	1.87
03)	Rental 5day @ \$105 per day	\$	525.00
		\$	2,326.87
	7% GST	\$	162.88
	Sub Total	\$	2,489.75
	Medical claim	\$	28.00
	Grand Total	\$	<u>2,517.75</u>

We enclosed herewith the following documents to support the claims:-

- a) Tax Invoice/ Letter of authorisation
- b) GIA report

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you  
Yours faithfully

  
Shaun Toh - 97432262

## Joy Irene (LKKAuto)

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Wednesday, 26 June 2019 2:53 PM  
**To:** phantom\_ong@hotmail.com  
**Cc:** Admin A  
**Subject:** ACCIDENT INVOLVING SMD 6210X AND SJK 9581D AND OTHERS ALONG JURONG TOWN HALL ROAD AVE ON 18.04.2019

### ONG YE RUI PATRICK

Policy Holder

Dear Sir,

OUR REF : CC4/ASM19007330/Jjb3  
YOUR REF : SMD 6210X

### ACCIDENT INVOLVING SMD 6210X AND SJK 9581D AND OTHERS ALONG JURONG TOWN HALL ROAD AVE ON 18.04.2019

We refer to the above subject matter and our telephone conversation earlier.

As spoken, we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s YEW TEE AUTOMOBILE TECH PTE LTD, acting on behalf of the owner of SJK 9581D against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle was involved in a three (3) vehicle chain collision causing your vehicle to hit Third Party claimant's vehicle in front.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) within 10 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## LETTER OF AUTHORITY

To whom it may concern,

Accident involving: SJK9581D and SMD6210X and SLU5820P on 18/04/2019

I/WE, SENIN BIN HASSAN, IC number: S1678963A as the owner of motor vehicle number SJK9581D, do hereby appoint M/S YEW TEE Automobile Tech Pte Ltd as my representative to write, negotiate and settle my claims against the other party involved in the abovementioned accident. M/S Yew Tee Automobile Tech Pte Ltd shall have the absolute discretion to settle all the matter at the best terms.

I/We also confirm and instruct that any agreed settlement sum in respect of my claim shall be paid to M/S YEW TEE AUTOMOBILE TECH PTE LTD and such payment will constitute a full and final discharge of my claims.

I further authorized M/S YEW TEE AUTOMOBILE TECH PTE LTD to execute the discharge voucher on my behalf.

Signature,




60158518



redefining / insurance

AXA INSURANCE PTE LTD



CLAIM REF : S9M01L62  
INSURED : ONG YE RUI PATRICK

**DISCHARGE VOUCHER**

We/I **SENIN BIN HASSAN** NRIC NO. **51678963A** hereby agree to accept the sum of dollars [ **TWO THOUSAND FOUR HUNDRED NINETY ONE ONLY.** ] (\$**2,491.00** ) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. **[SMD 6210X]** as a result of an accident along **[JURONG TOWNHALL ROAD]** on **[18/04/2019]** of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. **[SJK 9581D]**

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. **[SMD 6210X]** in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. **[SMD 6210X]**

Dated this 12 day of July 2019

Claimant's Signature : [Signature]

NRIC no./ Company Stamp : S 167 896 3A

Occupation/ Business : Indoor

Address : Blk 809A C.C.K Ave1 #12-264 S 681809.

Telephone No. : 94241355

Witness's Name : Lim Min Hwei

Witness's Signature : [Signature]

Witness's NRIC No. : G2666559R



AXA Insurance Pte Ltd (Company Reg. No. 199903512M)  
8 Shenton Way, #24-01 AXA Tower, Singapore 068811  
Customer Centre #B1-01  
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

**WITHOUT PREJUDICE** to:  
(a) Insurers' Subrogated Claim and/or  
(b) Any Personal Injury Claims  
[Note: This Notice supersedes any inconsistencies found in this Discharge Voucher]

Joy



**YEW TEE AUTOMOBILE TECH PTE LTD**

HQ: BLK 6 WOODLANDS ROAD 399-F YEW TEE IND EST S(678006)

BR: SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

BR: MEGA@WOODLANDS, 39 WOODLANDS CLOSE #01-12 S(737856)

GST Reg No. 200311009C

Singapore

67653373 67023113

INFO@YEWTEEGROUP.COM

WWW.YEWTEEGROUP.COM

Company Registration No. 200311009C

**ADDRESS**

AXA INSURANCE SINGAPORE

PTE LTD

AXA INSURANCE SINGAPORE

PTE LTD

**TP TAX INVOICE MC1905015**

**DATE 25/05/2019**

**VEHICLE NO.**

SJK9581D

ACTIVITY	QTY	RATE	TAX	AMOUNT
Lump sum repair	1	1,800.00	7% SR	1,800.00
TP Search fee	1	1.87	7% SR	1.87
Rental Of Vehicle	5	105.00	7% SR	525.00
Medical claim	1	28.00	Out of Scope	28.00

Cheque should be crossed & made payable to "YEW TEE AUTOMOBILE TECH PTE LTD" and strictly send to our HQ address.

SUBTOTAL

2,354.87

GST TOTAL

162.88

**TOTAL**

**SGD 2,517.75**

Accepted By

Accepted Date

  
ISSUED BY STAFF

E. & O.E.



友立旅遊服務私人有限公司

UNIQUE TOURIST SERVICE (PTE) LTD

1, Roehor Road, #02-574,  
Roehor Centre Singapore 180001  
Tel: 6292 7656 Fax: (65) 6293 9720  
E-mail: unigtour@singnet.com.sg  
STB LIC TA/00076

Co. Reg. No.: 197401067R  
GST Reg. No.: M2-0019671-8

**TAX INVOICE**

NO. WP2017636

Mr Senin Bin Hassan  
Blk 809A Choa Chu Kang Avenue 1  
# 12-624  
Singapore 681809

20, Sin Ming Lane,  
#08-51, Midview City  
Singapore 573968  
Tel: 6292 7656

18.05.2019

Singapore, \_\_\_\_\_ 20

DATE	PARTICULARS	°	\$	cts
	Rental of one unit Toyota Corolla Altis 1.6 Auto Registration no. SJE 8110 T self driven as from 13.05.2019 to 18.05.2019.			
	5 days at \$105.00 per day		\$	525.00
	Add GST at 7%		\$	525.00
	Amount Due		\$	36.75
			\$	<u>561.75</u>
( SIN DOLLARS: FIVE HUNDRED SIXTY ONE AND SEVENTY FIVE CENTS ONLY )				
	Standard Rated Supplies:\$		525.00	
	Total Amount of GST:\$		36.75	

AUTHORISED SIGNATURE



## CCK FAMILY CLINIC

Blk 304 Choa Chu Kang Ave 4, #01-653, S'pore 680304.  
Tel: 6891 0338 • Fax: 6891 0983

### Receipt

---

Date : 19 Apr 2019  
Receipt No. : 990917  
Ref : 108807

For medical services rendered to

Name : MUHD SYAHMI BIN SENIN

NRIC : S88403471

Total amount \$ 28.00

( Dollars Twenty Eight Only )

Inclusive of GST \$ 1.83

GST No : 20-0201430-W

CCK FAMILY CLINIC PTE LTD  
Blk 304 Choa Chu Kang Ave 4  
#01-653 Singapore 680304  
Tel: 6891 0338 Fax: 6891 0983

---

Signature



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-19-062520  
 Date of Request: 22/04/2019

Your Ref No: Online Purchase

Yew Tee Automobile Tech Pte Ltd  
 Blk 6 Woodlands Road 399F,  
 Yew Tee Ind Estate  
 Singapore 678006

Dear Sir/Madam,

Enquiry Date 22/04/2019  
 Enquiry By Toh Tze Chang  
 TP Vehicle No. SMD6210X  
 Accident Date 18/04/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SMD6210X	AXA Insurance Pte Ltd	28/08/2018-27/08/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SMD 6210K (Insd veh)	Model:	HONDA FIT
	SJK 9581D (TP veh)		
Date of Accident:	18/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:\$		14,549.22
Final Repair Cost	:\$		1,926.00
Loss of Use	:\$		days at \$0.00 per day
Rental (if any)	:\$		535.00 5 days
LTA / GIA Search Fee	:\$		2.00

Others: Medical Fee	:\$		28.00
---------------------	-----	--	-------

	:\$		
Final Settlement Sum	:\$		2,491.00

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_  
 BOLA Liability: \_\_\_100\_\_\_(%) Assessed Liability (\*): \_\_\_100\_\_\_(%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown		
1)	YEW TEE AUTOMOBILE TECH PTE LTD	:\$ 2,491.00

\_\_\_\_\_  
 JOANNE LEE KHANG MIN  
 LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
 28/08/2019  
 Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19007330/Jhb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:LYNN

Date : 28-08-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 6210K	Veh. Inspected	SJK 9581D
Policy No.	P2170103	Coverage (\$)	0.00
Claim No.	S9M01L62	Excess (\$)	0.00
Assign From		Assign Date	25/04/2019

## 2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE61110497	Colour	BLUE
Odometer	151655	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R14	MICHELIN	6 mm
L/H Front Tyre	175/65 R14	MICHELIN	6 mm
R/H Rear Tyre	175/65 R14	MICHELIN	6 mm
L/H Rear Tyre	175/65 R14	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION,  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	18/04/2019	Inspection Date	26/04/2019
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 9581D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR TAILGATE (WCP) (CONSISTENT)	BUCKLED	260.00	260.00
1	REAR TAILGATE LOCK (WCP) (CONSISTENT)	SERVICEABLE	78.00	-
1	REAR TAILGATE LOCK CATCH (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR TAILGATE RUBBER (WCP) (CONSISTENT)	DEFORMED	50.00	50.00
1	REAR TAILGATE INNER BOARD (WCP) (CONSISTENT)	NOT NECESSARY	70.00	-
1	REAR TAILGATE HINGE RH (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR TAILGATE HINGE LH (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR TAILGATE OUTER GARNISH (WCP) (CONSISTENT)	NOT NECESSARY	70.00	-
2	REAR NUMBER PLATE LAMP (WCP) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR BUMPER (WCP) (CONSISTENT)	DEFORMED	160.00	160.00
1	REAR BUMPER SIDE RETAINER LH (WCP) (CONSISTENT)	NOT NECESSARY	15.00	-
1	REAR BUMPER SIDE RETAINER RH (WCP) (CONSISTENT)	NOT NECESSARY	15.00	-
1	REAR BUMPER BRACKET RH (WCP) (CONSISTENT)	NOT NECESSARY	13.00	-
1	REAR BUMPER BRACKET LH (WCP) (CONSISTENT)	NOT NECESSARY	13.00	-
1	REAR BUMPER STAY RH (WCP) (CONSISTENT)	NOT NECESSARY	25.00	-
1	REAR BUMPER STAY LH (WCP) (CONSISTENT)	NOT NECESSARY	25.00	-
1	REAR BUMPER REINFORCEMENT (WCP) (CONSISTENT)	NOT NECESSARY	180.00	-
1	REAR BUMPER TOWING COVER (WCP) (CONSISTENT)	SCRATCHED	13.00	13.00
1	REAR TAILLAMP LH (WCP) (CONSISTENT)	NOT NECESSARY	130.00	-
1	REAR TAILLAMP RH (WCP) (CONSISTENT)	NOT NECESSARY	130.00	-
1	REAR TAILLAMP LOWER BRACKET RH (WCP) (CONSISTENT)	NOT NECESSARY	28.00	-
1	REAR TAILLAMP LOWER BRACKET LH (WCP) (CONSISTENT)	NOT NECESSARY	28.00	-
1	REAR END PANEL (WCP) (CONSISTENT)	NOT NECESSARY	220.00	-
1	REAR END PANEL INNER GARNISH (WCP) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR SPARE TYRE PANEL (WCP) (CONSISTENT)	NOT NECESSARY	370.00	-
1	REAR SPARE TYRE BOARD (WCP) (CONSISTENT)	NOT NECESSARY	130.00	-
1	FRONT BUMPER (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	230.00	-

Report Ref No. CC4/ASM19007330/Jhb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER SIDE RETAINER RH (WCP) (CONSISTENT)	NOT NECESSARY	18.00	-
1	FRONT BUMPER SIDE RETAINER LH (WCP) (CONSISTENT)	NOT NECESSARY	18.00	-
1	FRONT BUMPER LOWER GRILLE (WCP) (CONSISTENT)	NOT NECESSARY	300.00	-
1	FRONT GRILLE (WCP) (CONSISTENT)	NOT NECESSARY	85.00	-
1	FRONT GRILLE LOGO (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT HEADLAMP RH (WCP) (CONSISTENT)	NOT NECESSARY	400.00	-
1	FRONT HEADLAMP LH (WCP) (CONSISTENT)	NOT NECESSARY	400.00	-
1	FRONT HEADLAMP PANEL RH (WCP) (CONSISTENT)	NOT NECESSARY	22.00	-
1	FRONT HEADLAMP PANEL LH (WCP) (CONSISTENT)	NOT NECESSARY	22.00	-
1	BONNET (WCP) (CONSISTENT)	NOT NECESSARY	270.00	-
1	BONNET HINGE RH (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	BONNET HINGE LH (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	BONNET HINGE LOCK (WCP) (CONSISTENT)	NOT NECESSARY	75.00	-
1	BONNET HINGE LOCK CATCH (WCP) (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT SUPPORT PANEL (WCP) (CONSISTENT)	NOT NECESSARY	200.00	-
1	AIRCON CONDENSER (WCP) (CONSISTENT)	NOT NECESSARY	300.00	-
2	AIRCON CONDENSER AIR GUIDE (WCP) (CONSISTENT)	NOT NECESSARY	52.00	-
1	AIRCON CONDENSER FAN COWLING (WCP) (CONSISTENT)	NOT NECESSARY	78.00	-
1	AIRCON CONDENSER FAN MOTOR (WCP) (CONSISTENT)	NOT NECESSARY	110.00	-
1	AIRCON CONDENSER FAN BLADE (WCP) (CONSISTENT)	NOT NECESSARY	95.00	-
1	REAR FENDER RH (WCP) (CONSISTENT)	NOT NECESSARY	400.00	-
1	REAR FENDER LH (WCP) (CONSISTENT)	NOT NECESSARY	400.00	-
1	REAR FENDER INNER TRIM BOARD RH (WCP) (CONSISTENT)	NOT NECESSARY	170.00	-
1	REAR FENDER INNER TRIM BOARD LH (WCP) (CONSISTENT)	NOT NECESSARY	170.00	-
1	REAR FENDER INNER SHIELD RH (WCP) (CONSISTENT)	NOT NECESSARY	57.00	-
1	REAR FENDER INNER SHIELD LH (WCP) (CONSISTENT)	NOT NECESSARY	57.00	-
1	RADIATOR (WCP) (CONSISTENT)	NOT NECESSARY	300.00	-
1	RADIATOR FAN COWLING (WCP) (CONSISTENT)	NOT NECESSARY	60.00	-
1	RADIATOR FAN MOTOR (WCP) (CONSISTENT)	NOT NECESSARY	200.00	-
1	RADIATOR FAN BLADE (WCP) (CONSISTENT)	NOT NECESSARY	70.00	-

Report Ref No. CC4/ASM19007330/Jhb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON SUCTION PIPE (WCP) (CONSISTENT)	NOT NECESSARY	170.00	-
1	AIR CON RETURN PIPE (WCP) (CONSISTENT)	NOT NECESSARY	172.00	-
1	AIR CON DISCHARGE PIPE (WCP) (CONSISTENT)	NOT NECESSARY	180.00	-
	LESS 20% DISCOUNT		-	-96.60
	COST PLUS 10%		755.40	-
			<b>8,309.40</b>	<b>386.40</b>
	<b>SPECIAL NETT ITEMS</b>			
1	REAR TAILGATE INNER BOARD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	REAR BUMPER LOWER SKIRT (SPORTS) (SN) (CONSISTENT)	NOT NECESSARY	350.00	-
1	FRONT BUMPER LOWER SKIRT (SPORTS) (SN) (CONSISTENT)	NOT NECESSARY	350.00	-
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	48.00	48.00
1	SET REAR BUMPER SENSORS (SN) (CONSISTENT)	SHORTED	220.00	200.00
			<b>1,133.00</b>	<b>283.00</b>
	<b>LABOUR</b>			
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	30.00
	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR TAILGATE.		80.00	50.00
	TO REMOVE & REFIT AIR-CON COMPRESSOR ,AIR-CON MOTOR ,CONDENSER ,PIPES & VACUUM ,INCLUDING REFILLING OF GAS.	NOT NECESSARY	180.00	-
	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS.		30.00	30.00
	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.		100.00	100.00

Report Ref No. CC4/ASM19007330/Jhb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,600.00	600.00
	TO CARRY -OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	40.00	-
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	NOT NECESSARY	45.00	-
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		80.00	20.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,800.00	700.00
			4,155.00	1,530.00
<b>GRAND TOTAL</b>			<b>13,597.40</b>	<b>2,199.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,800.00</b>

Report Ref No. CC4/ASM19007330/Jhb3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
MEDICAL_FEE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
LKKInspection (6).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
LKKAdjustment1a (7).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2019
DV.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	VISHNU BATHAM Shekhar	19 July 2019
LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
MARKED ESTIMATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
MANDATE 1A - YEW TEL - SJK 9581D.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LJK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
 SURVEY PHOTOS.pdf	Reports & Statement	Others	LJK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
 LETTER TO INSURED.pdf	Reports & Statement	Others	LJK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
 IA-9581D.pdf	Reports & Statement	Others	LJK AUTO CONSULTANTS PTE LTD (TP)	2 May 2019
 SMO6310X INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	25 April 2019
 SLU5820P GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	25 April 2019
 TP 991 FROM WORKSHOP WITH GIA REPORT.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	25 April 2019
 P2370103_P5.pdf	Forms / Claim Documents	Policy Schedule / Certificate of Insurance	KHONG Lynn	24 April 2019
 SJN9581D TP2.PDF	Reports & Statement	GIA Report	KUMAR Shalendra	24 April 2019