

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

**INSURER : AXA INSURANCE SINGAPORE PTE LTD****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1904/016
Policy No:	5107630825	Date of Loss:	18/04/2019
Vehicle Reg. No.:	<b>SJK9581D</b>	Driveable?	no
Driver Age:	19/04/1989	Third Party Vehicle No.:	SMD6210X, SLU5820P
Any Injuries?	no	Contact No:	94241355
Insured/Claimant:	SENIN BIN HASSAN	Driver:	MUHAMMAD SYAHMI BIN SENIN

Make/Model:	Honda, FIT 1.3G A	Vehicle Reg. Date:	18/04/2019
Vehicle Colour:	BLUE	Engine Number:	L13A4122428
Chassis No:	GE61110497	Odometer:	
Total Loss?	<b>NO</b>	Est. Duration of Repair(Day)	

Description of Accident/loss CHAIN COLLISION  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

**COST OF CLAIMS**

	Amount
Parts	8,309.40
Miscellaneous Items	1,133.00
Labour	2,190.00
Paintwork Labour	1,965.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>13,597.40</b>
<b>GST 7.00%(S\$):</b>	<b>951.82</b>
<b>Nett Amount(S\$):</b>	<b>14,549.22</b>

This claim is handled by: Sky Toh T C

Joy

C/S \$1800/- 4days of repair.

## REPAIR DETAILS

Estimates On Parts			Rate	Amount	%Disc	After Disc
No.	Qty	Particulars				
1	1	REAR TAILGATE <i>BVC</i>	0.00	260.00	+10.00	286.00
2	1	REAR TAILGATE LOCK <i>SVC X</i>	0.00	78.00	+10.00	85.80
3	1	REAR TAILGATE LOCK CATCH <i>nx</i>	0.00	30.00	+10.00	33.00
4	1	REAR TAILGATE RUBBER <i>DEF</i>	0.00	50.00	+10.00	55.00
5	1	REAR TAILGATE INNER BOARD <i>! nx</i>	0.00	70.00	+10.00	77.00
6	1	REAR TAILGATE HINGE RH <i>nx</i>	0.00	30.00	+10.00	33.00
7	1	REAR TAILGATE HINGE LH <i>nx</i>	0.00	30.00	+10.00	33.00
8	1	REAR TAILGATE OUTER GARNISH <i>! nx</i>	0.00	70.00	+10.00	77.00
9	2	REAR NUMBER PLATE LAMP <i>nx</i>	0.00	80.00	+10.00	88.00
10	1	REAR BUMPER <i>Repair x DEF</i>	0.00	160.00	+10.00	176.00
11	1	REAR BUMPER SIDE RETAINER LH <i>? nx</i>	0.00	15.00	+10.00	16.50
12	1	REAR BUMPER SIDE RETAINER RH <i>? nx</i>	0.00	15.00	+10.00	16.50
13	1	REAR BUMPER BRACKET RH <i>nx</i>	0.00	13.00	+10.00	14.30
14	1	REAR BUMPER BRACKET LH <i>nx</i>	0.00	13.00	+10.00	14.30
15	1	REAR BUMPER STAY RH <i>nx</i>	0.00	25.00	+10.00	27.50
16	1	REAR BUMPER STAY LH <i>nx</i>	0.00	25.00	+10.00	27.50
17	1	REAR BUMPER REINFORCEMENT <i>? nx</i>	0.00	180.00	+10.00	198.00
18	1	REAR BUMPER TOWING COVER <i>SCR</i>	0.00	13.00	+10.00	14.30
19	1	REAR TAILLAMP LH <i>? nx</i>	0.00	130.00	+10.00	143.00
20	1	REAR TAILLAMP RH <i>? nx</i>	0.00	130.00	+10.00	143.00
21	1	REAR TAILLAMP LOWER BRACKET RH <i>nx</i>	0.00	28.00	+10.00	30.80
22	1	REAR TAILLAMP LOWER BRACKET LH <i>nx</i>	0.00	28.00	+10.00	30.80
23	1	REAR END PANEL <i>? nx</i>	0.00	220.00	+10.00	242.00
24	1	REAR END PANEL INNER GARNISH <i>? nx</i>	0.00	60.00	+10.00	66.00
25	1	REAR SPARE TYRE PANEL <i>nx</i>	0.00	370.00	+10.00	407.00
26	1	REAR SPARE TYRE BOARD <i>nx</i>	0.00	130.00	+10.00	143.00
27	1	FRONT BUMPER <i>Repair x</i>	0.00	230.00	+10.00	253.00
28	1	FRONT BUMPER SIDE RETAINER RH <i>nx</i>	0.00	18.00	+10.00	19.80
29	1	FRONT BUMPER SIDE RETAINER LH <i>nx</i>	0.00	18.00	+10.00	19.80
30	1	FRONT BUMPER LOWER GRILLE <i>nx</i>	0.00	300.00	+10.00	330.00
31	1	FRONT GRILLE <i>nx</i>	0.00	85.00	+10.00	93.50
32	1	FRONT GRILLE LOGO <i>nx</i>	0.00	30.00	+10.00	33.00
33	1	FRONT HEADLAMP RH <i>nx</i>	0.00	400.00	+10.00	440.00
34	1	FRONT HEADLAMP LH <i>nx</i>	0.00	400.00	+10.00	440.00
35	1	FRONT HEADLAMP PANEL RH <i>nx</i>	0.00	22.00	+10.00	24.20
36	1	FRONT HEADLAMP PANEL LH <i>nx</i>	0.00	22.00	+10.00	24.20
37	1	BONNET <i>nx</i>	0.00	270.00	+10.00	297.00
38	1	BONNET HINGE RH <i>nx</i>	0.00	35.00	+10.00	38.50
39	1	BONNET HINGE LH <i>nx</i>	0.00	35.00	+10.00	38.50
40	1	BONNET HINGE LOCK <i>nx</i>	0.00	75.00	+10.00	82.50
41	1	BONNET HINGE LOCK CATCH <i>nx</i>	0.00	120.00	+10.00	132.00
42	1	FRONT SUPPORT PANEL <i>nx</i>	0.00	200.00	+10.00	220.00
43	1	AIRCON CONDENSER <i>nx</i>	0.00	300.00	+10.00	330.00
44	2	AIRCON CONDENSER AIR GUIDE <i>nx</i>	0.00	52.00	+10.00	57.20
45	1	AIRCON CONDENSER FAN COWLING <i>nx</i>	0.00	78.00	+10.00	85.80
46	1	AIRCON CONDENSER FAN MOTOR <i>nx</i>	0.00	110.00	+10.00	121.00
47	1	AIRCON CONDENSER FAN BLADE <i>nx</i>	0.00	95.00	+10.00	104.50
48	1	REAR FENDER RH <i>nx</i>	0.00	400.00	+10.00	440.00
49	1	REAR FENDER LH <i>nx</i>	0.00	400.00	+10.00	440.00
50	1	REAR FENDER INNER TRIM BOARD RH <i>nx</i>	0.00	170.00	+10.00	187.00
51	1	REAR FENDER INNER TRIM BOARD LH <i>nx</i>	0.00	170.00	+10.00	187.00
52	1	REAR FENDER INNER SHIELD RH <i>nx</i>	0.00	57.00	+10.00	62.70
53	1	REAR FENDER INNER SHIELD LH <i>nx</i>	0.00	57.00	+10.00	62.70

Estimates On Parts						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	RADIATOR <i>any</i>	0.00	300.00	+10.00	330.00
55	1	RADIATOR FAN COWLING <i>any</i>	0.00	60.00	+10.00	66.00
56	1	RADIATOR FAN MOTOR <i>any</i>	0.00	200.00	+10.00	220.00
57	1	RADIATOR FAN BLADE <i>any</i>	0.00	70.00	+10.00	77.00
58	1	AIR CON SUCTION PIPE <i>any</i>	0.00	170.00	+10.00	187.00
59	1	AIR CON RETURN PIPE <i>any</i>	0.00	172.00	+10.00	189.20
60	1	AIR CON DISCHARGE PIPE <i>any</i>	0.00	180.00	+10.00	198.00

*20% Discount on parts*

Total Parts (S\$) 8,309.40

Estimates of Miscellaneous Items						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE INNER BOARD CLIPS <i>any</i>	0.00	30.00	0.00	30.00
2	1	REAR NUMBER PLATE <i>any</i>	0.00	35.00	0.00	35.00
3	1	REAR BUMPER CLIPS <i>rec</i>	0.00	35.00	0.00	35.00
4	1	FRONT BUMPER CLIPS <i>any</i>	0.00	30.00	0.00	30.00
5	1	FRONT NUMBER PLATE <i>any</i>	0.00	35.00	0.00	35.00
6	1	REAR BUMPER LOWER SKIRT (SPORTS) <i>any</i>	0.00	350.00	0.00	350.00
7	1	FRONT BUMPER LOWER SKIRT (SPORTS) <i>any</i>	0.00	350.00	0.00	350.00
8	1	REAR WINDSCREEN SEALANT <i>rec</i>	0.00	48.00	0.00	48.00
9	1	REAR BUMPER SENSORS (1 SET) <i>shorted</i>	0.00	220.00	0.00	<del>220.00</del>

Sub Total (S\$) 1,133.00

Estimates On Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	<del>80.00</del> 30
2	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 X
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	<del>80.00</del> 50
4	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	0.00	180.00 X
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
6	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 ✓
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,600.00	1,600.00	0.00	<del>1,600.00</del> 600

Gross Labour Cost (S\$) 2,190.00

Estimates On Paint Work Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 X
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	<del>80.00</del> 20
4	1	To Spray painting on the Replaced and Repair	1,800.00	1,800.00	0.00	<del>1,800.00</del> 650 700

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.				
<b>Gross Labour Cost (\$\$)</b>						<b>1,965.00</b>

< END OF ESTIMATES >

Here fix - LKK

26/4/19

L/S 4 days

*[Signature]*

Total - \$1800/-

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: