

08/11/14
Sivayur

REF: FCF

ASSIGNMENT

From: _____ Date: 26/4/19

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 786X

at Workshop m/s Automobile Hub

of 1 Kaki Blk Ave 6 #02-11

Insured: Autobuy

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 1:30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Date: _____ Person Contacted: _____

N/S	O/S

Veh No: PA 786X Yr Regn: 17/2/2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Hiace 2.5 c.c 2494

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 503705 T/Radio: Insured / Std / NI / NA

Eng/No: 2KD1A14355

C/No: KDH2220013530

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: Bearway 195/150
R: Maxtrac 195/150

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bearway F / Maxtrac R

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>23/4/19</u>	D.O.I. <u>25/4/19</u>

Survey held at Automobile Hub Enterprise

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 04 JUL 2019

Lim / Pls see my remarks

HS accepted by workshop

HS 2450/2 CRED \$9910, 80%

* MV	23,000/2 (CR)	2/9/19	
PV	8,078/2		TGim
NV	14,922/2		

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 1

Date/Time, File Return to?
 2)

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	2x15=30
Transportation:	170+30
S + RS, SI	50
Photos	50
Others	32
TOTAL	332

Report Format: TP
 Lump Sum / I.B.F. (\$) 2450

MOTOR SURVEY ASSIGNMENT

Date	24-04-2019	Our Ref No. D19002747MFSH
Accident Date	23-04-2019	Claim Type. Third Party
Insured Vehicle	SHC3387D	Third Party Vehicle. PA786X
Survey Location	1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @ KAKI BUKIT	
Contact Person.	LIM	
Contact No.	97864483/ 97864483	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOMOBILE HUB ENTERPRISE	Attention. NIL
Cc : TP Solicitor	KANNAN SG	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Cindy Tan

From: Cindy Tan <cindy.tan@kannansg.com.sg>
Sent: Wednesday, 24 April, 2019 3:18 PM
To: 'motor_claims@first-insurance.com.sg'
Subject: YRef: SHC 3387D Oref: KSG/4934/2019/K/ct

Dear Sirs / Mdm **WITHOUT PREJUDICE**

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : KHAN LIMO SERVICE (UEN NO. 53328933E)
ACCIDENT INVOLVING VEHICLES NO. PA 786X & SHC 3387D ALONG MCE / KPE JUST BEFORE ENTERING TUNNEL ON 23 APRIL 2019 AT 1310 HRS
PRE-REPAIR INSPECTION NOTICE

We act for M/s Khan Limo Service, the owner of motor vehicle No. PA 786X, which was involved in the aforesaid accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-

Place: M/s Automobile Hub Enterprise
1 Kaki Bukit Avenue 6
#02-11 Autobay@Kaki Bukit
Singapore 417883

Contact Person: Mr Lim - 9786 4483

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

Lim Teow Suan
97361577
26/4/19 ~~1430~~ 1430 hrs

TEL: (+65) 6429 0253
FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 15 May 2019 5:45 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Joanne Yong Lai fong'
Subject: RE: SURVEY ASSESSMENT - D19002747MFSH/1
Attachments: CSFCI19007341Bqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of PA 786X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 25 April 2019 4:47 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002747MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange on 26.4.2019.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 25 April, 2019 2:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002747MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002747MFSH
Our Ref: CS/FCI19007341/Bqd3

Date: 15 May 2019

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. PA 786X.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/04/2019 at the premises of M/s AUTOMOBILE HUB, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 12,360.00</u>
Revised Estimate Amount	: <u>S\$ 4,636.85</u>
“Check” Items Amount	: <u>S\$ 2,523.75</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the o/s portion.



Yours faithfully

Lim TG
Automotive Assessor

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8933E
Vehicle Details	
Vehicle No.:	PA786X
Vehicle to be Exported:	No
Intended Deregistration Date:	06 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 2.5 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2KD1414355
Chassis No.:	KDH2220013530
Maximum Power Output:	-
Open Market Value:	\$38,240.00
Original Registration Date:	17 Feb 2006
First Registration Date:	17 Feb 2006
Transfer Count:	1
Actual ARF Paid:	\$1,912.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Feb 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,695.00
COE Rebate Amount:	\$8,078.00
Total Rebate Amount:	\$8,078.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 06 May 2019

OK

Dep 10,670/yr
889 /month

MV 23,000/2
PV 8,078/2
NV 14,922/2

Lim T Gin
6/5/19 Lim



Toyota Hiace 3.0M (COE till 06/2022) \$29,800 \$9,660 /yr 06-Jun-2007 2,982 cc - Van Available

Fuel Type: Diesel

Very Well Maintained By Previous Owner. Most Importantly, Accident Free! Buy With No Worries As Toyota Usually Doesn't Give Much Headaches. Don't Want To Invest Too Much On A Brand New Vehicle? No Pro...

Posted: 13-Mar-2019 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M (COE till 01/2022) \$23,800 \$8,740 /yr 25-Jan-2007 2,982 cc - Van Available

Fuel Type: Diesel

Good Condition, Servicing Done, Vehicle Well Maintained, Bank/In-House Available, Welcome Trade-In, Price Negotiable. Call Now For Viewing.

SG Motor Link Pte Ltd

Posted: 03-May-2019 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

PREMIUM AD



Toyota Hiace 2.5M (COE till 12/2021) - N.A 18-Jan-2007 2,494 cc - Van SOLD

Fuel Type: Diesel

CHEAPEST IN THE MARKET! New Paint! New Leather Upholstery! Well Maintained By Previous Owner! Fuel Efficient & Maintenance Friendly! Hassle-Free For Your Everyday Drive! Insurance And Loan Available F...

Net Link Partners Pte Ltd

Posted: 05-Mar-2019 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

PREMIUM AD



Toyota Hiace Commuter 2.5M (COE till 10/2021) \$20,888 \$8,440 /yr 26-Oct-2006 2,494 cc - Bus Available

Fuel Type: Diesel

High Demand Class 3 Commuter Van, Cheapest In The Market. Wear And Tear All Fixed. 100% Loan Approval.

Posted: 15-Apr-2019 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

DIRECT OWNER



Stand out with a bidded car plate number!

Bring luck and prosperity with an auspicious car licence plate number starting from only \$2,3xx! Single digit and lucky numbers available right here!

Find out more!



Toyota Hiace 2.5M (COE till 05/2021) \$21,800 \$10,670 /yr 22-May-2006 2,494 cc - Bus Available

Fuel Type: Diesel

Cheaper In Town, 5 Doors Urvan! Then Rent. Well Kept Condition! Powerful Aircon! Easy In House Finance, High Trade In, Don't Miss! Call Us Now For Viewing To Believe!

Posted: 04-May-2019 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 2.5M (COE till 03/2021) - N.A 15-Mar-2006 2,494 cc - Van SOLD

Fuel Type: Diesel

Manual Unit, Good Condition. Low Millage Done, One Owner Used Till Now.

Posted: 14-Mar-2019 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 2.5M (New 5-yr COE) - N.A 13-Mar-2006 2,494 cc - Van SOLD

Fuel Type: Diesel

New 5 Year Coe Toyota Hiace 5 Door. High Loan Available, Trade In Welcome. Engine & Gearbox In Good Condition. See To Believe! Call Now To Arrange Viewing!

Net Link Partners Pte Ltd

Posted: 01-Mar-2019 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

PREMIUM AD



Toyota Hiace 2.5M (COE till 12/2020) - N.A 19-Jan-2006 2,494 cc - Bus SOLD

Fuel Type: Diesel

Good For Business Starter Or Short Term Uses. Can Renew Another 5 Year COE Again Later. If Not Can Sell Van Body At Least 6000 -8000 To Delaer To Renew For COE. Car Rental Company Or Car Dealer Friend...

Posted: 21-Mar-2019 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 2.5M \$29,800 N.A 12-Aug-2005 2,494 cc - Bus Available

Fuel Type: Diesel

Rare One Owner, 4 Door Commuter Van For Your Business Needs, Very Fuel Efficient, Loan And High Trade-In Available. Call Us Now To Arrange For A No Obligation Viewing And For An In-Depth Consultation ...

Posted: 01-May-2019 Tags: 2005 Toyota Hiace, 2005 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 2.5A (COE till 07/2020) - N.A 05-Jul-2005 2,494 cc - Van SOLD

Fuel Type: Diesel

Rarely Seen Auto Gear Hiace, Regularly Servicing And Repairs By Trusted Workshop. Price Non-negotiable.m. Comfort Driving Like Saloon Car. Cash & Carry.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2019 10:57
Date Of Accident	23/04/2019 13:10
Exact Location Of Accident	MCE KPE JUST ENTERING TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA786X
Insured/Policyholder	
Name Of Registered Owner	KHAN LIMO SERVICE
Co Reg No	53328933E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96484368

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5107199794
Cover Note Number	

Driver

Name of Driver	NURULAMIN S/O KADER MOHIADEEN
NRIC No	S0412754D
Date Of Birth	13/11/1949
Occupation	INDOOR
Date Of Driving Pass	23/10/1969
Driving Experience	49 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96484368
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 910 #02-127
TAMPINES STREET 91

Postcode 520910

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I was making the lane change from lane 5 to lane 4 after checking for safety. While I was almost completing the lane change, vehicle B changed lane from lane 3 to lane 4, from my rear right. Vehicle B sped up and overtook my vehicle A. This resulted in the left rear wheel area of vehicle B to side swipe into the right front wheel area of my vehicle A.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC3387D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver ONG THIAN HUAT

NRIC/Passport Number S0141044Z

Contact Number 97853030

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was making the lane change from lane 5 to lane 4 after checking for safety. While I was almost completing the lane change, vehicle B changed lane from lane 3 to lane 4, from my rear right. Vehicle B sped up and overtook my vehicle A. This resulted in the left rear wheel area of vehicle B to side swipe into the right front wheel area of my vehicle A.

Declaration

I/We declare the foregoing particulars are true in every respect.

KHAN LIMO SERVICE

24/04/19 / 10:52

Policyholder's Signature / Date & Time

24/04/19 / 10:52

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2019 10:57
Date Of Accident	23/04/2019 13:10
Exact Location Of Accident	MCE KPE JUST ENTERING TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA786X
Insured/Policyholder	
Name Of Registered Owner	KHAN LIMO SERVICE
Co Reg No	53328933E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96484368

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5107199794
Cover Note Number	

Driver

Name of Driver	NURULAMIN S/O KADER MOHIADEEN
NRIC No	S0412754D
Date Of Birth	13/11/1949
Occupation	INDOOR
Date Of Driving Pass	23/10/1969
Driving Experience	49 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96484368
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 910 #02-127 TAMPINES STREET 91
Postcode	520910
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was making the lane change from lane 5 to lane 4 after checking for safety. While I was almost completing the lane change, vehicle B changed lane from lane 3 to lane 4, from my rear right. Vehicle B sped up and overtook my vehicle A. This resulted in the left rear wheel area of vehicle B to side swipe into the right front wheel area of my vehicle A.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3387D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ONG THIAN HUAT
NRIC/Passport Number	S0141044Z
Contact Number	97853030
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : PASSENGER

GENDER: : MALE

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 24/04/2019 / 10:52

Report No: MT _____

D.O.A: 23/04/2019

Vehicle No: PA786N

Reporting Type: _____

Time: 13:10 hrs

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

KHAN LIMO SERVICE

24/04/19 / 10:52

Policyholder's Signature / Date & Time



24/04/19 / 10:52

Driver's Signature (If driver is not the policyholder) / Date & Time


Alan Tang (S098825)
Customer Care Executive
Motor Service Centre



Witnessed by Reporting Centre Personnel

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was making the lane change from lane 5 to lane 4 after checking for safety. While I was almost completing the lane change, vehicle B changed lane from lane 3 to lane 4, from my rear right. Vehicle B sped up and overtook my vehicle A. This resulted in the left rear wheel area of vehicle B to side swipe into the right front wheel area of my vehicle A.

Declaration

I/We declare the foregoing particulars are true in every respect.

KHAN LIMO SERVICE

24/04/19 / 10:52

Policyholder's Signature / Date & Time

24/04/19 / 10:52

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel


Repair Estimate

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
 Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Make/Model: Toyota Hiace Commuter GL 3.0 AT 2WD 4DR LWB
 Engine/Chassis No.: KDH2220013530
 Date of accident:
 Damaged area: O/S Front

Date: 25/4/2019
 Claim Type: TP
 VRN: PA786X



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper	1	\$ 754.00	\$ 754.00
2	Front bumper side retainer	2	\$ 149.60	\$ 299.20
3	Top corner panel o/s	1	\$ 485.00	\$ 485.00
4	Top corner panel garnish o/s	1	\$ 337.00	\$ 337.00
5	Head lamp o/s	1	\$ 785.00	\$ 785.00
6	Head lamp lower bracket o/s	1	\$ 42.00	\$ 42.00
7	Front door o/s	1	\$ 1,745.00	\$ 1,745.00
8	Front door inner trim board o/s	1	\$ 586.00	\$ 586.00
9	Front door window channel o/s	1	\$ 165.00	\$ 165.00
10	Front door window regulator o/s	1	\$ 287.00	\$ 287.00
11	Front door window regulator motor o/s	1	\$ 399.00	\$ 399.00
12	Front door weatherstrip o/s	1	\$ 185.00	\$ 185.00
13	Front door lower seal o/s	1	\$ 140.00	\$ 140.00
14	Front door pillar outer o/s	1	\$ 765.00	\$ 765.00
15	Front door hinge o/s	2	\$ 116.00	\$ 232.00
16	Front step panel garnish o/s	1	\$ 256.00	\$ 256.00
17	Front step panel o/s	1	\$ 522.00	\$ 522.00
18	Wing mirror assy o/s	1	\$ 549.00	\$ 549.00
19	Wing mirror glass o/s	1	\$ 137.00	\$ 137.00
20	Front lower arm o/s	1	\$ 435.00	\$ 435.00
21	Front wheel knuckle o/s	1	\$ 313.00	\$ 313.00
22	Front wheel bearing o/s	1	\$ 297.00	\$ 297.00
23	Front shock absorber o/s	1	\$ 346.00	\$ 346.00
24	Front wheel cowling o/s	1	\$ 266.00	\$ 266.00
Subtotal				\$ 10,327.20
List discount				25.00%
Total				\$ 7,745.40

N/A X
 N/A X
 N/A X
 N/A X
 N/A X
 N/A X
 DD ✓
 ? N/A X
 BT ✓ P/A X
 N/A X
 N/A X
 NEC ✓
 NEC
 R X
 BT ✓ X S/C
 BR ✓ P/A X
 BT ✓ ? N/A X
 N/A X
 N/A X
 ?
 ?
 ?
 ?
 ? } N/A X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1552.50

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips	16	\$ 3.50	\$ 30.00 56.00
2	Top corner panel garnish o/s sealant	1	\$ 60.00	\$ 60.00
3	Head lamp o/s clips	4	\$ 3.50	\$ 14.00
4	Front door inner trim board o/s clips	8	\$ 2.50	\$ 20.00
5	Front door pillar inner trim o/s clips	6	\$ 2.60	\$ 15.60
6	Front step panel garnish o/s bolts	4	\$ 4.50	\$ 18.00
7	Front wheel cowling o/s clips	6	\$ 3.50	\$ 21.00
8	Front wheel R15 o/s	1	\$ 450.00	\$ 450.00
9	Front wheel outer cover o/s	1	\$ 180.00	\$ 180.00
10	Front tyre 195R15C o/s	1	\$ 380.00	\$ 380.00
Total				\$ 1,214.60

NEC
 NEG XNN
 NNX
 NECV
 NECV XNN
 NECV
 NECV
 ? NNX
 SCR ✓
 50g Dep ✓

409.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 800.00 1,400.00
2	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
3	To remove and refit o/s front door components, check and alignment.	0.5	\$ 50.00 100.00
4	To disconnect doors wire harness of electrical component to facilitate repairs, reconnect and check power window function.	0.25	\$ 50.00
5	To remove and refit o/s front door glass to facilitate repair.	0.5	\$ 100.00
6	To remove and refit o/s front tyre to replace rim. To perform tyre balancing and wheel alignment.	0.75	\$ 80.00 150.00
7	To remove and refit o/s front undercarriage for replacement of parts.	1.25	\$ 180.00 250.00
8	Supply spray paint material and necessary items to respray o/s front door, o/s top corner panel and garnish, o/s step panel and other affected area / panel.	6	\$ 600.00 1,200.00
9	To rust proof all affected portions after repair.	0.5	\$ 60.00 100.00
Total labour			\$ 3,400.00

✓
 500
 ✓ 30
 ✓ XNN
 NNX
 ✓ 30
 ✓ XNN
 ✓ 50 500

1160.00

Estimate Grand Total	\$ 12,360.00
-----------------------------	---------------------

? Pic
 Lump sum repair
 Repair days 4

Lim Teow Quan
 LKK Auto Consultants
 him

[Signature]
 15/5/19

26/4/19 @20% 3121.50
 1430 hrs 624.30
 2497.20
 4/5 2450/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007341/Bqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-07-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3387D	Veh. Inspected	PA 786X
Policy No.		Coverage (\$)	0.00
Claim No.	D19002747MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	25/04/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE 2.5	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	KDH2220013530	Colour	SILVER
Odometer	503705	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	BEARWAY	5 mm
L/H Front Tyre	195 R15C	BEARWAY	5 mm
R/H Rear Tyre	195 R15C	MAXTREX	5 mm
L/H Rear Tyre	195 R15C	MAXTREX	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/04/2019	Inspection Date	25/04/2019
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 786X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	NOT NECESSARY	754.00	-
2	FRONT BUMPER SIDE RETAINER @\$149.60	NOT NECESSARY	299.20	-
1	TOP CORNER PANEL O/S	NOT NECESSARY	485.00	-
1	TOP CORNER PANEL GARNISH O/S	NOT NECESSARY	337.00	-
1	HEAD LAMP O/S	NOT NECESSARY	785.00	-
1	HEAD LAMP LOWER BRACKET O/S	NOT NECESSARY	42.00	-
1	FRONT DOOR O/S	DENTED	1,745.00	1,745.00
1	FRONT DOOR INNER TRIM BOARD O/S	NOT NECESSARY	586.00	-
1	FRONT DOOR WINDOW CHANNEL O/S	NOT NECESSARY	165.00	-
1	FRONT DOOR WINDOW REGULATOR O/S	NOT NECESSARY	287.00	-
1	FRONT DOOR WINDOW REGULATOR MOTOR O/S	NOT NECESSARY	399.00	-
1	FRONT DOOR WEATHERSTRIP O/S	NECESSARY	185.00	185.00
1	FRONT DOOR LOWER SEAL O/S	NECESSARY	140.00	140.00
1	FRONT DOOR PILLAR OUTER O/S	TO REPAIR SEE LABOUR	765.00	-
2	FRONT DOOR HINGE O/S @\$116.00	SERVICEABLE	232.00	-
1	FRONT STEP PANEL GARNISH O/S	NOT NECESSARY	256.00	-
1	FRONT STEP PANEL O/S	NOT NECESSARY	522.00	-
1	WING MIRROR ASSY O/S	NOT NECESSARY	549.00	-
1	WING MIRROR GLASS O/S	NOT NECESSARY	137.00	-
1	FRONT LOWER ARM O/S	NOT NECESSARY	435.00	-
1	FRONT WHEEL KNUCKLE O/S	NOT NECESSARY	313.00	-
1	FRONT WHEEL BEARING O/S	NOT NECESSARY	297.00	-
1	FRONT SHOCK ABSORBER O/S	NOT NECESSARY	346.00	-
1	FRONT WHEEL COWLING O/S	NOT NECESSARY	266.00	-
	LESS 25% DISCOUNT		-2,581.80	-517.50
			7,745.40	1,552.50
SPECIAL NETT ITEMS				
16	FRONT BUMPER CLIPS @\$3.50 (SN)	NECESSARY	56.00	30.00
1	TOP CORNER PANEL GARNISH O/S SEALANT (SN)	NOT NECESSARY	60.00	-
4	HEAD LAMP O/S CLIPS @\$3.50 (SN)	NOT NECESSARY	14.00	-

Report Ref No. CS/FCI19007341/Bqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	FRONT DOOR INNER TRIM BOARD O/S CLIPS @\$2.50 (SN)	NECESSARY	20.00	20.00
6	FRONT DOOR PILLAR INNER TRIM O/S CLIPS @\$2.60 (SN)	NOT NECESSARY	15.60	-
4	FRONT STEP PANEL GARNISH O/S BOLTS @\$4.50 (SN)	NECESSARY	18.00	18.00
6	FRONT WHEEL COWLING O/S CLIPS @\$3.50 (SN)	NECESSARY	21.00	21.00
1	FRONT WHEEL R15 O/S (SN)	NOT NECESSARY	450.00	-
1	FRONT WHEEL OUTER COVER O/S (SN)	SCRATCHED	180.00	120.00
1	FRONT TYRE 195R15C O/S (SN)	CUT	380.00	200.00
			1,214.60	409.00
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR OUTER O/S.		1,400.00	500.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS		50.00	30.00
	TO REMOVE AND REFIT O/S FRONT DOOR COMPONENTS, CHECK AND ALIGNMENT.		100.00	50.00
	TO DISCONNECT DOORS WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK POWER WINDOW FUNCTION.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT O/S FRONT DOOR GLASS TO FACILITATE REPAIR.	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT O/S FRONT TYRE TO REPLACE RIM. TO PERFORM TYRE BALANCING AND WHEEL ALIGNMENT.		150.00	30.00
	TO REMOVE AND REFIT O/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS.	NOT NECESSARY	250.00	-
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY O/S FRONT DOOR, O/S TOP CORNER PANEL AND GARNISH, O/S STEP PANEL AND OTHER AFFECTED AREA / PANEL.		1,200.00	500.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.		100.00	50.00
			3,400.00	1,160.00
GRAND TOTAL			12,360.00	3,121.50

Report Ref No. CS/FCI19007341/Bqd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00
---	--	--	--	----------

Report Ref No. CS/FCI19007341/Bqd3e2

MARKET VALUE: \$23,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,078.00=NETT VALUE: \$14,922.00

LIM TEOW GUAN
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.