

REF: 08/FCI19007342/JS d3/12

Period of Instruction

Surveyor

Hwee Jia

ASSIGNMENT (Office)

CWS

From (Person)

Joanne Yong

of

FCI

Date/Time

9.35am @ 16/4/19

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No

SKQ 3985T

Insured

SHC 1127B

at Workshop no

Jong sheng Motor

Tel

676 39733

of

Blk 6 No. 399 G Woodlands Rd Yew Tee Ind. Est.

Policy No

Claim No

D19002463MFSH

Sum Insured

Excess

Make of Veh

D.O.A

01/04/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement

Date/Time

11:30am @ 16/4/19

Person Contacted

Miss Woon

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SKQ 3985T - NS/INC17020287/Klabn2

DOA: 17/10/17

SHC 1127B - 08/TMI19001676/Nqd3n2

DOA: 24/9/2019

17/05/19

@ 14:04 pm revised PA to Joanne Yong via email.

09/11/19

REF:

FCI

ASSIGNMENT

From:

Date:

15.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 3985T

at Workshop m/s Long Sheng

of Blk 6 Woodlands Rd Yen Tee 399-G

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$20K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKQ 3985T

Yr Regn: 27 Nov 2007

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

c.c 1598

Colour:

Gold

A/C: Insured / Std / NI / NA

Sp. Reading

342274

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0532EC107158900

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenze

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

1/4/19

D.O.I.

15/5/19

Survey held at

Long Sheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - \$20000

PV - \$14802

NV - \$5198

MV - \$20,000/- } NetH - \$5198
LTA - \$14,802/-

RECEIVED 27 MAY 2019

Confirmed L/S \$2700/- Slags of repair.
(@ 1.203.30 Red - 31%)

21/5/2019

Date/Time, File Pass to?

27/05/19

1)

Typ. 5

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

130

50

50 + 50

32

312

Report Format :

Lump Sum / I.B.I: (\$ 2,700/- L/S)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002463MFSH

Date: 17 May 2019

Our Ref: CS/FCI19007342/Jsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKQ 3985T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/05/2019 at the premises of M/s Long Sheng Motor Service and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,580.53</u>
Revised Estimate Amount	: S\$ <u>3,818.02</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Ong Hwee Jie
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-04-2019	Our Ref No. D19002463MFSH
Accident Date	01-04-2019	Claim Type. Third Party
Insured Vehicle	SHC1127B	Third Party Vehicle. SKQ3985T
Survey Location	BLK 6 NO. 399-G WOODLANDS ROADYEW TEE INDUSTRIAL ESTATE	
Contact Person.	MISS WOON	
Contact No.	67639733/ 0	Fax No. 67639866
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LONG SHENG MOTOR SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Long Sheng Motor Service

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: 09 May 2019 12:56
To: lsmstyc@singnet.com.sg
Cc: Joanne Yong Lai fong; CWS Motor Claims
Subject: RE: PRI REQUEST : FC REF: SHC1127B. (D19002463MFSH) & TP REF: SKQ3985T. (SKQ3985T) ACCIDENT ON 01-04-2019

Without Prejudice

Dear Sir/Madam,

We wish to state that we are agreeable to WITHOUT PREJUDICE – admit liability with quantum to be agreed.

Kindly liaise with our surveyor accordingly.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

From: Long Sheng Motor Service [mailto:lsmstyc@singnet.com.sg]
Sent: Tuesday, April 30, 2019 12:23 PM
To: 'CWS Motor Claims'
Subject: RE: PRI REQUEST : FC REF: SHC1127B. (D19002463MFSH) & TP REF: SKQ3985T. (SKQ3985T) ACCIDENT ON 01-04-2019

Dear Claim Department,

May we know your insured already report this accident to your company or not?

If reported already may we know how many liability for this case?

Thank you.

Best Regards,

Miss Woon

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0700C
Vehicle Details	
Vehicle No.:	SKQ3985T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2007
Engine No.:	3ZZ4713137
Chassis No.:	MR053ZEC107158900
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,795.00
Original Registration Date:	27 Nov 2007
First Registration Date:	27 Nov 2007
Transfer Count:	3
Actual ARF Paid:	\$16,275.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$14,802.00
Total Rebate Amount:	\$14,802.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 May 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 17 May 2019 2:04 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002463MFSH/1
Attachments: SKQ 3985T - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SKQ 3985T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 17 April 2019 8:23 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002463MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 16 April 2019 9:35 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002463MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Transfer Of Vehicle Ownership (Acknowledgement)

Vehicle Details

Vehicle No.:	SKQ3985T		
Vehicle Type:	N18 - Passenger (Co) Company Car (Single Rate)	Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA	Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Chassis No.:	MR053ZEC107158900	Engine No.:	3ZZ4713137
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	4
Engine Capacity:	1598 cc	Power Rating:	-
Unladen Weight:	1115 kg	Maximum Laden Weight:	1600 kg
Primary Colour:	Beige	Secondary Colour:	-
IU Label No.:	1124473389	Maximum Power Output:	81.0 kW (108 bhp)
First Registration Date:	27 Nov 2007	Original Registration Date:	27 Nov 2007
Manufacturing Year:	2007	Open Market Value:	\$14,795.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$8,137.00
No. of Transfer:	3	Actual ARF Paid:	\$16,275.00

Owner Particulars

Owner Name:	LIP FONG RENOVATION SERVICES
Owner ID Type:	Business
Owner ID:	43370700C
Registered Address Type:	HDB / HUDC
Registered Block/House No.:	44
Registered Street Name:	BENDEMEER ROAD
Registered Unit No.:	#01 - 1466
Registered Building Name:	-
Registered Postal Code:	330044
COE No./Expiry Date:	2007120101002216W / 26 Nov 2022
COE Bid Category:	A - Car (1600cc & below)
PQP Paid:	\$20,997.00

龙胜汽车服务 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733

Fax: 67639866

Email: lsmstyc@singnet.com.sg

• To display on...
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 10.05.2019

Owner: LIP FONG RENOVATION SERVICES

Attention: MS First Capital Insurance Limited - Motor Claims Department

RE: ACCIDENT FOR VEHICLE NO. SKQ3985T TOYOTA COROLLA ALTIS 1.6 A (2007) DOA: 01.04.2019
estimated cost of repair of the above mentioned vehicle:-

Replacement Parts:-

Page 1

1 pc	Rear Bumper	DEF ✓	\$	391.60	
2 pcs	Rear Bumper Side Retainer LH/RH @ S\$39.90	rec ✓	\$	79.80	
1 pc	Rear Bootlid	BUL ✓	\$	712.60	
1 pc	Rear Bootlid "TOYOTA" Emblem	rec ✓	\$	39.10	
1 pc	Rear Bootlid "COROLLA" Emblem	rec ✓	\$	38.60	
1 pc	Rear Bootlid "ALTIS" Emblem	rec ✓	\$	38.30	
1 pc	Rear Bootlid "VVTI" Emblem	rec ✓	\$	37.10	
1 pc	Rear Bootlid Inner Weatherstrip	CUT ✓	\$	89.30	
1 pc	Rear Bootlid Inner Lock	SUL X	\$	113.70	
1 pc	Rear End Panel	BUL ✓	\$	421.70	
1 pc	Rear End Panel Inner Garnish	CRA ✓	\$	118.90	
1 pc	Rear Tail Lamp RH	291.70 CRA ✓	\$	2,080.70	2372.40
	Less 25%		\$	(520.18)	
			\$	1,560.53	

To Repair

1pc Rear Spare Tyre Panel ~~To Repair~~ R

Special Nett:

	Reverse Sensor	shorted ✓	\$	280.00	200
	Rear Panel Sealant	rec ✓	\$	40.00	40
Add :	Rear Tail Lamp Lower Panel Rivet @ \$3.00 (8 pcs)	rec ✓	\$	24.00	10
	Labour Charges		\$	700.00	600
	Spray Painting		\$	720.00	650
	To Remove & Replace Rear Bootlid and Compartment		\$	120.00	50
	To Remove & Replace Rear Reverse Sensor		\$	80.00	30
	Tuff Kote		\$	60.00	40
	Check Wiring		\$	60.00	30
	Total Amount :		\$	3,580.53	

Total - \$2700/-

3903.30
Three Jia - CLK
15/5/19
L/S 5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007342/Jsd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1127B	Veh. Inspected	SKQ 3985T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002463MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	16/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053ZEC107158900	Colour	GOLD	
Odometer	342274	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	FIRENZA	6 mm	
L/H Front Tyre	185/70 R14	FIRENZA	6 mm	
R/H Rear Tyre	185/70 R14	FIRENZA	6 mm	
L/H Rear Tyre	185/70 R14	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2019	Inspection Date	15/05/2019	
Survey held at	LONG SHENG MOTOR SERVICE BLK 6, NO. 399-G, WOODLANDS RD YEW TEE IND. ESTATE SINGAPORE 678007.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 3985T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	391.60	391.60
2	REAR BUMPER SIDE RETAINER LH/RH @\$39.90	NECESSARY	79.80	79.80
1	REAR BOOTLID	BUCKLED	712.60	712.60
1	REAR BOOTLID "TOYOTA" EMBLEM	NECESSARY	39.10	39.10
1	REAR BOOTLID "COROLLA" EMBLEM	NECESSARY	38.60	38.60
1	REAR BOOTLID "ALTIS" EMBLEM	NECESSARY	38.30	38.30
1	REAR BOOTLID "VVTI" EMBLEM	NECESSARY	37.10	37.10
1	REAR BOOTLID INNER WEATHERSTRIP	CUT	89.30	89.30
1	REAR BOOTLID INNER LOCK	SERVICEABLE	113.70	-
1	REAR END PANEL	BUCKLED	421.70	421.70
1	REAR END PANEL INNER GARNISH	CRACKED	118.90	118.90
1	REAR TAIL LAMP RH	CRACKED	291.70	291.70
	LESS 25% DISCOUNT		-593.10	-564.68
			1,779.30	1,694.02
SPECIAL NETT ITEMS				
1	REAR SPARE TYRE PANEL (NPA)(SN)	TO REPAIR SEE LABOUR	-	-
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR PANEL SEALANT (SN)	NECESSARY	80.00	40.00
8	REAR TAIL LAMP LOWER PANEL RIVET @\$3.00 (SN)	NECESSARY	24.00	10.00
			384.00	250.00
LABOUR				
	LABOUR CHARGES INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		700.00	600.00
	SPRAY PAINTING.		720.00	650.00
	TO REMOVE & REPLACE REAR BOOTLID AND COMPARTMENT.		120.00	50.00
	TO REMOVE & REPLACE REAR REVERSE SENSOR.		80.00	30.00
	TUFF KOTE.		60.00	40.00
	CHECK WIRING.		60.00	30.00
			1,740.00	1,400.00

Report Ref No. CS/FCI19007342/Jsd3n2



GRAND TOTAL		3,903.30	3,344.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CS/FCI19007342/Jsd3n2

MARKET VALUE: \$20,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,802.00=NETT VALUE: \$5,198.00

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.