

ASS. REC. BY:

REF:

28/MSG19007350/Kqd3

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Monica chng

of

MSLG

Date/Time:

25/4/19 10:20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MYTC3

To Inspect Vehicle No:

SHD 9826J

Insured:

SFF 4468E

at Workshop n/s

7 hrs cab

Tel:

82876666

of

NO. 2 Amk St. 63

Policy No:

27193944 SMP

Claim No:

591441

Sum Insured:

Balance:

Make of Veh

(Client's Record)

D.O.A

23/4/19

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

04am @ 25/4/19

Person Contacted:

Amenda

Vehicle

IN / OUT

Date/Time

Action/Instruction () Estimate

SHD 9826J - NBA / MSG19007183/Y

DUA: 23/4/19

SFF 4468 E - NBA / MSG19007183/Y

DUA: 23/4/19

24/4/19 @ 4.33pm moved to Monica Chung re Monica.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	At	Open	Ref	Ad Submitted	Inv Auth'd	Status
Main	24 Apr 2019	25 Apr 2019 10:20					New Assignment Cancel Case
		Assign					

Main | Insurance | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MAHESH ARJANDA CHOOLANI		ID: 51590208F
Main Claimant:	TRANS-CAB SERVICES PTE LTD		
Vehicle Reg. No.:	SHD9826J	Date of Loss:	23/04/2019 14:00 - :59 [59 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 591441	Policy/Cover Note No.:	27193444SMP (Comprehensive) Coverage: 29/09/2018 - 28/09/2019
Vehicle Reg. No. (Insured):	SFF4468E	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/04/2019]		
Driver/Custodian (Insured):	ABDULLAH BIN HASSAN [], NRIC: S0066770F, Tel: +6597927534 Email:		
Adj Asg. Remarks:	LIABILITY:100% CONTACT AMANDA 6213 0998		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Tag	Solution	Handler	Assigned By	Completed On	Created On	Done?
No results.								

Shiau Chan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 30 April 2019 12:58 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: TP VEHICLE SHD 9826J (DOA: 23/04/2019) -- AAD1904-226
Attachments: image001.wmz

Hi Shiau Chan

We confirmed COR amount \$ 3,300.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, 29 April, 2019 5:25 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHD 9826J (DOA: 23/04/2019)

Dear Wai Yin,

WITHOUT PREJUDICE

Based on our surveyor's estimate marking, the calculation of repair cost will be at Lump Sum \$3,300.00 and 3 repair days.

Kindly check.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 29 Apr 2019

Preliminary Advice

Insured Vehicle No	: SFF4468E	Accident Date	: 23/04/2019
TP Vehicle No	: SHD9826J	Assignment Date	: 25/04/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 3.00
Date of Inspection	: 25/04/2019		
Inspection At	: TRANS-CAB SERVICES PTE LTD (HQ) 2 ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,888.37
Revised Amount	:S\$	4,125.19
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,125.19
Lump Sum Repair	:S\$	3,300.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9826J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C001017
Chassis No.:	VF1ABL15AUC277403
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	25 Apr 2014
First Registration Date:	25 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	24 Apr 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$59,871.00
COE Rebate Amount:	\$22,472.00
Total Rebate Amount:	\$31,845.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2019 15:31
Date Of Accident	23/04/2019 14:30
Exact Location Of Accident	SINARAN DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9826J
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303678K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LEE CHUAN ANN
NRIC No	S1485526B
Date Of Birth	25/05/1961
Occupation	OUTDOOR
Date Of Driving Pass	09/05/1979
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85186468
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 363B SEMBAWANG CRESCENT #11-747
Postcode	752363
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HEATHER RODOCKER - 90026423 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 23.04.2019 at about 1430 hours, I was travelling on the extreme left lane along Sinaran Drive when Vehicle B (SFF4468E) which was travelling on my right, swerved into my lane and hit onto my taxi right side portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFF4468E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ABDULLAH BIN HASSAN
NRIC/Passport Number	S0066770F
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see the attach G/A report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Galliac Sketch Plan Form_V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9826J

AAD1904-226


 29/4/19

 Not authorized
 L1 Imp & 3300h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD 9826J

VF1ABL15AUC277403

RENAULT

LATITUDE

23.4.2019

MSIG

25/4/2014

PART**LIST**

1	DOOR PANEL FRT LH	\$	2,844.66	} X
1	DOOR HINGE UPPER LH	\$	261.28	
1	DOOR HINGE LOWER LH	\$	300.55	
1	DOOR CHECK FRT LH	\$	194.77	
1	DOOR LOCK FRT LH	\$	908.75	
1	DOOR CATCH FRT LH	\$	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	477.76	
1	DOOR HANDLE COVER FRT LH	\$	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	133.60	
1	DOOR REGULATOR FRT LH	\$	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46	} X
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97	
1	DOOR PANEL REAR LH	\$	2,844.66	
1	DOOR GUIDE REAR LH	\$	176.82	
1	DOOR HINGE UPPER LH	\$	274.50	
1	DOOR HINGE LOWER LH	\$	300.55	
1	DOOR CHECK REAR LH	\$	203.06	
1	DOOR LOCK REAR LH	\$	908.75	
1	DOOR HANDLE OUTER REAR LH	\$	126.49	
1	DOOR HANDLE CAP REAR LH	\$	35.52	
1	DOOR HANDLE SEAL REAR LH	\$	7.89	
1	DOOR HANDLE COVER REAR LH	\$	13.22	
1	DOOR HANDLE MODULE REAR LH	\$	133.60	
1	DOOR REGULATOR REAR LH	\$	1,135.10	

Trans-cab Auto Services Pte Ltd**AAD1904-226**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9826J

1	DOOR REGUALTOR MOTOR REAR LH	\$	893.75
1	DOOR REGULATOR NUT REAR LH	\$	12.43
1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH	\$	423.10
1	DOOR MOULDING REAR LH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH	\$	1,509.06
1	DOOR WATER SHIELD REAR LH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR LH	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66
1	DOOR SEAL REAR LH	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64
1	FENDER PANEL REAR LH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR LH	\$	543.47
1	DOOR MIRROR ASSY LH	\$	1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	466.51
1	ROCKER PANEL INNER LH	\$	1,024.79
1	ROCKER PANEL CENTER LH	\$	990.25
1	BUMPER COVER REAR	\$	1,108.46
		\$	28,198.60
		10% \$	2,819.86
		\$	25,378.74

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	X
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X

Trans-cab Auto Services Pte Ltd

AAD1904-226

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9826J

1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	✓
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	601A
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	155A
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	601A
1	DOOR CHECK BOLT	\$	nn	22.69	} X
1	DOOR GUIDE SCREW	\$	nn	10.85	
1	DOOR HINGE BOLT	\$	nn	10.85	
1	DOOR HINGE NUT RH	\$	nn	14.60	
1	DOOR CHECK BOLT	\$	nn	22.69	
1	DOOR CHECK NUT	\$	nn	3.75	
1	DOOR LOCK SCREW L70Y	\$	nn	6.12	
1	DOOR CATCH SCREW L70Y	\$	nn	10.06	} X
1	LEFT REAR TYRE RIM	\$	nn	380.00	
1	LEFT REAR TYRE	\$	nn	330.00	

TOTAL	\$	1,329.63
-------	----	----------

TOTAL PARTS	\$	26,708.37
-------------	----	-----------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,200.00	5001
----	----------	------

To apply paint protection system (PPS) maintain and enhancement

\$	nn	380.00	X
----	----	--------	---

Putty and spray painting of the affected portion.

\$	4,200.00	8801
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	301
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	nn	380.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd

AAD1904-226

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9826J

To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 2d
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00 X
Towing Fee	\$	na 120.00 X
TOTAL	\$	10,180.00
Over All Total	\$	36,888.37

LUMP SUM(REPAIR DAY)

~~20-DAYS~~

3 days

Trans-cab Auto Services Pte Ltd hereby notify the Repairs of the following:

- To ensure vehicle safety during
- To ensure vehicle safety during
- To ensure vehicle safety during
- To ensure vehicle safety during
- To ensure vehicle safety during
- To ensure vehicle safety during
- To ensure vehicle safety during
- To ensure vehicle safety during

Accompanied by Repairs

Signature

Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Apr 2019		25 Apr 2019 10:20 Edit Adj Rpt	\$53,300.00 Edit Estimates	\$53,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	MAHESH ARJANDAS CHOOLANI , ID: S1590208F								
Main Claimant:	TRANS-CAB SERVICES PTE LTD								
Vehicle Reg. No.:	SHD9826J	Date of Loss:	23/04/2019 14:00 - :59 [59 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 591441	Policy/Cover Note No.:	27193444SMP (Comprehensive) Coverage: 29/09/2018 - 28/09/2019						
Vehicle Reg. No. (Insured):	SFF4468E	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, S69111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/05/2019]								
Driver/Custodian (Insured):	ABDULLAH BIN HASSAN () , NRIC: S0066770F, Tel: +6597927534 Email:								
Adj Asg. Remarks:	LIABILITY:100% CONTACT: AMANDA 6213 0998								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD9826J (591441)
[SFF4468E]
TP
TRANS-CAB SERVICES PTE LTD
Apr 23 2019 2:00PM
[MAHESH ARJANDAS CHOOLANI]
Trans-Cab Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page 1	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	24/04/19 15:20	Accident Statement From: SC - Reg. No: SFF4468E, Claimant: MAHESH ARJANDAS CHOOLANI			Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	29/04/19 16:31	Adjuster Immediate Advice			Load HTM		
Photos/Images						3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	30/04/19 13:49	General View			Load JPG	☒	
2	30/04/19 13:49	General View			Load JPG	☒	
3	30/04/19 13:49	General View			Load JPG	☒	
4	30/04/19 13:49	General View			Load JPG	☒	
5	30/04/19 13:49	General View			Load JPG	☒	
6	30/04/19 13:49	General View			Load JPG	☒	
7	30/04/19 13:49	General View			Load JPG	☒	
8	30/04/19 13:49	General View			Load JPG	☒	
9	30/04/19 13:49	General View			Load JPG	☒	
10	30/04/19 13:49	General View			Load JPG	☒	
11	30/04/19 13:49	General View			Load JPG	☒	
12	30/04/19 13:49	General View			Load JPG	☒	
13	30/04/19 13:49	General View			Load JPG	☒	
14	30/04/19 13:49	General View			Load JPG	☒	
15	30/04/19 13:49	General View			Load JPG	☒	
16	30/04/19 13:49	Odometer Reading			Load JPG	☒	
17	30/04/19 13:49	Chassis Number			Load JPG	☒	
18	30/04/19 13:49	General View			Load JPG	☒	
Documentation						1 per page 1	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	24/04/19 15:20	E-FILE REPORT (SHD4468E) From: SC - Reg. No: SFF4468E, Claimant: MAHESH ARJANDAS CHOOLANI			Load PDF		
2	24/04/19 15:21	TP EST BILL & ACCDT REPORT			Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19007350/KQD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27193444SMP

Claimant Vehicle No : SHD9826J

Insured Vehicle No : SFF4468E

Date of Loss: 23/04/2019

Nature of Claim: TP

Claim No: 591441

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9826J

Make & Model: RENAULT LATITUDE, 2.0 L (A)

Engine No: M9R8839C001017

Reg. Date: 25/04/2014 (Man. Year: 2013)

Chassis No: VF1ABL15AUC277403

Colour: Metallic White/Red

Odometer: 323692 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Goodyear 8 mm

Rear Left Side: Goodyear 8 mm

Front Right Side: Goodyear 8 mm

Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,708.35	2,695.19	24,013.16	89.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,180.00	1,430.00	8,750.00	85.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,888.35	4,125.19	32,763.16	88.82
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	36,888.35	3,300.00	33,588.35	91.05
+ GST 7.00/7.00% (S\$)	2,582.18	231.00	2,351.18	91.05
Nett Amount (S\$)	39,470.53	3,531.00	35,939.53	91.05

INSPECTION

Date of Assignment: 25/04/2019

Date Inspected: 25/04/2019 Inspected At:

Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9826J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
2	1		*DOOR HINGE UPPER LH	Repair	261.28 FL	*- FL
3	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
4	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
5	1		*DOOR LOCK FRT LH	Repair	908.75 FL	*- FL
6	1		*DOOR CATCH FRT LH	Serviceable	131.23 FL	*- FL
7	1		*DOOR HANDLE OUTER FRT LH	Serviceable	477.76 FL	*- FL
8	1		*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*- FL
9	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
10	1		*DOOR REGULATOR FRT LH	Serviceable	505.19 FL	*- FL
11	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	796.46 FL	*- FL
12	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*- FL
13	1		*DOOR PANEL REAR LH	Dented / Warped	2,844.66 FL	*2,844.66 FL
14	1		*DOOR GUIDE REAR LH	Serviceable	176.82 FL	*- FL
15	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
16	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
17	1		*DOOR CHECK REAR LH	Serviceable	203.06 FL	*- FL
18	1		*DOOR LOCK REAR LH	Repair	908.75 FL	*- FL
19	1		*DOOR HANDLE OUTER REAR LH	Serviceable	126.49 FL	*- FL
20	1		*DOOR HANDLE CAP REAR LH	Serviceable	35.52 FL	*- FL
21	1		*DOOR HANDLE SEAL REAR LH	Serviceable	7.89 FL	*- FL
22	1		*DOOR HANDLE COVER REAR LH	Serviceable	13.22 FL	*- FL
23	1		*DOOR HANDLE MODULE REAR LH	Serviceable	133.60 FL	*- FL
24	1		*DOOR REGULATOR REAR LH	Serviceable	1,135.10 FL	*- FL
25	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	893.75 FL	*- FL
26	1		*DOOR REGULATOR NUT REAR LH	Serviceable	12.43 FL	*- FL
27	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*- FL
28	1		*DOOR FINISHER REAR LH	Serviceable	423.10 FL	*- FL
29	1		*DOOR MOULDING REAR LH	Serviceable	176.82 FL	*- FL
30	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
31	1		*DOOR MOULDING SCREW L70Y	Not Necessary	6.91 FL	*- FL
32	1		*DOOR CASING REAR LH	Serviceable	1,509.06 FL	*- FL
33	1		*DOOR WATER SHIELD REAR LH	Serviceable	30.39 FL	*- FL
34	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
35	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
36	1		*DOOR FINISHER INNER REAR LH	Serviceable	323.44 FL	*- FL
37	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	46.97 FL	*- FL
38	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
39	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
41	1		*DOOR GRAB HANDLE REAR LH	Serviceable	210.96 FL	*- FL
42	1		*DOOR BLIND REAR LH	Serviceable	741.80 FL	*- FL
43	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	410.66 FL	*- FL
44	1		*DOOR SEAL REAR LH	Serviceable	162.02 FL	*- FL
45	1		*DOOR GLASS RUBBER SEAL REAR LH	Serviceable	229.31 FL	*- FL
46	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	334.69 FL	*- FL
47	1		*DOOR WAIST SEAL INNER REAR LH	Serviceable	115.64 FL	*- FL
48	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
49	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
50	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
51	1		*DOOR MIRROR ASSY LH	Serviceable	1,483.40 FL	*- FL
52	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
53	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
54	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
55	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*- FL
56	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
57	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
58	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
59	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
60	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
61	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
62	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
63	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
64	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
65	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS
66	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS
67	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
68	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
69	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
70	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
71	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
72	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
73	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
74	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS
75	1		*LEFT REAR TYRE RIM	Serviceable	380.00 FS	*- FS
76	1		*LEFT REAR TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	29,528.21	2,979.66
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,819.86	284.47
Total Parts (\$\$)	26,708.35	2,695.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,200.00	500.00
2	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	880.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TOWING FEE	New	120.00	0.00
Gross Labour Cost (S\$)			10,180.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >