

References

ASSIGNMENT

Veh No: SM1260643. Yr Regn: 2018 / Assn

Type: ☐ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Altis cc 1598

Colour: Blue A/C: Insured / Std / NI / NA

So Reading 15494. T/Radio: Insured / Std / NI / NA

Eng/No:

CN0: MRO53REH604587779

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 705/55R16

R: 205/25R16

N/S	O/S

R: 205/25R16

Front Rear
R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.L. 25/04/19

Survey held at Keny

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

83592

Date/Time, File Pass to?	Date/Time, File Return to?	<u>Part Prices Check:</u>		Survey Fee:	Date:
1)	2)	IN	OUT	Basic & Add.	
3)	4)			__ \$ + RS, __ \$	
5)	6)			Photos	
Prel. Report:				Others	
Final Report:				TOTAL	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900106
Date: 25 Apr 2019
Veh Reg No: SMD6064B
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chasis No: MR053REH604587779
Reg. Date: 28/08/2018
Your Ref No: SKH8800H

Claim Type: Third Party
Accident Date: 25/04/2019
TP Veh Reg No: SKH8800H

Asker

Estimate Repair Cost to Vehicle No :SMD6064B

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC REAR BUMPER <i>rehab</i>	482.70 ✓	
2	1 PC REAR BUMPER REINFORCEMENT <i>Best</i>	420.10 ✓	
3	2 PCS REAR BUMPER SIDE RETAINER <i>pc</i>	228.80 ✓	
4	2 PCS TAIL LAMP LOWER RETAINER <i>pc</i>	135.20 x	
5	1 PC REAR BUMPER REFLECTOR <i>rehab</i>	88.90 ✓	
6	2 PCS REAR BUMPER SCREW HOUSING <i>pc</i>	36.40 x	
7	2 PCS REVERSE SENSORS <i>pc</i>	576.40 ✓	
8	2 PCS REVERSE SENSORS RING <i>pc</i>	43.20 ✓	
9	1 PC BOOT LID RUBBER <i>pc</i>	166.40 x	
10	1 PC TAIL LAMP <i>pc</i>	409.60 x	
		2,587.70	
	Less 25%	646.93	1,940.79
Labour			
11	1 TO CHECK WIRING	50.00 <i>30</i>	
12	1 TO SPRAY UNDERSEAL	100.00 <i>x</i>	
13	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 <i>50</i>	
14	1 (REAR) TO SPRAY PAINTING	1,000.00 <i>640</i>	
15	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	850.00 <i>400</i>	
		2,080.00	2,080.00

1840.10

1380.08

1130

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 25/04/2019
TP Veh Reg No: SKH8800H

Estimate No: EST1900106
Date: 25 Apr 2019
Veh Reg No: SMD6064B
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chasis No: MR053REH604587779
Reg. Date: 28/08/2018
Your Ref No: SKH8800H

Estimate Repair Cost to Vehicle No :SMD6064B

Quantity	Description	List Price S\$	Amount S\$
	Total		S\$ 4,020.79
	Add GST @ 7%		281.46
	Total Amount Payable		S\$ 4,302.25

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED AND TWO AND CENTS
TWENTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
1/2 P/P 25/04/19.
03 days.

Total 2510.08
(P/P)



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR0420196064AIG
Your Ref : SKH8800H

Date : 11 SEP 2019

WITHOUT PREJUDICE

AIG Asia Pacific Insurance Pte Ltd
C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933
Attention : Motor Claim Department

Dear Sirs,

Accident involving SMD6064B and SKH8800H on 25.04.2019 along Hong Kong St twds New Bridge Rd.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SKH8800H.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by Mr Chua Thiam Poh, the owner of motor-vehicle no: SMD6064B, we submit their claim to you:

Cost of repairs (Inclusive of 7% GST)	\$ 2,685.79
Loss of use/Income (4 days (3 + 1 Sunday) x \$150.00-Pte Hire)	\$ 600.00
GIA search	\$ 2.00
	<u>\$ 3,287.79</u>
	=====

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1900491
- 2) GIA report and certificate insurance of SMD6064B
- 3) GIA search fee & invoice

We hope to receive your early reply soon.

Thank you.

Yours faithfully,
KANG CAR REPAIRERS PTE LTD

.....



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19007356/Apb3

8 APRIL 2019

EIO HOCK KUANG
6A HOUGANG STREET 11
#05-14
SINGAPORE 538756

Dear Sir/Madam,

**ACCIDENT INVOLVING SKH 8800H & SMD 6064B ALONG/AT JUNCTION OF
HONG KONG ST AND NEW BRIDGE ROAD ON 25/04/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SMD 6064B against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: JiaLe@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Chua Thiam Poh ("the third party claimant")
of Blk 435C Fernvale Rd #15-222 S793435 (address),
owner of SMD6064B (vehicle no.) hereby authorize
Kang Car Repairers Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SMD6064B that was
damaged pursuant to the accident which occurred on 25.04.2019 (date) along
Hong Kong St twds New Bridge Rd (location)
involving vehicle no/s SKH8800H ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment fortherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 25 day of Apr (month) 20 19 (year)


Signed by "the third party claimant"

KANG CAR REPAIRERS PTE. LTD.

Signed by "the workshop"

This Discharge Voucher applies strictly for Claimant's claim for personal-injury/ property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER (AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I KANG CAR REPAIRERS PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 2,685.79 (repair costs), S\$ 240.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SMD6064B that was damaged pursuant to the accident which occurred on 25.04.2019 (date) along HONG KONG ST TWDS NEW BRIDGE RD (location) involving vehicle no/s SKH8800H

This is pursuant to the inspection conducted on 25/04/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHUA THIAM POH ("third party claimant") of vehicle no. SMD6064B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SMD6064B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 day of SEPTEMBER (month) 20 19 (year)



Signed by AIG appointed surveyor

KANG CAR REPAIRERS PTE. LTD.

Chopped & Signed by "the workshop"



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Your Ref No: SKH8800H
Claim Type: Third Party
Accident Date: 25/04/2019
TP Veh Reg No: SKH8800H

Final No: KCR-INV1900491
Claim No: EST1900106
Date: 29 Aug 2019
Policy No: 5108741596
Veh Reg No: SMD6064B
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053REH604587779
Engine No: 1ZR0C07464
Reg. Date: 28/08/2018

Tax Invoice to Vehicle No :SMD6064B

Description	Quantity	List Price	PAGE:1
			Amount
		SS	SS

As recommended by surveyor to proceed repair at total cost/lumpsum cost	S\$ 2,510.08
Add GST @ 7%	175.71
Total Amount payable	S\$ 2,685.79

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SIX HUNDRED EIGHTY FIVE AND CENTS
SEVENTY NINE ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-065095

Date of Request: 25/04/2019

Your Ref No: Online Purchase

Kang Car Repairers Pte Ltd
No 1 Kaki Bukit Ave 6
#02-06 AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 25/04/2019
Enquiry By Yee Mei Cheng
TP Vehicle No. SKH8800H
Accident Date 25/04/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKH8800H	AIG Asia Pacific Insurance Pte. Ltd.	28/05/2018-27/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-065095

Date of Request: 25/04/2019

Your Ref No: Online Purchase

Kang Car Repairers Pte Ltd
No 1 Kaki Bukit Ave 6
#02-06 AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 25/04/2019
Enquiry By Yee Mei Cheng
TP Vehicle No. SKH8800H
Accident Date 25/04/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2019 Edit Reg		25 Apr 2019 00:00 Edit Adj Rpt	S\$2,510.07 Edit Estimates	S\$2,510.07 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	EIO HOCK KUANG , ID: S1394280C								
Main Claimant:	CHUA THIAM POH , ID: S1688359Z								
Vehicle Reg. No.:	SMD6064B	Date of Loss:	25/04/2019 08:00 - :59 [7 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4984022365SG	Policy/Cover Note No.:	2100301193 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKH8800H	Policy No. (Claimant):	5108741596						
		Excess:							
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



*SMD6064B (4984022365SG)
[SKH8800H]
TP
CHUA THIAM POH
Apr 25 2019 8:00AM
[EIO HOCK KUANG]
Kang Car Repairs Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
13	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
14	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
16	01/08/19 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
17	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	01/08/19 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/04/19 18:43	TP ESTIMATE + TP GIA REPORT		Load PDF	
2	09/10/19 10:14	WORKSHOP INVOICE		Load PDF	
3	09/10/19 10:14	AUTHORISATION TO ACT FORM		Load PDF	
4	09/10/19 10:14	Release Voucher		Load PDF	
5	09/10/19 10:14	GIA SEARCH		Load PDF	
6	09/10/19 10:14	LDD		Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
7	09/10/19 10:14	LETTER TO OI			Load PDF
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/04/19 09:01	OI GIA REPORT			Load PDF

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKH8800H (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SMD6064B (TP veh)		1.6 STANDARD (A)
Date of Accident:	25/04/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	4,302.22
Final Repair Cost	:	\$	2,685.79
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,927.79

4.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 2,927.79
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19007358/AEA3Q2

Date: 09/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100301193
 Claimant SMD6064B Insured Vehicle No : SKH8800H
 Vehicle No : SMD6064B
 Date of Loss: 25/04/2019 Nature of Claim: TP Claim No: 4984022365SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD6064B
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 Standard (A) Engine No: 1ZR0C07464
 Reg. Date: 28/08/2018 (Man. Year: 2018) Chassis No: MR053REH604587779
 Colour: Blue Odometer: 15494 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,940.77	1,380.07	560.70	28.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,130.00	950.00	45.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,020.77	2,510.07	1,510.70	37.57
+ GST 7.00/7.00% (S\$)	281.45	175.70	105.75	37.57
Nett Amount (S\$)	4,302.22	2,685.77	1,616.45	37.57
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,927.77		

INSPECTION

Date of Assignment: 25/04/2019
 Date Inspected: 25/04/2019 Inspected At: Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06
 AutoBay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	482.70 FL	*482.70 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	420.10 FL	*420.10 FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	228.80 FL	*228.80 FL
4	2		*TAIL LAMP LOWER RETAINER	Not Necessary	135.20 FL	*- FL
5	1		*REAR BUMPER REFLECTOR	Cracked	88.90 FL	*88.90 FL
6	2		*REAR BUMPER SCREW MOULDING	Not Necessary	36.40 FL	*- FL
7	2		*REVERSE SENSORS	Damaged	576.40 FL	*576.40 FL
8	2		*REVERSE SENSORS RING	Necessary	43.20 FL	*43.20 FL
9	1		*BOOT LID RUBBER	Not Necessary	166.40 FL	*- FL
10	1		*TAIL LAMP	Not Necessary	409.60 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,587.70	1,840.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	646.93	460.03
Total Parts (\$\$)	1,940.77	1,380.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY UNDERSEAL	New	100.00	0.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
4	(REAR) TO SPRAY PAINTING	New	1,000.00	650.00
5	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTION ,AND FOR CUTTING/WELDING WORKS	New	850.00	400.00
Gross Labour Cost (S\$)			2,080.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >