

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900106
Date: 25 Apr 2019
Veh Reg No: SMD6064B
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chasis No: MR053REH604587779
Reg. Date: 28/08/2018
Your Ref No: SKH8800H

Claim Type: Third Party
Accident Date: 25/04/2019
TP Veh Reg No: SKH8800H

Asher

Estimate Repair Cost to Vehicle No :SMD6064B

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>rehard</i>	482.70 ✓	
2	1 PC REAR BUMPER REINFORCEMENT <i>Bent</i>	420.10 ✓	
3	2 PCS REAR BUMPER SIDE RETAINER <i>pc</i>	228.80 ✓	
4	2 PCS TAIL LAMP LOWER RETAINER <i>pc</i>	135.20 x	
5	1 PC REAR BUMPER REFLECTOR <i>rehard</i>	88.90 x	
6	2 PCS REAR BUMPER SCREW HOUSING <i>pc</i>	36.40 x	
7	2 PCS REVERSE SENSORS <i>pc</i>	576.40 ✓	
8	2 PCS REVERSE SENSORS RING <i>pc</i>	43.20 ✓	
9	1 PC BOOT LID RUBBER <i>pc</i>	166.40 x	
10	1 PC TAIL LAMP <i>pc</i>	409.60 x	
		2,587.70	
	Less 25%	646.93	1,940.79
Labour			
11	1 TO CHECK WIRING	50.00 <i>30</i>	
12	1 TO SPRAY UNDERSEAL	100.00 x	
13	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 <i>50</i>	
14	1 (REAR) TO SPRAY PAINTING	1,000.00 <i>660</i>	
15	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	850.00 <i>400</i>	
		2,080.00	2,080.00

1840.10

1380.08

1130

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 25/04/2019
TP Veh Reg No: SKH8800H

Estimate No: EST1900106
Date: 25 Apr 2019
Veh Reg No: SMD6064B
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chasis No: MR053REH604587779
Reg. Date: 28/08/2018
Your Ref No: SKH8800H

Estimate Repair Cost to Vehicle No :SMD6064B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 4,020.79
	Add GST @ 7%		281.46
	Total Amount Payable		<u>S\$ 4,302.25</u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED AND TWO AND CENTS
TWENTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
1/2 P/P 25/04/19.
030mgs.

total: 2510.08
(P/P)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Hongkong St turning left to New Bridge Rd. In the midst of turning left, I heard somebody honing so I stopped. Suddenly, Vehicle B (SKH 8800H) from behind collided to my rear portion causing damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature 25/4/2019
Date & Time: 12.15pm

Driver's Signature _____ 25/4/2019
(If driver is not the policyholder)
Date & Time: _____ 12.15pm

Reporting Centre Personnel's Signature