



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLZ5868B

Goh Hong Ling (wu Fengling)

25 Saraca Drive
Singapore 807517

64813984

Vehicle & Document Information
WIP No 32877
Reg No/Reg Date SLZ5868B / 14/03/2018
Date In/Mileage / 0
Chassis No WDC2533462F379065
Engine No 27492031316398
Make/Model MB/MB GLC 250 4MATIC COUPE (C253)
Colour/Trim 029 992 Selenite Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WCV34413	CRDVCH	24/04/2019/ 17:53	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 1800025031 // 24/04/2019 DRIVE IN/EXCESS : 24/04/2019 // TP VEH NO SHC5139R AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON : S BPNSUB 1 PC REAR NO PLATE WITH CASING A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH. A BPIRES RESPRAY REAR BUMPER A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS. A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT M REAR BUMPER ? X R M REAR BUMPER LOWER (47- M REAR BUMPER MOULDING (chrome) (47- M REAR BASIC MOUNTING FOR BUMPER X SVC				NEC60.00 ✓ 960 1200.00 600 750.00 0.10 380.00 ✓ 120.00 ✓ 1.00 1196.44 00.00 1196.44 1.00 690.66 00.00 690.66 1.00 412.39 00.00 412.39 1.00 199.69 00.00 199.69

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 5,009.18
7% GST on 5009.18 350.64
Total Payable 5,359.82

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after repair work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is required for the commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting
• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation
• The above estimate is on a "No Work No Fee" basis

• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany