

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMGK3850JX223053
License No: SMA5444K
Mileage: 5914
Engine No: L13B11030814

Document No: SVO19028361
Printed By: JACKNG
Order Date: 6. May 2019
Order Time: 11:14:34 AM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl'd GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TAN KIAN SENG OWNER INSURER:TOKIO MARINE ACC DATE:18/04/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE TP VEH:SLS 1040 K						
04715-T5A-J50ZZ	1 FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	2 SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	3 SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	4 CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
04636-TAR-300ZZ	5 PANEL SET,R.RR.OUTER	1	548.30	25	411.22	28.79	440.01
42700-T5S-M72	6 WHEEL,DISK AL 15X7	1	418.40	25	313.80	21.97	335.77
73525-SYY-000	7 RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57
91501-T5A-003	8 CLIPQUARTER WINDSHIELD A	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	9 CLIPQUARTER WINDSHIELD B	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	10 CLIPQUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	11 WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
	SUM PARTS:				1,213.91	84.98	1,298.89
BOSUN		1	50.00		50.00	3.50	53.50
	SUNDRIES						
BOJSE	1718	1	120.00		120.00	8.40	128.40
	BODY JOINT SEALANT FOR RHS REAR FENDER						
BML02I		1	280.00		280.00	19.60	299.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R	1466	1	380.00		380.00	26.60	406.60
	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)						
BG52D	1438	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL RR. R QTR GLASS. (N)						
BMI02D	1438	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)						
BKRP21S	1466	1	2,520.00		2,520.00	176.40	2,696.40
	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW ALL DAMAGE PARTS.						
BP04R	1718	1	1,350.00		1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)						
	SUM LABOUR:				5,540.00	387.80	5,927.80



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMGK3850JX223053
License No: SMA5444K
Mileage: 5914
Engine No: L13B11030814

Document No: SVO19028361
Printed By: JACKNG
Order Date: 6. May 2019
Order Time: 11:14:34 AM
Service Advisor: JACK NG

BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.60	192.60
			SUM EXT SERVICE:	180.00	12.60	192.60
			TOTAL SGD	6,933.91	485.38	7,419.29
Total Payable (SGD)						7,419.29

GST Amount is calculated from individual line(s)

L04
9am



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMA5444K
Chassis No : JHMGK3850JX223053
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : TAN KIAN SENG
Ins Policy No. :
Date of Accident : 18/4/2019

Document No. : SQT19001862
Date : 26. Apr 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : L13B11030814
Date | Time : 26. Apr 2019 1:45:04 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TAN KIAN SENG OWNER INSURER:TOKIO MARINE ACC DATE:18/04/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE TP VEH:SLS 1040 K						
04715-T5A-J50ZZ	① FACE,RR.BUMPER / CUT	1	492.70	25	369.52	25.87	395.39
71505-T5A-J50	GARNISH,RR.BUMPER ?	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	② SPACER,R.RR.BUMPER SIDE / ALK	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	③ SPACER,L.RR.BUMPER SIDE / ALK	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	④ CLIP,BUMPER / ALK	7	2.30	25	12.07	0.84	12.91
04636-TAR-300ZZ	⑤ PANEL SET,R.RR.OUTER / DD	1	548.30	25	411.22	28.79	440.01
42700-TAR-E91	⑥ DISK ALUMINIUM WHEEL,16X6 (Rear RH) CUT	1	772.30	25	579.22	40.55	619.77
73511-T5A-003	GLASSR.QUARTER ?	1	153.60	25	115.20	8.06	123.26
73525-SYY-000	⑦ RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57
91501-T5A-003	⑧ CLIPQUARTER WINDSHIELD A / ALK	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	⑨ CLIPQUARTER WINDSHIELD B	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	⑩ CLIPQUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	⑪ WINDSCREEN SEALANT (N) / ALK	1	60.00		60.00	4.20	64.20
Sum Item					1623.25	113.63	1736.88
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR RHS REAR FENDER	1	150.00	120	150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00	280	380.00	26.60	406.60
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00		380.00	26.60	406.60

Printed on 26/4/2019 2:09:24 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMA5444K
Chassis No : JHMGK3850JX223053
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : TAN KIAN SENG
Ins Policy No :
Date of Accident : 18/4/2019

Document No. : SQT19001862 Page 2
Date : 26. Apr 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : L13B11030814
Date | Time : 26. Apr 2019 1:45:04 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	280.00	✓	280.00	19.60	299.60
BM102D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	800.00	560	800.00	56.00	856.00
BKRP21S	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW ALL	1	4500.00	2520	4500.00	315.00	4815.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2500.00	1350	2500.00	175.00	2675.00
Sum Labor					9090.00	636.30	9,726.30
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By

Steve (LKK)

Date & Time

6/5/19 10.10am

Excess

Status

Signature

7 days

WTL Mynia

P/P

RJ bel spy

Total Amount 10,893.25 762.53 11,655.78

Total (Inclusive of GST) 11,655.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 26/4/2019 2:09:24 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.