

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

L04
9am**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMA5444K

Chassis No : JHMGK3850JX223053

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : TAN KIAN SENG

Ins Policy No. :

Date of Accident : 18/4/2019

Document No. : SQT19001862

Date : 26. Apr 2019

Customer No. : WZA006

Svc Advisor : JACK NG

Engine No : L13B11030814

Date | Time : 26. Apr 2019 1:45:04 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TAN KIAN SENG OWNER INSURER:TOKIO MARINE ACC DATE:18/04/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE TP VEH:SLS 1040 K						
04715-T5A-J50ZZ	FACE,RR.BUMPER / CUT	1	492.70	25	369.52	25.87	395.39
71505-T5A-J50	GARNISH,RR.BUMPER ?	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE / ALK	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE / ALK	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER / ALK	7	2.30	25	12.07	0.84	12.91
04636-TAR-300ZZ	PANEL SET,R.RR.OUTER / DD	1	548.30	25	411.22	28.79	440.01
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6 (Rear RH) CUT	1	772.30	25	579.22	40.55	619.77
73511-T5A-003	GLASSR.QUARTER ?	1	153.60	25	115.20	8.06	123.26
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57
91501-T5A-003	CLIPQUARTER WINDSHIELD A / ALK	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIPQUARTER WINDSHIELD B	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / ALK	1	60.00		60.00	4.20	64.20
Sum Item					1623.25	113.63	1,736.88
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR RHS REAR FENDER	1	150.00	120	150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00	280	380.00	26.60	406.60
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00	/	380.00	26.60	406.60

Printed on 26/4/2019 2:09:24 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMA5444K
Chassis No : JHMGK3850JX223053
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : TAN KIAN SENG
Ins Policy No. :
Date of Accident : 18/4/2019

Document No. : SQT19001862 **Page** 2
Date : 26. Apr 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : L13B11030814
Date | Time : 26. Apr 2019 1:45:04 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	280.00	✓	280.00	19.60	299.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	800.00	560	800.00	56.00	856.00
BKRP21S	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW ALL	1	4500.00	2520	4500.00	315.00	4815.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2500.00	1350	2500.00	175.00	2675.00
Sum Labor					9090.00	636.30	9,726.30
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By

Steve (LKK)

Date & Time

6/5/19 10.10am

Excess

Status

Signature

Total Amount 10,893.25 762.53 11,655.78

Total (Inclusive of GST) 11,655.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 26/4/2019 2:09:24 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.