

not subject
 25/4/19
 21/2 #7789-45
 ABWIN 諭輝

IVAN TEO
 ABWIN SERVICE PTE LTD
 DID: 67139416
 Fax: 67139415
 HP:

Date : 25/04/2019
 TP Vehicle No. : SDH9155L
 To : AXA Insurance Singapore Pte Ltd
 Attn : Motor Claim Department

Owner : NG SHIRLEY ANN
 AIG ASIA PACIFIC INSURANCE PTE LTD
 Certificate No. : 1700025767-01
 Vehicle No. : SLE-2104-C
 Make & Model : TOYOTA SIENTA 1.5 (A)

Accident Date: 23/04/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR BUMPER	D/S \$422.00	—
10	REAR BUMPER CLIPS	1pc \$50.00	—
1	REAR BUMPER SIDE RETAINER RH	1pc \$82.00	X
1	REAR BUMPER SIDE RETAINER LH	1pc \$82.00	X
1	TAILLAMP LH	CR9 \$420.00	—
1	TAILLAMP RH	CU7 \$420.00	2
10	TAILLAMP CLIPS	17 \$50.00	X
1	TAILGATE	Reds. 20 \$1,220.00	—
1	TAILGATE LOCK CATCH	399.20 \$500.00	—
1	TAILGATE WEATHERSTRIP	295.10 \$420.00	—
1	TAILGATE LOGO - TOYOTA	68.50 \$95.00	—
1	TAILGATE EMBLEM " SIENTA"	17 \$60.00	X
1	TAILGATE INNER TRIM BOARD	17 \$240.00	X
1	REAR WHEEL HOUSING PANEL	12 \$520.00	X
2	REAR NO PLATE LAMPS	17 \$190.00	X
1	REAR END PANEL	50/4.0 \$460.00	—
1	REAR END PANEL TOP GARNISH	17.5 \$200.00	—
10	REAR END PANEL TOP GARNISH CLIPS	17 \$50.00	X
1	REAR WINDSCREEN MOULDING RH & LH	17 \$85.00	—
1	REAR TAILGATE INNER HANDLE GARNISH	DE \$57.00	X
1	LOCK SENSOR	21pc \$160.00	—
1	TAILGATE RUBBER	Replaced \$420.00	X
1	REAR BOOT TRAY	Dis/Tru \$510.00	—
1	TAILGATE TRIM BOARD	17 \$240.00	X
10	TAILGATE TRIM BOARD CLIPS	17 \$50.00	X
1	REAR BUMPER LOWER GARNISH	184.50 D/S \$220.00	—

Sub Total

\$7,223.00

Discount 25% on Parts

(\$1,805.75)

\$5,417.25

4951.7

Rear fender inner trim board RH one
 Rear bumper block garnish RH one
 Rear end panel inner 50/4.0

Date : 25/04/2019
 TP Vehicle No. :
 To :
 Attn : Motor Claim Department

IVAN TEO
 ABWIN SERVICE PTE LTD
 DID: 67139416
 Fax: 67139415
 HP:

Owner : NG SHIRLEY ANN
 AIG ASIA PACIFIC INSURANCE PTE LTD
 Certificate No. : 1700025767-01
 Vehicle No. : SLE-2104-C
 Make & Model : TOYOTA SIENTA 1.5 (A)

Accident Date: 23/04/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
Special Nett			
1	REAR SEALANT <i>windscreen</i>	\$150.00	<i>50 S.N</i>
1	REAR BODY SEAL	\$150.00	<i>X</i>
1	REVERSE SENSOR	\$280.00	<i>200 S.N</i>
1	REAR NO PLATE WITH CASING	\$65.00	<i>X</i>
	Sub Total	\$645.00	

Labour & Misc

TO CHECK WIRING AND FOCUS TAILLAMP	\$150.00	<i>30</i>
TO DISMANTLE & REPLACE REVERSE SENSOR	\$150.00	<i>50</i>
TO TRANSFER ALL REAR TAILGATE FITTING TO NEW	\$250.00	<i>60</i>
TO DISMANTLE & INSTALL REAR WINDSCREEN GLASS	\$150.00	<i>120</i>
TO APPLY TUFF KOTE ON AFFECTED AREA.	\$180.00	<i>60</i>
TO PANEL BEATING, KNOCKING THE REAR & TO RESTORE BACK ALL THE NECESSARY PARTS	\$1,800.00	<i>1100</i>
TO PUTTY & SPRAY PAINT ON THE AFFECTED AREA.	\$1,600.00	<i>1100</i>
Sub Total	\$4,280.00	<i>6692.60</i>

Sub Total

\$10,342.25

GST 7%

\$723.96

Total

\$11,066.21

P- 5019.45
S.N - 250.00
(chm - 2520.00)
7789.45

SUPPLEMENTARY

Date : 06/06/2019
 TP Vehicle No. : SDM-9155-L
 To : AXA INSURANCE SINGAPORE PTE LTD
 Attn : Motor Claim Department

YVONNE
 ABWIN SERVICE PTE LTD
 DID:
 Fax:
 HP:

Owner : NG SHIRLEY ANN
 AIG ASIA PACIFIC INSURANCE PTE LTD
 Certificate No. : 1700025767-01
 Vehicle No. : SLE-2104-C
 Make & Model : TOYOTA SIENTA 1.5 (A)

Accident Date: 23/04/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	REAR BUMPER ^{color} TOP GARNISH LHS	Repaint \$184.50	X
1	REAR BUMPER SIDE GARNISH LHS	paint \$177.60	/
1	REAR BUMPER SIDE GARNISH RHS	paint \$177.60	/
1	REAR FENDER INNER TRIM BOARD RHS	one \$657.90	/
1	REAR END PANEL INNER	Bodywork \$728.20	/
	Sub Total	\$1,925.80	
	Discount 25% on Parts	(\$481.45)	
		\$1,444.35	
	Sub Total	\$1,444.35	
	GST 7%	\$101.10	
	Total	\$1,545.45	