

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0527/2019/DY/TF
Date : 23-Apr-19

Vehicle NOT IN workshop

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Kim Huak
Address : Blk 239 Bishan Street 22
#18-200
Singapore 570239
Telephone : HP +65 91860819
Type of Claim : Own Damage Claims
Policy No. : 170006442-01
Vehicle No : **SKQ 3829 L**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Oct-17
Engine No : CHZ 528805
Chassis No : WAUZZZ8V9J1011749
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Apr-19
Place of Accident : Nee Ann City

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 3829 L

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	s/n \$ 360.00 ✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00 500
3	To respray front bumper and bonnet.	\$ 1,500.00 1100
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 3,252.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 3829 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>rehd</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS	\$ 170.00	✗
3	FRONT BUMPER GUIDE SECTION - LH	\$ 35.00	✗
4	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	\$ 270.00	✗
5	FRONT BUMPER LOWER GRILLE - CENTER	\$ 146.00	✗
6	FRONT BUMPER COVER TRIM - LH <i>new</i>	\$ 148.00	✗
7	RADIATOR GRILLE <i>combined new</i>	\$ 1,301.00	✓
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	\$ 174.00	✗
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 171.00	✗
10	FRONT BUMPER REINFORCEMENT <i>new</i>	\$ 660.00	✗
11	FOAM FILLER PIECE ?	\$ 172.00	?
12	FRONT BUMPER TOP COVER <i>new</i>	\$ 111.00	✗
13	A/C STICKER	\$ 7.00	✗
14	CAUTION STICKER <i>new</i>	\$ 13.00	✗
15	LED HEAD LIGHT - LH	\$ 5,029.00	✗
16	HEADLIGHT LIFT CYLINDER - LH <i>new</i>	\$ 128.00	✗
17	FRONT NO. PLATE <i>new</i>	\$ 40.00	✓
18	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS		\$ 10,905.00	
TOTAL LABOUR CHARGES		\$ 3,252.00	
GRAND TOTAL		\$ 14,157.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *25/04/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorized Repairs, 6 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant