

18/5/2010

INS CASE OWNER:

CC 3 / AXA140

1944 8

1K2

n/3

LKK:
IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

13/10/14

Assg Date:

13/10/14

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKH 6007 U

Name of Insured:

Ng Ai Leng

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

12/10/14

Claim No.:

C0319003

Policy No.:

P1332145

Make / Model:

Volkswagen

Place of Accident:

Along Orchard Rd on the left
Nest Lane

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: Wong Yung Zhi Jonathan

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: 81205450

(V/L: YES / NO Insured Liability:

% Final ? Yes / No



INSRS:

WSP: Trans Cab

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/11/14

Zayyer

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver's Own Vehicle Number:

Insurance Company:

SHF 511 R - X

SKH 6007 U - X

10/12/15 3:33

called OSD. spoke to Mr Wong. Inform
about the claim. Confirm the accident.
OSD rear ended TP. Agreed to
settle the claim and amount of
RCD will be affected.

letter out.

27/10/15

Email to A&A. Inform them we
submit w/p. See attached email.

STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA:

Medical Bill:

Approval Email:

Payment Breakdown Form:

Others:

FINAL SETTLEMENT

Date:

Confirm with

Repair Cost:

S\$

Final Liability

100 % (Agreed / Assessed)

BOLA S/N No.: 27

Loss of Rental:

S\$

(days)

If NO or B 28, Ass. Lia

cc

cc

(x days)

Format Type: w/p TP did not submit

ASS. REC. BY:

ASSIGNMENTKenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHF 511R Yr Regn: 06, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c. 1995Colour M White / Red A/C: Insured / Std / NI / NASp. Reading 57581 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFI AB 15 AUG 278245Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 5 mmL/Bal. 4 mm L/Bal. 5 mmD.O.A. 12/10/14 D.O.I. 13/10/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/3/15 8 51.97.29 Confirmed Damage (4 x 133.75 + 200)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

Survey Fee: _____

Transportation: _____

____ \$ + RS. ____ \$

Photos _____

Others _____

Report Format : _____

Red CP 16825.44, 76.10

TRANS-CAB AUTO SERVICES PTE LTD

NO.466-468 Tagore industrial avenue singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHF 511R - AXA**ROEL**

Date

Not Notarized

131

85197.29

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 511R - ROEL

VF1ABL15AUC278245

RENAULT

LATITUDE

12.10.2014

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	Bu	710.55 ✓
2	1	BUMPER LOWER REAR	\$	add'l	492.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	Nil	72.74 ✓
4	1	BUMPER BRACKET SIDE RH REAR	\$	Nil	87.16 X
5	1	BUMPER RETAINER RH REAR	\$	Sn	28.84 X
6	1	BUMPER REFLECTOR RH	\$	Sn	27.96 X
7	1	BUMPER BRACKET SIDE LH REAR	\$	Nil	87.16 X
8	1	BUMPER RETAINER LH REAR	\$	Sn	28.84 X
9	1	BUMPER REFLECTOR LH	\$	Sn	27.96 X
10	1	BUMPER BEAM REAR	\$	Bt	498.41 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	Bt	144.84 ✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	Bt	144.84 ✓
13	1	BOOT REAR	\$	R	1,841.46 X
14	1	BOOT FINISHER (Moulding)	\$	Sn	358.25 X
15	1	BOOT WHEATERSTRIP	\$	Sn	207.08 X
16	1	BOOT REFLECTOR LAMP RH	\$	Sn	316.25 X
17	1	BOOT REFLECTOR LAMP LH	\$	Sn	316.25 X
18	1	BOOT BADGE 'RENAULT'	\$	na	144.46 X
19	1	BOOT BADGE	\$	na	144.46 X
20	1	BOOT STRUT (SPRING)	\$	Sn	176.97 X
21	1	TAILLAMP RH	\$	Sn	354.20 X
22	1	TAILLAMP LH	\$	Sn	354.20 X
23	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,403.77 X
24	1	SPARE WHEEL PANEL TRIM	\$	Sn	392.44 X
25	1	OUTER PANEL REAR (End Panel)	\$	Bt	943.44 ✓
26	1	OUTER PANEL REAR (End Panel)TRIM	\$	CPA	259.33 ✓
27	1	EXHAUST REAR	\$	R	8,400.00 X
28	1	EXHAUST CAP REAR	\$	Sn	147.75 X

TOTAL	\$	18,112.45
10%	\$	1,811.25
	\$	16,301.21

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.466-468 Tagore industrial avenue singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHF 511R - AXA**Special Nett**

1SET	PARKING AID	\$	q/h Short 600.00 ✓
1SET	REAR BUMPER CLIP	\$	nee 66.00 ✓
1SET	BUMPER BRACKET CTR CLIP(Necessary)	\$	nee 33.00 ✓
1SET	BUMPER LOWER REAR RIVET(Necessary)	\$	nee 22.00 ✓
1SET	BUMPER LOWER REAR CLIP(Necessary)	\$	nee 66.00 ✓
1SET	BUMPER BEAM BOLT	\$	su 33.00 X
1	EXHAUST MOUNTING REAR	\$	su 17.82 X
1SET	BOOT FINISHER NUT (Necessary)	\$	su 24.20 X
1	BOOT STICKER "Trans-cab"	\$	nn 30.00 X
1	BOOT STICKER "6555-3333"	\$	nn 30.00 X
2	Rear windscreen sealant	\$	nn 80.00 X
1	Windscreen moulding	\$	nn 100.00 X
1	Rear Windscreen Inner Sponge Seal	\$	nn 100.00 X

TOTAL \$ 1,202.02**TOTAL PARTS \$ 17,503.23**

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 660/

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same R.

\$ 1,500.00 600/

To Rust-Proofing Of The Affected Areas.

\$ 170.00 300/

To reinstall rear bumper parking sensor.

\$ 170.00 600/

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ nn 170.00 X

To repair and realign rear exhaust pipe.

\$ 170.00 600/

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 170.00 600/

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.466-468 Tagore industrial avenue singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHF 511R - AXA

To transfer of rear luggage floor panel fittings,
attachment and perform water seepage test. \$ *Repair* 170.00 X

To supply and re-do rear luggage floor panel
insulation padding. \$ *NA* 380.00 X

To check steering geometry and computer
wheel alignment \$ *NA* 220.00 X

TOTAL \$ 4,520.00

Over All Total \$ 22,023.23

Repair Days**10 Days
(PARTS BY PARTS)**

Admin B

From: Tan Tiong Beng [tantiong.beng@axa.com.sg]
Sent: Wednesday, 5 November, 2014 4:02 PM
To: admin-b@lkkauto.com; assignments@lkkauto.com; sur@lkkauto.com
Cc: Tan Kwee May
Subject: Direct Settlement / Trans-Cab Auto / C0319003 / OD SKH6007U / TP SHF511R / 12.10.14 / EST \$22,023.23 / KM
Attachments: TP GIA Report.pdf; TP Estimate.pdf; Photo - SHF 511R.pdf; Preliminary Advice - SHF 511R.pdf; SKH6007U - 121014.PDF

Dear Kwee May,

Pls revise the VTP in AS400. Thank you.

From: Jacy Goh Lay Ting
Sent: Wednesday, November 05, 2014 1:27 PM
To: Tan Tiong Beng
Subject: FW: Direct Settlement - Acc Invl SKH 6007U (OI : AXA - TBA) & SHF 511R (TP : LKK - CC3/AXA14019448//kzm3) on 12/10/2014

Thank you

Jacy Goh
Executive Assistant - Claims SITF
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
jacy.goh@axa.com.sg
Customer Care: 1800 8804741(Press 3)
Website: www.axa.com.sg

 **We are all born to protect, but for me it's a calling.**
Discover our stories on www.borntoprotect.sg

redefining / insurance



This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

 Please consider the environment before printing this email

From: Kitty Teo Poh Guek
Sent: Friday, October 17, 2014 11:23 AM
To: Jacy Goh Lay Ting
Subject: FW: Direct Settlement - Acc Invl SKH 6007U (OI : AXA - TBA) & SHF 511R (TP : LKK - CC3/AXA14019448//kzm3) on 12/10/2014

fya

Kitty TEO

Executive Assistant – Motor Claims

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811

kitty.teo@axa.com.sg

Customer Care: 1800 8804741(Press 3)

Website: www.axa.com.sg



redefining / standards

This message is confidential: its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Please consider the environment before printing this email

From: Admin B [<mailto:Admin-B@lkkauto.com>]

Sent: Thursday, 16 October, 2014 5:07 PM

To: Tan Tiong Beng; Kitty Teo Poh Guek; Winnie Ho Ping Ping

Cc: 'Zayyer'; 'Sharon Yee'; 'Admin-B (LKK Auto)'; 'KKLau'

Subject: Direct Settlement - Acc Invl SKH 6007U (OI : AXA - TBA) & SHF 511R (TP : LKK - CC3/AXA14019448//kzm3) on 12/10/2014

Dear Sir/Madam

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHF 511R at M/s Trans-Cab Auto Services Pte Ltd.

Enclosed herewith a copy of TP's GIA report , estimated cost of repair, photos and preliminary advice for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Zayyer and he can be contacted at DID: 6841 2409.

Thanks & Regards,

PEI LIN

LKK Auto Consultants Pte Ltd

DID: 6366 0055

Fax: 6741 4108

[Home](#) | [About Us](#) | [Services](#)**Driving Licence
Enquiry****Outstanding
Traffic Offence****About Driving
In Singapore****Singapore Police
Force Website**[Home>Driving Licence Information](#)
[>Licence Enquiry Options>Status of Driving Licence](#)[Terms and Conditions](#) | [FAQs](#) | [Help](#)[LOGOUT](#)

Status of Driving Licence

Licence Number: S8312764C
Status of Driving Licence: Valid
Classes of Licence: 3
Expiry Date: Valid for life unless revoked, suspended or disqualified.

The above information is accurate as at 07/11/2014 12:01 AM

[Print Licence Status](#)

Please do not use the Back or Forward button on your browser or double-click a hyperlink as this may end your transactions.

Rate this e-Service.

If you encounter any problems with this-eService, please contact us at
http://www.spf.gov.sg/contactus/contactus_index.htm.
You may also give us your comments at <http://www.spf.gov.sg/feedback.htm>.

Last updated/reviewed on 03/08/2007.

[Privacy Statement](#)

@ 2007 Government of Singapore



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AXA14019448/Kzm3

11 February 2015

NG AI LENG

9 Dairy Farm Road

#06-04

Singapore 679038

Dear Sir/Madam,

ACCIDENT INVOLVING SKH 6007U & SHF 511R ON 12/10/2014

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved.

Please call us if you have further queries.

Yours faithfully,

Zayer

DID: 6841 2409

FAX: 6741 4108

Email: zayyer@lkkauto.com

Case Handler

c.c. *AXA Insurance Singapore Pte Ltd*
(Motor Claims Dept)

Zayyer

From: Tan Kwee May <kweemay.tan@axa.com.sg>
Sent: Wednesday, 28 October, 2015 11:22 AM
To: Stacey Ng Pei Sze
Cc: Zayyer
Subject: FW: Date of accident on 12/10/2014 involving vehicle SKH 6007U & SHF 511R
Attachments: email from AXA.pdf

Dear Stacey
Fyna. Tks
C0319003

Regards
Kwee May TAN
Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01 AXA Tower, Singapore 068811
kweemay.tan@axa.com.sg
Website: www.axa.com.sg
Customer Care 1800 880 4741

"This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately."

From: Zayyer [mailto:zayyer@lkkauto.com]
Sent: Tuesday, October 27, 2015 7:49 PM
To: Tan Kwee May
Cc: Admin A; Zayyer; CS A Team; Olivia Lau; Bryan Ang; KKLau
Subject: Date of accident on 12/10/2014 involving vehicle SKH 6007U & SHF 511R

Dear Kwee May,

Date of accident on 12/10/2014 involving vehicle SKH 6007U & SHF 511R

We refer to the above matter.

Be informed that our surveyor had finalised above matter with TP's repairer since 4 March 2015.

TP's repairer did not submit the LOD until now. In view of no further development, we will proceed to temporary close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly.

Best Regards,

Zayer | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: zayyer@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE SINGAPORE PTE LTD

Ref : CC3/AXA14019448/Kza3n2

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 02-11-2015



ATTN: STACEY NG

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKH 6007U	Veh. Inspected	SHF 511R
Policy No.	P1332145	Coverage (\$)	0.00
Claim No.	C0319003	Excess (\$)	0.00
Assign From		Assign Date	13/10/2014

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278245	Colour	METALLIC WHITE / RED
Odometer	57561	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GOODYEAR	4 mm
L/H Front Tyre	215/60 R16	GOODYEAR	4 mm
R/H Rear Tyre	215/60 R16	GOODYEAR	5 mm
L/H Rear Tyre	215/60 R16	GOODYEAR	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/10/2014	Inspection Date	13/10/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 511R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED	710.55	710.55
1	BUMPER LOWER REAR (CONSISTENT)	DENTED / DISTORTED	492.84	492.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	DISTORTED	72.74	72.74
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	NO SUCH PARTS	87.16	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	28.84	-
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	27.96	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	NO SUCH PARTS	87.16	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	28.84	-
1	BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	27.96	-
1	BUMPER BEAM REAR (CONSISTENT)	BENT	498.41	498.41
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	BENT	144.84	144.84
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	BENT	144.84	144.84
1	BOOT REAR (CONSISTENT)	TO REPAIR SEE LABOUR	1,841.46	-
1	BOOT FINISHER (MOULDING) (CONSISTENT)	SERVICEABLE	358.25	-
1	BOOT WHEATERSTRIP (CONSISTENT)	SERVICEABLE	207.08	-
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	SERVICEABLE	316.25	-
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	SERVICEABLE	316.25	-
1	BOOT BADGE 'RENAULT' (CONSISTENT)	NOT NECESSARY	144.46	-
1	BOOT BADGE (CONSISTENT)	NOT NECESSARY	144.46	-
1	BOOT STRUT (SPRING) (CONSISTENT)	SERVICEABLE	176.97	-
1	TAILLAMP RH (CONSISTENT)	SERVICEABLE	354.20	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	354.20	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	1,403.77	-
1	SPARE WHEEL PANEL TRIM (CONSISTENT)	SERVICEABLE	392.44	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	BENT	943.44	943.44
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	CRACKED	259.33	259.33
1	EXHAUST REAR (CONSISTENT)	TO REPAIR SEE LABOUR	8,400.00	-
1	EXHAUST CAP REAR (CONSISTENT)	SERVICEABLE	147.75	-

Report Ref No. CC3/AXA14019448/Kza3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,811.25	-326.70
			16,301.20	2,940.29
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN) (CONSISTENT)	SHORTED	600.00	600.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NECESSARY	22.00	22.00
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BEAM BOLT (SN) (CONSISTENT)	SERVICEABLE	33.00	-
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER NUT (SN) (CONSISTENT)	SERVICEABLE	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			1,202.02	787.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	660.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCUSIVE OF THE REPAIR OF BOOT REAR, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) AND EXHAUST REAR.		1,500.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.		170.00	60.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-

Report Ref No. CC3/AXA14019448/Kza3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			4,520.00	1,470.00
GRAND TOTAL			22,023.22	5,197.29
RECOMMENDED COST OF REPAIRS				5,197.29

Report Ref No. CC3/AXA14019448/Kza3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.