



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WICK ADAM
 (LONGPAC)

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

TP Longpac
 Vic

ESTIMATE

Repair Code : CLM15195

Date in : 24/04/2019

Vehicle Num. : SLP7220J

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218342/LEB5918354

Contact : 66550005 97585062

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>to m</i>	1	762.70	✓ 762.70
REAR BUMPER RH REFLECTOR <i>cul d</i>	1	141.10	✓ 141.10
REAR BUMPER SIDE RETAINER L/R <i>RH m</i>	2	23.00	23 46.00
REAR RH BUMPER SIDE <i>Del m d</i>	1	195.00	✓ 195.00
REAR RH FENDER ARCH GARNISH <i>ut</i>	1	195.00	✓ 195.00
REAR RH FENDER INNER AIR VENT <i>new</i>	1	30.30	X 30.30
REAR RH TAILLAMP <i>cracked</i>	1	474.60	✓ 474.60
Subtotal before discount			1,844.70
Percentage discount 20%			368.94
Sub-total 1			1,475.76
REAR BUMPER CLIPS - SET <i>} new</i>	1	50.00	30 50.00
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>} new</i>	1	40.00	20 40.00
REAR RH TAILAMP CLIPS - SET <i>new</i>	1	30.00	X 30.00
Subtotal before discount			120.00
Percentage discount 0%			0.00
Sub-total 2			120.00
Parts-total			1,595.76

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 97585062

ESTIMATE

Repair Code : CLM15195

Date in : 24/04/2019

Vehicle Num. : SLP7220J

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218342/LEB5918354

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

30 ~~60.00~~

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

X 120.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

680

450 ~~650.00~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

200 ~~450.00~~

To apply anti-rust chemical on repaired and replaced panel.

X 40.00

Labour Total

1,320.00

Parts & Labour Total

2,915.76

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2163.12

W/S: 1.7K

030mp

1.7K

030mp