

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0514/2019/DY/TF
Date : 18-Apr-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no. : **SKH 8926 D**

QBE Insurance (International) Ltd
60 Anson Road
#11-01, Mapletree Anson
Singapore 079914

Hi Adrian

5 days - ok - jb - 3 Jun 19

Attn: Motor Claims Dept
Fax: 6534 5356

Owner's Name : Hitachi Capital Asia Pacific Pte Ltd
Address : 111 Somerset Road, TripleOne-Somerset
: #14-05
: Singapore 238164
Telephone : 67341222
Type of Claim : Third Party Claim
Policy No. : G 300064574 MCY
Vehicle No : **SLS 8971 C**
Model Code : Audi Q5 Sport 2.0 TFSI qu
Model / Year : Oct-17
Engine No : DAX 013972
Chassis No : WAUZZZF2H2051379
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Apr-19
Place of Accident : PIE Northbound near Exit 13

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 8971 C

S/n	Nature of Jobs		Estimated Charges	
1	To remove and transfer rhs rear door's multi-lock system and power window	s/n	\$ 280.00	\$ 280.00
2	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function and renew according to damage.	s/n	\$ 280.00	\$ 280.00
3	To dismantle and renew rhs rear door and rear bumper. Inspect rhs rear fender for damages. Reinstall all parts removed. (\$700.00)		\$ 2,100.00	\$ 1,400.00
4	To respray rhs front and rear doors, door covers, rhs rear fender, rear bumper, mid bumper and wheel arch trims.		\$ 5,000.00	\$ 3,000.00
5	To renew rhs rear rim. Carry out wheel	s/n	\$ 280.00	
6	To carry out diagnostic check	s/n	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 8,132.00</u>	<u>\$ 5,152.00</u>

Painting charges for QBE

1. Rhs frt door \$700

2. Rhs rear door (New) \$800

3. Rear bumper - \$700

4. Door cover \$400.00

5. Wheel arc - \$400 TOTAL \$3000.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 8971 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR DOOR - RH	\$ 2,829.00	\$ 2,829.00
2	REAR DOOR SEAL BRACKET - RH	\$ 39.00	
3	GROMMET	\$ 8.00	
4	BONDING AGENT	\$ 45.00	
5	SEALING STRIP	\$ 15.00	
6	REAR DOOR CATCH - RH	\$ 132.00	\$ 132.00
7	SILL PANEL TRIM - RH	\$ 234.00	\$ 234.00
8	REAR DOOR SEAL	2 \$ 391.00	\$ 391.00
9	REAR DOOR REGULATOR WITH MOTOR - RH	\$ 277.00	\$ 276.50
10	REAR DOOR LOWER COVER	\$ 577.00	\$ 576.50
11	REAR WHEEL ARCH TRIM - LH / RH	\$ 974.00	\$ 974.00
12	REAR BUMPER	\$ 1,571.00	
13	REAR BUMPER GUIDE SECTION - RH	\$ 75.00	
14	REAR TYRE RIM - RH	\$ 923.00	
15	RUBBER VALVE	\$ 13.00	
16	SUNDRIES	\$ 400.00	\$ 11.10
TOTAL PARTS CHARGES		: \$ 8,503.00	\$ 5,424.10
TOTAL LABOUR CHARGES		: \$ 8,132.00	\$ 5,152.00
GRAND TOTAL		: \$ 16,635.00	\$ 10,576.10