

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0514/2019/DY/TF
Date : 18-Apr-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no. : SKH 8926 D

QBE Insurance (International) Ltd

60 Anson Road

#11-01, Mapletree Anson

Singapore 079914

Attn: Motor Claims Dept

Fax: 6534 5356

Owner's Name : Hitachi Capital Asia Pacific Pte Ltd
Address : 111 Somerset Road, TripleOne-
Somerset
: #14-05
: Singapore 238164
Telephone : 67341222
Type of Claim : Third Party Claim
Policy No. : G 300064574 MCY
Vehicle No : **SLS 8971 C**
Model Code : Audi Q5 Sport 2.0 TFSI qu
Model / Year : Oct-17
Engine No : DAX 013972
Chassis No : WAUZZZF2H2051379
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Apr-19
Place of Accident : PIE Northbound near Exit 13

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 8971 C

S/n	Nature of Jobs		Estimated Charges	
1	To remove and transfer rhs rear door's multi-lock system and power window devices.	s/n	\$ 280.00	✓
2	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function and renew according to damage.	s/n	\$ 280.00	✓
3	To dismantle and renew rhs rear door and rear bumper. Inspect rhs rear fender for damages. Reinstall all parts removed.		\$ 2,100.00	1200
4	To respray rhs front and rear doors, door covers, rhs rear fender, rear bumper, mid bumper and wheel arch trims.		\$ 5,000.00	2600 $3 \times 600 = 1800$ Arch trim x 2 = $200 \times 2 = 400$ Door Cover x 2 = $200 \times 2 = 400$ <u>2600</u>
5	To renew rhs rear rim. Carry out wheel alignment.	s/n	\$ 280.00	✓
6	To carry out diagnostic check	s/n	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 8,132.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 8971 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR DOOR - RH <i>Dented</i>	\$ 2,829.00	✓
2	REAR DOOR SEAL BRACKET - RH ?	\$ 39.00	?
3	GROMMET ?	\$ 8.00	?
4	BONDING AGENT ?	\$ 45.00	?
5	SEALING STRIP ?	\$ 15.00	?
6	REAR DOOR CATCH - RH <i>new</i>	\$ 132.00	+
7	SILL PANEL TRIM - RH <i>cut</i>	\$ 234.00	✓
8	REAR DOOR SEAL <i>new</i>	2 \$ 391.00	✓
9	REAR DOOR REGULATOR WITH MOTOR - RH <i>new</i>	\$ 277.00	+
10	REAR DOOR LOWER COVER <i>cut</i>	\$ 577.00	✓
11	REAR WHEEL ARCH TRIM - LH / RH <i>new</i>	\$ 974.00	✓
12	REAR BUMPER <i>Regis</i>	\$ 1,571.00	+
13	REAR BUMPER GUIDE SECTION - RH <i>new</i>	\$ 75.00	+
14	REAR TYRE RIM - RH <i>new</i>	\$ 923.00	+
15	RUBBER VALVE <i>new</i>	\$ 13.00	+
16	SUNDRIES ?	\$ 400.00	?
TOTAL PARTS CHARGES :		\$ 8,503.00	
TOTAL LABOUR CHARGES :		\$ 8,132.00	
GRAND TOTAL :		\$ 16,635.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 25/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : see authorised, 05 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant