



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 02/05/2019

Attn: The Motor Claims Department

Your Insured veh no : SHD 9797 J

AXA Insurance S'pore Pte Ltd

8 Shenton way
27-01 AXA Tower
Singapore 068811

Joy

WITHOUT PREJUDICE

(By Email Only)

03/05/19
10am

Adrian 96893735

ZVW 301212259

Dear Sir / Madam

Estimate Cost Repair Bill To Toyota Hybrid 1.8 NO SJY 3921 Y & SHD 9797 J on 24/04/2019 @19:30

To Supply:-

1pc	Front bumper	Red	\$ 921.10	✓
1pc	Front bumper side retainer	in	\$ 80.00	✓
1pc	Front bumper ford lamp RH	red in	\$ 411.10	✓
1pc	Front bumper ford lamp cover RH	Red	\$ 198.10	✓
1pc	Front head lamp RH	cut	\$ 1,011.10	✓
1pc	Front fender RH	Brushed	\$ 738.10	✓
1pc	Front fender inner cowling	meaker	\$ 180.10	+
			\$ 3,539.60	
			less 25%	\$ 884.90
				\$ 2,654.70

2948.40
221.30

To dismantl & replace damage parts, panel beat where necessary.

\$ ~~550.00~~ 400

To putty, apply primer & spray paint on the affecte portion.

1030 \$ 700.00 600

To check wiring functions.

\$ 80.00 30
\$ 3,984.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj total: 3241.30
H/S 03/05/19 H/S: 2-61C
OHDays ✓