

15/5/2010

INS. CASE OWNER:

minnie

CC 4 ksm
/AXA1900 7796 Tigher

LKK:

IDAC:

Surveyor:

Taufich

DOI:

ASSIGNMENT

010519

Date / Time:

16/4/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMF 2248C

Name of Insured:

YONG SHAW LOON

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

16/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SAMOZLG7/112825

Policy No.:

UPA/P2231568

Make / Model:

VEXUS

Place of Accident:

CTE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLA 6711C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

4LA 6711C - X

SMF 2248C - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

3-5-19 JGY

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

3-5-19

w/ OI - CLEARED.

13-6-19

PENDING FINALIZATION

2618

Rec WOK to TP (pending WOK)
 TO seek mandati.
 Pending mandate approval.
 offer \$17,595.28 (pending acceptance).

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time: 16/4/19 10:25AM

Confirm with: Jack

Confirm by: Taufich

Repair Cost:

SS 15,144.19

9 days

Reduction: \$294.88

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 16,204.28

Loss of Rental (LOR):

SS 1498.00

14 days

X \$107 w/ (14/17)

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 17,702.28

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 17702.28

Name 1:

Kah Motor Co. Sdn. Bhd.

GIA.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
w/ m/ a

[illegible]

Taufel

REF:

AXA

ASSIGNMENT

From _____ Date: _____
Estimated Cost: _____
OD (TP) WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop n/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 874K
IDAG Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est Repairs: 9 days Res: Yes or No
Lump Sum: 141 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Jack

Veh No: SLA 673/L Yt Regu: 2016 March
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
Make: Honda HKV C.C. 1497
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 115742 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: MR HKU 1830 FP 000750

Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R17
R: n/a

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 2/5/19 1030

Survey field at Ksh Motor Workshop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

920K repair unit - inform Jack

76747

P/P \$15,144.19/- Cred- \$9294.88 / 38%

* 9 repair days + 2 sat + 2 sunday + 1 PRS = 13 days

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

3 + PRS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLA6731L

Chassis No : MRHRU1830FP000750

Model : HRV LX-SIN CVT YM 2015

Owner's Name : YAHYA BIN MOHAMED

Ins Policy No. :

Date of Accident : 25/4/2019

Document No. : SQT19001906

Page 1

Date : 2. May 2019

Customer No. : WZA006

Svc Advisor : JACK NG

Engine No : L15Z71001402

Date | Time : 2. May 2019 8:49:53 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:YAHYA BIN MOHAMED OWNER INSURER: ACC DATE:25/04/2019 SURVEYED BY: DATE: REF NO: TP INSURER:NTUC INCOME TP VEH:SMK 2248 C						
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	156.30 ?		156.30	10.94	167.24
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	156.30 ?		156.30	10.94	167.24
71501-T8N-T50	FACERR.BUMPER	344.79 1	463.70 de		463.70	32.46	496.16
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER RH	62.62 1	83.50 de de		83.50	5.85	89.35
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER LH	62.62 1	83.50 de		83.50	5.85	89.35
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	12.90 1	17.20 ne		17.20	1.20	18.40
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	12.90 1	17.20 ne		17.20	1.20	18.40
91505-TM8-003	CLIP,BUMPER	13.80 8	2.30 ne		18.40	1.29	19.69
68100-T8P-U10ZZ	TAILGATE COMP	641.79 1	855.70 bt		855.70	59.90	915.60
74440-T7A-003	WEATHERSTRIPTAILGATE - photo	74.02 1	98.70 de		98.70	6.91	105.61
74800-T7A-J01	LOCK ASSYTAILGATE - photo	59.17 1	78.90 pr		78.90	5.52	84.42
74813-T5A-003	STRIKER ASSYTAILGATE	18.52 1	24.70 bt		24.70	1.73	26.43
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER	1	105.30 ?		105.30	7.37	112.67
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE	142.35 1	189.80 one		189.80	13.29	203.09
75701-T5A-000	EMBLEM H	8.02 1	10.70 ne		10.70	0.75	11.45
66100-T8N-T00ZZ	PANEL COMPRR. photo	308.92 1	411.90 ? bt		411.90	28.83	440.73
04655-T7Y-T00ZZ	PANEL SETRR.FLOOR photo	1	506.10 ?		506.10	35.43	541.53
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00 nw		320.00	22.40	342.40
74940-SZW-003	BUZZER ASSYSMART	45.09 1	61.30 ?		61.30	4.29	65.59

Printed on 2/5/2019 9:38:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLA6731L
Chassis No : MRHRU1830FP000750
Model : HRV LX-SIN CVT YM 2015
Owner's Name : YAHYA BIN MOHAMED
Ins Policy No :
Date of Accident : 25/4/2019

Document No. : SQT19001906
Date : 2. May 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : L15Z71001402
Date | Time : 2. May 2019 8:49:53 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	14.47	19.30	✓	19.30	1.35	20.65
73226-SZW-000	DAMPERSTD 5X5	6.37	8.50	✓	8.50	0.60	9.10
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	14.47	19.30	✓	19.30	1.35	20.65
76711-T6A-003	CAPPIVOT	3.60	4.80	✓	4.80	0.34	5.14
91501-S70-003	FASTENER BW/SHIELD	15.90	5.30	✓	21.20	1.48	22.68
91502-S70-003	FASTENER B	7.95	5.30	✓	10.60	0.74	11.34
91536-SS0-J01	FASTENER AW/SHIELD	5.70	3.80	✓	7.60	0.53	8.13
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00	✓	120.00	8.40	128.40
Sum Item					3870.50	270.94	4,141.44
BOSUN	SUNDRIES	1	100.00	50.00	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	150.00	120.00	150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	150.00	120.00	150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	150.00	120.00	150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00	280.00	380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00	✓	380.00	26.60	406.60
BC01R	REMOVE & INSTALL VIEW CAMERAS (N)	1	450.00	✓	450.00	31.50	481.50
BC03R	RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	450.00	✓	450.00	31.50	481.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN(N)	1	560.00	✓	560.00	39.20	599.20
BG01D	WINDSCREEN DAM KIT	1	150.00	100.00	150.00	10.50	160.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	560.00	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	560.00	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS	1	6000.00	2800 R & R panel. 5040 R & R panel. 6000.00	6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4500.00	1800 R & R 2700	4500.00	315.00	4815.00
Sum Labor					15020.00	1,051.40	16,071.40

Survey By

Printed on 2/5/2019 9:38:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

424439-07



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLA6731L
Chassis No : MRHRU1830FP000750
Model : HRV LX-SIN CVT YM 2015
Owner's Name : YAHYA BIN MOHAMED
Ins Policy No. :
Date of Accident : 25/4/2019

Document No. : SQT19001906
Date : 2. May 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : L15Z71001402
Date | Time : 2. May 2019 8:49:53 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	2/5/19 @ 1030						
Excess							
Status	WIP						
Signature							
Total Amount					18,890.50	1,322.34	20,212.84
Total (Inclusive of GST)							20,212.84

Tanpin LKK. 7-8 days with floor panel. 12 days with floor panel.

20664.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/5/2019 9:38:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Supplementary

Customer: ****7676G / YAHYA BIN
Chassis No: MRHRU1830FP000750
License No: SLA6731L
Mileage: 113549
Engine No: L15Z71001402

Document No: SVO19027810
Printed By: JACKNG
Order Date: 3. May 2019
Order Time: 11:30:19 AM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
39680-TV0-E01C5	SENSOR ASSYPARKING	1	82.10	25	61.57	4.31	65.88
39681-T7A-H01ZB	RETAINER PARKING SENSOR	2	62.10	25	93.15	6.52	99.67
33502-T7A-J01	LAMP UNITR.	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL.LID	1	269.90	25	202.42	14.17	216.59
33552-T7A-J01	LAMP UNITL.	1	441.50	25	331.12	23.18	354.30
84640-T8N-T01ZA	LINING ASSYRR.PANEL	1	66.60	25	49.95	3.50	53.45
84610-T8N-T01ZA	BASE COMPR.TRUNK SIDE LINING	1	131.20	25	98.40	6.89	105.29
84660-T8N-T01ZA	BASE COMPL.TRUNK SIDE LINING	1	131.20	25	98.40	6.89	105.29
84521-T8N-T01ZA	BOARD ASSYTRUNK FLOOR	1	92.90	25	69.67	4.88	74.55
84550-T7W-A00	BOX COMPTTRUNK FLOOR	1	118.00	25	88.50	6.20	94.70
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER	1	89.30	25	66.97	4.69	71.66
84441-S2K-000ZB	POCKETTAILGATE PULL	1	15.20	25	11.40	0.80	12.20
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
90676-SA7-003	GROMMET.SCREW.5	2	2.30	25	3.45	0.24	3.69
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
SUM PARTS:					1,774.38	124.23	1,898.61
TOTAL SGD					1,774.38	124.23	1,898.61

Total Payable (SGD)

1,898.61

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE PTE
Chassis No: MRHRU1830FP000750
License No: SLA6731L
Mileage: 113549
Engine No: L15Z71001402

Document No: SVO19027810
Printed By: JACKNG
Order Date: 3. May 2019
Order Time: 11:30:19 AM
Service Advisor: JACK NG

BOSUN	0760	1	50.00	50.00	3.50	53.50
	SUNDRIES <i>new</i>					
BOJSE	0760	1	120.00	120.00	8.40	128.40
	BODY JOINT SEALANT FOR TAILGATE					
BOJSE	0760	1	120.00	120.00	8.40	128.40
	BODY JOINT SEALANT FOR END PANEL					
BML02I	1864	1	280.00	280.00	19.60	299.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)					
BA02R	1864	1	380.00	380.00	26.60	406.60
	REMOVE & RENEW REVERSE SENSORS-4 PGS (N)					
BC01R	0760	1	450.00	450.00	31.50	481.50
	REMOVE & INSTALL VIEW CAMERAS (N) PARKING ASSIST SYSTEM					
BC03R	0760	1	450.00	450.00	31.50	481.50
	RESET & CALLIBRATE SMART ENTRY SYSTEM(N) AND RESET SYSTEM.					
BG02D	1864	1	560.00	560.00	39.20	599.20
	REMOVE & INSTALL RR. WINDSCREEN. (N)					
BG01D		1	100.00	100.00	7.00	107.00
	WINDSCREEN DAM KIT <i>new</i>					
BKTG02R	1864	1	560.00	560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)					
BMI03D	1864	1	560.00	560.00	39.20	599.20
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)					
BKRP02M	1864	1	5,040.00	5,040.00	352.80	5,392.80
	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM					
BP06R	1865	1	2,700.00	2,700.00	189.00	2,889.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)					

SUM LABOUR: 11,370.00 795.90 12,165.90**TOTAL SGD 15,144.19 1,060.09 16,204.28****Total Payable (SGD) 16,204.28**

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer:	WZA006 / AXA INSURANCE PTE	Document No:	SVO19027810
Chassis No:	MRHRU1830FP000750	Printed By:	JACKNG
License No:	SLA6731L	Order Date:	3. May 2019
Mileage:	113549	Order Time:	11:30:19 AM
Engine No:	L15Z71001402	Service Advisor:	JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:YAHYA BIN MOHAMED						
	OWNER INSURER:						
	ACC DATE:25/04/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:NTUC INCOME						
	TP VEH:SMK 2248 C						
71501-T8N-T50	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER	1	83.50	25	62.62	4.38	67.00
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER	1	83.50	25	62.62	4.38	67.00
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
68100-T8P-U10ZZ	TAILGATE COMP	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14	63.31
74813-T5A-003	STRIKER ASSYTAILGATE	1	24.70	25	18.52	1.30	19.82
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE	1	189.80	25	142.35	9.96	152.31
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
66100-T8N-T00ZZ	PANEL COMPRR.	1	411.90	25	308.92	21.62	330.54
74940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97	3.22	49.19
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
39680-TV0-E01C5	SENSOR ASSYPARKING	1	82.10 <i>new</i>	25	61.57	4.31	65.88
39681-T7A-H01ZB	RETAINER PARKING SENSOR	2	62.10 <i>new</i>	25	93.15	6.52	99.67
33502-T7A-J01	LAMP UNITR.	1	441.50 <i>cur</i>	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90 <i>cur</i>	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL.LID	1	269.90 <i>cur</i>	25	202.42	14.17	216.59
33552-T7A-J01	LAMP UNITL.	1	441.50 <i>cur</i>	25	331.12	23.18	354.30
84640-T8N-T01ZA	LINING ASSYRR.PANEL	1	66.60 <i>de</i>	25	49.95	3.50	53.45
84610-T8N-T01ZA	BASE COMPR.TRUNK SIDE LINING	1	131.20 <i>de</i>	25	98.40	6.89	105.29
84660-T8N-T01ZA	BASE COMPL.TRUNK SIDE LINING	1	131.20 <i>de</i>	25	98.40	6.89	105.29
84521-T8N-T01ZA	BOARD ASSYTRUNK FLOOR	1	92.90 <i>de</i>	25	69.67	4.88	74.55
84550-T7W-A00	BOX COMPRTRUNK FLOOR	1	118.00 <i>de</i>	25	88.50	6.20	94.70
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER	1	89.30 <i>de</i>	25	66.97	4.69	71.66
84441-S2K-000ZB	POCKETTAILGATE PULL	1	15.20 <i>de</i>	25	11.40	0.80	12.20
75722-T7W-A01	EMBLEMRR.	1	13.30 <i>cur</i>	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50 <i>cur</i>	25	10.87	0.76	11.63
90676-SA7-003	GROMMET.SCREW.5	2	2.30 <i>cur</i>	25	3.45	0.24	3.69
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00 <i>bt</i>		45.00	3.15	48.15
SUM PARTS:					3,774.19	264.19	4,038.38

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 7676G

Vehicle Details

Vehicle No.: SLA6731L
Vehicle to be Exported: No
Intended Deregistration Date: 03 May 2019
Vehicle Make: HONDA
Vehicle Model: HRV 1.5 LX CVT ABS
D/AIRBAG 2WD
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: L15Z71001402
Chassis No.: MRHRU1830FP000750
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$23,133.00
Original Registration Date: 11 Mar 2016
First Registration Date: 11 Mar 2016
Transfer Count: 0
Actual ARF Paid: \$24,387.00

Intended PARF Rebate Details
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 Mar 2026
PARF Rebate Amount: \$18,290.00

Intended COE Rebate Details
COE Expiry Date: 10 Mar 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$51,301.00
COE Rebate Amount: \$35,152.00
Total Rebate Amount: \$53,442.00

The information contained herein is correct as at 03 May 2019

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

**CHEAPEST CAR
INSURANCE RENEWAL**
Compare
10+ Insurers

GET A

Honda HR-V

Price Range

Depreciation

2016

Vehicle Type

Home » Used Cars » SG Car Consign Pte Ltd » Honda HR-V 1.5A LX

Honda HR-V 1.5A LX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price

\$73,900

Depreciation ?

\$9,180 /yr

View models with similar depre

Reg Date

18-Jan-2016

(6yrs 8mths 14days COE left)

Mileage

50,000 km (15.2k /yr)

Manufactured ?

2015

Road Tax ?

\$684 /yr

Transmission

Auto

Dereg Value ?

\$58,143 as of today (change)

OMV ?

\$23,228

COE ?

\$59,200

ARF ?

\$24,520

Engine Cap

1,497 cc

Power

88.0 kW (118 bhp)

Curb Weight ?

1,221 kg

No. of Owners ?

1

Type of Vehicle

SUV



Price Cha

74K

72K

70K

68K

Nov

Click on the poi

Features

White Color. View specs of the Honda HR-V (2015)

Accessories

As Per Factory Fittings.

Description

Look No Further, Low Mileage That Is Serviced By Agent. Direct Owner's White, Jan 2016 HRV 1.5 LX CVT ABS D/AIRBAG 2WD With Brown Leather Upholstery Owned By 1 Private Owner Selling Due To Upgrading To New Car. Original Paintwork Condition, Genuine Mileage And Well Kept. Trade In And Loan Are Available. Don't Miss, Must Call To Arrange Before Viewing This Unit Today.

Category

PARF Car

Compare

LKK AUTO CONSULTANTS PTE LTD (TP)

KOH mto ✓

« Service Request Details

Claim

S9M01LG7

Reference

None 

Loss Date

25 April 2019

Report Date

25 Apr 2019 3:55:06 PM

Request Date

26 April 2019

Due Date

26 April 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More 

Vehicle Information

Incident Vehicle Registration #

SLA6731L

Make

TPVD HONDA

Model

HR-V-1.5 (A)

Primary Contact/Insured

YONG SHIAO VOON

115 WOODGROVE AVENUE, 737830, Singapore

SHIAO.VOON.YONG@GMAIL.COM

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[View Message](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 03/12/2019

Survey Details:

Date of loss	25-Apr-19
Date of appointment	26-Apr-19
Date of survey	2-May-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLA 6731L
Make and Model	HONDA HRV 1.5 LX CVT ABS
Date of registration	11/3/2016
Excess	
Market Value	\$74,000
Parf Rebate	\$26,363
Nett Loss	\$47,637

Repair details:

Initial Estimate	\$ 18,890.50
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,774.19
Check items (estimate)	\$ -
Labour	\$ 11,370.00
Total	\$ 15,144.19
Lump Sum(if applicable)	\$ -

Number of days for repair	9
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

09 RECOMMENDED REPAIR DAYS + 2 SATURDAYS + 2 SUNDAYS +
1PRS = 14 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 16,204.28	W/GST
Loss of use	\$ -	
Loss of rental (W/GST)	\$ 1,498.00	14days x \$107
Loss of income	\$ -	
LTA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 17,702.28	



<MANDATE IA> - S9M01LG7 {ACCIDENT INVOLVING SMK 2248C & SLA 6731L ON 25/04/2019}

Type

🔔 Question

Message

LIABILITY: 100% BOLA 527 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$17,702.28 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply



<MANDATE IA> - S9M01LG7 {ACCIDENT INVOLVING SMK 2248C & SLA 6731L ON 25/04/2019}

Type

🔗 Question

Message

HI CECILIA, PLS PROCEED. FOR LOR, PLS PROPOSE @ 13 DAYS AS PRS NOT APPLICABLE. TKS

Reply



RE: <MANDATE IA> - S9M01LG7 {ACCIDENT INVOLVING SMK 2248C & SLA 6731L ON 25/04/2019}

Type

🔗 Question

Message

Dear Winnie, TP reject offer, propose 1 more day for LOR. Kindly let us have your approval/instruction. Thanks - CCL

Reply



<MANDATE IA> - S9M01LG7 {ACCIDENT INVOLVING SMK 2248C & SLA 6731L ON 25/04/2019}

Type

🔗 Question

Message

Hi Cecilia, pls proceed. tks

Reply



Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. : SINV-BM19001870
 Invoice Date : 01/11/19
 Order No. : SVO19027810
 Reference :
 Job Card No. : 10556
 Date/Time Received : 02/05/19 / 8:40:53 AM
 Licence No. : SLA6731L
 Model : HRV LX-SIN CVT YM 2015
 Car Chassis No. : MRHRU1830FP000750
 Car Engine No. : L15Z71001402
 Mileage : 113549
 Service Advisor : JACK NG 1838A
 Served By : JACKNG
 Page : 1

AXA INSURANCE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734

Payment Term : 30 Days

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:YAHYA BIN MOHAMED							
	OWNER INSURER:							
	ACC DATE:25/04/2019							
	SURVEYED BY:							
	DATE:							
	REF NO:							
	TP INSURER:NTUC INCOME							
	TP VEH:SMK 2248 C							
71501-T8N-T50	FACERR.BUMPER	1	Each	463.70	25	347.77	24.34	372.11
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER	1	Each	83.50	25	62.62	4.38	67.00
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER	1	Each	83.50	25	62.62	4.38	67.00
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	Each	17.20	25	12.90	0.90	13.80
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	Each	17.20	25	12.90	0.90	13.80
91505-TM8-003	CLIP,BUMPER	8	Each	2.30	25	13.80	0.97	14.77
68100-T8P-U10ZZ	TAILGATE COMP	1	Each	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE	1	Each	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE	1	Each	78.90	25	59.17	4.14	63.31
74813-T5A-003	STRIKER ASSYTAILGATE	1	Each	24.70	25	18.52	1.30	19.82
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE	1	Each	189.80	25	142.35	9.96	152.31
75701-T5A-000	EMBLEMH	1	Each	10.70	25	8.02	0.56	8.58
66100-T8N-T00ZZ	PANEL COMPRR.	1	Each	411.90	25	308.92	21.62	330.54
74940-SZW-003	BUZZER ASSYSMART	1	Each	61.30	25	45.97	3.22	49.19
BOSUN	0760 SUNDRIES	1	Hours	50.00		50.00	3.50	53.50
BOJSE	0760 BODY JOINT SEALANT FOR TAILGATE	1	Hours	120.00		120.00	8.40	128.40
BOJSE	0760 BODY JOINT SEALANT FOR END PANEL	1	Hours	120.00		120.00	8.40	128.40
BML02I	1864 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	280.00		280.00	19.60	299.60
BA02R	1864 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	380.00		380.00	26.60	406.60
BC01R	0760 REMOVE & INSTALL VIEW CAMERAS (N) PARKING ASSIST SYSTEM	1	Hours	450.00		450.00	31.50	481.50
BC03R	0760 RESET & CALIBRATE SMART ENTRY SYSTEM(N) AND RESET SYSTEM.	1	Hours	450.00		450.00	31.50	481.50
BG02D	1864 REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	560.00		560.00	39.20	599.20
BG01D	1864 WINDSCREEN DAM KIT	1	Hours	100.00		100.00	7.00	107.00
BKTG02R	1864 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	Hours	560.00		560.00	39.20	599.20

Printed by JACKNG on 01 Nov 2019 at 8:29:26 AM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions. Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms. Interest will be charged at 2% per month on overdue amounts.

Please give us your feedback by scanning the QR Code using mobile device.



**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734**Payment Term :** 30 Days**Service Tax Invoice**

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No.	:	SINV-BM19001870
Invoice Date	:	01/11/19
Order No.	:	SVO19027810
Reference	:	
Job Card No.	:	10556
Date/Time Received	:	02/05/19 / 8:49:53 AM
Licence No.	:	SLA6731L
Model	:	HRV LX-SIN CVT YM 2015
Car Chassis No.	:	MRHRU1830FP000750
Car Engine No.	:	L15Z71001402
Mileage	:	113549
Service Advisor	:	JACK NG 1838A
Served By	:	JACKNG
Page	:	2

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Amount incld GST
	ALIGN TAILGATE.(N)							
BMI03D	1864 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	Hours	560.00		560.00	39.20	599.20
BKRP02M	1864 CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	Hours	5,040.00		5,040.00	352.80	5,392.80
BP06R	1865 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	Hours	2,700.00		2,700.00	189.00	2,889.00
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	Each	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	Each	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	Each	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	Each	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40
39680-TV0-E01C5	SENSOR ASSYPARKING	1	Each	82.10	25	61.57	4.31	65.88
39681-T7A-H01ZB	RETAINER PARKING SENSOR	2	Each	62.10	25	93.15	6.52	99.67
33502-T7A-J01	LAMP UNITR.	1	Each	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID	1	Each	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL.LID	1	Each	269.90	25	202.42	14.17	216.59
33552-T7A-J01	LAMP UNITL.	1	Each	441.50	25	331.12	23.18	354.30
84640-T8N-T01ZA	LINING ASSYRR.PANEL	1	Each	66.60	25	49.95	3.50	53.45
84610-T8N-T01ZA	BASE COMPR.TRUNK SIDE LINING	1	Each	131.20	25	98.40	6.89	105.29
84660-T8N-T01ZA	BASE COMPL.TRUNK SIDE LINING	1	Each	131.20	25	98.40	6.89	105.29
84521-T8N-T01ZA	BOARD ASSYTRUNK FLOOR	1	Each	92.90	25	69.67	4.88	74.55
84550-T7W-A00	BOX COMPTTRUNK FLOOR	1	Each	118.00	25	88.50	6.20	94.70
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER	1	Each	89.30	25	66.97	4.69	71.66
84441-S2K-000ZB	POCKETTAILGATE PULL	1	Each	15.20	25	11.40	0.80	12.20
75722-T7W-A01	EMBLEMRR.	1	Each	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	Each	14.50	25	10.87	0.76	11.63
90676-SA7-003	GROMMET.SCREW.5	2	Each	2.30	25	3.45	0.24	3.69
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	Each	45.00		45.00	3.15	48.15

Sum Labor	11,370.00	795.90	12,165.90
Sum Item	3,774.19	264.19	4,038.38
Total SGD	15,144.19	1,060.09	16,204.28

Printed by: JACKNG on 01 Nov 2019 at 8:29:26 AM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your
feedback by scanning
the QR Code using
mobile device.



**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734

Payment Term : 30 Days

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No.	:	SINV-BM19001870
Invoice Date	:	01/11/19
Order No.	:	SVO19027810
Reference	:	
Job Card No.	:	10556
Date/Time Received	:	02/05/19 / 0:49:53 AM
Licence No.	:	SLA6731L
Model	:	HRV LX-SIN CVT YM 2015
Car Chassis No.	:	MRHRU1830FP000750
Car Engine No.	:	L15Z71001402
Mileage	:	113549
Service Advisor	:	JACK NG 1838A
Served By	:	JACKNG
Page	:	3

Total Payable (SGD)

16,204.28

Printed by JACKNG on 01 Nov 2019 at 8:29:26 AM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your
feedback by scanning
the QR Code using
mobile device.





Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
Body Repair & Paint Centre
6A Mandai Estate
Singapore 729903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd

Date : 13/11/2019

8 Shenton Way
#27-01
Singapore 068811

Attn: Motor Claims Department

Your ref : SMK 2248 C

Our ref : SLA 6731 L

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLA 6731 L AND SMK 2248 C ON 25/04/2019

We refer to the item(s) marked (✓) below:

- (✓) We refer to your email dated 28/04/2019.
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- () Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to : **desmondtoh@honda.com.sg**
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following :-
 - Repair Cost **S\$16,204.28 payable to Kah Motor Co. Sdn. Bhd.**
 - Loss of Rental **S\$107.00 x 14 Working days = \$1,498.00 payable to Yahya Bin Mohamed**
- (✓) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (✓) Letter of Authority, Discharge voucher

Thank you.

Yours faithfully,

Jack ng



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19007396/T1gb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: WINNIE HO		Date : 19-12-2019 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 2248C	Veh. Inspected	SLA 6731L	
Policy No.	VPA/P2253568	Coverage (\$)	0.00	
Claim No.	S9M01LG7	Excess (\$)	0.00	
Assign From	WINNIE HO	Assign Date	26/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHRU1830FP000750	Colour	SILVER	
Odometer	115742	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2019	Inspection Date	02/05/2019	
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 6731L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REFLECTOR ASSYR.RR. (SN) (CONSISTENT)	NOT NECESSARY	156.30	-
1	REFLECTOR ASSYL.RR. (SN) (CONSISTENT)	NOT NECESSARY	156.30	-
1	FACERR.BUMPER (SN) (CONSISTENT)	DEFORMED	463.70	347.77
1	FACER.RR.BUMPER CORNER RH (SN) (CONSISTENT)	DEFORMED	83.50	62.62
1	FACEL.RR.BUMPER CORNER LH (SN) (CONSISTENT)	DEFORMED	83.50	62.62
1	SPACER,R.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	17.20	12.90
1	SPACER,L.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	17.20	12.90
8	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	18.40	13.80
1	TAILGATE COMP (SN) (CONSISTENT)	BENT	855.70	641.77
1	WEATHERSTRIP TAILGATE (SN) (CONSISTENT)	DEFORMED	98.70	74.02
1	LOCK ASSY TAILGATE (SN) (CONSISTENT)	JAMMED	78.90	59.17
1	STRIKER ASSY TAILGATE (SN) (CONSISTENT)	BENT	24.70	18.52
1	SWITCH ASSY TAILGATE OPENER (SN) (CONSISTENT)	NOT NECESSARY	105.30	-
1	GARNISH ASSY RR.LICENSE (SN) (CONSISTENT)	CRACKED	189.80	142.35
1	EMBLEMH (SN) (CONSISTENT)	NECESSARY	10.70	8.02
1	PANEL COMPRR. (SN) (CONSISTENT)	BENT	411.90	308.92
1	PANEL SETRR.FLOOR (SN) (CONSISTENT)	NOT NECESSARY	506.10	-
4	ACT RR.SENSOR (SN) (CONSISTENT)	NOT NECESSARY	320.00	-
1	BUZZER ASSY SMART (SN) (CONSISTENT)	CRACKED	61.30	45.97
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	50.00
1	WINDSCREEN DAM KIT (SN) (CONSISTENT)	NECESSARY	150.00	100.00
1	SENSOR ASSY PARKING (SN) (CONSISTENT) (ADDITIONAL)	NOT WORKING	61.57	61.57
2	RETAINER PARKING SENSOR (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	93.15	93.15
1	LAMP UNITR. (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	331.12	331.12
1	LIGHT ASSY,R.LID (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	202.42	202.42
1	LIGHT ASSYL.LID (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	202.42	202.42
1	LAMP UNITL. (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	331.12	331.12
1	LINING ASSYRR.PANEL (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	49.95	49.95

Report Ref No. CC4/ASM19007396/T1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BASE COMPR.TRUNK SIDE LINING (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	98.40	98.40
1	BASE COMPL.TRUNK SIDE LINING (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	98.40	98.40
1	BOARD ASSYTRUNK FLOOR (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	69.67	69.67
1	BOX COMPARTRUNK FLOOR (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	88.50	88.50
1	LINING ASSYTAILGATE LOWER (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	66.97	66.97
1	POCKETTAILGATE PULL (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	11.40	11.40
1	EMBLEMRR. (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	9.97	9.97
1	EMBLEM,RR. I-VTEC (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	10.87	10.87
2	GROMMET.SCREW.5 (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	3.45	3.45
1	NUMBER PLATE WITH CASING-L (SN) (CONSISTENT) (ADDITIONAL)	BENT	45.00	45.00
1	RUBBER C. WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	19.30	14.47
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	8.50	6.37
1	RUBBER CL.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	19.30	14.47
1	CAPPVOT (SN) (CONSISTENT)	NECESSARY	4.80	3.60
4	FASTENER BW/SHIELD (SN) (CONSISTENT)	NECESSARY	21.20	15.90
2	FASTNER B (SN) (CONSISTENT)	NECESSARY	10.60	7.95
2	FASTENER AW/SHIELD (SN) (CONSISTENT)	NECESSARY	7.60	5.70
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	120.00
			5,894.88	3,924.19
	LABOUR			
	BODY JOINT SEALANT FOR TAILGATE.		150.00	120.00
	BODY JOINT SEALANT FOR END PANEL.		150.00	120.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		380.00	280.00
	REMOVE & RENEW REVERSE SENSORS.		380.00	380.00
	REMOVE & INSTALL VIEW CAMERAS.		450.00	450.00
	RESET & CALLIBRATE SMART ENTRY SYSTEM.		450.00	450.00
	REMOVE & INSTALL RR. WINDSCREEN.		560.00	560.00

Report Ref No. CC4/ASM19007396/T1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST.		800.00	560.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		800.00	560.00
	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.		6,000.00	5,040.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		4,500.00	2,700.00
1	BODY SEALANT FOR FLOOR PANEL.	NOT NECESSARY	150.00	-
			14,770.00	11,220.00
GRAND TOTAL			20,664.88	15,144.19
RECOMMENDED COST OF REPAIRS				15,144.19

Report Ref No. CC4/ASM19007396/T1gb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.