


MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: ERGO	DATE	: 25/04/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SME5542P		
MODEL	: HONDA FREED 1.5G HYBRID AUTO		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 24-Apr-19
		TIME	: 17:30HRS
THIRD PARTY REQUESTOR / CONTACT		: MS HONG / SHARON	



CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>torn</i>	1	\$ 890.50	\$ 890.50
2	FRONT BUMPER RETAINER LH <i>new</i>	1	\$ 52.20	\$ 52.20
3	FRONT PILLAR <i>Repair</i>	1	\$ 3,855.20	\$ 3,855.20
4	FRONT DASHBOARD SIDE GARNISH <i>lt</i>	1	\$ 117.60	\$ 117.60
5	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00
6	FRONT FENDER LH <i>Repair</i>	1	\$ 560.00	\$ 560.00
7	FRONT FENDER EMBLEM <i>new</i>	1	\$ 108.00	\$ 108.00
8	FRONT QUARTER GLASS LH <i>shattered</i>	1	\$ 520.00	\$ 520.00
9	FRONT QUARTER GLASS MOULDING <i>new</i>	1	\$ 103.00	\$ 103.00
10	FRONT QUARTER GLASS INNER GARNISH <i>lt</i>	1	\$ 130.00	\$ 130.00
11	FRONT SIDE MIRROR ASSY <i>missing</i>	1	\$ 620.00	\$ 620.00
12	FRONT SIDE MIRROR COVER <i>missing</i>	1	\$ 120.00	\$ 120.00
13	FRONT DOOR LH <i>Dented</i>	1	\$ 1,388.50	\$ 1,388.50
14	FRONT DOOR LOCK <i>new</i>	1	\$ 290.00	\$ 290.00
15	FRONT DOOR STICKER <i>Abuse new</i>	2	\$ 90.00	\$ 180.00
16	FRONT DOOR WEATHERSTRIP <i>new</i>	1	\$ 240.24	\$ 240.24
17	FRONT DOOR GLASS <i>lt</i>	1	\$ 722.00	\$ 722.00
18	FRONT DOOR GLASS CHANNEL <i>lt</i>	1	\$ 140.00	\$ 140.00

1280

50

19	FRONT DOOR GLASS OUTER GARNISH <i>at</i>	1	\$ 190.00	\$ 190.00	-
20	FRONT DOOR OUTER HANDLE(BIG) <i>at</i>	1	\$ 290.00	\$ 290.00	-
21	FRONT DOOR OUTER HANDLE INNER RUBBER <i>new</i>	1	\$ 45.50	\$ 45.50	+
22	FRONT DOOR OUTER HANDLE END <i>new</i>	1	\$ 105.20	\$ 105.20	+
23	FRONT DOOR OUTER HANDLE INNER RUBBER <i>new</i>	1	\$ 45.50	\$ 45.50	+
24	REAR DOOR LH <i>Dented</i>	1	\$ 1,388.50	\$ 1,388.50	1265
25	REAR DOOR STICKER <i>new</i>	1	\$ 90.00	\$ 90.00	50
26	REAR DOOR OUTER HANDLE(BIG) <i>Disturbed</i>	1	\$ 203.00	\$ 203.00	-
27	REAR DOOR OUTER HANDLE INNER RUBBER <i>new</i>	1	\$ 45.50	\$ 45.50	-
28	REAR DOOR OUTER HANDLE END <i>at</i>	1	\$ 105.20	\$ 105.20	-
29	REAR DOOR OUTER HANDLE INNER RUBBER <i>new</i>	1	\$ 45.50	\$ 45.50	-
30	REAR FENDER <i>Repair</i>	1	\$ 1,588.70	\$ 1,588.70	+

7273
5818.40

TOTAL PRICE \$ 14,359.84
LESS 20% \$ 2,871.97
SUB TOTAL PRICE \$ 11,487.87

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS <i>new</i>	1	\$ 20.00	\$ 20.00	-
2	FRONT WINDSCREEN SEALANT <i>3 new</i>	1	\$ 120.00	\$ 120.00	60
3	FRONT QUARTER GLASS SEALANT	1	\$ 120.00	\$ 120.00	40

120 TOTAL \$ 260.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00	700.		
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	1300.		
3	WIRING CHECK	\$ 250.00	30		
4	TO REMOVE AND REFIX FRONT WINDSCREEN	\$ 180.00	120.		
5	TO REMOVE AND REFIX FRONT DASHBOARD	\$ 320.00	20 220.		
6	TO REMOVE AND REFIX FRONT QUARTER GLASS	\$ 100.00	40		
7	TO TRANSFER FRONT & REAR DOOR MECHANISM LH	\$ 280.00	160.		
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET	\$ 180.00	x		
9	TO VACUUM INTERIOR WHOLE CAR DUE TO SHATTERED GLASS	\$ 260.00	80.		

TOTAL \$5,570.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,747.87
TOTAL LABOUR COST : \$ 5,570.00
TOTAL REPAIR COST : \$ 17,317.87

APPROVED DETAILS

SURVEYOR :

total: 8588.40
L/S: 6850
Adrian Ling.
4/5 26/04/19.
08 Days.

2650

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :