



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJC8616L
Make & Model : SUBARU, IMPREZA 5D 1.5R AWD
AT, JF1GH3KS59G035385
Year of Manufacture : 2009

Estimation No. : E19040019
DOA : 01/03/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper	1.00	654.00	0.00 788.00 0.00 CUT ✓
2	Rear bumper retainer (LH)	1.00	0.00	78.50 0.00 NNX
3	Rear bumper retainer (RH)	1.00	65.00	0.00 78.50 0.00 NEC ✓
4	Rear bumper reflector (RH)	1.00	62.30	0.00 92.50 0.00 ? / nec
5	Tail lamp (RH)	1.00	0.00	642.00 0.00 ? X NNX
6	Tail lamp lower bracket (RH)	1.00	52.00	0.00 89.60 0.00 ? nec
7	Rear fender (RH)	1.00	0.00	1152.00 0.00 RX
8	Rear fender inner shield (RH)	1.00	✓ 0.00	120.00 0.00 ? / nec
9	Rear fender QTR glass	1.00	0.00	126.00 0.00 NNX
10	Fuel lid	1.00	0.00	45.00 0.00 NNX
11	Rear door (RH)	1.00	840.30	0.00 940.00 0.00 DD ✓
12	Rear door outer handle	1.00	0.00	0.00 0.00 NNX
13	Rear door window frame	1.00	✓ 0.00	120.00 0.00 NEC ✓
14	Rear door lock	1.00	0.00	0.00 0.00 NNX
15	Rear door window regulator	1.00	0.00	0.00 0.00 NNX
16	Rear door power window motor	1.00	0.00	0.00 0.00 NNX
17	Rear wheel rim (RH)	1.00	280.00	0.00 116.00 0.00 CUT ✓
18	Rear absorber (RH)	1.00	0.00	176.00 0.00 ? X
19	Rear knuckle arm (RH)	1.00	0.00	387.70 0.00 ? X
20	Rear lower arm (RH)	1.00	0.00	575.00 0.00 ? X
21	Rear upper arm (RH)	1.00	0.00	0.00 0.00 ? X
22	Rear trailing arm (RH)	1.00	0.00	0.00 0.00 ? X
23	Rear toe arm (RH)	1.00	0.00	0.00 0.00 ? X
24	Rear knuckle bearing (RH)	1.00	316.00	0.00 316.00 0.00 ? NEC ✓

Continue on next page...

2509.30



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJC8616L
 Make & Model : SUBARU, IMPREZA 5D 1.5R AWD
 ATJF1GH3KS59G035385
 Year of Manufacture : 2009

Estimation No. : E19040019
 DOA : 01/03/2019

No	Description	Qty	U/P	Amt
			Amt	S\$ 0.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 0.00

Section: Special Nett Items

25	Rear bumper clip set	1.00	50.00	30.00	50.00	NECV
26	Rear fender inner shield clip set	1.00	50.00	30.00	50.00	✓ nec
27	Rear wheel tyre (RH)	1.00	250.00		250.00	NNX
28	Rear fender QTR glass sealant	1.00	50.00		50.00	NNX
29	Tail lamp clip (RH)	1.00	20.00		20.00	NECV
			Amt		S\$ 420.00	80.00
			Discount (0.00%)		S\$ 0.00	
			Subtotal		S\$ 420.00	

Section: Labour Items

30	To R&R rear bumper reverse sensor	1.00	60.00		60.00	✓
31	To check wiring & lighting system	1.00	80.00	50.00	80.00	✓
32	To supply under coating & putty on parts replaced	1.00	80.00	60.00	80.00	✓
33	To perform anti-rust treatment on affected areas	1.00	60.00		60.00	✓
34	To conduct all wheel alignment before & after	1.00	180.00	120.00	180.00	✓
35	To R&R rear RH door mechanism	1.00	250.00	100.00	250.00	✓
36	To R&R rear under carriage damaged parts	1.00	350.00		350.00	? 150.00
37	To press knuckle bearing assy	1.00	100.00		100.00	? 50.00 ✓
38	To R&R rear trims, garnish & seats assy	1.00	250.00	100.00	250.00	✓
39	To R&R fuel tank to cut & weld	1.00	300.00		300.00	NNX
40	To R&R rear wheel rim, tyre & balancing	1.00	60.00	30.00	60.00	✓
41	To repair, replace and realign damaged areas	1.00	800.00	450.00	800.00	✓
42	To spray painting on affected areas	1.00	800.00	600.00	800.00	✓
43	To perform water seepage test after repair	1.00	120.00		120.00	NNX

Continue on next page...

1830.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJC8616L
Make & Model : SUBARU, IMPREZA 5D 1.5R AWD
ATJF1GH3KS59G035385
Year of Manufacture : 2009

Estimation No. : E19040019
DOA : 01/03/2019

No	Description	Qty	U/P	Amt
44	Sundries	1.00	50.00	50.00

Amt S\$ 3,540.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,540.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

? photo

Lump sum repair
Repair days 5

Lin Teow Guan
Lin

29/4/19

1200 hrs

Adrian Ling.
29/04/19.
3:45pm Resurvey.

TC Lim
23/7/19

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 420.00
Labour Items Subtotal	S\$ 3,540.00
Total	S\$ 3,960.00