

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help To arrange
Surveyor to Survey this
Vehicle thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLW7672B
Chassis No : MRHFC5650JT000414
Model : CIVIC 1.6 VTI YM2018
Owner's Name : LIANG YIN CHUM
Ins Policy No. :
Date of Accident : 25/4/2019

Document No. : SQT19001858 Page 1
Date : 26. Apr 2019
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B25500467
Date | Time : 26. Apr 2019 9:01:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: LIANG YIN CHUM						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 25/4/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SLG8979U						
67550-TEA-T00ZZ	PANELL.RR.DOOR <i>Dented</i>	1	717.50	25	✓ 538.12	37.67	575.79
72965-TEA-T01	MOLDING ASSY,L.RR.DR INNER <i>new</i>	1	56.70	25	✓ 42.52	2.98	45.50
73227-TEA-003	RUBBER C WINDSHIELD DAM <i>new</i>	1	17.20	25	✓ 12.90	0.90	13.80
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>new</i>	3	9.70	25	✓ 21.82	1.53	23.35
91501-S70-003	FASTENER BW/SHIELD <i>new</i>	2	5.30	25	✓ 7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD <i>new</i>	2	3.80	25	✓ 5.70	0.40	6.10
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	2.90	25	✓ 4.35	0.30	4.65
73125-SR3-000	RUBBER, W/SHIELD <i>new</i>	1	12.60	25	✓ 9.45	0.66	10.11
73126-SR3-000	RUBBER, W/SHIELD <i>new</i>	1	14.40	25	✓ 10.80	0.76	11.56
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>new</i>	3	60.00		✓ 180.00	12.60	192.60
73550-TEA-T01	GLASS ASSYL.QUARTER WINDSHIEL <i>new</i>	1	136.60	25	✓ 102.45	7.17	109.62
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE <i>Dented</i>	1	711.60	25	✓ 533.70	37.36	571.06
74592-TEA-T00	FENDERL.RR.INNER <i>new</i>	1	63.00	25	+ 47.25	3.31	50.56
90682-SEA-003	CLIP ABUMPER <i>new</i>	1	2.60	25	+ 1.95	0.14	2.09
91501-TR0-003	CLIP,INNER FENDER <i>new</i>	7	2.80	25	+ 14.70	1.03	15.73
91512-SED-003	CLIPINNER FENDER <i>new</i>	4	2.20	25	+ 6.60	0.46	7.06
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>Repair</i>	1	617.20	25	+ 462.90	32.40	495.30
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>new</i>	1	2.30	25	✓ 1.72	0.12	1.84
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>new</i>	1	11.50	25	✓ 8.62	0.60	9.22

Printed on 26/4/2019 10:58:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT19001858	Page	2
	8 SHENTON WAY	Date	: 26. Apr 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SLW7672B	Engine No	: R16B25500467		
Chassis No	: MRHFC5650JT000414	Date Time	: 26. Apr 2019 9:01:35 AM		
Model	: CIVIC 1.6 VTI YM2018	Surveyor Name	:		
Owner's Name	: LIANG YIN CHUM	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 25/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIP,BUMPER <i>pc</i>	7	2.30	25	✓ 12.07	0.84	12.91
42700-TEA-T61	DISKALUMINIUM WHEEL <i>cut</i>	1	297.80	25	✓ 223.35	15.63	238.98
HK-215/55R16H452	HANKOOK TYRE <i>new</i>	1	148.00		+ 148.00	10.36	158.36
42200-TBA-A02	BEARING ASSYRR.HUB UNIT ?	1	160.40	25	? 120.30	8.42	128.72
52215-TBA-A00	KNUCKLE COMPL.RR. ?	1	153.20	25	? 114.90	8.04	122.94
52320-TEA-T00	LINK COMPSTABILIZER RR. ?	1	22.90	25	? 17.17	1.20	18.37
52355-TEA-T00	ARM COMP BL.RR.LOWER ?	1	61.60	25	? 46.20	3.23	49.43
52365-TEA-T00	ARM COMPL.RR.TRAILING ?	1	41.10	25	? 30.82	2.16	32.98
52370-TEA-T00	ARM COMP ARR.LOWER ?	1	41.70	25	? 31.27	2.19	33.46
52510-TEA-T00	ARM COMPRR.UPPER ?	1	71.60	25	? 53.70	3.76	57.46
Sum Item					2811.28	196.78	3,008.06
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		✓ 180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00		✓ 250.00	17.50	267.50
Sum Ext. Service					430.00	30.10	460.10
BOSUN	SUNDRIES	1	50.00		20 ✓ 50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		60 ✓ 80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		✓ 100.00	7.00	107.00
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	130.00		+ 130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		180 ✓ 250.00	17.50	267.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	250.00		✓ 250.00	17.50	267.50
BG51R	REPLACE RR. L QTR GLASS.(N)	1	280.00		✓ 280.00	19.60	299.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		✓ 300.00	21.00	321.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00		280 ✓ 320.00	22.40	342.40
BMI02D	REMOVE & INSTALL SPEAKER BOARD, RR SEATS, REAR	1	350.00		250 ✓ 350.00	24.50	374.50
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	380.00		✓ 380.00	26.60	406.60

Printed on 26/4/2019 10:58:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLW7672B

Chassis No : MRHFC5650JT000414

Model : CIVIC 1.6 VTI YM2018

Owner's Name : LIANG YIN CHUM

Ins Policy No. :

Date of Accident : 25/4/2019

Document No. : SQT19001858 Page 3

Date : 26. Apr 2019

Customer No. : WZA006

Svc Advisor : LIM CHOU SIONG

Engine No : R16B25500467

Date | Time : 26. Apr 2019 9:01:35 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKFE21R	CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL	1	2100.00	1680	2100.00	147.00	2247.00
BP03R	SPRAY PAINTING ON RR BUMPER, RR L FENDER & RR L	1	1500.00	1350	1500.00	105.00	1605.00
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
Sum Labor					6170.00	431.90	6,601.90

Survey By : _____

Date & Time : _____

Excess : _____

Status : _____

Signature : _____

C Slim
81006303 (HP)

Total Amount 9,411.28 658.78 10,070.06

Total (Inclusive of GST) 10,070.06

Adrian Lj
P/P 30/04/19.
08 hrs

Printed on 26/4/2019 10:58:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.