

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986
TEL: 67275700
ATTN: Motor Claim Department

Estimate No: EST1900107

Date: 25 Apr 2019

Veh Reg No: SKS9585P

Make/Model: M.BENZ E200 SEDAN (R17)

Chasis No: WDD2120342B125269

Reg. Date: 18/05/2015

Your Ref No: SGU2200H

Claim Type: Third Party

Accident Date: 25/04/2019

TP Veh Reg No: SGU2200H

Estimate Repair Cost to Vehicle No :SKS9585P

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BONNET <i>Dented</i>	2,826.00	✓
2	1 PC BONNET TRIM <i>new</i>	266.00	+
3	1 PC BONNET LOGO <i>new</i>	112.00	✓
4	1 PC HEADLAMP RH <i>cracked</i>	3,747.00	✓
5	1 PC HEADLAMP PANEL RH <i>new</i>	166.00	+
6	1 PC FRT FENDER RH <i>Buckled</i>	1,139.00	✓
7	1 PC FRT FENDER COWLING RH <i>Delnd</i>	312.00	✓
8	1 PC FRT GRILLE <i>cracked.</i>	1,139.00	✓
9	1 PC FRT GRILLE TOP RUBBER <i>new</i>	145.00	+
10	1 PC FRT GRILLE EMBLEM <i>new</i>	47.00	✓
11	1 PC FRT BUMPER <i>Delnd</i>	1,585.00	✓
12	1 PC FRT BUMPER REINFORCEMENT <i>Best.</i>	583.00	✓
13	1 PC FRT BUMPER SPONGE <i>cracked</i>	139.00	✓
14	1 PC FRT BUMPER GRILLE <i>new</i>	98.00	+
15	1 PC FRT BUMPER TOWING COVER <i>new</i>	36.60	+
16	1 PC FRT BUMPER SIDE RETAINER RH <i>new</i>	134.00	✓
17	1 PC FRT FOG LAMP COVER RH <i>cracked.</i>	59.00	✓
18	1 PC FRT FOG LAMP COVER BASE RH <i>cracked</i>	227.00	✓
19	1 PC FRT FOG LAMP COVER CHROME RH <i>cracked</i>	106.00	✓
20	2 PCS FRT BUMPER PARKING SENSORS <i>Damaged</i>	960.00	✓
		13,826.60	
	Less 10%	1,382.66	12,443.94
	Special Net		
21	1 SET BONNET TRIM CLIPS <i>new</i>	60.00	+
22	1 SET FRT GRILLE CLIPS <i>new</i>	60.00	20
23	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	48.00	+
24	1 SET FRT BUMPER CLIPS <i>new</i>	60.00	30
25	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00	25

12675

11409.50

75

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986
TEL: 67275700
ATTN: Motor Claim Department

Estimate No: EST1900107
Date: 25 Apr 2019
Veh Reg No: SKS9585P
Make/Model: M.BENZ E200 SEDAN (R17)
Chasis No: WDD2120342B125269
Reg. Date: 18/05/2015
Your Ref No: SGU2200H

Claim Type: Third Party
Accident Date: 25/04/2019
TP Veh Reg No: SGU2200H

Estimate Repair Cost to Vehicle No :SKS9585P

Quantity	Description	List Price	Amount
		SS	SS
		268.00	268.00
	Labour		
26	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	750
27	1 TO SPRAY PAINTING	1,300.00	750
28	1 TO SPRAY UNDERSEAL	80.00	+
29	1 TO REPLACE PARKING SENSORS	100.00	60
30	1 TO CHECK WIRING	50.00	30
31	1 TO RE-PROGRAMME AND RE-SET	300.00	100
		3,030.00	3,030.00
	Total		S\$ 15,741.94
	Add GST @ 7%		1,101.94
	Total Amount Payable		S\$ 16,843.88

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND EIGHT HUNDRED FORTY THREE AND CENTS EIGHTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

Adrian Lij
L/S 26/04/19-
05 Days
For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Supplementary: 1270.08

total: 17442.58

L/S: 11550

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700

ATTN: Motor Claim Department

Estimate No: EST1900107

Date: 25 Jun 2019

Veh Reg No: SKS9585P

Make/Model: M.BENZ E200 SEDAN
(R17)

Chasis No: WDD2120342B125269

Reg. Date: 18/05/2015

Your Ref No: SGU2200H

Claim Type: Third Party

Accident Date: 25/04/2019

TP Veh Reg No: SGU2200H

Estimate Repair Cost to Vehicle No :SKS9585P

Quantity	Description	List Price	Amount
		SS	SS
	Supplementary Parts to Repair		
	List Price		
1	1 PC FRT PARKING SENSOR RELAY <i>Painted.</i>	536.90	✓
2	1 PC FRT SIDE BRACKET <i>Best.</i>	86.90	✓
3	1 PC FRT BUMPER INNER GARNISH <i>cracked.</i>	189.70	✓
4	1 PC FRT BUMPER LOWER GARNISH <i>scratched.</i>	277.80	✓
5	1 PC FRT BUMPER LOWER GARNISH MOULDING <i>cracked</i>	319.90	✓
		1,411.20	
	Less 10%	141.12	1,270.08
	Total		S\$ 1,270.08
	GST Amount		S\$ 88.91
	Total Amount Payable		S\$ 1,358.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

For Kang Car Repairers Pte Ltd

Ali Singh
AUTHORISED SIGNATURE

Supplementary: 1270.08.