

INSURANCE

INS. CASE OWNER:

ENCOUNTERED

CC 6 /AIG1900

7419 A1234

LKK:

IDAC:

Surveyor:

Adrian

DOL:

ASSIGNMENT

75/4/19

Date/Time:

75/4/19

Registered in Meriton:

75/4/19

Pre-assign / CCU / FTE:

SFA 420K



Insured Vehicle No.:

OH CHENY FAN

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

75/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: **TADA YASUHO**

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

41487104059

Policy No.:

2003764694

Make / Model:

UNIMORVER

Place of Accident:

ALEXANDRA RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFA 5885K

GBH 5479P

SFA 420K

SJR 1687P



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kang

7P

Date/Time:

5/2/19 - 7/2/19 - 9/2/19 - 11/2/19 - 13/2/19 - 15/2/19 - 17/2/19 - 19/2/19 - 21/2/19 - 23/2/19 - 25/2/19 - 27/2/19 - 29/2/19 - 31/2/19 - 3/3/19 - 5/3/19 - 7/3/19 - 9/3/19 - 11/3/19 - 13/3/19 - 15/3/19 - 17/3/19 - 19/3/19 - 21/3/19 - 23/3/19 - 25/3/19 - 27/3/19 - 29/3/19 - 31/3/19 - 3/4/19 - 5/4/19 - 7/4/19 - 9/4/19 - 11/4/19 - 13/4/19 - 15/4/19 - 17/4/19 - 19/4/19 - 21/4/19 - 23/4/19 - 25/4/19 - 27/4/19 - 29/4/19 - 31/4/19 - 3/5/19 - 5/5/19 - 7/5/19 - 9/5/19 - 11/5/19 - 13/5/19 - 15/5/19 - 17/5/19 - 19/5/19 - 21/5/19 - 23/5/19 - 25/5/19 - 27/5/19 - 29/5/19 - 31/5/19 - 3/6/19 - 5/6/19 - 7/6/19 - 9/6/19 - 11/6/19 - 13/6/19 - 15/6/19 - 17/6/19 - 19/6/19 - 21/6/19 - 23/6/19 - 25/6/19 - 27/6/19 - 29/6/19 - 31/6/19 - 3/7/19 - 5/7/19 - 7/7/19 - 9/7/19 - 11/7/19 - 13/7/19 - 15/7/19 - 17/7/19 - 19/7/19 - 21/7/19 - 23/7/19 - 25/7/19 - 27/7/19 - 29/7/19 - 31/7/19 - 3/8/19 - 5/8/19 - 7/8/19 - 9/8/19 - 11/8/19 - 13/8/19 - 15/8/19 - 17/8/19 - 19/8/19 - 21/8/19 - 23/8/19 - 25/8/19 - 27/8/19 - 29/8/19 - 31/8/19 - 3/9/19 - 5/9/19 - 7/9/19 - 9/9/19 - 11/9/19 - 13/9/19 - 15/9/19 - 17/9/19 - 19/9/19 - 21/9/19 - 23/9/19 - 25/9/19 - 27/9/19 - 29/9/19 - 31/9/19 - 3/10/19 - 5/10/19 - 7/10/19 - 9/10/19 - 11/10/19 - 13/10/19 - 15/10/19 - 17/10/19 - 19/10/19 - 21/10/19 - 23/10/19 - 25/10/19 - 27/10/19 - 29/10/19 - 31/10/19 - 3/11/19 - 5/11/19 - 7/11/19 - 9/11/19 - 11/11/19 - 13/11/19 - 15/11/19 - 17/11/19 - 19/11/19 - 21/11/19 - 23/11/19 - 25/11/19 - 27/11/19 - 29/11/19 - 31/11/19 - 3/12/19 - 5/12/19 - 7/12/19 - 9/12/19 - 11/12/19 - 13/12/19 - 15/12/19 - 17/12/19 - 19/12/19 - 21/12/19 - 23/12/19 - 25/12/19 - 27/12/19 - 29/12/19 - 31/12/19 - 3/1/20 - 5/1/20 - 7/1/20 - 9/1/20 - 11/1/20 - 13/1/20 - 15/1/20 - 17/1/20 - 19/1/20 - 21/1/20 - 23/1/20 - 25/1/20 - 27/1/20 - 29/1/20 - 31/1/20 - 3/2/20 - 5/2/20 - 7/2/20 - 9/2/20 - 11/2/20 - 13/2/20 - 15/2/20 - 17/2/20 - 19/2/20 - 21/2/20 - 23/2/20 - 25/2/20 - 27/2/20 - 29/2/20 - 31/2/20 - 3/3/20 - 5/3/20 - 7/3/20 - 9/3/20 - 11/3/20 - 13/3/20 - 15/3/20 - 17/3/20 - 19/3/20 - 21/3/20 - 23/3/20 - 25/3/20 - 27/3/20 - 29/3/20 - 31/3/20 - 3/4/20 - 5/4/20 - 7/4/20 - 9/4/20 - 11/4/20 - 13/4/20 - 15/4/20 - 17/4/20 - 19/4/20 - 21/4/20 - 23/4/20 - 25/4/20 - 27/4/20 - 29/4/20 - 31/4/20 - 3/5/20 - 5/5/20 - 7/5/20 - 9/5/20 - 11/5/20 - 13/5/20 - 15/5/20 - 17/5/20 - 19/5/20 - 21/5/20 - 23/5/20 - 25/5/20 - 27/5/20 - 29/5/20 - 31/5/20 - 3/6/20 - 5/6/20 - 7/6/20 - 9/6/20 - 11/6/20 - 13/6/20 - 15/6/20 - 17/6/20 - 19/6/20 - 21/6/20 - 23/6/20 - 25/6/20 - 27/6/20 - 29/6/20 - 31/6/20 - 3/7/20 - 5/7/20 - 7/7/20 - 9/7/20 - 11/7/20 - 13/7/20 - 15/7/20 - 17/7/20 - 19/7/20 - 21/7/20 - 23/7/20 - 25/7/20 - 27/7/20 - 29/7/20 - 31/7/20 - 3/8/20 - 5/8/20 - 7/8/20 - 9/8/20 - 11/8/20 - 13/8/20 - 15/8/20 - 17/8/20 - 19/8/20 - 21/8/20 - 23/8/20 - 25/8/20 - 27/8/20 - 29/8/20 - 31/8/20 - 3/9/20 - 5/9/20 - 7/9/20 - 9/9/20 - 11/9/20 - 13/9/20 - 15/9/20 - 17/9/20 - 19/9/20 - 21/9/20 - 23/9/20 - 25/9/20 - 27/9/20 - 29/9/20 - 31/9/20 - 3/10/20 - 5/10/20 - 7/10/20 - 9/10/20 - 11/10/20 - 13/10/20 - 15/10/20 - 17/10/20 - 19/10/20 - 21/10/20 - 23/10/20 - 25/10/20 - 27/10/20 - 29/10/20 - 31/10/20 - 3/11/20 - 5/11/20 - 7/11/20 - 9/11/20 - 11/11/20 - 13/11/20 - 15/11/20 - 17/11/20 - 19/11/20 - 21/11/20 - 23/11/20 - 25/11/20 - 27/11/20 - 29/11/20 - 31/11/20 - 3/12/20 - 5/12/20 - 7/12/20 - 9/12/20 - 11/12/20 - 13/12/20 - 15/12/20 - 17/12/20 - 19/12/20 - 21/12/20 - 23/12/20 - 25/12/20 - 27/12/20 - 29/12/20 - 31/12/20 - 3/1/21 - 5/1/21 - 7/1/21 - 9/1/21 - 11/1/21 - 13/1/21 - 15/1/21 - 17/1/21 - 19/1/21 - 21/1/21 - 23/1/21 - 25/1/21 - 27/1/21 - 29/1/21 - 31/1/21 - 3/2/21 - 5/2/21 - 7/2/21 - 9/2/21 - 11/2/21 - 13/2/21 - 15/2/21 - 17/2/21 - 19/2/21 - 21/2/21 - 23/2/21 - 25/2/21 - 27/2/21 - 29/2/21 - 31/2/21 - 3/3/21 - 5/3/21 - 7/3/21 - 9/3/21 - 11/3/21 - 13/3/21 - 15/3/21 - 17/3/21 - 19/3/21 - 21/3/21 - 23/3/21 - 25/3/21 - 27/3/21 - 29/3/21 - 31/3/21 - 3/4/21 - 5/4/21 - 7/4/21 - 9/4/21 - 11/4/21 - 13/4/21 - 15/4/21 - 17/4/21 - 19/4/21 - 21/4/21 - 23/4/21 - 25/4/21 - 27/4/21 - 29/4/21 - 31/4/21 - 3/5/21 - 5/5/21 - 7/5/21 - 9/5/21 - 11/5/21 - 13/5/21 - 15/5/21 - 17/5/21 - 19/5/21 - 21/5/21 - 23/5/21 - 25/5/21 - 27/5/21 - 29/5/21 - 31/5/21 - 3/6/21 - 5/6/21 - 7/6/21 - 9/6/21 - 11/6/21 - 13/6/21 - 15/6/21 - 17/6/21 - 19/6/21 - 21/6/21 - 23/6/21 - 25/6/21 - 27/6/21 - 29/6/21 - 31/6/21 - 3/7/21 - 5/7/21 - 7/7/21 - 9/7/21 - 11/7/21 - 13/7/21 - 15/7/21 - 17/7/21 - 19/7/21 - 21/7/21 - 23/7/21 - 25/7/21 - 27/7/21 - 29/7/21 - 31/7/21 - 3/8/21 - 5/8/21 - 7/8/21 - 9/8/21 - 11/8/21 - 13/8/21 - 15/8/21 - 17/8/21 - 19/8/21 - 21/8/21 - 23/8/21 - 25/8/21 - 27/8/21 - 29/8/21 - 31/8/21 - 3/9/21 - 5/9/21 - 7/9/21 - 9/9/21 - 11/9/21 - 13/9/21 - 15/9/21 - 17/9/21 - 19/9/21 - 21/9/21 - 23/9/21 - 25/9/21 - 27/9/21 - 29/9/21 - 31/9/21 - 3/10/21 - 5/10/21 - 7/10/21 - 9/10/21 - 11/10/21 - 13/10/21 - 15/10/21 - 17/10/21 - 19/10/21 - 21/10/21 - 23/10/21 - 25/10/21 - 27/10/21 - 29/10/21 - 31/10/21 - 3/11/21 - 5/11/21 - 7/11/21 - 9/11/21 - 11/11/21 - 13/11/21 - 15/11/21 - 17/11/21 - 19/11/21 - 21/11/21 - 23/11/21 - 25/11/21 - 27/11/21 - 29/11/21 - 31/11/21 - 3/12/21 - 5/12/21 - 7/12/21 - 9/12/21 - 11/12/21 - 13/12/21 - 15/12/21 - 17/12/21 - 19/12/21 - 21/12/21 - 23/12/21 - 25/12/21 - 27/12/21 - 29/12/21 - 31/12/21 - 3/1/22 - 5/1/22 - 7/1/22 - 9/1/22 - 11/1/22 - 13/1/22 - 15/1/22 - 17/1/22 - 19/1/22 - 21/1/22 - 23/1/22 - 25/1/22 - 27/1/22 - 29/1/22 - 31/1/22 - 3/2/22 - 5/2/22 - 7/2/22 - 9/2/22 - 11/2/22 - 13/2/22 - 15/2/22 - 17/2/22 - 19/2/22 - 21/2/22 - 23/2/22 - 25/2/22 - 27/2/22 - 29/2/22 - 31/2/22 - 3/3/22 - 5/3/22 - 7/3/22 - 9/3/22 - 11/3/22 - 13/3/22 - 15/3/22 - 17/3/22 - 19/3/22 - 21/3/22 - 23/3/22 - 25/3/22 - 27/3/22 - 29/3/22 - 31/3/22 - 3/4/22 - 5/4/22 - 7/4/22 - 9/4/22 - 11/4/22 - 13/4/22 - 15/4/22 - 17/4/22 - 19/4/22 - 21/4/22 - 23/4/22 - 25/4/22 - 27/4/22 - 29/4/22 - 31/4/22 - 3/5/22 - 5/5/22 - 7/5/22 - 9/5/22 - 11/5/22 - 13/5/22 - 15/5/22 - 17/5/22 - 19/5/22 - 21/5/22 - 23/5/22 - 25/5/22 - 27/5/22 - 29/5/22 - 31/5/22 - 3/6/22 - 5/6/22 - 7/6/22 - 9/6/22 - 11/6/22 - 13/6/22 - 15/6/22 - 17/6/22 - 19/6/22 - 21/6/22 - 23/6/22 - 25/6/22 - 27/6/22 - 29/6/22 - 31/6/22 - 3/7/22 - 5/7/22 - 7/7/22 - 9/7/22 - 11/7/22 - 13/7/22 - 15/7/22 - 17/7/22 - 19/7/22 - 21/7/22 - 23/7/22 - 25/7/22 - 27/7/22 - 29/7/22 - 31/7/22 - 3/8/22 - 5/8/22 - 7/8/22 - 9/8/22 - 11/8/22 - 13/8/22 - 15/8/22 - 17/8/22 - 19/8/22 - 21/8/22 - 23/8/22 - 25/8/22 - 27/8/22 - 29/8/22 - 31/8/22 - 3/9/22 - 5/9/22 - 7/9/22 - 9/9/22 - 11/9/22 - 13/9/22 - 15/9/22 - 17/9/22 - 19/9/22 - 21/9/22 - 23/9/22 - 25/9/22 - 27/9/22 - 29/9/22 - 31/9/22 - 3/10/22 - 5/10/22 - 7/10/22 - 9/10/22 - 11/10/22 - 13/10/22 - 15/10/22 - 17/10/22 - 19/10/22 - 21/10/22 - 23/10/22 - 25/10/22 - 27/10/22 - 29/10/22 - 31/10/22 - 3/11/22 - 5/11/22 - 7/11/22 - 9/11/22 - 11/11/22 - 13/11/22 - 15/11/22 - 17/11/22 - 19/11/22 - 21/11/22 - 23/11/22 - 25/11/22 - 27/11/22 - 29/11/22 - 31/11/22 - 3/12/22 - 5/12/22 - 7/12/22 - 9/12/22 - 11/12/22 - 13/12/22 - 15/12/22 - 17/12/22 - 19/12/22 - 21/12/22 - 23/12/22 - 25/12/22 - 27/12/22 - 29/12/22 - 31/12/22 - 3/1/23 - 5/1/23 - 7/1/23 - 9/1/23 - 11/1/23 - 13/1/23 - 15/1/23 - 17/1/23 - 19/1/23 - 21/1/23 - 23/1/23 - 25/1/23 - 27/1/23 - 29/1/23 - 31/1/23 - 3/2/23 - 5/2/23 - 7/2/23 - 9/2/23 - 11/2/23 - 13/2/23 - 15/2/23 - 17/2/23 - 19/2/23 - 21/2/23 - 23/2/23 - 25/2/23 - 27/2/23 - 29/2/23 - 31/2/23 - 3/3/23 - 5/3/23 - 7/3/23 - 9/3/23 - 11/3/23 - 13/3/23 - 15/3/23 - 17/3/23 - 19/3/23 - 21/3/23 - 23/3/23 - 25/3/23 - 27/3/23 - 29/3/23 - 31/3/23 - 3/4/23 - 5/4/23 - 7/4/23 - 9/4/23 - 11/4/23 - 13/4/23 - 15/4/23 - 17/4/23 - 19/4/23 - 21/4/23 - 23/4/23 - 25/4/23 - 27/4/23 - 29/4/23 - 31/4/23 - 3/5/23 - 5/5/23 - 7/5/23 - 9/5/23 - 11/5/23 - 13/5/23 - 15/5/23 - 17/5/23 - 19/5/23 - 21/5/23 - 23/5/23 - 25/5/23 - 27/5/23 - 29/5/23 - 31/5/23 - 3/6/23 - 5/6/23 - 7/6/23 - 9/6/23 - 11/6/23 - 13/6/23 - 15/6/23 - 17/6/23 - 19/6/23 - 21/6/23 - 23/6/23 - 25/6/23 - 27/6/23 - 29/6/23 - 31/6/23 - 3/7/23 - 5/7/23 - 7/7/23 - 9/7/23 - 11/7/23 - 13/7/23 - 15/7/23 - 17/7/23 - 19/7/23 - 21/7/23 - 23/7/23 - 25/7/23 - 27/7/23 - 29/7/23 - 31/7/23 - 3/8/23 - 5/8/23 - 7/8/23 - 9/8/23 - 11/8/23 - 13/8/23 - 15/8/23 - 17/8/23 - 19/8/23 - 21/8/23 - 23/8/23 - 25/8/23 - 27/8/23 - 29/8/23 - 31/8/23 - 3/9/23 - 5/9/23 - 7/9/23 - 9/9/23 - 11/9/23 - 13/9/23 - 15/9/23 - 17/9/23 - 19/9/23 - 21/9/23 - 23/9/23 - 25/9/23 - 27/9/23 - 29/9/23 - 31/9/23 - 3/10/23 - 5/10/23 - 7/10/23 - 9/10/23 - 11/10/23 - 13/10/23 - 15/10/23 - 17/10/23 - 19/10/23 - 21/10/23 - 23/10/23 - 25/10/23 - 27/10/23 - 29/10/23 - 31/10/23 - 3/11/23 - 5/11/23 - 7/11/23 - 9/11/23 - 11/11/23 - 13/11/23 - 15/11/23 - 17/11/23 - 19/11/23 - 21/11/23 - 23/11/23 - 25/11/23 - 27/11/23 - 29/11/23 - 31/11/23 - 3/12/23 - 5/12/23 - 7/12/23 - 9/12/23 - 11/12/23 - 13/12/23 - 15/12/23 - 17/12/23 - 19/12/23 - 21/12/23 - 23/12/23 - 25/12/23 - 27/12/23 - 29/12/23 - 31/12/23 - 3/1/24 - 5/1/24 - 7/1/24 - 9/1/24 - 11/1/24 - 13/1/24 - 15/1/24 - 17/1/24 - 19/1/24 - 21/1/24 - 23/1/24 - 25/1/24 - 27/1/24 - 29/1/24 - 31/1/24 - 3/2/24 - 5/2/24 - 7/2/24 - 9/2/24 - 11/2/24 - 13/2/24 - 15/2/24 - 17/2/24 - 19/2/24 - 21/2/24 - 23/2/24 - 25/2/24 - 27/2/24 - 29/2/24 - 31/2/24 - 3/3/24 - 5/3/24 - 7/3/24 - 9/3/24 - 11/3/24 - 13/3/24 - 15/3/24 - 17/3/24 - 19/3/24 - 21/3/24 - 23/3/24 - 25/3/24 - 27/3/24 - 29/3/24 - 31/3/24 - 3/4/24 - 5/4/24 - 7/4/24 - 9/4/24 - 11/4/24 - 13/4/24 - 15/4/24 - 17/4/24 - 19/4/24 - 21/4/24 - 23/4/24 - 25/4/24 - 27/4/24 - 29/4/24 - 31/4/24 - 3/5/24 - 5/5/24 - 7/5/24 - 9/5/24 - 11/5/24 - 13/5/24 - 15/5/24 - 17/5/24 - 19/5/24 - 21/5/24 - 23/5/24 - 25/5/24 - 27/5/24 - 29/5/24 - 31/5/24 - 3/6/24 - 5/6/24 - 7/6/24 - 9/6/24 - 11/6/24 - 13/6/24 - 15/6/24 - 17/6/24 - 19/6/24 - 21/6/24 - 23/6/24 - 25/6/24 - 27/6/24 - 29/6/24 - 31/6/24 - 3/7/24 - 5/7/24 - 7/7/24 - 9/7/24 - 11/7/24 - 13/7/24 - 15/7/24 - 17/7/24 - 19/7/24 - 21/7/24 - 23/7/24 - 25/7/24 - 27/7/24 - 29/7/24 - 31/7/24 - 3/8/24 - 5/8/24 - 7/8/24 - 9/8/24 - 11/8/24 - 13/8/24 - 15/8/24 - 17/8/24 - 19/8/24 - 21/8/24 - 23/8/24 - 25/8/24 - 27/8/24 - 29/8/24 - 31/8/24 - 3/9/24 - 5/9/24 - 7/9/24 - 9/9/24 - 11/9/24 - 13/9/24 - 15/9/24 - 17/9/24 - 19/9/24 - 21/9/24 - 23/9/24 - 25/9/24 - 27/9/24 - 29/9/24 - 31/9/24 - 3/10/24 - 5/10/24 - 7/10/24 - 9/10/24 - 11/10/24 - 13/10/24 - 15/10/24 - 17/10/24 - 19/

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SJR1681P Yr Regn: 2009 JuneType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios cc 1497Colour: Silver A/C: Insured / Std / Nil / NASp. Reading: 279567 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MROS3HY930S115627Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 1capsen

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 25/04/19Survey held at KangDes. of Damages: FR / Roar / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

UG \$17,000.00

CRPD: \$15,922.71 / 48%

Pending CBE Renewal

MV: 31K

PV: 13.9K (Upon Renewal)

Nett: 17.1K.

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + R5, SI

Photos

Others

TOTAL

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST-201300201N

7 53222

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416

ATTN: Motor Claim Department

Estimate No: EST1900105

Date: 25 Apr 2019

Veh Reg No: SJR1681P

Make/Model: TOYOTA VIOS J AUTO

Chasis No: MR053HY9305115627

Reg. Date: 11/06/2009

Your Ref No: SFQ420K

Claim Type: Third Party

Accident Date: 23/04/2019

TP Veh Reg No: SFQ420K

Vic

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented</i>	584.90	—
2	2 PCS BOOT LID HINGE <i>Bent</i>	135.80	—
3	1 PC BOOTLID LOGO	47.70	—
4	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	44.20	✓
5	1 PC BOOTLID "J" EMBLEM	34.40	✓
6	1 PC BOOTLID OUTER KEY LOCK <i>new</i>	98.90	+
7	1 PC BOOTLID INNER LOCK <i>2nd</i>	165.90	✓
8	1 PC BOOT LID INNER LOCK CHECKER <i>Bent</i>	38.40	—
9	1 PC BOOT LID GARNISH <i>Dented</i>	145.70	✓
10	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	113.80	+
11	1 PC BOOT LID RUBBER <i>at</i>	175.30	✓
12	1 PC REAR FENDER LH <i>Buckled</i>	864.80	✓
13	1 PC REAR FENDER INNER TRIM LH <i>Dented</i>	224.20	—
14	1 PC REAR FENDER MUDFLAP LH <i>new</i>	45.60	+
15	1 PC REAR DOOR LOCK LH <i>new</i>	246.60	+
16	1 PC REAR DOOR RUBBER LH <i>new</i>	166.70	+
17	1 PC REAR FENDER RH <i>Buckled</i>	864.80	✓
18	1 PC REAR FENDER INNER TRIM RH <i>Dented</i>	224.20	—
19	1 PC REAR DOOR LOCK RH <i>new</i>	246.60	+
20	1 PC REAR DOOR RUBBER RH <i>new</i>	166.70	+
21	1 PC REAR FENDER MUDFLAP RH <i>new</i>	45.60	+
22	1 PC REAR WINDSCREEN RUBBER <i>new</i>	96.70	✓
23	1 PC TAIL LAMP - RH <i>Cracked</i>	409.90	—
24	1 PC TAIL LAMP PANEL RH <i>Dented Buckled</i>	105.10	✓
25	1 PC TAIL LAMP LH <i>Cracked</i>	409.90	—
26	1 PC TAIL LAMP PANEL LH <i>Buckled</i>	105.10	—
27	1 PC REAR PANEL <i>Disturbed</i>	571.80	—
28	1 PC REAR PANEL TRIM <i>Dented</i>	200.70	—
29	1 PC SPARE TYRE PANEL <i>Repair</i>	637.80	+
30	1 PC SPARE TYRE COVER <i>torn</i>	144.70	—

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000

FAX: 68357416

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 23/04/2019

TP Veh Reg No: SFQ420K

Estimate No: EST1900105

Date: 25 Apr 2019

Veh Reg No: SJR1681P

Make/Model: TOYOTA VIOS J AUTO

Chasis No: MR053HY9305115627

Reg. Date: 11/06/2009

Your Ref No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		SS	SS
31	1 PC SPARE TYRE PANEL RH SPONGE <i>3 Reformed</i>	214.10 ✓	
32	1 PC SPARE TYRE PANEL LH SPONGE	214.10 ✓	
33	1 PC SPARE TYRE PANEL INNER SPONGE <i>cracked</i>	132.30 ✓	
34	2 PCS SPARE TYRE SIDE SMALL COVER <i>new</i>	131.20 ✓	
35	1 PC SPARE TYRE RH SIDE PANEL <i>3 Reformed</i>	166.70 ✓	
36	1 PC SPARE TYRE LH SIDE PANEL <i>3 Reformed</i>	166.70 ✓	
37	1 PC REAR BUMPER <i>Distorted</i>	467.50 ✓	
38	2 PCS REAR BUMPER BRACKET <i>Best</i>	127.40 ✓	
39	1 PC REAR BUMPER REFLECTOR - RH <i>cracked</i>	82.80 ✓	
40	1 PC REAR BUMPER REFLECTOR - LH <i>cracked</i>	82.80 ✓	
41	2 PCS REAR BUMPER SIDE RETAINER <i>3 new</i>	184.60 ✓	
42	2 PCS REAR BUMPER SMALL RETAINER	64.20 ✓	
43	1 PC EXHAUST PIPE <i>Reformed</i>	595.20 ✓	
44	2 PCS EXHAUST PIPE MOUNTING <i>new</i>	57.80 ✓	
45	1 PC BONNET <i>Buckled</i>	471.40 ✓	
46	2 PCS BONNET HINGE <i>Best</i>	88.60 ✓	
47	1 PC BONNET LOCK <i>Reformed</i>	82.30 ✓	
48	1 PC BONNET LOCK CABLE <i>new</i>	64.90 ✓	
49	2 PCS BONNET RUBBER <i>new</i>	102.40 ✓	
50	1 PC FRT FENDER RH <i>Buckled</i>	530.10 ✓	
51	1 PC FRT FENDER COWLING RH <i>new</i>	148.90 ✓	
52	1 PC FRT FENDER "VVTI" EMBLEM <i>new</i>	44.80 ✓	
53	1 PC FRT FENDER LH <i>Buckled</i>	530.10 ✓	
54	1 PC FRT FENDER COWLING LH <i>new</i>	148.90 ✓	
55	1 PC FRT FENDER "VVTI" EMBLEM LH <i>new</i>	44.80 ✓	
56	1 PC FRT SUPPORT PANEL <i>Distorted</i>	788.60 ✓	
57	1 PC FRT BUMPER <i>Distorted</i>	467.30 ✓	
58	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	372.10 ✓	
59	2 PCS FRT BUMPER BRACKET <i>Best</i>	423.20 ✓	
60	1 PC FRT BUMPER TOP BRACKET <i>Reformed</i>	121.40 ✓	
61	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	109.60 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		SS	SS
62	1 PC FRT BUMPER GRILLE <i>canled</i>	74.80 ✓	
63	1 PC FRT FOG LAMP COVER RH <i>3 per in</i>	85.50 +	
64	1 PC FRT FOG LAMP COVER LH	85.50 +	
65	1 PC FRT TOWING COVER <i>behind</i>	28.20 ✓	
66	1 PC FRT GRILLE <i>canled</i>	350.40 ✓	
67	1 PC FRT GRILLE EMBLEM <i>new</i>	50.80 ✓	
68	1 PC FRT GRILLE CHROME <i>canled</i>	121.40 ✓	
69	1 PC HEADLAMP LH <i>canled</i>	525.30 ✓	
70	1 PC HEADLAMP PANEL RH <i>Bent</i>	95.50 ✓	
71	1 PC HEADLAMP RH <i>canled</i>	525.30 ✓	
72	1 PC HEADLAMP PANEL LH <i>Bent</i>	95.50 ✓	
73	1 PC AIR CONDENSER <i>Bent</i>	1,026.60 ✓	
74	2 PCS FRT AIR CONDENSER BOTTOM MOUNTING <i>new</i>	48.80 +	
75	1 PC FRT AIR SUCTION PIPE <i>2 per in</i>	286.10 +	
76	1 PC AIRCON DISCHARGE HOSE <i>3 per in Bent</i>	388.90 ✓	
77	1 PC FRT AIRCON LIQUID PIPE <i>new</i>	271.70 +	
78	1 PC RADIATOR <i>Bent</i>	1,607.00 ✓	
79	1 PC RADIATOR TOP HOSE <i>3 per in</i>	39.60 +	
80	1 PC RADIATOR BOTTOM HOSE	65.80 +	
81	1 PC RADIATOR COWLING <i>canled</i>	225.80 ✓	
82	1 PC RADIATOR FAN MOTOR ASSY <i>Damaged</i>	575.80 ✓	
83	2 PCS RADIATOR SIDE GARNISH <i>canled</i>	73.80 ✓	
84	1 PC RADIATOR UNDER COVER <i>new</i>	124.90 +	
85	1 PC FRT EXHAUST MANIFOLD <i>not cut</i>	488.90 +	
86	1 PC THROTTLE BODY <i>new</i>	822.10 +	
87	1 PC AIR CLEANER BOX ASSY <i>canled</i>	477.80 ✓	
88	1 PC AIR CLEANER OUTLET HOSE <i>behind</i>	69.20 ✓	
89	1 PC HORN <i>Bent</i>	104.20 ✓	
90	1 PC FRT WIPER WATER TANK <i>new</i>	106.70 +	
91	1 PC FRONT WIPER WATER TANK MOTOR <i>new</i>	228.70 +	
92	1 PC WIPER PANEL GARNISH <i>cut</i>	562.30 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06/ Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
93	1 PC WIPER PANEL GARNISH RH <i>missing</i>	81.40 ✓	
94	1 PC FRT STEERING WHEEL AIRBAG <i>} Activated</i>	2,156.50 ✓	
95	1 PC FRT STEERING WHEEL AIRBAG SENSORS	302.10 ✓	
96	1 PC AIRBAG CONTROL UNIT <i>} Activated</i>	905.80 ✓	
97	1 PC FRT RH SEAT BELT ASSY <i>} Activated</i>	744.60 ✓	
98	1 PC FRT LH SEAT BELT ASSY <i>} Activated</i>	744.60 ✓	
99	1 PC FRT AIRBAG IMPACT SENSOR <i>Activated</i>	302.10 ✓	
		29,459.30	
		Less 25%	7,364.83
			22,094.71
	Special Net		
100	1 PC REAR NUMBER PLATE <i>new</i>	50.00 ✓	
101	1 SET REAR FENDER INNER TRIM CLIPS <i>new</i>	48.00 <i>30</i>	
102	1 SET REAR FENDER INNER TRIM CLIPS RH <i>new</i>	48.00 <i>30</i>	
103	1 PC REAR WINDSCREEN SEAL <i>2 new</i>	60.00 <i>40</i>	
104	1 PC REAR WINDSCREEN SEALANT <i>2 new</i>	60.00 <i>40</i>	
105	1 SET REVERSE SENSORS <i>Damaged</i>	250.00 <i>200</i>	
106	1 SET REAR PANEL TRIM CLIPS <i>new</i>	48.00 <i>10</i>	
107	1 SET REAR BUMPER CLIPS <i>new</i>	60.00 <i>30</i>	
108	1 SET FRT FENDER COWLING CLIPS RH <i>2 new</i>	60.00 <i>+</i>	
109	1 SET FRT FENDER COWLING CLIPS LH <i>2 new</i>	60.00 <i>+</i>	
110	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	48.00 <i>20</i>	
111	1 PC FRT NUMBER PLATE <i>Best</i>	50.00 ✓	
112	1 SET FRT BUMPER CLIPS <i>new</i>	48.00 <i>30</i>	
113	1 SET FRT GRILLE CLIPS <i>new</i>	48.00 <i>15</i>	
114	1 SET FRT WIPER PANEL GARNISH CLIPS <i>new</i>	40.00 <i>20</i>	
		978.00	978.00
	Labour		
115	1 TO CHECK WIRING	50.00 <i>30</i>	
116	1 (REAR) TO REMOVE AND REFIX WINDSCREEN	120.00 ✓	
117	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 <i>80</i>	
118	1 TO REMOVE AND REFIT PETROL TANK	150.00 <i>80</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
119	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00 4	
120	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
121	1 TO SPRAY UNDERSEAL	200.00 80	
122	1 (REAR) TO SPRAY PAINTING	1,800.00 1400	
123	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,400.00 1650	1820
124	1 TOWING	100.00 60	
125	1 TO CHECK WIRING (FRT)	50.00 30	
126	1 TO REFILL AIRCON GAS	120.00 ✓	
127	1 TO SPRAY UNDERSEAL	180.00 50	
128	1 (FRONT) TO SPRAY PAINTING	1,800.00 1200	
129	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00 1200	
130	1 TO PROGRAM AND RESET	350.00 150	
131	1 TO REMOVE AND REFIT AIR BAG	500.00 300	
		9,850.00	9,850.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No liability for consequential damage
- Subject to final approval from insurance company

Acknowledged by Repairer

Signature: _____

Date: _____

Total S\$ 32,922.71

Add GST @ 7% 2,304.59

Total Amount Payable S\$ 35,227.30

TOTAL SINGAPORE DOLLAR THIRTY FIVE THOUSAND TWO HUNDRED TWENTY SEVEN AND CENTS THIRTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Handwritten notes: 15,74.42, A/S: 17K, (Nett Value), 4/5 25/04/19, 21 Pys.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	502C
Vehicle Details	
Vehicle No.:	SJR1681P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	INZX916593
Chassis No.:	MR053HY9305115627
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,047.00
Original Registration Date:	11 Jun 2009
First Registration Date:	11 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$12,047.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,943.00
COE Rebate Amount:	\$13,470.00
Total Rebate Amount:	\$13,470.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Aug 2019

OK

Print Received Message

This mail is associated with :

***SJR1681P (4048721030SG)
[SFQ420K]**

TP
YIP CHIN SIANG
Apr 23 2019 5:00PM
[OH CHENG FAI]
Kang Car Repairers Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 08/10/2019 09:59 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$19484.00) - SJR1681P - Claim Handler: Ler, Bernard-JQ

Approved:19484.00:Cost of Repair \$18,190.00 As per surveyor finalization Loss of Rental \$1,284.00 12 days @ S\$ 100/day + GST LTA/ GIA Search Fee \$10.00 Total \$19,484.00



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR0420191681AIG
Your Ref : SFQ420K

Date : **5 SEP 2019**

WITHOUT PREJUDICE

AIG Asia Pacific Insurance Pte Ltd
C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933
Attention : Motor Claim Department

Dear Sirs,

Accident involving SJR1681P and SFQ420K on 23.04.2019 along Alexandra Rd twds Pasir Panjang.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SFQ420K.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by Mr Yip Chin Siang, the owner of motor-vehicle no: SJR1681P, we submit his claim to you:

Cost of repairs (Inclusive of 7% GST)	\$ 18,190.00
Loss of rental (12 days x \$120.00 w/gst)	\$ 1,440.00
LTA search by Law Firm	\$ 10.00
	<u>\$ 19,642.00</u>
	=====

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1900494
- 2) GIA report and certificate insurance of SJR1681P
- 3) Rental Invoice and rental agreement
- 4) GIA search fee & invoice

We hope to receive your early reply soon.

Thank you.

Yours faithfully,

KANG CAR REPAIRERS PTE LTD

.....



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG19007419/Ahb3

24 JULY 2019

**OH CHENG FAI
BLOCK 32 KEPPEL BAY DRIVE
#02-54
SINGAPORE 098651**

Dear Sir/Madam,

ACCIDENT INVOLVING SFQ 420K / SJR 1681P / OTHERS ON 23/04/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,


Vic Alpeh
Case Handler

LKK Auto Consultants Pte Ltd
Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AIG

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)


I, Yip Chin Siang ("the third party claimant")
of Blk 27 Upper Boon Keng Road #05-658 (S) 384102 (address),
owner of SJR1681P (vehicle no.) hereby authorize
Kang Car Repairers Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJR1681P that was
damaged pursuant to the accident which occurred on 23.04.2019 (date) along
Alexandra Rd twds Pasir Panjang (location)
involving vehicle no/s SFQ420K ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment fortherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 24 day of Apr (month) 20 19 (year)

KANG CAR REPAIRERS PTE. LTD.


Signed by "the third party claimant"


Signed by "the workshop"

This Discharge Voucher applies strictly for Claimant's claim for ~~property~~ property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.
This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **KANG CAR REPAIRERS PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$19,480.00** (Global Sum – all in) for vehicle no. **SJR 1681P** that was damaged pursuant to the accident which occurred on **23/04/2019** (date) along **ALEXANDRA ROAD** (location) involving vehicle no/s **SFO 420K**. This is pursuant to the inspection conducted on **25/04/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **YIP CHIN SIANG** ("the third party claimant") of vehicle no. **SJR 1681P** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJR 1681P** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

- 8 OCT 2019

Dated this _____ (day) of _____ (month) 2019 (year)



LWP

Signed by appointed surveyor

KANG CAR REPAIRERS PTE LTD

Signed by "the workshop" (with chop)



江氏修理汽車私人有限公司

KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883

TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg

Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416

ATTN: Motor Claim Department

Your Ref No: SFQ420K

Claim Type: Third Party

Accident Date: 23/04/2019

TP Veh Reg No: SFQ420K

Final No: KCR-INV1900494
Claim No: EST1900105
Date: 29 Aug 2019
Policy No: 5095528363-01
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chassis No: MR053HY9305115627
Engine No: INZX916593
Reg. Date: 11/06/2009

Tax Invoice to Vehicle No :SJR1681P

Description

| Quantity |

List Price

SS

PAGE:1

Amount

SS

As recommended by surveyor to proceed repair at total cost/lumpsum cost	SS 17,000.00
Add GST @ 7%	1,190.00
Total Amount payable	SS 18,190.00

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND ONE HUNDRED NINETY ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
YIP CHIN SIANG BLK 2D UPPER BOON KENG ROAD #05-658 SINGAPORE 384002

DATE	INVOICE NO.
09-May-2019	A 39321

		VHA NO.	DUE DATE	VEH. NO.
		A 39321	09-May-2019	SLR 6343 J
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT	
RENTAL FROM 24 APRIL 2019 TO 06 MAY 2019 YOUR REF: SJR 1681 P	12	112.14917	1,345.79	
GST @ 7%			\$94.21	
TOTAL			\$1,440.00	

All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.



bizSAFE

VEHICLE HIRING AGREEMENT

HIRER'S PARTICULARS

Name (as in IC): CHIN SIAN BOO
 NRIC/Passport No: 5125502C Date of Birth: 25/4/1976
 Address: APT BIR 2D 4th Floor 100/101/102/103 Age: 30
#05-658 St: 329602
 Name & Address of Employer: _____
 Occupation: _____ Driving Exp: 30
 Driving Licence No: _____ Passed Date: 18/12/1998
 D/L Type: Local/Int'l/Other: _____
 Tel(O): _____ (R): _____ HP: 92251197

DRIVER'S PARTICULARS


Name (as in IC): _____
 NRIC/Passport No: _____ Date of Birth: _____
 Address: _____ Age: _____
 S() _____
 Occupation: _____ Driving Exp: _____ Yrs _____
 Driving Licence No: _____ Passed / Expiry Date: _____
 D/L Type: Local/Int'l/Other: _____ Contact No: _____

Hirer's Own Vehicle No: SIR 1671P Replace Veh No: SLR 6343J
 Loan Vehicle No: SGR 7841R VR No: 8427
 Make & Model: TOYOTA T-VIN Auto/Manual Group: _____
 CHARGES: \$ _____ cts
 Daily 12 day @ \$ 120 Per day 1440
 Weekly/Monthly week @ \$ _____ Per week/Monthly _____
 Others _____
 QDW/PAI @ \$ _____ Per day/Monthly _____
 Delivery/Collection Svc _____
 GST _____
 OR No: 18/12 (A) SUB-TOTAL \$1440
 Petrol Level: OUT E 1/4 1/2 3/4 F
 Surcharge: IN _____
 First _____ km FREE per day GST _____
 Excess mileage is chargeable at _____ cents per km TOTAL CHARGES _____

Security Deposit: \$ _____ Bank: _____
 CASH/NETS/VISA/MC/AMEX/CHQ No: _____
 Expiry Date: _____ Card ID No: _____
 Name as in Card: _____

NON-WAIVER EXCESS (Subject to GST): \$ 2000
ACCESSORIES CHECK
☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: Danny Additional Driver's Signature: _____
 SINGAPORE Use Only



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given by BKW Rent A Car Pte Ltd in connection with this agreement is true.

IMPORTANT

- The Hirer and the authorized driver must be over 25 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/Authorized Driver.
- All vehicles are supplied with petrol and should returned with petrol level (Reverse A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level).
- No refund for early return of vehicle. The Hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of QDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (for instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expenses (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserves the right not to replace an replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to bear all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The Hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is still and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other related matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
4/5/17	1550	3210	Abail	

Return of Vehicle: The Hirer Driver is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc.)

Date In	Time In	Mileage	Check By	Remarks
6/5/17				

Hirer's/Driver Signature

Hirer's/Driver Signature

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : KANG CAR REPAIRERS PTE LTD	BILL NO: B045 /2019
YOUR REF:	
OUR REF : ACS.KC.LTA.APR & MAR.2019	DATE : 3/6/19

TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.

(I) LTA SEARCHES FOR THE MONTH APRIL 2019

1. FBJ 4401Z as at 5.4.19	\$10.00
2. SFQ 420K as at 23.4.19	\$10.00
3. SLX 4007L as at 13.4.19	\$10.00 \$ 30.00


(II) LTA SEARCHES FOR THE MONTH MAY 2019

1. ET 169H as at 29.5.19	\$10.00
2. SKS 9973C as at 26.5.19	\$10.00
3. WC 6222Z as at 9.5.19	\$10.00 \$ 30.00

Total:

\$ 60.00

[SINGAPORE DOLLARS: SIXTY ONLY.]



M/s A C SYED & PARTNERS
ADVOCATES & SOLICITORS
SINGAPORE

We reserved the right to forward a subsequent bill for any disbursements omitted herein.

E. & O.E.

Enquire Vehicle & Owner Information (Vehicle No. SFQ420K As At 23 Apr 2019 / 17:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: ACS.KC.LTA.04.19

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S7178127E
Owner Name: OH CHENG FAI
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 32
Registered Street Name: KEPPEL BAY DRIVE
Registered Unit No.: # 02 - 54
Registered Building Name: CARIBBEAN AT KEPPEL BAY
Registered Postal Code: 098651

Current Vehicle Details

Vehicle No.: SFQ420K
Make Description/Model: LAND ROVER / RANGE ROVER EVOQUE 2.0 T55 5R
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Apr 2019 Edit Reg		25 Apr 2019 00:00 Edit Adj Rpt	S\$17,000.00 Edit Estimates	S\$17,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	OH CHENG FAI, ID: S7178127E		
Main Claimant:	YIP CHIN SIANG, Co. Reg. No.: S1735502C		
Vehicle Reg. No.:	SJR1681P	Date of Loss:	23/04/2019 17:00 - :59 [118 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4048721030SG	Policy/Cover Note No.:	2100376469 (Comprehensive)
Vehicle Reg. No. (Insured):	SFQ420K	Policy No. (Claimant):	S095528363-01
		Excess:	
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/05/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (08/10/2019): Alert - Adj Mandate Approved (S\$19484.00) - SJR1681P - Claim Handler: Ler, Berna...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR1681P (40487210305G)
[SFQ420K]
TP
YIP CHIN SIANG
Apr 23 2019 5:00PM
[OH CHENG FAI]
Kang Car Repairers Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
Letters/Correspondences						1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit			
Photos/Images						3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/08/19 09:24	General View		Load JPG	☒		
2	01/08/19 09:24	General View		Load JPG	☒		
3	01/08/19 09:24	General View		Load JPG	☒		
4	01/08/19 09:24	General View		Load JPG	☒		
5	01/08/19 09:24	General View		Load JPG	☒		
6	01/08/19 09:24	General View		Load JPG	☒		
7	01/08/19 09:24	General View		Load JPG	☒		
8	01/08/19 09:24	General View		Load JPG	☒		
9	01/08/19 09:24	General View		Load JPG	☒		
10	01/08/19 09:24	General View		Load JPG	☒		
11	01/08/19 09:24	General View		Load JPG	☒		
12	01/08/19 09:24	General View		Load JPG	☒		
13	01/08/19 09:24	General View		Load JPG	☒		
14	01/08/19 09:24	General View		Load JPG	☒		
15	01/08/19 09:24	General View		Load JPG	☒		
16	01/08/19 09:24	General View		Load JPG	☒		
17	01/08/19 09:24	General View		Load JPG	☒		
18	01/08/19 09:24	General View		Load JPG	☒		
19	01/08/19 09:24	General View		Load JPG	☒		
20	01/08/19 09:24	General View		Load JPG	☒		
21	01/08/19 09:24	General View		Load JPG	☒		
22	01/08/19 09:24	General View		Load JPG	☒		
23	01/08/19 09:24	General View		Load JPG	☒		
24	01/08/19 09:24	General View		Load JPG	☒		
25	01/08/19 09:24	General View		Load JPG	☒		
26	01/08/19 09:24	General View		Load JPG	☒		
27	01/08/19 09:24	General View		Load JPG	☒		
28	01/08/19 09:24	General View		Load JPG	☒		
29	01/08/19 09:24	General View		Load JPG	☒		
30	01/08/19 09:24	General View		Load JPG	☒		
31	01/08/19 09:24	General View		Load JPG	☒		
32	01/08/19 09:24	General View		Load JPG	☒		
33	01/08/19 09:24	General View		Load JPG	☒		
34	01/08/19 09:24	General View		Load JPG	☒		
35	01/08/19 09:24	General View		Load JPG	☒		
36	01/08/19 09:24	General View		Load JPG	☒		
37	01/08/19 09:24	General View		Load JPG	☒		
38	01/08/19 09:24	General View		Load JPG	☒		
39	01/08/19 09:24	General View		Load JPG	☒		
40	01/08/19 09:24	General View		Load JPG	☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	01/08/19 09:24	General View	 Load JPG	☒
42	01/08/19 09:24	General View	 Load JPG	☒
43	01/08/19 09:24	General View	 Load JPG	☒
44	01/08/19 09:24	General View	 Load JPG	☒
45	01/08/19 09:24	General View	 Load JPG	☒
46	01/08/19 09:24	General View	 Load JPG	☒
47	01/08/19 09:24	General View	 Load JPG	☒
48	01/08/19 09:24	General View	 Load JPG	☒
49	01/08/19 09:24	General View	 Load JPG	☒
50	01/08/19 09:24	General View	 Load JPG	☒
51	01/08/19 09:24	General View	 Load JPG	☒
52	01/08/19 09:24	General View	 Load JPG	☒
53	01/08/19 09:24	General View	 Load JPG	☒
54	01/08/19 09:24	General View	 Load JPG	☒
55	01/08/19 09:24	General View	 Load JPG	☒
56	01/08/19 09:24	General View	 Load JPG	☒
57	01/08/19 09:24	General View	 Load JPG	☒
58	01/08/19 09:24	General View	 Load JPG	☒
59	01/08/19 09:24	General View	 Load JPG	☒
60	01/08/19 09:24	General View	 Load JPG	☒
61	01/08/19 09:24	General View	 Load JPG	☒
62	01/08/19 09:24	General View	 Load JPG	☒
63	01/08/19 09:24	General View	 Load JPG	☒
64	01/08/19 09:24	General View	 Load JPG	☒
65	01/08/19 09:24	General View	 Load JPG	☒
66	01/08/19 09:24	General View	 Load JPG	☒
67	01/08/19 09:24	General View	 Load JPG	☒
68	01/08/19 09:24	General View	 Load JPG	☒
69	01/08/19 09:24	General View	 Load JPG	☒
70	01/08/19 09:24	General View	 Load JPG	☒
71	01/08/19 09:24	General View	 Load JPG	☒
72	01/08/19 09:24	General View	 Load JPG	☒
73	01/08/19 09:24	General View	 Load JPG	☒
74	01/08/19 09:24	General View	 Load JPG	☒
75	01/08/19 09:24	General View	 Load JPG	☒
76	01/08/19 09:24	General View	 Load JPG	☒
77	01/08/19 09:24	General View	 Load JPG	☒
78	01/08/19 09:24	General View	 Load JPG	☒
79	01/08/19 09:24	General View	 Load JPG	☒
80	01/08/19 09:24	General View	 Load JPG	☒
81	01/08/19 09:24	General View	 Load JPG	☒
82	01/08/19 09:24	General View	 Load JPG	☒
83	01/08/19 09:24	General View	 Load JPG	☒
84	01/08/19 09:24	General View	 Load JPG	☒
85	01/08/19 09:24	General View	 Load JPG	☒
86	01/08/19 09:24	General View	 Load JPG	☒
87	01/08/19 09:24	General View	 Load JPG	☒
88	01/08/19 09:24	General View	 Load JPG	☒
89	01/08/19 09:24	General View	 Load JPG	☒
90	01/08/19 09:24	General View	 Load JPG	☒
91	01/08/19 09:24	General View	 Load JPG	☒
92	01/08/19 09:24	General View	 Load JPG	☒
93	01/08/19 09:24	General View	 Load JPG	☒
94	01/08/19 09:24	General View	Load JPG	☒
95	01/08/19 09:24	General View	Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
96	01/08/19 09:24	General View	 Load JPG	☒	
97	01/08/19 09:24	General View	 Load JPG	☒	
98	01/08/19 09:24	General View	 Load JPG	☒	
99	01/08/19 09:24	General View	 Load JPG	☒	
100	01/08/19 09:24	General View	 Load JPG	☒	
101	01/08/19 09:24	General View	 Load JPG	☒	
102	01/08/19 09:24	General View	 Load JPG	☒	
103	01/08/19 09:24	General View	 Load JPG	☒	
104	01/08/19 09:24	General View	 Load JPG	☒	
105	01/08/19 09:24	General View	 Load JPG	☒	
106	01/08/19 09:24	General View	 Load JPG	☒	
107	01/08/19 09:24	General View	 Load JPG	☒	
108	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
109	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
110	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
111	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
112	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
113	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
114	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
115	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
116	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
117	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
118	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
119	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
120	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
121	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
122	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
123	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
124	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
125	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
126	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
127	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
128	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
129	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
130	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
131	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
132	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
133	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
134	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
135	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
136	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
137	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
138	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
139	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
140	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
141	01/08/19 09:25	Reinspection Photo	 Load JPG	☒	
142	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
143	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
144	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
145	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
146	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
147	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
148	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
149	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
150	01/08/19 09:25	Reinspection Photo	Load JPG	☒	
151	01/08/19 09:25	Reinspection Photo	Load JPG	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
152	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
153	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
154	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
155	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
156	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
157	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
158	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
159	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
160	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
161	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
162	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
163	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
164	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
165	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
166	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
167	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
168	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
169	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
170	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
171	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
172	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
173	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
174	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
175	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
176	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
177	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
178	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
179	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
180	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
181	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
182	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
183	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
184	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
185	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
186	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
187	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
188	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
189	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
190	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
191	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
192	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
193	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
194	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
195	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
196	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
197	01/08/19 09:25	Reinspection Photo	 Load JPG	☒
198	01/08/19 09:25	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/04/19 18:06	TP GIA REPORT	 Load PDF	
2	24/07/19 14:09	LETTER TO OI	 Load PDF	
3	01/08/19 11:33	TP ESTIMATE - FINALIZED	 Load PDF	
4	27/09/19 14:42	RENTAL RECEIPT	 Load PDF	
5	27/09/19 14:42	LTA SEARCH	 Load PDF	
6	27/09/19 14:42	LOD	 Load PDF	
7	17/10/19 11:09	WORKSHOP INVOICE	 Load PDF	
8	17/10/19 11:09	AUTHORISATION TO ACT FORM	 Load PDF	

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
9	17/10/19 11:09	LKK Auto Consultants Pte Ltd (HQ)	Release Voucher		Load PDF
No	Finalized On			Thumbnail	Print
1	29/04/19 12:23	AIG Asia Pacific Insurance Pte. Ltd. (SG)	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFQ420K (Insd veh)	Model:	TOYOTA VIOS 1.5 J (A)
	SJR1681P (TP veh)		
Date of Accident:	23/04/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	35,227.04
Final Repair Cost	:	\$	19,480.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	12 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	19,480.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 19,480.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

17 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19007419/AHB3Q2

Date: 17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100376469
 Claimant Vehicle No: SJR1681P Insured Vehicle No: SFQ420K
 Date of Loss: 23/04/2019 Nature of Claim: TP Claim No: 4048721030SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR1681P**
 Make & Model: TOYOTA VIOS, 1.5 J (A) Engine No: INZX916593
 Reg. Date: 11/06/2009 (Man. Year: 2009) Chassis No: MR053HY9305115627
 Colour: Silver Odometer: 279567 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
 Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,072.47	18,472.17	4,600.30	19.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,850.00	6,750.00	3,100.00	31.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,922.47	25,222.17	7,700.30	23.39
Approved Total (Overridden) (S\$)		17,000.00		
(S\$)	32,922.47	17,000.00	15,922.47	48.36
+ GST 7.00/7.00% (S\$)	2,304.57	1,190.00	1,114.57	48.36
Nett Amount (S\$)	35,227.04	18,190.00	17,037.04	48.36
+ Car Rental (12.0 x S\$100.00/day + 7.00% GST) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		10.00		
Nett Liability (S\$)		19,484.00		
Global Sum Settlement (S\$)		19,480.00		

INSPECTION

Date of Assignment: 25/04/2019
 Date Inspected: 25/04/2019 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06
 AutoBay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	584.90 FL	*584.90 FL
2	2		*BOOT LID HINGE	Bent	135.80 FL	*135.80 FL
3	1		*BOOTLID LOGO	Necessary	47.70 FL	*47.70 FL
4	1		*BOOT LID VIOS EMBLEM	Necessary	44.20 FL	*44.20 FL
5	1		*BOOTLID J EMBLEM	Necessary	34.40 FL	*34.40 FL
6	1		*BOOTLID OUTER KEY LOCK	Not Necessary	98.90 FL	*- FL
7	1		*BOOTLID INNER LOCK	Damaged	165.90 FL	*165.90 FL
8	1		*BOOT LID INNER LOCK CHECKER	Bent	38.40 FL	*38.40 FL
9	1		*BOOT LID GARNISH	Deformed	145.70 FL	*145.70 FL
10	2		*REAR NUMBER PLATE LAMP	Not Necessary	113.80 FL	*- FL
11	1		*BOOT LID RUBBER	Cut	175.30 FL	*175.30 FL
12	1		*REAR FENDER LH	Buckled	864.80 FL	*864.80 FL
13	1		*REAR FENDER INNER TRIM LH	Deformed	224.20 FL	*224.20 FL
14	1		*REAR FENDER MUDFLAP LH	Not Necessary	45.60 FL	*- FL
15	1		*REAR DOOR LOCK LH	Not Necessary	246.60 FL	*- FL
16	1		*REAR DOOR RUBBER LH	Not Necessary	166.70 FL	*- FL
17	1		*REAR FENDER RH	Buckled	864.80 FL	*864.80 FL
18	1		*REAR FENDER INNER TRIM RH	Deformed	224.20 FL	*224.20 FL
19	1		*REAR DOOR LOCK RH	Not Necessary	246.60 FL	*- FL
20	1		*REAR DOR RUBBER RH	Not Necessary	166.70 FL	*- FL
21	1		*REAR FENDER MUDFLAP RH	Not Necessary	45.60 FL	*- FL
22	1		*REAR WINDSCREEN RUBBER	Necessary	96.70 FL	*96.70 FL
23	1		*TAIL LAMP -RH	Cracked	409.90 FL	*409.90 FL
24	1		*TAIL LAMP PANEL RH	Buckled	105.10 FL	*105.10 FL
25	1		*TAIL LAMP LH	Cracked	409.90 FL	*409.90 FL
26	1		*TAIL LAMP PANEL LH	Buckled	105.10 FL	*105.10 FL
27	1		*REAR PANEL	Distorted	571.80 FL	*571.80 FL
28	1		*REAR PANEL TRIM	Deformed	200.70 FL	*200.70 FL
29	1		*SPARE TYRE PANEL	Repair	637.80 FL	*- FL
30	1		*SPARE TYRE COVER	Torn	144.70 FL	*144.70 FL
31	1		*SPARE TYRE PANEL RH SPONGE	Deformed	214.10 FL	*214.10 FL
32	1		*SPARE TYRE PANEL LH SPONGE	Deformed	214.10 FL	*214.10 FL
33	1		*SPARE TYRE PANEL INNER SPONGE	Cracked	132.30 FL	*132.30 FL
34	2		*SPARE TYRE SIDE SMALL COVER	Not Necessary	131.20 FL	*- FL
35	1		*SPARE TYRE RH SIDE PANEL	Repair	166.70 FL	*- FL
36	1		*SPARE TYRE LH SIDE PANEL	Repair	166.70 FL	*- FL
37	1		*REAR BUMPER	Distorted	467.50 FL	*467.50 FL
38	1		*REAR BUMPER BRACKET	Bent	127.40 FL	*127.40 FL
39	1		*REAR BUMPER REFLECTOR -RH	Cracked	82.80 FL	*82.80 FL
40	1		*REAR BUMPER REFLECTOR -LH	Cracked	82.80 FL	*82.80 FL
41	2		*REAR BUMPER SIDE RETAINER	Necessary	184.60 FL	*184.60 FL
42	2		*REAR BUMPER SMALL RETAINER	Necessary	64.20 FL	*64.20 FL
43	1		*EXHAUST PIPE	Repair	595.20 FL	*- FL
44	2		*EXHAUST PIPE MOUNTING	Not Necessary	57.80 FL	*- FL
45	1		*BONNET	Buckled	471.40 FL	*471.40 FL
46	2		*BONNET HINGE	Bent	88.60 FL	*88.60 FL
47	1		*BONNET LOCK	Damaged	82.30 FL	*82.30 FL
48	1		*BONNET LOCK CABLE	Not Necessary	64.90 FL	*- FL
49	2		*BONNET RUBBER	Not Necessary	102.40 FL	*- FL
50	1		*FRT FENDER RH	Buckled	530.10 FL	*530.10 FL
51	1		*FRT FENDER COWLING RH	Not Necessary	148.90 FL	*- FL
52	1		*FRT FENDER VVTI EMBLEM	Necessary	44.80 FL	*44.80 FL
53	1		*FRT FENDER LH	Buckled	530.10 FL	*530.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRT FENDER COWLING LH	Not Necessary	148.90 FL	*- FL
55	1		*FRT FENDER VVTI EMBLEM LH	Necessary	44.80 FL	*44.80 FL
56	1		*FRT SUPPORT PANEL	Distorted	788.60 FL	*788.60 FL
57	1		*FRT BUMPER	Distorted	467.30 FL	*467.30 FL
58	1		*FRT BUMPER REINFORCEMENT	Bent	372.10 FL	*372.10 FL
59	2		*FRT BUMPER BRACKET	Bent	423.20 FL	*423.20 FL
60	1		*FRT BUMPER TOP BRACKET	Distorted	121.40 FL	*121.40 FL
61	2		*FRT BUMPER SIDE RETAINER	Necessary	109.60 FL	*109.60 FL
62	1		*FRT BUMPER GRILLE	Cracked	74.80 FL	*74.80 FL
63	1		*FRT FOGLAMP COVER RH	Not Necessary	85.50 FL	*- FL
64	1		*FRT FOG LAMP COVER LH	Not Necessary	85.50 FL	*- FL
65	1		*FRT TOWING COVER	Deformed	28.20 FL	*28.20 FL
66	1		*FRT GRILLE	Cracked	350.40 FL	*350.40 FL
67	1		*FRT GRILLE EMBLEM	Necessary	50.80 FL	*50.80 FL
68	1		*FRT GRILLE CHROME	Cracked	121.40 FL	*121.40 FL
69	1		*HEADLAMP LH	Cracked	525.30 FL	*525.30 FL
70	1		*HEADLAMP PANEL RH	Bent	95.50 FL	*95.50 FL
71	1		*HEADLAMP RH	Cracked	525.30 FL	*525.30 FL
72	1		*HEADLAMP PANEL LH	Bent	95.50 FL	*95.50 FL
73	1		*AIR CONDENSER	Dented	1,026.60 FL	*1,026.60 FL
74	1		*FRT AIR CONDENSER BOTTOM MOUNTING	Not Necessary	48.80 FL	*- FL
75	1		*FRT AIR SUCTION PIPE	Not Necessary	286.10 FL	*- FL
76	1		*AIRCON DISCHARGE HOSE	Bent	388.90 FL	*388.90 FL
77	1		*FRT AIRCON LIQUID PIPE	Not Necessary	271.70 FL	*- FL
78	1		*RADIATOR	Dented	1,607.00 FL	*1,607.00 FL
79	1		*RADIATOR TOP HOSE	Not Necessary	39.60 FL	*- FL
80	1		*RADIATOR BOTTOM HOSE	Not Necessary	65.80 FL	*- FL
81	1		*RADIATOR COWLING	Cracked	225.80 FL	*225.80 FL
82	1		*RADIATOR FAN MOTOR ASSY	Damaged	575.80 FL	*575.80 FL
83	2		*RADIATOR SIDE GARNISH	Cracked	73.80 FL	*73.80 FL
84	1		*RADIATOR UNDER COVER	Not Necessary	124.90 FL	*- FL
85	1		*FRT EXHAUST MANIFOLD	Cut	488.90 FL	*488.90 FL
86	1		*THROTTLE BODY	Not Necessary	822.10 FL	*- FL
87	1		*AIR CLEANER BOX ASSY	Cracked	477.80 FL	*477.80 FL
88	1		*AIR CLEANER OUTLET HOSE	Deformed	69.20 FL	*69.20 FL
89	1		*HORN	Bent	104.20 FL	*104.20 FL
90	1		*FRT WIPER WATER TANK	Not Necessary	106.70 FL	*- FL
91	1		*FRONT WIPER WATER TANK MOTOR	Not Necessary	228.70 FL	*- FL
92	1		*WIPER PANEL GARNISH	Cut	562.30 FL	*562.30 FL
93	1		*WIPER PANEL GARNISH RH	Missing	81.40 FL	*81.40 FL
94	1		*FRT STEERING WHEEL AIRBAG	Activated	2,156.50 FL	*2,156.50 FL
95	1		*FRT STEERING WHEEL AIRBAG SENSORS	Activated	302.10 FL	*302.10 FL
96	1		*AIRBAG CONTROL UNIT	Activated	905.80 FL	*905.80 FL
97	1		*FRT RH SEAT BELT ASSY	Activated	744.60 FL	*744.60 FL
98	1		*FRT LH SEAT BELT ASSY	Activated	744.60 FL	*744.60 FL
99	1		*FRT AIRBAG IMPACT SENSOR	Activated	302.10 FL	*302.10 FL
100	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
101	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	48.00 FS	*30.00 FS
102	1		*SET REAR FENDER INNER TRIM CLIPS RH	Necessary	48.00 FS	*30.00 FS
103	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*40.00 FS
104	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
105	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
106	1		*SET REAR PANEL TRIM CLIPS	Necessary	48.00 FS	*10.00 FS
107	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
108	1		*SET FRT FENDER COWLING CLIPS RH	Not Necessary	60.00 FS	*- FS
109	1		*SET FRT FENDER COWLING CLIPS LH	Not Necessary	60.00 FS	*- FS
110	1		*SET FRT BUMPER GRILLE CLIPS	Necessary	48.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
111	1		*FRT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
112	1		*SET FRT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
113	1		*SET FRT GRILLE CLIPS	Necessary	48.00 FS	*15.00 FS
114	1		*SET FRT WIPER PANEL GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,437.30	24,457.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,364.83	5,985.73
Total Parts (\$\$)	23,072.47	18,472.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	(REAR) TO REMOVE AND REFIX WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REFIT SEAT CUSHION	New	200.00	80.00
4	TO REMOVE AND REFIT PETROL TANK	New	150.00	80.00
5	TO REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	0.00
6	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
7	TO SPRAY UNDERSEAL	New	200.00	80.00
8	(REAR) TO SPRAY PAINTING	New	1,800.00	1,400.00
9	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	2,400.00	1,800.00
10	TOWING	New	100.00	60.00
11	TO CHECK WIRING (FRT)	New	50.00	30.00
12	TO REFILL AIRCON GAS	New	120.00	120.00
13	TO SPRAY UNDERSEAL	New	180.00	50.00
14	(FRONT) TO SPRAY PAINTING	New	1,800.00	1,200.00
15	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,600.00	1,200.00
16	TO PROGRAM AND RESET	New	350.00	150.00
17	TO REMOVE AND REFIT AIR BAG	New	500.00	300.00
Gross Labour Cost (S\$)			9,850.00	6,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >