

Kang Car Repairers Pte Ltd

55022

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Vic

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented</i>	584.90	✓
2	2 PCS BOOT LID HINGE <i>Bent</i>	135.80	✓
3	1 PC BOOTLID LOGO	47.70	✓
4	1 PC BOOT LID "VIOS" EMBLEM <i>3 new</i>	44.20	✓
5	1 PC BOOTLID "J" EMBLEM	34.40	✓
6	1 PC BOOTLID OUTER KEY LOCK <i>new</i>	98.90	✓
7	1 PC BOOTLID INNER LOCK <i>2 new</i>	165.90	✓
8	1 PC BOOT LID INNER LOCK CHECKER <i>Bent</i>	38.40	✓
9	1 PC BOOT LID GARNISH <i>Replaced</i>	145.70	✓
10	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	113.80	✓
11	1 PC BOOT LID RUBBER <i>at</i>	175.30	✓
12	1 PC REAR FENDER LH <i>Buckled</i>	864.80	✓
13	1 PC REAR FENDER INNER TRIM LH <i>Replaced</i>	224.20	✓
14	1 PC REAR FENDER MUDFLAP LH <i>new</i>	45.60	✓
15	1 PC REAR DOOR LOCK LH <i>new</i>	246.60	✓
16	1 PC REAR DOOR RUBBER LH <i>new</i>	166.70	✓
17	1 PC REAR FENDER RH <i>Buckled</i>	864.80	✓
18	1 PC REAR FENDER INNER TRIM RH <i>Replaced</i>	224.20	✓
19	1 PC REAR DOOR LOCK RH <i>3 new</i>	246.60	✓
20	1 PC REAR DOOR RUBBER RH	166.70	✓
21	1 PC REAR FENDER MUDFLAP RH <i>new</i>	45.60	✓
22	1 PC REAR WINDSCREEN RUBBER <i>new</i>	96.70	✓
23	1 PC TAIL LAMP - RH <i>cracked</i>	409.90	✓
24	1 PC TAIL LAMP PANEL RH <i>Replaced Buckled</i>	105.10	✓
25	1 PC TAIL LAMP LH <i>cracked</i>	409.90	✓
26	1 PC TAIL LAMP PANEL LH <i>Buckled</i>	105.10	✓
27	1 PC REAR PANEL <i>Disturbed</i>	571.80	✓
28	1 PC REAR PANEL TRIM <i>Replaced</i>	200.70	✓
29	1 PC SPARE TYRE PANEL <i>Repair</i>	637.80	✓
30	1 PC SPARE TYRE COVER <i>turn</i>	144.70	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
31	1 PC SPARE TYRE PANEL RH SPONGE <i>Reformed</i>	214.10 ✓	
32	1 PC SPARE TYRE PANEL LH SPONGE	214.10 ✓	
33	1 PC SPARE TYRE PANEL INNER SPONGE <i>cracked</i>	132.30 ✓	
34	2 PCS SPARE TYRE SIDE SMALL COVER <i>new</i>	131.20 +	
35	1 PC SPARE TYRE RH SIDE PANEL <i>Reformed</i>	166.70 +	
36	1 PC SPARE TYRE LH SIDE PANEL <i>Reformed</i>	166.70 +	
37	1 PC REAR BUMPER <i>Distorted</i>	467.50 ✓	
38	2 PCS REAR BUMPER BRACKET <i>Best</i>	127.40 ✓	
39	1 PC REAR BUMPER REFLECTOR - RH <i>cracked</i>	82.80 ✓	
40	1 PC REAR BUMPER REFLECTOR - LH <i>cracked</i>	82.80 ✓	
41	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	184.60 ✓	
42	2 PCS REAR BUMPER SMALL RETAINER	64.20 ✓	
43	1 PC EXHAUST PIPE <i>Reformed</i>	595.20 +	
44	2 PCS EXHAUST PIPE MOUNTING <i>new</i>	57.80 +	
45	1 PC BONNET <i>Buckled</i>	471.40 ✓	
46	2 PCS BONNET HINGE <i>Best</i>	88.60 ✓	
47	1 PC BONNET LOCK <i>Reformed</i>	82.30 ✓	
48	1 PC BONNET LOCK CABLE <i>new</i>	64.90 +	
49	2 PCS BONNET RUBBER <i>new</i>	102.40 +	
50	1 PC FRT FENDER RH <i>Buckled</i>	530.10 ✓	
51	1 PC FRT FENDER COWLING RH <i>new</i>	148.90 +	
52	1 PC FRT FENDER "VVTI" EMBLEM <i>new</i>	44.80 ✓	
53	1 PC FRT FENDER LH <i>Buckled</i>	530.10 ✓	
54	1 PC FRT FENDER COWLING LH <i>new</i>	148.90 +	
55	1 PC FRT FENDER "VVTI" EMBLEM LH <i>new</i>	44.80 ✓	
56	1 PC FRT SUPPORT PANEL <i>Distorted</i>	788.60 ✓	
57	1 PC FRT BUMPER <i>Distorted</i>	467.30 ✓	
58	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	372.10 ✓	
59	2 PCS FRT BUMPER BRACKET <i>Best</i>	423.20 ✓	
60	1 PC FRT BUMPER TOP BRACKET <i>Distorted</i>	121.40 ✓	
61	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	109.60 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
62	1 PC FRT BUMPER GRILLE <i>cancel</i>	74.80 ✓	
63	1 PC FRT FOG LAMP COVER RH <i>3 per a</i>	85.50 +	
64	1 PC FRT FOG LAMP COVER LH	85.50 +	
65	1 PC FRT TOWING COVER <i>beh d</i>	28.20 ✓	
66	1 PC FRT GRILLE <i>cancel</i>	350.40 ✓	
67	1 PC FRT GRILLE EMBLEM <i>new</i>	50.80 ✓	
68	1 PC FRT GRILLE CHROME <i>cancel</i>	121.40 ✓	
69	1 PC HEADLAMP LH <i>cancel</i>	525.30 ✓	
70	1 PC HEADLAMP PANEL RH <i>Best</i>	95.50 ✓	
71	1 PC HEADLAMP RH <i>cancel</i>	525.30 ✓	
72	1 PC HEADLAMP PANEL LH <i>Best</i>	95.50 ✓	
73	1 PC AIR CONDENSER <i>Dented</i>	1,026.60 ✓	
74	2 PCS FRT AIR CONDENSER BOTTOM MOUNTING <i>new</i>	48.80 +	
75	1 PC FRT AIR SUCTION PIPE <i>2 new</i>	286.10 +	
76	1 PC AIRCON DISCHARGE HOSE <i>new Best</i>	388.90 ✓	
77	1 PC FRT AIRCON LIQUID PIPE <i>new</i>	271.70 +	
78	1 PC RADIATOR <i>Dented</i>	1,607.00 ✓	
79	1 PC RADIATOR TOP HOSE <i>3 per a</i>	39.60 +	
80	1 PC RADIATOR BOTTOM HOSE	65.80 +	
81	1 PC RADIATOR COWLING <i>cancel</i>	225.80 ✓	
82	1 PC RADIATOR FAN MOTOR ASSY <i>Dented</i>	575.80 ✓	
83	2 PCS RADIATOR SIDE GARNISH <i>cancel</i>	73.80 ✓	
84	1 PC RADIATOR UNDER COVER <i>new</i>	124.90 +	
85	1 PC FRT EXHAUST MANIFOLD <i>new cut</i>	488.90 +	
86	1 PC THROTTLE BODY <i>new</i>	822.10 +	
87	1 PC AIR CLEANER BOX ASSY <i>cancel</i>	477.80 ✓	
88	1 PC AIR CLEANER OUTLET HOSE <i>beh d</i>	69.20 ✓	
89	1 PC HORN <i>Best</i>	104.20 ✓	
90	1 PC FRT WIPER WATER TANK <i>new</i>	106.70 +	
91	1 PC FRONT WIPER WATER TANK MOTOR <i>new</i>	228.70 +	
92	1 PC WIPER PANEL GARNISH <i>cut</i>	562.30 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
93	1 PC WIPER PANEL GARNISH RH <i>missing</i>	81.40 ✓	
94	1 PC FRT STEERING WHEEL AIRBAG <i>Activated</i>	2,156.50 ✓	
95	1 PC FRT STEERING WHEEL AIRBAG SENSORS <i>Activated</i>	302.10 ✓	
96	1 PC AIRBAG CONTROL UNIT <i>Activated</i>	905.80 ✓	
97	1 PC FRT RH SEAT BELT ASSY <i>Activated</i>	744.60 ✓	
98	1 PC FRT LH SEAT BELT ASSY <i>Activated</i>	744.60 ✓	
99	1 PC FRT AIRBAG IMPACT SENSOR <i>Activated</i>	302.10 ✓	
		29,459.30	
	Less 25%	7,364.83	22,094.71
	Special Net		
100	1 PC REAR NUMBER PLATE <i>new</i>	50.00 ✓	
101	1 SET REAR FENDER INNER TRIM CLIPS <i>new</i>	48.00 <i>30</i>	
102	1 SET REAR FENDER INNER TRIM CLIPS RH <i>new</i>	48.00 <i>30</i>	
103	1 PC REAR WINDSCREEN SEAL <i>new</i>	60.00 <i>40</i>	
104	1 PC REAR WINDSCREEN SEALANT <i>new</i>	60.00 <i>40</i>	
105	1 SET REVERSE SENSORS <i>Damaged</i>	250.00 <i>200</i>	
106	1 SET REAR PANEL TRIM CLIPS <i>new</i>	48.00 <i>10</i>	
107	1 SET REAR BUMPER CLIPS <i>new</i>	60.00 <i>30</i>	
108	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	60.00 ✓	
109	1 SET FRT FENDER COWLING CLIPS LH <i>new</i>	60.00 ✓	
110	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	48.00 <i>20</i>	
111	1 PC FRT NUMBER PLATE <i>Best</i>	50.00 ✓	
112	1 SET FRT BUMPER CLIPS <i>new</i>	48.00 <i>30</i>	
113	1 SET FRT GRILLE CLIPS <i>new</i>	48.00 <i>15</i>	
114	1 SET FRT WIPER PANEL GARNISH CLIPS <i>new</i>	40.00 <i>20</i>	
		978.00	978.00
	Labour		
115	1 TO CHECK WIRING	50.00 <i>30</i>	
116	1 (REAR) TO REMOVE AND REFIX WINDSCREEN	120.00 ✓	
117	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 <i>80</i>	
118	1 TO REMOVE AND REFIT PETROL TANK	150.00 <i>80</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SFQ420K

Estimate No: EST1900105
Date: 25 Apr 2019
Veh Reg No: SJR1681P
Make/Model: TOYOTA VIOS J AUTO
Chasis No: MR053HY9305115627
Reg. Date: 11/06/2009
Your Ref No: SFQ420K

Estimate Repair Cost to Vehicle No :SJR1681P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
119	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00 150.00	
120	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 80.00 50	
121	1 TO SPRAY UNDERSEAL	200.00 200.00 80	
122	1 (REAR) TO SPRAY PAINTING	1,800.00 1,800.00 1400	
123	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,400.00 2,400.00 1800	
124	1 TOWING	100.00 100.00 60	
125	1 TO CHECK WIRING (FRT)	50.00 50.00 30	
126	1 TO REFILL AIRCON GAS	120.00 120.00 ✓	
127	1 TO SPRAY UNDERSEAL	180.00 180.00 50	
128	1 (FRONT) TO SPRAY PAINTING	1,800.00 1,800.00 1200	
129	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00 1,600.00 1200	
130	1 TO PROGRAM AND RESET	350.00 350.00 150	
131	1 TO REMOVE AND REFIT AIR BAG	500.00 500.00 300	
		9,850.00	9,850.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supply and installation of parts and labour is subject to final approval from insurance Company

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

Acknowledged by Repairer
Signature:
Date:

Signature: L.S. 24.42

A/S: 17K (Nett Value)

Adrian L
4/s 25/04/19
21 Pgs.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Total S\$ 32,922.71
Add GST @ 7% 2,304.59
Total Amount Payable S\$ 35,227.30

TOTAL SINGAPORE DOLLAR THIRTY FIVE THOUSAND TWO HUNDRED TWENTY SEVEN AND CENTS THIRTY ONLY