

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date: 26/04/2019

TO:

EQ Insurance Compnay Ltd

5 Maxwell Road

#17-00 Tower Block, MND Complex

Singapore 069110

Cilia

Our Customer: Chung Kwang Nam

Vehicle No: SKU2611H

Model: Posche Panamera

Manufacture Year: 2011

Date of Accident: 25/4/2019

Total Estimate Repair Days: 7

Total Pages: 1 WP0222972CL000519.

Re: Repair Estimate For Third Party Claim against SMA6861H

Fax: 6224 3903

Attn: Motor Claims Department

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				-
1	Rear bumper tom	1	\$3,300.00	\$3,300.00	- 217
2	Rear bumper side retainer RH	1	\$665.00	\$665.00	
3	Rear sports rim RH	1	\$3,600.00	\$3,600.00	17
4	Rear fender RH MU	1	repair	repair	
5	Tail lamp RH	1	\$1,900.00	\$1,900.00	L.
	2071		Total	\$9,465.00	
	2011		Less 10%	\$946.50	
	2265	^	Sub Total 1	\$8,518.50	
	2/62//	Ų			
В.	Spare Parts (S/Nett)				6.0
1	Rear bumper sticker wrap	1	\$1,200.00	\$1,200.00	- 000
2	Rear fender sticker wrap	1	\$1,500.00	\$1,500.00	
3	Rear tyre RH	1	\$750.00	\$750.00	X .
4	Rear bumper clip	10	\$10.00	\$100.00	50
	Sub-Total 2			\$3,550.00	9 53
		\$12,068.50			
C.	Labour				
1	To check wiring.			\$50,00	- 30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$400.00	250
3	Spray painting all affected parts & areas.			\$600.00	300
4	To check wheels with computerized wheel alignment.			\$150.00	+
5	To spray anti-rust undercoat.			\$30.00	+
	500 Total Labour			\$1,230.00	
	Total Repair Cost			\$13,298.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party Een gy is on a "Without Prejudice" basis
- · No illegatematiciant Granz Services Pte Ltd
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Su	rveyor's Details		
Name			
Contact			
Survey Date			
Recommender	Authorize / Not Authoriz		
Before Paint	Yes / No		