

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 51001
Date Estimated : 26/04/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -

Amit Mody
10H Braddell Hill
#19-30
Braddell View
Singapore 579727

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN.NO.	CHASSIS NO.	REGN.DATE	MODEL	MLEAGE	
SLP280G	VX86808	22/11/2013	X1 sDrive20i	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT

To replace rear bumper and attachments include knocking out dents caused by the accident

850.00

850.00 ✓

To spray paint rear bumper

934.00

934.00 ✓

To check electrical wiring systems and lightings at the rear section for proper function

150.00

150.00 ✓

Sundries

80.00

80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER CARRIER ✓	444.50	1.00		444.50
REAR BUMPER TRIM PANEL PRIMED ✓	763.15	1.00		763.15
RR BUMPER BOTTOM TRIM PANEL (SPORTL) ✓	343.45	1.00		343.45
# EXPANDING RIVET * ✓ <i>ALC</i>	1.35	10.00		13.50

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,564.00
Total Labour & Parts :	3,578.00 ✓
Deduction for Excess :	
Total Repair Costs less Excess:	3,578.00
GST @7%:	250.50
Grand Total :	3,829.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 51001
Date Estimated : 26/04/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Amit Mody
10H Braddell Hill
#19-30
Braddell View
Singapore 579727

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN.NO.	CHASSE NO.	REGN.DATE	MODEL	MILEAGE
SLP280G	VX86808	22/11/2013	X1 sDrive20i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET * / MEK	1.35	10.00		13.50

Total Labour:	
Total Parts:	13.50
Total Labour & Parts:	13.50

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



Due 8/5
6/5/2019
Sunny & Kpi

GST REG. NO : M2 - 0020081 - X

26 APR 2019

E S T I M A T E

Estimate No. : b1 51001
Date Estimated : 26/04/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Amit Mody
10H Braddell Hill
#19-30
Braddell View
Singapore 579727

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP280G	VX86808	22/11/2013	X1 sDrive20i	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock
on accident dent

850 1,275.00

Spray painting rear bumper]

974 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

7 80.00

Total Labour 1: 2,570.00

DESCRIPTION

RR BUMPER CTR GUIDE ✓
RR BUMPER CARRIER ?
RR BUMPER LH GUIDE ?
RR BUMPER RH GUIDE ?
TOWING HINGE LH ✓
TOWING HINGE RH ✓
REAR BUMPER TRIM PANEL PRIMED ✓
RR BUMPER BOTTOM TRIM PANEL (SPORTL) ✓
LH REFLECTOR X
RH REFLECTOR ?

QTY	PRIC	VALUE
1	62.85	62.85
1	444.50	444.50
1	58.35	58.35
1	58.35	58.35
1	4.40	4.40
1	4.40	4.40
1	763.15	763.15
1	343.45	343.45
1	36.80	36.80
1	36.80	36.80

Total Parts : 1,813.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51001
Date Estimated : 26/04/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP280G	VX86808	22/11/2013	X1 sDrive20i	0

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 615/M 11.09am Claim No. _____
Date & Time 6/5/19 11.09am Excess S\$ _____
Surveyor's Name Steve (LKK) Sign _____
Surveyor's Tel 8322 8813 Authorised Yes/No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PM Yes/No _____
Surveyor's E-mail _____
No. of Working Days Recommended _____

wil *Amir*
P/P
Ry *beF spy*
3 *days*

Labour 1	:	2,570.00
Parts	:	1,813.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	306.81
Grand Total	:	4,689.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

Time Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Due 8/5
6/5/2019

Sunny & Repi



GST REG. NO : M2 - 0020081 - X

ESTIMATE

26 APR 2019

Estimate No. : b1 51001
Date Estimated : 26/04/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Amit Mody
10H Braddell Hill
#19-30
Braddell View
Singapore 579727

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP280G	VX86808	22/11/2013	X1 sDrive20i	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

Spray painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

Tot

DESCRIPTION

RR BUMPER CTR GUIDE

RR BUMPER CARRIER

RR BUMPER LH GUIDE

RR BUMPER RH GUIDE

TOWING HINGE LH

TOWING HINGE RH

REAR BUMPER TRIM PANEL PRIMED

RR BUMPER BOTTOM TRIM PANEL (SPORTL

LH REFLECTOR

RH REFLECTOR

QTY

1

1

1

1

1

1

1

1

1

1

Tot

Steve 7/5/19

Long. taken photo

Email sent to Steve. Like
6/5/19.