

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0534/2019/DY
Date	:	25-Apr-19

Vehicle NOT IN workshop

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Marcello Nusiner
Address	:	152 Laurel Wood Ave Singapore 275859
Telephone	:	HP +65 96700955
Type of Claim	:	Own Damage Claims
Policy No.	:	2100478608-02
Vehicle No	:	SLE 7239 P
Model Code	:	Audi A3 SEDAN 1.4 TFSI
Model / Year	:	Jul-16
Engine No	:	CZC 564593
Chassis No	:	WAUZZZ8V8G1105405
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	24-Apr-19
Place of Accident	:	6th Avenue Holland Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 7239 P

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	s/n \$ 360.00 ✓
2	To remove and renew aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum regas.	s/n \$ 1,200.00 ?
3	To dismantle and renew front bumper, bonnet, rhs front fender and rhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 4,500.00 1250. without lock carrier
4	To respray front bumper, bonnet, hinges, rhs front fender and both upper A-pillar. x	\$ 3,500.00 1650
5	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 9,752.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 7239 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Replaced</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	x
3	FRONT BUMPER COVER TRIM - RH <i>new</i>	\$ 148.00	x
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	\$ 148.00	x
5	FRONT BUMPER PULL STRAP <i>new</i>	\$ 187.00	+
6	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 35.00	x
7	FRONT BUMPER AIR GUIDE GRILLE - RH ?	\$ 99.00	?
8	RADIATOR GRILLE <i>Replaced</i>	\$ 637.00	✓
9	RADIATOR GRILLE INNER COVER <i>Replaced</i>	\$ 89.00	—
10	FRONT BUMPER REINFORCEMENT ?	\$ 660.00	?
11	FOAM FILLER PIECE ?	\$ 125.00	?
12	FRONT BUMPER REINFORCEMENT COVER ?	\$ 51.00	?
13	CAUTION STICKER ?	\$ 13.00	?
14	A/C STICKER ?	\$ 7.00	?
15	HORN - HIGH TONE <i>new</i>	\$ 182.00	4.
16	FRONT FENDER - RH <i>Repair</i>	\$ 778.00	x
17	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ 65.00	+
18	FRONT FENDER BRACKET - RH <i>new</i>	\$ 35.00	+
19	POP RIVET <i>new</i>	\$ 15.00	+
20	FRONT FENDER BRACE - RH <i>new</i>	\$ 88.00	1
SUB-TOTAL SPARE PARTS		\$ 5,362.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 7239 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$ 158.00	<i>x</i>
22	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 81.00	<i>x</i>
23	BONNET <i>Dented</i>	\$ 2,898.00	<i>✓</i>
24	BONNET ATTACHMENT PARTS <i>?</i>	\$ 149.00	<i>?</i>
25	BONNET HINGE - LH / RH <i>new</i>	\$ 112.00	<i>x</i>
26	BONNET GAS FILLED STRUT <i>new</i>	\$ 109.00	<i>x</i>
27	BONNET CATCH HOOK <i>?</i>	\$ 81.00	<i>?</i>
28	BONNET STRIKER <i>?</i>	2 \$ 200.00	<i>?</i>
29	BONNET EDGE PROTECTION <i>new</i>	\$ 25.00	<i>✓</i>
30	BONNET CATCH HOOK <i>?</i>	\$ 58.00	<i>?</i>
31	BONNET LOCK WITH MICRO SWITCH <i>?</i>	\$ 367.00	<i>?</i>
32	BONNET BOWDEN CABLE <i>new</i>	\$ 53.00	<i>x</i>
33	BONNET LID LOCK CABLE <i>new</i>	\$ 67.00	<i>x</i>
34	BONNET LID LOCK COVER <i>?</i>	\$ 9.00	<i>x</i>
35	HEADLIGHT - RH <i>could</i>	\$ 1,825.00	<i>✓</i>
36	HEADLIGHT LIFT CYLINDER - RH <i>?</i>	\$ 181.00	<i>?</i>
37	LIFT CYLINDER HOSE - RH <i>new</i>	\$ 170.00	<i>x</i>
38	LOCK CARRIER <i>?</i>	\$ 663.00	<i>?</i>
39	COOLANT <i>?</i>	\$ 84.00	<i>?</i>
40	A/C CONDENSER <i>?</i>	\$ 516.00	<i>?</i>
SUB-TOTAL SPARE PARTS		\$ 7,806.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 7239 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	RADIATOR ?	TBC	?
42	ADDITIONAL RADIATOR ?	\$ 837.00	?
43	LOCK CARRIER AIR GUIDE - LH / RH ?	\$ 44.00	?
44	LOCK CARRIER TOP AIR GUIDE - RH / LH ?	\$ 8.00	?
45	LOCK CARRIER AIR GUIDE - UPPER CENTRE ?	\$ 11.00	?
46	FRONT NO. PLATE <i>Bent</i>	\$ 40.00	✓
47	SUNDRIES ?	\$ 700.00	?
TOTAL SPARE PARTS :		\$ 14,808.00	
TOTAL LABOUR CHARGES :		\$ 9,752.00	
GRAND TOTAL :		\$ 24,560.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 26/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant