



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

*Not Yet Reported by  
 SJV5926L @13:55  
 07 MAY 2019*

<b>Customer</b> :	AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	<b>Document No.</b> :	SQT19001866	<b>Page</b>	1
<b>Registration No</b> :	SMA4208H	<b>Date</b>	: 26. Apr 2019	<b>Customer No.</b>	: WZA006
<b>Chassis No</b> :	JHMRC1890JC202675	<b>Svc Advisor</b>	: ARY CHUA WAI NGENE	<b>Engine No</b>	: K24W72401483
<b>Model</b> :	ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO)	<b>Date   Time</b>	: 26. Apr 2019 4:47:37 PM	<b>Surveyor Name</b>	: DID : +65 6846 5673
<b>Owner's Name</b> :	CHRISTOPHER KOH CHUNG HUANG	<b>Survey Date</b>	: HP : +65 8106 6306	<b>Authorisation Date</b>	: Email : arychua@honda.com.sg
<b>Ins Policy No.</b> :	10843131				
<b>Date of Accident</b> :	25/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72616) OWNER: CHRISTOPHER KOH CHUNG HUANG OWNER INSURER: AVIVA LTD ACC DATE: 25-04-2019@10.00AM ACC: BLK 500 NEWTON FOOD CENTRE OPEN CARPARK  SURVEYED BY: REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SJV5926L - HYUNDAI/TUCSON/GREY						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	<i>nc</i> 1	60.00	✓	60.00	4.20	64.20
34150-T6A-J51	LIGHT ASSY,R.LID	<i>17</i> 1	386.20	X	289.65	20.28	309.93
34155-T6A-J51	LIGHT ASSY,L.LID	<i>17</i> 1	378.60	X	283.95	19.88	303.83
75722-T6A-901	EMBLEM,RR.	<i>nc</i> 1	31.00	✓	23.25	1.63	24.88
75701-T6A-000	EMBLEMH	<i>nc</i> 1	26.30	✓	19.72	1.38	21.10
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER	<i>nc</i> 1	557.20	X	417.90	29.25	447.15
71593-T6A-003	SPACERR.RR.BUMPER SIDE	<i>17</i> 1	19.10	X	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	<i>17</i> 1	19.10	X	14.32	1.00	15.32
71517-T6A-901ZF	SPOILER ASSY,L.RR.	<i>17</i> 1	98.70	X	74.02	5.18	79.20
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	<i>nc</i> 2	18.00	✓	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	<i>nc</i> 1	16.90	✓	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	<i>nc</i> 1	16.90	✓	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	<i>nc</i> 4	3.90	✓	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	<i>nc</i> 1	3.70	✓	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	<i>nc</i> 2	8.50	✓	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	<i>nc</i> 1	4.80	✓	3.60	0.25	3.85
91505-TM8-003	CLIP,BUMPER	<i>nc</i> 8	2.30	✓	13.80	0.97	14.77
66100-T6A-Q00ZZ	PANEL COMP,REAR	<i>nc</i> 1	460.80	X	345.60	24.19	369.79
74440-T6A-003	WEATHERSTRIPTAILGATE	<i>17</i> 1	117.40	X	88.05	6.16	94.21

Printed on 26/4/2019 5:59:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE S'PORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

Registration No : SMA4208H

Chassis No : JHMRC1890JC202675

Model : ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO)

Owner's Name : CHRISTOPHER KOH CHUNG HUANG

Ins Policy No. : 10843131

Date of Accident : 25/4/2019

Document No. : SQT19001866

Date : 26. Apr 2019

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W72401483

Date | Time : 26. Apr 2019 4:47:37 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	11	175.50	X 25	131.62	9.21	140.83
74800-TF0-J02	LOCKTAILGATE	11	185.40	X 25	139.05	9.73	148.78
68100-T6A-Q10ZZ	TAILGATE COMP	Body	1070.80	25	803.10	56.22	859.32
<b>Sum Item</b>					<b>2801.51</b>	<b>196.10</b>	<b>2,997.61</b>
BOSUN	SUNDRIES	1	60.00	20	60.00	4.20	64.20
BOBC	BODY UNDERSIDE COATING (N)	11	100.00	X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	11	100.00	X	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	100	140.00	9.80	149.80
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00	140	180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	11	250.00	X	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	300	350.00	24.50	374.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00	300	350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	X	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	450	550.00	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00	1350	2800.00	196.00	2996.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	4800.00	1120	4800.00	336.00	5136.00
<b>Sum Labor</b>					<b>10480.00</b>	<b>733.60</b>	<b>11,213.60</b>

Survey By

Date & Time

Excess

Status

Signature

*mercy LKH*  
*8/7/19 @ 9.30*  
*not done*  
*to be done per poly. 5/7*

<b>Total Amount</b>	13,281.51	929.70	14,211.21
<b>Total (Inclusive of GST)</b>			<b>14,211.21</b>

**LRV and Consultants hereby notify the Insurer the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 26/4/2019 5:59:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.