

Surveyor

REF:

III

ASSIGNMENT

From: Date: 30/4/19

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 9682R

at Workshop m/s Ah Lim Motor

of 10 Amk Ind. Park 2A # 01-09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 10:30am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 13 days Res: Yes or No

Lum Sum: 1.8.1% 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{sup}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMJ 9682R Yr Regn: 03, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda (A) 157 c.c. 1317

Colour: M. D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 2332 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK3 1345827

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 175 / 70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 23/4/19 D.O.I. 30/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$12374.90 / - (Red = \$5316.28 / 30%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Apr 2019)
 Parts: 143 HONDA FIT 1.3 GF CVT (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SMJ9682R/30/04/2019 09:54
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BONNET	As	20.00	0.00	*550.00 FL	—
2	2		*FRONT BONNET HINGE LH & RH	R	20.00	0.00	*90.00 FL	✓
3	2		*FRONT BONNET RUBBER CENTRE LH & RH	Sm	20.00	0.00	*44.00 FL	✓
4	2		*FRONT BONNET RUBBER SIDE LH & RH	Sm	20.00	0.00	*28.60 FL	✓
5	1		*FRONT BONNET INNER LOCK	WH	20.00	0.00	*90.50 FL	✓X
6	1		*FRONT GRILLE	KA	20.00	0.00	*352.90 FL	✓
7	1		*FRONT GRILLE EMBLEM	WH	20.00	0.00	*23.40 FL	✓X
8	1		*FRONT GRILLE CHROME MOULDING TOP	CR	20.00	0.00	*265.00 FL	—
9	1		*FRONT GRILLE CHROME MOULDING LOWER	Sm	20.00	0.00	*225.00 FL	—
10	8		*FRONT GRILLE CLIPS	HEL	20.00	0.00	*31.20 FL	✓
11	2		*HEADLAMP LH & RH	WH	20.00	0.00	*1,590.00 FL	✓ 285
12	1		*FRONT BUMPER	Bu	20.00	0.00	*495.00 FL	—
13	2		*FRONT BUMPER SIDE RETAINERS LH & RH	AL/D17	20.00	0.00	*30.80 FL	4 1540
14	15		*FRONT BUMPER CLIPS	Re	20.00	0.00	*58.50 FL	—
15	1		*FRONT BUMPER LOWER AIR GRILLE	WH	20.00	0.00	*180.00 FL	—
16	1		*FRONT BUMPER REINFORCEMENT	ODR	20.00	0.00	*203.80 FL	✓
17	2		*FOG LAMP COVER LH & RH	Sm	20.00	0.00	*116.60 FL	X
18	1		*RADIATOR SUPPORT PANEL	R	20.00	0.00	*455.00 FL	X
19	1		*RADIATOR SUPPORT PANEL TOP GARNISH	Sm	20.00	0.00	*12.40 FL	✓
20	8		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	an	20.00	0.00	*31.20 FL	X
21	1		*AIR CON CONDENSER	WH	20.00	0.00	*810.00 FL	✓
22	1		*RADIATOR ASSY	WH Sm	20.00	0.00	*1,250.00 FL	X
23	1		*RADIATOR FAN MOTOR	Sm	20.00	0.00	*336.00 FL	X
24	1		*RADIATOR FAN BLADE	Sm	20.00	0.00	*78.00 FL	X
25	1		*RADIATOR FAN COWLING	Sm	20.00	0.00	*150.00 FL	X
26	1		*REAR WINDSCREEN MOULDING	Re	20.00	0.00	*120.00 FL	—
27	1		*TAILGATE	Re	20.00	0.00	*814.00 FL	—
28	1		*TAILGATE EMBLEM	Re	20.00	0.00	*15.70 FL	—
29	1		*TAILGATE FIT LOGO	Re	20.00	0.00	*35.00 FL	—
30	2		*TAILGATE LAMP LH & RH	WH	20.00	0.00	*77.00 FL	✓
31	1		*TAILGATE REVERSE CAMERA	WH	20.00	0.00	*1,041.00 FL	✓
32	1		*TAILGATE INNER LOCK	WH	20.00	0.00	*157.10 FL	—
33	1		*TAILGATE RUBBER	Reform	20.00	0.00	*92.30 FL	—
34	2		*TAILAMP LH & RH	CR	20.00	0.00	*474.80 FL	—
35	1		*REAR BUMPER	Re	20.00	0.00	*492.60 FL	—
36	2		*REAR BUMPER SIDE RETAINERS LH & RH	CR	20.00	0.00	*23.00 FL	—
37	15		*REAR BUMPER CLIPS	Re	20.00	0.00	*58.50 FL	—
38	1		*REAR BUMPER LOWER COVER	Re	20.00	0.00	*130.60 FL	—
39	15		*REAR BUMPER CLIPS	Re	20.00	0.00	*58.50 FL	—
40	2		*REAR BUMPER SIDE GRILLE LH & RH	CR Re	20.00	0.00	*96.00 FL	X
41	1		*END PANEL	Re	20.00	0.00	*390.00 FL	—
42	1		*END PANEL TOP GARNISH	Re	20.00	0.00	*60.80 FL	—
43	1		*SPARE TYRE PANEL	Re/19	20.00	0.00	*697.00 FL	—
44	1		*SPARE TYRE PANEL TOP TRIMBOARD -CHECK PRICE	WH	20.00	0.00	*. FL	✓
45	2		*REAR FENDER INNER TRIM LH & RH	Reform	20.00	0.00	*331.20 FL	✓

Ah Lim Motor Company/SMJ9682R/30/04/2019 09:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

**DMPPHQ19-002252 PRIVATE CAR
Comprehensive**

Certificate No.: DMPPHQ19-002252

1. Index Mark and Registration Number of Vehicles
UKJW62N **SM7 9682 R**

2. Name of Policyholder
LI XINWANG

3. Effective Date of the Commencement of Insurance for the purpose of the Act
26/03/2019 **26/3/19**

4. Date of Expiry of Insurance
25/03/2020 **25/3/2020**

5. Person or Classes of Persons entitled to drive*

- (a) The Policyholder
(b) Any other person who is driving on the Policyholder's order or with his permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

Limitations as to Use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover:

- (a) use for hire or reward
(b) use for racing, pace-making, reliability trials or speed testing
(c) use for the carriage of goods (other than samples) in connection with any trade or business
(d) use for any purpose in connection with the Motor Trade

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Form: PK2

Excess:

Insured/Named Driver 500500.00

Unnamed Drivers 5001,000.00

VEDD Additional 5003,000.00

EQ Motor Accident
Hotline

6311 3211



137/I Insurance Agency

er of Citystate

Authorised Signatory
EQ Insurance Company Limited

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2659J

Vehicle Details

Vehicle No.:	SMJ9682R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3 GF CVT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	L13B1454476
Chassis No.:	GK31345827
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,421.00
Original Registration Date:	26 Mar 2019
First Registration Date:	26 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$5,421.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2029
PARF Rebate Amount:	\$4,065.00

Intended COE Rebate Details

COE Expiry Date:	25 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,301.00
COE Rebate Amount:	\$21,040.00
Total Rebate Amount:	\$25,105.00

The information contained herein is correct as at 24 Apr 2019

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimac@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : LI XINHAO
 BLK 314 HOUGANG AVE 5 #09-123
 SINGAPORE 530314

Claim No: MC1900334
 No: MF1900380
 Date: 02 Jul 2019
 Policy No: DMPPHQ19-002252
 Veh Reg No: SMJ9682R
 Make/Model: HONDA FIT 1.3 GF CVT

ATTN:
 Your Ref No: -
 Claim Type: Third Party
 Accident Date: 23/04/2019
 TP Veh Reg No: SHA4962Y

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SMJ9682R

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT BONNET	1 PC	550.00	
2 FRONT GRILLE	1 PC	352.90	
3 FRONT GRILLE CHROME MOULDING TOP	1 PC	265.00	
4 FRONT GRILLE CHROME MOULDING LOWER	1 PC	225.00	
5 FRONT GRILLE CLIPS	8 PC	31.20	
6 HEADLAMP LH	1 PC	795.00	
7 FRONT BUMPER	1 PC	495.00	
8 FRONT BUMPER SIDE RETAINERS LH	1 PC	15.40	
9 FRONT BUMPER CLIPS	15 PC	58.50	
10 FRONT BUMPER REINFORCEMENT	1 PC	203.80	
11 AIR CON CONDENSER	1 PC	810.00	
12 RADIATOR ASSY	1 PC	1,250.00	
13 REAR WINDSCREEN MOULDING	1 PC	120.00	
14 TAILGATE	1 PC	814.00	
15 TAILGATE EMBLEM	1 PC	15.70	
16 TAILGATE FIT LOGO	1 PC	35.00	
17 TAILGATE INNER LOCK	1 PC	157.10	
18 TAILGATE RUBBER	1 PC	92.30	
19 TAILAMP LH & RH	2 PC	474.80	
20 REAR BUMPER	1 PC	492.60	
21 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	23.00	
22 REAR BUMPER CLIPS	15 PC	58.50	
23 REAR BUMPER LOWER COVER	1 PC	130.60	
24 REAR BUMPER CLIPS	15 PC	58.50	
25 REAR BUMPER SIDE GRILLE LH & RH	2 PC	96.00	
26 END PANEL	1 PC	390.00	
27 END PANEL TOP GARNISH	1 PC	60.80	
28 SPARE TYRE PANEL	1 PC	697.00	
29 REAR FENDER INNER TRIM LH & RH	2 PC	331.20	
30 REAR BUMPER CENTER LOWER GARNISH	1 PC	125.00	
31 REAR NUMBER PLATE GARNISH	1 PC	270.00	
32 REAR TAIL LAMP CLIP LH	1 PC	7.00	
33 REAR BAFFLE SILENCER TOP COVER	1 PC	35.00	
34 FRONT BUMPER BEAM UPPER LH	1 PC	60.00	
35 STAY FRONT GRILLE	1 PC	42.00	
36 BUZZER ASSY	1 PC	140.00	
37 ANTENNA	1 PC	120.00	
38 POCKET	1 PC	22.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170

SAPP

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : LI XINHAO
 BLK 314 HOUGANG AVE 5 #09-123
 SINGAPORE 530314

Claim No: MC1900334
 No: MF1900380
 Date: 02 Jul 2019
 Policy No: DMPPHQ19-002252
 Veh Reg No: SMJ9682R
 Make/Model: HONDA FIT 1.3 GF CVT

ATTN:
 Your Ref No: -
 Claim Type: Third Party
 Accident Date: 23/04/2019
 TP Veh Reg No: SHA4962Y

Repair Cost to Vehicle No (For Finalization):SMJ9682R

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
39 REAR TOOL BOX	1 PC	130.00	
		10,049.90	
	Less 20%	2,009.98	8,039.92
Special Nett			
40 NUMBER PLATE	1 PC	35.00	
41 REVERSE SENSOR	2 PC	200.00	
42 INNER SEAL	1 PC	20.00	
43 SEALANT	1 PC	40.00	
44 COOLANT	1 PC	30.00	
		325.00	325.00
LABOUR			
45 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. (FRONT)	1 PC	20.00	
46 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
47 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
48 TO SPRAY FRONT BONNET,FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL.	1 PC	600.00	
49 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.(REAR)	1 PC	20.00	
50 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	
51 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	100.00	
52 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	
53 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	50.00	
54 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	90.00	
55 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	
56 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL,SPARE TYRE PANEL. TO KNOCK & REPAIR REAR FENDERLH & RH,REAR CHASSIS LH & RH,ROOF PANEL,INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,200.00	
57 TO SPRAY TAILGATE, REAR BUMPER,END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR CHASSIS LH & RH, ROOF PANEL	1 PC	1,000.00	

No. 10 Ang Mo Kio Ind. Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT - FOR INFORMATION

M/S : LI XINHAO
BLK 314 HOUGANG AVE 5 #09-123
SINGAPORE 530314

Claim No: MC1900334
No: MF1900380
Date: 02 Jul 2019
Policy No: DMPPHQ19-002252
Veh Reg No: SMJ9682R
Make/Model: HONDA FIT 1.3 GF CVT

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SHA4962Y

Repair Cost to Vehicle No (For Finalization):SMJ9682R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
58 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
		3,950.00	3,950.00
INSURANCE			
59 MERIMEN CHARGES	1 EA	10.00	
		10.00	10.00
Total			S\$ 12,324.92
Less Excess			S\$ 0.00
Amount Before GST			S\$ 12,324.92
Add GST @ 7%			862.74
Total Amount Payable			S\$ 13,187.66

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND ONE HUNDRED EIGHTY SEVEN AND CENTS SIXTY SIX ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 30/04/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-09 AMK AUTOPOINT Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)
 COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: EQ Insurance Company Ltd

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/INDIA
Policy No:		Date of Loss:	23/04/2019
Vehicle Reg. No.:	SMJ9682R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LI XINHAO		
Make/Model:	HONDA FIT, 1.3 GF CVT (A)	Vehicle Reg. Date:	26/03/2019
Vehicle Colour:	BLUE		
Engine No:	L13B1454476	Chassis No:	GK31345827
Odometer:	0 KM		

Paint Type:
 List Item Discount: 20.00 %
 Total Loss? NO
 Est. Duration of Repair (day) 15-13 days

Not Authorised
 Recovery B4 PAM

Description of Accident/Loss: REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.
 Remarks: -

Present Location: AH LIM MOTOR COMPANY (AMK)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	10,590.40
Labour	10.00
Paintwork Labour	6,180.00
Towing	0.00
	0.00
Gross Total (\$\$)	16,780.40
+ GST 7.00% (\$\$)	1,174.63
Nett Amount (\$\$)	17,955.03

LKM Auto Consultants hence notify the Repairer of the following:

- To recovery to cost that spray painting
- To supply damaged part(s) during recovery
- Part prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- No legal proceedings is allowed
- Supplementary survey must be recovered and is subject to final approval from Insurance Company

Authorised by: *[Signature]*
 Date: *[Date]*

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2019 15:03 Sendback Est	26 Apr 2019 15:54 S\$12,300.40	26 Apr 2019 17:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	-, ID: -		
Main Claimant:	LI XINHAO, ID: 59132659		
Vehicle Reg. No.:	SMJ9682R	Date of Loss:	23/04/2019 17:00 - :59 [28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA4962Y	Policy No. (Claimant):	DMPPHQ19-002252
		Excess:	
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

☐ ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

1252pm @ 29/4/19

vni

Gileen

ammy on 30/4/19

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 26 April 2019 5:31 PM
To: Eileen Chua; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: YOUR INSURED SHA4962Y DOA: 23/04/2019 & OUR CLIENT SMJ9682R

Dear Eileen,

LKK has been assigned through merimen.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Eileen Chua [mailto:ahlimmc@singnet.com.sg]
Sent: 26 April, 2019 4:12 PM
To: Motor Claim - III <motorclaim@iii.com.sg>; C Meenachi - III <Meenachi@iii.com.sg>
Subject: YOUR INSURED SHA4962Y DOA: 23/04/2019 & OUR CLIENT SMJ9682R

Hi Claim Team,

Please kindly arrange survey. GIA & Estimate for your attention. Already upload on Merimen.

And kindly advise the liability.

Best Regards,

Eileen Chua

Ah Lim Motor Company

No. 10 Ang Mo Kio Ind. Park 2A

#01-09 AMK Autopoint S(568047)

Tel: 64831244 Fax: 64836170

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

SMJ9682R (MCT19040655)
[SHA4962Y]
TP
LI XINHAO
Apr 23 2019 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
Ah Lim Motor Company

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/12/2019 13:57 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14287.79) - SMJ9682R - Claim Handler: Sherini Pillai

Approved:14287.79.

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC1900334

Your Ref : SHA4962Y

Date : 20/08/2019

INDIA INTERNATIONAL INSURANCE P/L

64 CECIL STREET #04/#05

IOB BUILDING

SINGAPORE 049711

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SMJ9682R and your Insured SHA4962Y ON 23/04/2019 17:40 ALONG AYE HEADING TOWARDS MCE

We refer to the above matter.

Please assess through your Insured's (SHA4962Y) report and our Client (SMJ9682R) – LI XINHAO's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence
- 4) LTA Search & Medical Invoice

The above vehicle was surveyed by Kenneth from LKK as appointed by INDIA on 30/04/2019.

We would quantify our claim as below:-

Cost of Repair : \$13,187.66

Loss Of Use : \$960.00(16 X \$60) Surveyor recommend 13 days. Add 2 Sundays and 1 Public holiday

Medical Fee : \$132.68

LTA Search : \$7.45

=====

Total : \$14,287.79

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,


AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Kee Mui Hong
Tel: 6483 1244 Fax: 6483 6170

Authorisation to Act

I, LI XINHAO (the third party claimant) of B/K 214 Hougang Ave 5 #09-123 8C 530314 (address), owner of SMJ9682R (Vehicle no) hereby authorise Ah Lim Motor Company (the workshop) to act for me in respect to my claim for repair costs and / or rental and / or loss of use (Claim) for my vehicle No. SMJ9682R that was damaged pursuant to the accident which occurred on 23/4/19 (date) along AYE Heading towards NCF (location) involving vehicle Nos SMJ9682R, SHA4962Y & SKK2762H (the Accident)

I further authorise the workshop to settle the above mentioned claim in a manner that they deem fit and the workshop is further authorised to receive the payment further to settlement of my claim with payment cheque/s made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle is concerned.

Dated this 24 day of April (month) 20 19 (year)


Signed by Third party claimant
Owner Veh No : SMJ9682R


Signed by the workshop

Personal data Protection Act 2012

I/ We acknowledge and consent to Ah Lim Motor Company collecting , using and disclosing and /or processing my/our personal data to Third Party service providers and/or Insurance company my / our personal data for the purpose of processing the claim and related insurance / claim matters.


Owner Signature

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LI XINHAO
BLK 314 HOUGANG AVE 5 #09-123
SINGAPORE 530314

Claim No: MC1900334
No: AL1901440
Date: 05 Aug 2019
Policy No: DMPPHQ19-002252
Veh Reg No: SMJ9682R
Make/Model: HONDA FIT 1.3 GF CVT

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SHA4962Y

Tax Invoice-Final Repair Cost to Vehicle No :SMJ9682R

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT BONNET	1 PC	550.00	
2 FRONT GRILLE	1 PC	352.90	
3 FRONT GRILLE CHROME MOULDING TOP	1 PC	265.00	
4 FRONT GRILLE CHROME MOULDING LOWER	1 PC	225.00	
5 FRONT GRILLE CLIPS	8 PC	31.20	
6 HEADLAMP LH	1 PC	795.00	
7 FRONT BUMPER	1 PC	495.00	
8 FRONT BUMPER SIDE RETAINERS LH	1 PC	15.40	
9 FRONT BUMPER CLIPS	15 PC	58.50	
10 FRONT BUMPER REINFORCEMENT	1 PC	203.80	
11 AIR CON CONDENSER	1 PC	810.00	
12 RADIATOR ASSY	1 PC	1,250.00	
13 REAR WINDSCREEN MOULDING	1 PC	120.00	
14 TAILGATE	1 PC	814.00	
15 TAILGATE EMBLEM	1 PC	15.70	
16 TAILGATE FIT LOGO	1 PC	35.00	
17 TAILGATE INNER LOCK	1 PC	157.10	
18 TAILGATE RUBBER	1 PC	92.30	
19 TAILAMP LH & RH	2 PC	474.80	
20 REAR BUMPER	1 PC	492.60	
21 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	23.00	
22 REAR BUMPER CLIPS	15 PC	58.50	
23 REAR BUMPER LOWER COVER	1 PC	130.60	
24 REAR BUMPER CLIPS	15 PC	58.50	
25 REAR BUMPER SIDE GRILLE LH & RH	2 PC	96.00	
26 END PANEL	1 PC	390.00	
27 END PANEL TOP GARNISH	1 PC	60.80	
28 SPARE TYRE PANEL	1 PC	697.00	
29 REAR FENDER INNER TRIM LH & RH	2 PC	331.20	
30 REAR BUMPER CENTER LOWER GARNISH	1 PC	125.00	
31 REAR NUMBER PLATE GARNISH	1 PC	270.00	
32 REAR TAIL LAMP CLIP LH	1 PC	7.00	
33 REAR BAFFLE SILENCER TOP COVER	1 PC	35.00	
34 FRONT BUMPER BEAM UPPER LH	1 PC	60.00	
35 STAY FRONT GRILLE	1 PC	42.00	
36 BUZZER ASSY	1 PC	140.00	
37 ANTENNA	1 PC	120.00	
38 POCKET	1 PC	22.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LI XINHAO
BLK 314 HOUGANG AVE 5 #09-123

SINGAPORE 530314

Claim No: MC1900334
No: AL1901440
Date: 05 Aug 2019
Policy No: DMPPHQ19-002252
Veh Reg No: SMJ9682R
Make/Model: HONDA FIT 1.3 GF CVT

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SHA4962Y

Tax Invoice-Final Repair Cost to Vehicle No :SMJ9682R

Description	Quantity	List Price S\$	Amount S\$
39 REAR TOOL BOX	1 PC	130.00	
		10,049.90	
	Less 20%	2,009.98	8,039.92
Special Nett			
40 NUMBER PLATE	1 PC	35.00	
41 REVERSE SENSOR	2 PC	200.00	
42 INNER SEAL	1 PC	20.00	
43 SEALANT	1 PC	40.00	
44 COOLANT	1 PC	30.00	
		325.00	325.00
LABOUR			
45 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. (FRONT)	1 PC	20.00	
46 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
47 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
48 TO SPRAY FRONT BONNET,FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL.	1 PC	600.00	
49 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.(REAR)	1 PC	20.00	
50 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	
51 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	100.00	
52 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	
53 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	50.00	
54 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	90.00	
55 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	
56 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL,SPARE TYRE PANEL. TO KNOCK & REPAIR REAR FENDERLH & RH,REAR CHASSIS LH & RH,ROOF PANEL,INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,200.00	
57 TO SPRAY TAILGATE, REAR BUMPER,END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR CHASSIS LH & RH, ROOF PANEL	1 PC	1,000.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
Singapore 568047
TEL: 6483 1244 FAX: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LI XINHAO
BLK 314 HOUGANG AVE 5 #09-123

SINGAPORE 530314

Claim No: MC1900334
No: AL1901440
Date: 05 Aug 2019
Policy No: DMPPHQ19-002252
Veh Reg No: SMJ9682R
Make/Model: HONDA FIT 1.3 GF CVT

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 23/04/2019
TP Veh Reg No: SHA4962Y

Tax Invoice-Final Repair Cost to Vehicle No :SMJ9682R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
58 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
		3,950.00	3,950.00
INSURANCE			
59 MERIMEN CHARGES	1 EA	10.00	
		10.00	10.00
Total			S\$ 12,324.92
Less Excess			S\$ 0.00
Amount Before GST			S\$ 12,324.92
Add GST @ 7%			862.74
Total Amount Payable			S\$ 13,187.66

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND ONE HUNDRED EIGHTY SEVEN AND CENTS SIXTY SIX ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 30/04/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
AUTHORISED SIGNATURE

E. & O. E.

Name : LI XINHAO
ID No : S9132659J
Visit No : D190084118
Visit Reason : MEDICAL CONSULTATION
AND ABNORMAL REVIEW
Location : STMC
Receipt No : 190064421
Date : 24/04/2019
ACRA Regn No. : 194700119G
GST Reg No. : M4-0000329-7
Page : 1 of 1

Service / Item	Amount (S\$)
CERVICAL SPINE + OBLIQUES	100.00
MEDICAL CONSULTATION - SHORT	24.00
Total Charges	124.00
GST @ 7%	8.68
	132.68
Total Amount Payable (with GST)	132.68
Previous Payment :	
Receipt No : 190064285 (VISA)	25.68
Final Payment:	
Amount Paid	107.00
Mode of Payment : VISA	
Outstanding Amount	0.00

sata 5-1A CommHealth Medical Centre
CommHealth† 5 Tampines Central 6
5-1A Telepark Singapore 529482
Tel: 6244 6688 Fax: 6702 0649

* Note to the Patient using CHAS: Please approach the registration counter staff for any refund matters. Kindly note that all administrative processes concerning refunds must be done within the same visit date. Otherwise, it will be forfeited.

This is a computer generated official receipt, no signature is required.

I AGREE TO PAY THE ABOVE TOTAL AMOUNT
ACCORDING TO CARD ISSUER AGREEMENT
*** CUSTOMER COPY ***

TOTAL SGD 107.00
NO SIGNATURE REQUIRED

DATE/TIME: 24APR19 11:06
TID: 40065282 MID: 16816341876
INVOICE: 006714 BATCH: 000657
MASTERCARD EXPIRY
XXXX XXXX XXXX 5319 XX/XX
APP CODE: R61719 HOST: DES
CONTACTLESS RRN: 911403086714
TC: 00712064730726 AID: A0000000001010
DMS (debit) TRN: 000000000

IDBS
TAMPINES MEDICAL CENTRE
BLK 5 TAMPINES CENTRAL 6
#01-01A TELEPARK BUILDING
SINGAPORE 529482

Name : LI XINHAO
ID No : S9132659J
Visit No : D190084118
Visit Reason : MEDICAL CONSULTATION
AND ABNORMAL REVIEW
Location : STMC
Receipt No : 190064285
Date : 24/04/2019
ACRA Regn No : 194700119G
GST Reg No : M4-0000329-7
Page : 1 of 1

Service / Item	Amount (S\$)
MEDICAL CONSULTATION - SHORT	24.00
Total Charges	24.00
GST @ 7%	1.68
	25.68
Total Amount Payable (with GST)	25.68

Final Payment:
Amount Paid 25.68
Mode of Payment : VISA
Outstanding Amount 0.00
Reference No : ---

sata SATA CommHealth Medical Centre
CommHealth† 5 Tampines Central 6
#01-01A Telepark Singapore 529482
Tel: 6244 6688 Fax: 6702 0649

* Note to the Patient using CHAS: Please approach the registration counter staff for any refund matters. Kindly note that all administrative processes concerning refunds must be done within the same visit date. Otherwise, it will be forfeited.

This is a computer generated official receipt, no signature is required.

DBS
TAMPINES MEDICAL CENTRE
BLK 5 TAMPINES CENTRAL 6
#01-01A TELEPARK BUILDING
SINGAPORE 529482

DATE/TIME: 24APR19 09:33
TID: 40805282 **HID:** 168168341876
INVOICE#: 006707 **BATCH#:** 080657
MASTERCARD
XXXX XXXX XXXX 5319 **EXPIRY**
APP# CODE: R09106 **XX/XX**
CONTACTLESS **RR#:** 911401065707 **HOST:** DBS
TC: F07B02061060946 **AID:** 0000000000000000
DOS Date: 1911-01-01

TOTAL SGD **25.68**
ID SIGNATURE REQUIRED

I AGREE TO PAY THE ABOVE TOTAL AMOUNT
ACCORDING TO CARD POSSES AGREEMENT
*** MERCHANT COPY ***

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2019 Sendback Est	30 Apr 2019 09:54 \$16,780.40	26 Apr 2019 17:29 Edit Adj Rpt	\$12,324.92 Edit Estimates	\$12,324.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD, ID: 199303821R								
Main Claimant:	LI XINHAO, ID: S91326593								
Vehicle Reg. No.:	SMJ9682R	Date of Loss:	23/04/2019 17:00 - :59 [28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19040655	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA4962Y	Policy No. (Claimant):	DMPPHQ19-002252						
		Excess:							
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (05/12/2019): Alert - Adj Mandate Approved (\$14287.79) - SMJ9682R - Claim Handler: Sherini Pi... - III_SG (29/04/2019): Alert - Adj Mandate Approved (\$0.00) - SMJ9682R - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SMJ9682R (MCT19040655)
[SHA4962Y]
TP
LI XINHAO
Apr 23 2019 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
Ah Lim Motor Company

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		☒
No	Finalized On	Ah Lim Motor Company (AMK)							Thumbnail	Print	
1	24/04/19 16:07	Video - Accident [Linked Accident Report Documents]							Load MP4		
Assessment Reports											
									1 per page		☒
No	Finalized On	Ah Lim Motor Company (AMK)							Thumbnail	Print	
1	30/04/19 09:54	Repairer Estimates							Load HTM		
Photos/Images											
									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	04/12/19 17:37	General View							Load JPG	☒	
2	04/12/19 17:37	General View							Load JPG	☒	
3	04/12/19 17:37	General View							Load JPG	☒	
4	04/12/19 17:37	General View							Load JPG	☒	
5	04/12/19 17:37	General View							Load JPG	☒	
6	04/12/19 17:37	General View							Load JPG	☒	
7	04/12/19 17:37	General View							Load JPG	☒	
8	04/12/19 17:37	General View							Load JPG	☒	
9	04/12/19 17:37	General View							Load JPG	☒	
10	04/12/19 17:37	General View							Load JPG	☒	
11	04/12/19 17:37	General View							Load JPG	☒	
12	04/12/19 17:37	General View							Load JPG	☒	
13	04/12/19 17:37	General View							Load JPG	☒	
14	04/12/19 17:37	General View							Load JPG	☒	
15	04/12/19 17:37	General View							Load JPG	☒	
16	04/12/19 17:37	General View							Load JPG	☒	
17	04/12/19 17:37	General View							Load JPG	☒	
18	04/12/19 17:37	General View							Load JPG	☒	
19	04/12/19 17:37	General View							Load JPG	☒	
20	04/12/19 17:37	General View							Load JPG	☒	
21	04/12/19 17:37	General View							Load JPG	☒	
22	04/12/19 17:37	General View							Load JPG	☒	
23	04/12/19 17:37	General View							Load JPG	☒	
24	04/12/19 17:37	General View							Load JPG	☒	
25	04/12/19 17:37	General View							Load JPG	☒	
26	04/12/19 17:37	General View							Load JPG	☒	
27	04/12/19 17:37	General View							Load JPG	☒	
28	04/12/19 17:37	General View							Load JPG	☒	
29	04/12/19 17:37	General View							Load JPG	☒	
30	04/12/19 17:37	General View							Load JPG	☒	
31	04/12/19 17:37	General View							Load JPG	☒	
32	04/12/19 17:37	General View							Load JPG	☒	
33	04/12/19 17:37	General View							Load JPG	☒	
34	04/12/19 17:37	General View							Load JPG	☒	
35	04/12/19 17:37	General View							Load JPG	☒	
36	04/12/19 17:37	General View							Load JPG	☒	

Video			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
				☒
37	04/12/19 17:37	General View		Load JPG ☒
38	04/12/19 17:37	General View		Load JPG ☒
39	04/12/19 17:37	General View		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/04/19 15:54	Log card (If available)		Load PDF ☒
2	26/04/19 15:54	Certificate of Insurance		Load PDF ☒
3	26/04/19 15:54	Driver's Driving License		Load PDF ☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/04/19 17:29	Singapore Accident Statement		Load PDF ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/19 11:11	TP ESTIMATE - MARKED		Load PDF ☒
2	29/11/19 10:55	WORKSHOP INVOICE		Load PDF ☒
3	29/11/19 10:55	MEDICAL FEE		Load PDF ☒
4	29/11/19 10:55	LTA SEARCH		Load PDF ☒
5	29/11/19 10:55	LOD		Load PDF ☒
6	13/02/20 10:37	AUTHORISATION TO ACT FORM		Load PDF ☒
7	13/02/20 10:37	DISCHARGE VOUCHER		Load PDF ☒

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	24/04/19 16:07	Video - Accident		Load MP4 ☒
Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	04/09/19 00:36	Accident Statement		Load HTM ☒
Photos/Images			3 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	24/04/19 14:27	Accident Photo		Load JPG ☒
2	24/04/19 14:27	Accident Photo		Load JPG ☒
3	24/04/19 14:27	Accident Photo		Load JPG ☒
4	24/04/19 14:27	Accident Photo		Load JPG ☒
5	24/04/19 14:27	Accident Photo		Load JPG ☒
6	24/04/19 14:27	Accident Photo		Load JPG ☒
7	24/04/19 14:27	Accident Photo		Load JPG ☒
8	24/04/19 14:27	Accident Photo		Load JPG ☒
9	24/04/19 14:27	Accident Photo		Load JPG ☒
10	24/04/19 14:27	Accident Photo		Load JPG ☒
11	24/04/19 14:27	Accident Photo		Load JPG ☒
12	24/04/19 14:27	Accident Photo		Load JPG ☒
13	24/04/19 14:27	Accident Photo		Load JPG ☒
14	24/04/19 14:27	Accident Photo		Load JPG ☒
15	24/04/19 14:27	Accident Photo		Load JPG ☒
16	24/04/19 14:27	Accident Photo		Load JPG ☒
17	24/04/19 14:27	Accident Photo		Load JPG ☒
18	24/04/19 16:07	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	24/04/19 14:19	Sketch Plan		Load TIF ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19007457/KGA3Q2

Date: 13/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SMJ9682R Insured Vehicle No: SHA4962Y
 Vehicle No: SMJ9682R
 Date of Loss: 23/04/2019 Nature of Claim: TP Claim No: MCT19040655

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ9682R
 Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1454476
 Reg. Date: 26/03/2019 (Man. Year: 2019) Chassis No: GK31345827
 Colour: Metallic Dark Blue Odometer: 2332 km
 Engine Capacity: 1317 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,590.40	8,364.92	2,225.48	21.01
Miscellaneous Items	10.00	11.00	-1.00	-10.00
Labour	6,180.00	3,950.00	2,230.00	36.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,780.40	12,325.92	4,454.48	26.55
Approved Total (Overridden) (S\$)		12,324.92		
(S\$)	16,780.40	12,324.92	4,455.48	26.55
+ GST 7.00/7.00% (S\$)	1,174.63	862.74	311.89	26.55
Nett Amount (S\$)	17,955.03	13,187.66	4,767.37	26.55
+ Loss of Use (16.0 x S\$50.00/day) (S\$)		800.00		
+ Medical Costs (S\$)		132.68		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		14,127.79		

INSPECTION

Date of Assignment: 26/04/2019 Present Location: Ah Lim Motor Company (AMK)
 Date Inspected: 30/04/2019 Inspected At: Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A,
 #01-09 AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 13.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2019)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ9682R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CENTER LOWER GARNISH	Damaged	-	*125.00 FL
2	1		*REAR NUMBER PLATE GARNISH	Damaged	-	*270.00 FL
3	1		*REAR TAIL LAMP CLIP LH	Necessary	-	*7.00 FL
4	1		*REAR BAFFLE SILENCER TOP COVER	Damaged	-	*35.00 FL
5	1		*FRONT BUMPER BEAM UPPER LH	Damaged	-	*60.00 FL
6	1		*STAY FRONT GRILLE	Damaged	-	*42.00 FL
7	1		*BUZZER ASSY	Damaged	-	*140.00 FL
8	1		*ANTENNA	Damaged	-	*120.00 FL
9	1		*POCKET	Damaged	-	*22.00 FL
10	1		*REAR TOOL BOX	Damaged	-	*130.00 FL
11	1		*FRONT BONNET	Bent	550.00 FL	*550.00 FL
12	2		*FRONT BONNET HINGE LH & RH	Repair	90.00 FL	*- FL
13	2		*FRONT BONNET RUBBER CENTRE LH & RH	Serviceable	44.00 FL	*- FL
14	2		*FRONT BONNET RUBBER SIDE LH & RH	Serviceable	28.60 FL	*- FL
15	1		*FRONT BONNET INNER LOCK	Not Necessary	90.50 FL	*- FL
16	1		*FRONT GRILLE	Cracked	352.90 FL	*352.90 FL
17	1		*FRONT GRILLE EMBLEM	Not Necessary	23.40 FL	*- FL
18	1		*FRONT GRILLE CHROME MOULDING TOP	Cracked	265.00 FL	*265.00 FL
19	1		*FRONT GRILLE CHROME MOULDING LOWER	Scratched	225.00 FL	*225.00 FL
20	8		*FRONT GRILLE CLIPS	Necessary	31.20 FL	*31.20 FL
21	1		*HEADLAMP LH & RH	N/S Cut	1,590.00 FL	*795.00 FL
22	1		*FRONT BUMPER	Buckled	495.00 FL	*495.00 FL
23	1		*FRONT BUMPER SIDE RETAINERS LH & RH	N/S Distorted	30.80 FL	*15.40 FL
24	15		*FRONT BUMPER CLIPS	Necessary	58.50 FL	*58.50 FL
25	1		*FRONT BUMPER LOWER AIR GRILLE	Not Necessary	180.00 FL	*- FL
26	1		*FRONT BUMPER REINFORCEMENT	Dented	203.80 FL	*203.80 FL
27	2		*FOG LAMP COVER LH & RH	Serviceable	116.60 FL	*- FL
28	1		*RADIATOR SUPPORT PANEL	Repair	455.00 FL	*- FL
29	1		*RADIATOR SUPPORT PANEL TOP GARNISH	Serviceable	12.40 FL	*- FL
30	8		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	31.20 FL	*- FL
31	1		*AIR CON CONDENSER	Damaged	810.00 FL	*810.00 FL
32	1		*RADIATOR ASSY	Damaged	1,250.00 FL	*1,250.00 FL
33	1		*RADIATOR FAN MOTOR	Serviceable	336.00 FL	*- FL
34	1		*RADIATOR FAN BLADE	Serviceable	78.00 FL	*- FL
35	1		*RADIATOR FAN COWLING	Serviceable	150.00 FL	*- FL
36	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
37	1		*TAILGATE	Bent	814.00 FL	*814.00 FL
38	1		*TAILGATE EMBLEM	Necessary	15.70 FL	*15.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*TAILGATE FIT LOGO	Necessary	35.00 FL	*35.00 FL
40	2		*TAILGATE LAMP LH & RH	Not Necessary	77.00 FL	*- FL
41	1		*TAILGATE REVERSE CAMERA	Not Necessary	1,041.00 FL	*- FL
42	1		*TAILGATE INNER LOCK	Dented	157.10 FL	*157.10 FL
43	1		*TAILGATE RUBBER	Deformed	92.30 FL	*92.30 FL
44	2		*TAILAMP LH & RH	Cut	474.80 FL	*474.80 FL
45	1		*REAR BUMPER	Bent	492.60 FL	*492.60 FL
46	2		*REAR BUMPER SIDE RETAINERS LH & RH	Cracked	23.00 FL	*23.00 FL
47	15		*REAR BUMPER CLIPS	Necessary	58.50 FL	*58.50 FL
48	1		*REAR BUMPER LOWER COVER	Bent	130.60 FL	*130.60 FL
49	15		*REAR BUMPER CLIPS	Necessary	58.50 FL	*58.50 FL
50	2		*REAR BUMPER SIDE GRILLE LH & RH	Cracked	96.00 FL	*96.00 FL
51	1		*END PANEL	Bent	390.00 FL	*390.00 FL
52	1		*END PANEL TOP GARNISH	Buckled	60.80 FL	*60.80 FL
53	1		*SPARE TYRE PANEL	Bent / Buckled	697.00 FL	*697.00 FL
54	1		*SPARE TYRE PANEL TOP TRIMBOARD -CHECK PRICE (NPA)	Not Necessary	0.00 FL	*- FL
55	2		*REAR FENDER INNER TRIM LH & RH	Deformed	331.20 FL	*331.20 FL
56	1		*NUMBER PLATE	Rear Serviceable / Frt Cracked	70.00 FS	*35.00 FS
57	2		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
58	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
59	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
60	1		*COOLANT	Necessary	30.00 FS	*30.00 FS
61	1		*AIR CON CONDENSER	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,123.00	10,374.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,532.60	2,009.98
Total Parts (\$\$)	10,590.40	8,364.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	11.00
Sub Total (S\$)			10.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING. (FRONT)	New	40.00	20.00
2	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00	30.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00	500.00
4	TO SPRAY FRONT BONNET;FRONT BUMPER; FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL.	New	800.00	600.00
5	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.(REAR)	New	40.00	20.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	150.00	100.00
8	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	New	300.00	0.00
9	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	60.00	60.00
10	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	New	60.00	50.00
11	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	90.00	90.00
12	TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	New	60.00	60.00
13	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL,SPARE TYRE PANEL. TO KNOCK & REPAIR REAR FENDERLH & RH,REAR CHASSIS LH & RH,ROOF PANEL,INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	2,000.00	1,200.00
14	TO SPRAY TAILGATE, REAR BUMPER,END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR CHASSIS LH & RH, ROOF PANEL	New	1,600.00	1,000.00
15	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES ,RADIATOR AND HOSES ,VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS	New	-	100.00
Gross Labour Cost (S\$)			6,180.00	3,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >