

ASS. REC. BY:

REF: 003/TM119007458/Kgd3n2

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: YN4215A

Policy No. M5001579

Claims No. M1902940


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 87116

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S140 5082P Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Perodua Longitude c.o. 1995

Colour M White / R AC: Insured / Std / NI / NA

Sp. Reading 120509 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 283240

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M/S / Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 24/4/19 D.O.I. 26/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|------------------|--|
| 1 | File pass to |
| | S140 5082P CO3/TM118010659/Kgd3n2 OSA: 08/6/18 |
| | YN 4215A |
| 29/4/19 @ 1.75pm | Email GIA & estimate to Tom. |
| 30/5 | 89737.03 Subst (Ref 838560.73, 80%) |

RECEIVED 31

Date/Time, File Pass to? : Prell. Report

11/31/5 Final : Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

- Add Fee: : Site Insp (\$)
- : Interview (\$)
- : Tech Invs (\$)
- : Weekend (\$)

| |
|-----|
| 250 |
| 11 |
| |
| |
| |
| 261 |

Report Format: men-7P

Lump Sum / I.B.I: (\$ 9737.03)

Shiau Chan (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 31 May 2019 1:17 PM
To: Shiau Chan (LKKAuto)
Subject: RE: TP VEHICLE SHD 5082P (DOA: 24/04/2019) -- AAD1904-238
Attachments: image001.wmz; IMG_1767.JPG; IMG_1777.JPG; IMG_1770.JPG

Hi Shiau Chan

We confirmed COR amount \$9,737.03 (b4 GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: Thursday, 30 May, 2019 1:34 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHD 5082P (DOA: 24/04/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation of repair cost will be at \$9,737.03 and 3 repair days.

Kindly check.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 29 April 2019 1:25 PM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 24/04/2019, SHD 5082P (TP VEHICLE), YN 4715A (OI VEHICLE)
Attachments: SHD5082 GIA-.pdf; SHD5082 EST-.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5082P at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 26/04/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD5082P
Vehicle to be Exported: Yes
Intended Deregistration Date: 25 Apr 2019
Vehicle Make: RENAULT
Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour: Red
Manufacturing Year: 2015
Engine No.: M9R8839C003167
Chassis No.: VF1ABL15AUC283240
Maximum Power Output: 127.0 kW (170 bhp)
Open Market Value: \$19,998.00
Original Registration Date: 08 Dec 2017
First Registration Date: 08 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Dec 2025
PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 07 Dec 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$34,159.00
COE Rebate Amount: \$27,327.00
Total Rebate Amount: \$42,325.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 25/04/2019 09:23 |
| Date Of Accident | 24/04/2019 18:40 |
| Exact Location Of Accident | DOVER ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SHD5082P |
| Insured/Policyholder | |
| Name Of Registered Owner | TRANS-CAB SERVICES PTE LTD |
| Co Reg No | 200303878K |
| Email Address | CLAIMS@TRANSCAB.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-62866666 |

Vehicle Particulars

| | |
|--|--------------------|
| Manufacturer | RENAULT |
| Model | LATITUDE-2.0 L (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE AND REWARD |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | TAXI |

Insurance Company

| | |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage | THIRD PARTY |
| Fleet Policy | YES |
| Policy Number | VPX/P1680520 |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | WANG FANG KOK |
| NRIC No | S1617452A |
| Date Of Birth | 17/08/1963 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 25/11/2009 |
| Driving Experience | 9 YEARS AND 4 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96806797 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|--|
| Address, | BLK 607 CLEMENTI WEST STREET 1 #12-60 |
| Postcode | 120607 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | DRIZZLING |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

On 24.04.2019 at about 1840hours, I was stationary straight on the extreme right lane along Dover Road when the traffic light was red. While stationary, suddenly I felt an impact. Vehicle B (YN4715A) hit onto my taxi's rear portion.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------------|
| Vehicle Registration Number | YN4715A |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | GOODS VEHICLE |
| Name of Driver | SRINIVASAN PRABHU |
| NRIC/Passport Number | G7940793W |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach on report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5082P

AAD1904-238

Not Authorized

Assuming B4 paint

89737-03

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 5082P
VF1ABL15AUC283240
RENAULT
LATITUDE
24.4.2019
TOKIO MARINE
8/12/2017

PART

LIST

| QTY | PART | PRICE | STATUS |
|-----|-------------------------------|---------------------------|--------|
| 1 | 1 BUMPER COVER REAR | \$ <i>Buclou</i> 1,108.46 | ✓ |
| 2 | 1 BUMPER LOWER REAR | \$ <i>CM</i> 768.84 | ✓ |
| 3 | 1 BUMPER BRACKET CTR REAR | \$ <i>Sn</i> 113.47 | X |
| 4 | 1 BUMPR BRACKET SIDE RH REAR | \$ <i>Sn</i> 135.97 | X |
| 5 | 1 BUMPR RETAINER RH REAR | \$ <i>Sn</i> 44.99 | X |
| 6 | 1 BUMPER REFLECTOR RH | \$ <i>Sn</i> 43.61 | X |
| 7 | 1 BUMPR BRACKET SIDE LH REAR | \$ <i>Sn</i> 135.97 | < |
| 8 | 1 BUMPR RETAINER LH REAR | \$ <i>Sn</i> 44.99 | < |
| 9 | 1 BUMPER REFLECTOR LH | \$ <i>CM</i> 43.61 | ✓ |
| 10 | 1 BUMPER BEAM REAR | \$ <i>Bz</i> 777.52 | ✓ |
| 11 | 1 BUMPER BEAM BRACKET LH REAR | \$ <i>Dry</i> 225.95 | — |
| 12 | 1 BUMPER BEAM BRACKET RH REAR | \$ <i>Bz</i> 225.95 | ✓ |
| 13 | 1 BOOT REAR | \$ <i>Bz</i> 2,872.68 | ✓ |
| 14 | 1 BOOT FINISHER | \$ <i>way</i> 470.06 | ✓ |
| 15 | 1 BOOT WHEATERSTRIP | \$ <i>Sn</i> 323.05 | X |
| 16 | 1 BOOT REFLECTOR LAMP LH | \$ <i>CM</i> 493.35 | ✓ |
| 17 | 1 BOOT REFLECTOR LAMP RH | \$ <i>CM</i> 493.35 | ✓ |
| 18 | 1 BOOT BADGE 'RENAULT' | \$ <i>Re</i> 225.36 | ✓ |
| 19 | 1 BOOT BADGE | \$ <i>Re</i> 225.36 | ✓ |
| 20 | 1 BOOT STRUT LH | \$ <i>Sn</i> 276.08 | } X |
| 21 | 1 BOOT STRUT RH | \$ <i>Sn</i> 276.08 | |
| 22 | 1 BOOT HINGE LH | \$ <i>R</i> 367.84 | |
| 23 | 1 BOOT HINGE RH | \$ <i>R</i> 367.84 | |
| 24 | 1 BOOT INNER TRIM | \$ <i>Sn</i> 586.45 | |
| 25 | 1 BOOT SWITCH | \$ <i>Sn</i> 168.13 | |
| 26 | 1 BOOT LOCK | \$ <i>R</i> 202.67 | |
| 27 | 1 BOOT LOCK CATCH | \$ <i>R</i> 74.40 | |
| 28 | 2 LICENCE PLATE LAMP | \$ <i>Sn</i> 50.52 | |
| 29 | 2 BOOT RUBBER PLUG | \$ <i>Sn</i> 221.81 | |

Trans-cab Auto Services Pte Ltd

AAD1904-238

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5082P

| | | | | | |
|----|---|----|------|----------|-----|
| 30 | 1 FENDER PANEL REAR RH | \$ | R | 3,299.13 | X |
| 31 | 1 WHEELARCH REAR RH | \$ | Sn | 543.47 | X |
| 32 | 1 FENDER PANEL INNER TRIM REAR RH | \$ | Sn | 671.45 | X |
| 33 | 1 FENDER PANEL REAR LH | \$ | R | 3,299.13 | X |
| 34 | 1 WHEELARCH REAR LH | \$ | Sn | 543.47 | X |
| 35 | 1 TAILLAMP LH | \$ | mgcm | 552.55 | ✓ |
| 36 | 1 TAILLAMP PANEL LH | \$ | R | 986.70 | X |
| 37 | 1 TAILLAMP RH | \$ | mgcm | 552.55 | ✓ |
| 38 | 1 TAILLAMP PANEL RH | \$ | R | 986.70 | } X |
| 39 | 1 OUTER PANEL REAR (End Panel) | \$ | R | 1,471.77 | |
| 40 | 1 OUTER PANEL REAR (End Panel)TRIM | \$ | Sn | 404.56 | |
| 41 | 1 SPARE WHEEL PANEL (Luggage Floor Panel) | \$ | R | 2,189.88 | |
| 42 | 1 SPARE WHEEL PANEL TRIM | \$ | Sn | 612.21 | |
| 43 | 1 EXHAUST REAR | \$ | R | 7,489.05 | |
| 44 | 1 EXHAUST CAP REAR | \$ | R | 230.49 | |

| | | | | | |
|--------------|-----------|--|--|------------------|----|
| | | | | | 47 |
| TOTAL | \$ | | | 35,197.49 | |
| 10% | \$ | | | 3,519.75 | |
| | \$ | | | 31,677.74 | |

Special Nett

| | | | | | |
|----|-------------------------------------|----|----|--------|------|
| 1 | 1SET PARKING AID | \$ | Sn | 700.00 | X |
| 2 | 1SET REAR BUMPER CLIP | \$ | na | 66.00 | ✓ |
| 3 | 1SET BUMPER BRACKET CTR CLIP | \$ | na | 33.00 | ✓ |
| 4 | 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | na | 10.00 | X |
| 5 | 1SET BUMPR RETAINER RH CLIP RR | \$ | na | 20.00 | X |
| 6 | 1SET BUMPR BRACKET SIDE CLIP LH RR | \$ | na | 10.00 | X |
| 7 | 1SET BUMPR RETAINER CLIP LH RR | \$ | na | 20.00 | X |
| 8 | 1SET BUMPER LOWER REAR RIVET | \$ | na | 22.00 | X |
| 9 | 1SET BUMPER LOWER REAR CLIP | \$ | na | 66.00 | ✓ |
| 10 | 1 EXHAUST MOUNTING REAR | \$ | Sn | 17.82 | X |
| 11 | 1SET BOOT FINISHER CLIP | \$ | na | 24.20 | X |
| 12 | 1 REAR BOOT STICKER 'TRANS-CAB' | \$ | na | 80.00 | 30na |
| 13 | 1 REAR BOOT STICKER '6555-3333' | \$ | na | 80.00 | 30na |

Trans-cab Auto Services Pte Ltd

AAD1904-238

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5082P

| | | | | | |
|----|-------------------------------------|----|-----------|--------|-----|
| 15 | 1SET FENDER WHEELARCH REAR RH CLIP | \$ | <i>na</i> | 35.00 | X |
| 16 | 1SET FENDER WHEELARCH REAR LH CLIP | \$ | <i>na</i> | 35.00 | X |
| 17 | 1 FENDER INNER TRIM CLIP LH | \$ | <i>na</i> | 28.00 | X |
| 18 | 1 FENDER INNER TRIM CLIP LH | \$ | <i>na</i> | 28.00 | X |
| 19 | 1 TAILLAMP CLIP RH | \$ | <i>na</i> | 5.00 | — |
| 20 | 1 TAILLAMP CLIP LH | \$ | <i>na</i> | 5.00 | — |
| 21 | 2 REAR WINDSCREEN SELANT | \$ | <i>na</i> | 80.00 | } X |
| 22 | 1 WINDSCREEN MOULDING | \$ | <i>na</i> | 100.00 | |
| 23 | 1 REAR WINDSCREEN INNER SPONGE SEAL | \$ | <i>na</i> | 100.00 | |
| 24 | 1 SPARE TYRE RIM (ROUE 7J 16H 2547) | \$ | <i>sh</i> | 385.00 | |
| 25 | 1 SPARE TYRE | \$ | <i>sh</i> | 330.00 | |

TOTAL \$ 2,280.02

TOTAL PARTS \$ 33,957.76

LABOUR

| | | | |
|---|----|------------------|-------------|
| Putty And Spray Painting Of The Affected Portion. | \$ | 6,000.00 | <i>6601</i> |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 6,000.00 | <i>5001</i> |
| To Rust-Proofing Of The Affected Areas. | \$ | 170.00 | <i>301</i> |
| To reinstall rear bumper parking sensor. | \$ | 170.00 | <i>601</i> |
| To transfer of bootlid fittings, attachments and perform water seepage test. | \$ | 170.00 | <i>601</i> |
| To repair and realign rear exhaust pipe. | \$ | <i>na</i> 170.00 | X |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | <i>na</i> 170.00 | X |

Trans-cab Auto Services Pte Ltd

AAD1904-238

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5082P

| | | | |
|--|----|-----------------|------------|
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | 170.00 | <i>602</i> |
| To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. | \$ | <i>~</i> 170.00 | <i>X</i> |
| To supply and re-do rear luggage floor panel insulation padding. | \$ | <i>~</i> 380.00 | <i>X</i> |
| To transfer of rear fender fittings, attachment and perform water seepage test. | \$ | <i>~</i> 380.00 | <i>X</i> |
| To transfer of rear windscreen fittings and conduct water seepage test. | \$ | <i>~</i> 170.00 | <i>X</i> |
| To check steering geometry and computer wheel alignment | \$ | <i>~</i> 220.00 | <i>X</i> |
| To transfer of rear door fittings, attachment and perform water seepage test. | \$ | <i>~</i> 380.00 | <i>X</i> |

TOTAL \$ 14,340.00**Over All Total \$ 48,297.76***48677.74***(LUMP SUM)****Repair Days***20-DAYS**3 days*

Lick Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19007458/KQD3N2

Date: 04/06/2019

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|----------|
| Handling Insurer: | Tokio Marine Insurance Singapore Ltd | Policy No: | MS001579 |
| Claimant Vehicle No : | SHD5082P | Insured Vehicle No : | YN4715A |
| Date of Loss: | 24/04/2019 | Nature of Claim: | TP |
| | | Claim No: | M1902940 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SHD5082P | Engine No: | M9R8839C003167 |
| Make & Model: | RENAULT LATITUDE, 2.0 L (A) | Chassis No: | VF1ABL15AUC283240 |
| Reg. Date: | 08/12/2017 (Man. Year: 2015) | Odometer: | 120509 km |
| Colour: | Metallic White/Red | | |
| Engine Capacity: | 1995 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-----------|------------------|-----------|
| Front Tyre Size: | 215/60R16 | Rear Tyre Size: | 215/60R16 |
| Front Left Side: | Giti 8 mm | Rear Left Side: | Giti 8 mm |
| Front Right Side: | Giti 8 mm | Rear Right Side: | Giti 8 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|------------------|------------------|--------------|
| Parts | 33,957.74 | 8,367.03 | 25,590.71 | 75.36 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 14,720.00 | 1,370.00 | 13,350.00 | 90.69 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 48,677.74 | 9,737.03 | 38,940.71 | 80.00 |
| + GST 7.00/7.00% (S\$) | 3,407.44 | 681.59 | 2,725.85 | 80.00 |
| Nett Amount (S\$) | 52,085.18 | 10,418.62 | 41,666.56 | 80.00 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 29/04/2019 | | |
| Date Inspected: | 26/04/2019 | Inspected At: | Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 03 Jun 2019) |
| Parts: 143 | RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SHD5082P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk * |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|--|----------------|-------------|--------------|
| 1 | 1 | *BUMPER COVER REAR | Buckled/Dented | 1,108.46 FL | *1,108.46 FL |
| 2 | 1 | *BUMPER LOWER REAR | Cracked | 768.84 FL | *768.84 FL |
| 3 | 1 | *BUMPER BRACKET CTR REAR | Serviceable | 113.47 FL | *- FL |
| 4 | 1 | *BUMPER BRACKET SIDE RH REAR | Serviceable | 135.97 FL | *- FL |
| 5 | 1 | *BUMPER RETAINER RH REAR | Serviceable | 44.99 FL | *- FL |
| 6 | 1 | *BUMPER REFLECTOR RH | Serviceable | 43.61 FL | *- FL |
| 7 | 1 | *BUMPER BRACKET SIDE LH REAR | Serviceable | 135.97 FL | *- FL |
| 8 | 1 | *BUMPER RETAINER LH REAR | Serviceable | 44.99 FL | *- FL |
| 9 | 1 | *BUMPER REFLECTOR LH | Cracked | 43.61 FL | *43.61 FL |
| 10 | 1 | *BUMPER BEAM REAR | Bent | 777.52 FL | *777.52 FL |
| 11 | 1 | *BUMPER BEAM BRACKET LH REAR | Distorted | 225.95 FL | *225.95 FL |
| 12 | 1 | *BUMPER BEAM BRACKET RH REAR | Bent | 225.95 FL | *225.95 FL |
| 13 | 1 | *BOOT REAR | Bent | 2,872.68 FL | *2,872.68 FL |
| 14 | 1 | *BOOT FINISHER | Warped | 470.06 FL | *470.06 FL |
| 15 | 1 | *BOOT WEATHERSTRIP | Serviceable | 323.05 FL | *- FL |
| 16 | 1 | *BOOT REFLECTOR LAMP LH | Cracked | 493.35 FL | *493.35 FL |
| 17 | 1 | *BOOT REFLECTOR LAMP RH | Cracked | 493.35 FL | *493.35 FL |
| 18 | 1 | *BOOT BADGE RENAULT | Necessary | 225.36 FL | *225.36 FL |
| 19 | 1 | *BOOT BADGE | Necessary | 225.36 FL | *225.36 FL |
| 20 | 1 | *BOOT STRUT LH | Serviceable | 276.08 FL | *- FL |
| 21 | 1 | *BOOT STRUT RH | Serviceable | 276.08 FL | *- FL |
| 22 | 1 | *BOOT HINGE LH | Repair | 367.84 FL | *- FL |
| 23 | 1 | *BOOT HINGE RH | Repair | 367.84 FL | *- FL |
| 24 | 1 | *BOOT INNER TRIM | Serviceable | 586.45 FL | *- FL |
| 25 | 1 | *BOOT SWITCH | Serviceable | 168.13 FL | *- FL |
| 26 | 1 | *BOOT LOCK | Repair | 202.67 FL | *- FL |
| 27 | 1 | *BOOT LOCK CATCH | Repair | 74.40 FL | *- FL |
| 28 | 2 | *LICENCE PLATE LAMP | Serviceable | 50.52 FL | *- FL |
| 29 | 2 | *BOOT RUBBER PLUG | Serviceable | 221.81 FL | *- FL |
| 30 | 1 | *FENDER PANEL REAR RH | Repair | 3,299.13 FL | *- FL |
| 31 | 1 | *WHEELARCH REAR RH | Serviceable | 543.47 FL | *- FL |
| 32 | 1 | *FENDER PANEL INNER TRIM REAR RH | Serviceable | 671.45 FL | *- FL |
| 33 | 1 | *FENDER PANEL REAR LH | Repair | 3,299.13 FL | *- FL |
| 34 | 1 | *WHEELARCH REAR LH | Serviceable | 543.47 FL | *- FL |
| 35 | 1 | *TAILLAMP LH | Mtg Cracked | 552.55 FL | *552.55 FL |
| 36 | 1 | *TAILLAMP PANEL LH | Repair | 986.70 FL | *- FL |
| 37 | 1 | *TAILLAMP RH | Mtg Cracked | 552.55 FL | *552.55 FL |
| 38 | 1 | *TAILLAMP PANEL RH | Repair | 986.70 FL | *- FL |
| 39 | 1 | *OUTER PANEL REAR (END PANEL) | Repair | 1,471.77 FL | *- FL |
| 40 | 1 | *OUTER PANEL REAR (END PANEL) TRIM | Serviceable | 404.56 FL | *- FL |
| 41 | 1 | *SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) | Repair | 2,189.88 FL | *- FL |
| 42 | 1 | *SPARE WHEEL PANEL TRIM | Serviceable | 612.21 FL | *- FL |
| 43 | 1 | *EXHAUST REAR | Repair | 7,489.05 FL | *- FL |
| 44 | 1 | *EXHAUST CAP REAR | Repair | 230.49 FL | *- FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|-------------------------------------|---------------|------------|-----------|
| 45 | 1 | *SET PARKING AID | Serviceable | 700.00 FS | *- FS |
| 46 | 1 | *SET REAR BUMPER CLIP | Necessary | 66.00 FS | *66.00 FS |
| 47 | 1 | *SET BUMPER BRACKET CTR CLIP | Necessary | 33.00 FS | *33.00 FS |
| 48 | 1 | *SET BUMPER BRACKET SIDE CLIP RH RR | Not Necessary | 10.00 FS | *- FS |
| 49 | 1 | *SET BUMPER RETAINER RH CLIP RR | Not Necessary | 20.00 FS | *- FS |
| 50 | 1 | *SET BUMPER BRACKET SIDE CLIP LH RR | Not Necessary | 10.00 FS | *- FS |
| 51 | 1 | *SET BUMPER RETAINER CLIP LH RR | Not Necessary | 20.00 FS | *- FS |
| 52 | 1 | *SET BUMPER LOWER REAR RIVET | Not Necessary | 22.00 FS | *- FS |
| 53 | 1 | *SET BUMPER LOWER REAR CLIP | Necessary | 66.00 FS | *66.00 FS |
| 54 | 1 | *EXHAUST MOUNTING REAR | Serviceable | 17.82 FS | *- FS |
| 55 | 1 | *SET BOOT FINISHER CLIP | Not Necessary | 24.20 FS | *- FS |
| 56 | 1 | *REAR BOOT STICKER TRANS-CAB | Necessary | 80.00 FS | *30.00 FS |
| 57 | 1 | *REAR BOOT STICKER 6555-3333 | Necessary | 80.00 FS | *30.00 FS |
| 58 | 1 | *SET FENDER WHEELARCH REAR RH CLIP | Not Necessary | 35.00 FS | *- FS |
| 59 | 1 | *SET FENDER WHEELARCH REAR LH CLIP | Not Necessary | 35.00 FS | *- FS |
| 60 | 1 | *FENDER INNER TRIM CLIP LH | Not Necessary | 28.00 FS | *- FS |
| 61 | 1 | *FENDER INNER TRIM CLIP LH | Not Necessary | 28.00 FS | *- FS |
| 62 | 1 | *TAILLAMP CLIP RH | Necessary | 5.00 FS | *5.00 FS |
| 63 | 1 | *TAILLAMP CLIP LH | Necessary | 5.00 FS | *5.00 FS |
| 64 | 2 | *REAR WINDSCREEN SEALANT | Not Necessary | 80.00 FS | *- FS |
| 65 | 1 | *WINDSCREEN MOULDING | Not Necessary | 100.00 FS | *- FS |
| 66 | 1 | *REAR WINDSCREEN INNER SPONGE SEAL | Not Necessary | 100.00 FS | *- FS |
| 67 | 1 | *SPARE TYRE RIM (ROUE 7J 16H 2547) | Serviceable | 385.00 FS | *- FS |
| 68 | 1 | *SPARE TYRE | Serviceable | 330.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (\$\$) | 37,477.49 | 9,270.59 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 3,519.75 | 903.56 |
| Total Parts (\$\$) | 33,957.74 | 8,367.03 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 6,000.00 | 660.00 |
| 2 | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME | New | 6,000.00 | 500.00 |
| 3 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 30.00 |
| 4 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 60.00 |
| 5 | TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 60.00 |
| 6 | TO REPAIR AND REALIGN REAR EXHAUST PIPE | New | 170.00 | 0.00 |
| 7 | TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE | New | 170.00 | 0.00 |
| 8 | TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 60.00 |
| 9 | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 10 | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING | New | 380.00 | 0.00 |
| 11 | TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 12 | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 13 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 14 | TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 14,720.00 | 1,370.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >