



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005915
INV Date 28/08/2020
Reference CC6/CTI19007481/Uds3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 6717Z
Insured Veh. GBA 8507Z
Claim No. SNM19D201870C02/7
Policy No. DMCVSN3009381903
Accident Date 25/04/2019
Inspection Date 29/04/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19007481/Uds3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 28-08-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 8507Z	Veh. Inspected	SLU 6717Z	
Policy No.	DMCVSN3009381903	Coverage (\$)	0.00	
Claim No.	SNM19D201870C02/7	Excess (\$)	0.00	
Assign From		Assign Date	29/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11228369	Colour	SILVER	
Odometer	18322	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2019	Inspection Date	29/04/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 6717Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR N/S	DENTED / BENT	1,455.10	1,120.30
1	FRONT DOOR GLASS N/S	DEEP CUT	845.50	645.20
1	FRONT DOOR GLASS OUTER MOULDING N/S	NOT NECESSARY	145.80	-
1	SET FRONT DOOR FRAME BLACK STICKER N/S	SCRATCHED	88.50	88.50
1	FRONT DOOR INNER LOCK N/S	NOT NECESSARY	299.20	-
1	FRONT DOOR INNER RUBBER N/S	NECESSARY	142.60	142.60
1	FRONT DOOR VIEW MIRROR ASSY N/S	CUT / SHORTED	1,105.20	890.50
1	FRONT DOOR OUTER HANDLE N/S	SCRATCHED	305.20	299.20
1	FRONT DOOR LOWER RUBBER N/S	NECESSARY	89.90	89.90
1	FRONT DOOR OUTER PILLAR N/S	TO REPAIR SEE LABOUR	899.20	-
1	FRONT DOOR INNER TRIM BOARD N/S	NOT NECESSARY	645.30	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	121.80	-
1	REAR DOOR N/S	TO REPAIR SEE LABOUR	1,215.30	-
1	SET REAR DOOR FRAME BLACK STICKER N/S	SCRATCHED	88.50	88.50
1	FRONT WINDSCREEN SEALANT	NOT NECESSARY	50.00	-
	LESS 20% DISCOUNT		-	-672.94
			7,497.10	2,691.76
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	150.00	-
	TO TRANSFER FRONT DOOR MECHANISM.		100.00	60.00
	TO REPROGRAMME & RESET SYSTEM.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.		80.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER PILLAR N/S AND REAR DOOR N/S .		880.00	520.00
	TO PUTTY & SPRAY PAINTING.		1,100.00	700.00
			2,510.00	1,350.00
	GRAND TOTAL		10,007.10	4,041.76



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00
---	--	--	-----------------

Report Ref No. CC6/CT119007481/Uds3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 6717Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 6717Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

