



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	9 2016 MITSUBISHI CANTER FEA01BR1SDEB MITXXX (GBF2304E)
Date of Loss	24 April 2019
Time of Loss	10.30
Loss Description	GBF2304E (INSD) HIT REAR OF GBC5406R (TP)
Comment	

Workshop Details

Total Rebate Amount	29030
Nett Loss Amount	\$33,970.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# GBF2304E

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

28/07/2016



Mileage

117414

Age of Vehicle

2

Driver Details

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2016

2016

Make

MITSUBISHI CANTER
FEA01BR1SDEB

MITSUBISHI

Model

MITXXX

CANTER FEA01BF

CATEGORY

FNOL
INFORMATIONPOST SURVEY
INFORMATION

Driver Name

SURIME BIN
HARIS

Date of Birth

26 December
1980

dd/mm/yyyy



Age

38

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	FEA01BA20263	FEA01BA20263
Engine No	4P10C24807	4P10C24807
Engine Capacity		2998
Sum Insured	0	0
Market Value	0	63000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	6	
Driver License #		
License Type		
License Issue Date	1 January 2013	dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S8040144B	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

29/04/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

700

Young/Inexperienced/
Named Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195R15X8

Front left side

YOKOHAMA9mm

Front right side

YOKOHAMA9mm

Rear Tyre Size

195R15X8(D)

Rear left side

YOKOHAMA9/9mm

Rear right side

YOKOHAMA9/9mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRONT BUMPER (WCP) (10%)	Bent	0	495	No					495	Reviewing	
		0	1		R/F BUMPER CORNER (WCP) (10%)	Buckled	0	209	No					209	Reviewing	
		0	1		FRONT GRILLE (WCP) (10%)	Cracked	0	319	No					319	Reviewing	
		0	1		FRONT MANUFACT BADGE (NPA)	Serviceable	0	0	No					0	Deny	
		0	1		BADGE (NPA)	Serviceable	0	0	No					0	Deny	
		0	1		BADGE (NPA)	Serviceable	0	0	No					0	Deny	
		0	1		RIGHT HEADLAMP ASSY (WCP) (10%)	Broken	0	385	No					385	Reviewing	
		0	1		R/F INDICATOR (WCP) (10%)	Broken	0	209	No					209	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		R/POSITION LAMP (WCP) (10%)	Broken	0	154	No					154	Reviewing	
		0	1		R/F CORNER PANEL (WCP) (10%)	Cracked	0	308	No					308	Reviewing	
		0	1		FRONT PANEL CPL (WCP) (10%)	Bent	0	715	No					715	Reviewing	
		0	1		FRONT PANEL TRIM (WCP) (10%)	Cracked	0	396	No					396	Reviewing	
		0	1		WINDSCREEN	Serviceable	0	0	No					0	Deny	
		0	1		WINDSCREEN SEAL (WCP) (10%)	Necessary	0	154	No					154	Reviewing	
		0	1		CAB SUPPORT	Repair	0	0	No					0	Deny	
		0	1		HEATER BLOWER	Serviceable	0	0	No					0	Deny	
		0	1		DOOR INNER LAMP (WCP) (10%)	Cracked	0	60.5	No					60.5	Reviewing	
		0	1		HEADLAMP LWR RUBBER (WCP) (10%)	Missing	0	22	No					22	Reviewing	
		0	1		RH MIRROR (WCP) (10%)	Cracked	0	82.5	No					82.5	Reviewing	
		0	1		MIRROR HANDLE COVER (WCP) (10%)	Missing	0	44	No					44	Reviewing	
Labour																

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
 	0		VACUUM & TOP UP AC	0	50	0	0	Reviewing		
 	0		ELECTRICAL WORK	0	20	0	0	Reviewing		
 	0		305.0 WU X 45.00 SGD / H	0	738	0	0	Reviewing		
 	0		LABOUR COST 102.0 WU X 45.00 SGD / H	0	396	0	0	Reviewing		
 	0		MATERIAL COST	0	133.96	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS OF
REPAIR :
7 DAYS

Reviewing

0



0

IU
BRACKET

Deny

0

NOT
NECESSARY

0

FRONT
NUMBER
PLATE

Reviewing

20

BENT





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$4,210.96

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$3,553.00

Labour

\$0.00

\$1,337.96

Miscellaneous

\$0.00

\$20.00

Excess

-\$700.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

1800





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount			\$1,100.00	
CATEGORY		ESTIMATE		ADJUSTED				
Miscellaneous		\$0.00		\$1,800.00				
Excess				-\$700.00				

Submit for Review