

INSPG:

INS. CASE OWNER:

CC 4/FWD1900

LKK:

WAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

Name of Insured:

Insured Tel No:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

4803295B

INSRS:
WSP:
Tel:
Liability:
RMKS:Tony
luckINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

17-06-19 FILE PASS TO TYPES TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authentication To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PDR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

43 \$55,800

(5 days) Reduction:

34 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 08.01.19

Confirm with: LPPHORE

Email ☒Call ☐

Final Liability:

500

(Agreed / Assessed) BOLA S/N No. : 21

If NO or B 28, Ass. Lia:

Repair Cost:

w/LOU: \$53,403.90

OI RDRP ENDED TP.

Loss of Rental (LOR):

\$5 -

(5 days)

Loss of Use (LOU):

\$5 480.00

(5 60 x 8 days)

Loss of Income (LOI):

\$5 -

(5 x 8 days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

(Tick only one)

GIA/LTA Search:

\$57.95

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost:

\$5 -

Total:

\$5 5,890.95

Global Sum SS:

FINAL PAYMENT

Date/Time: 08.01.19

Confirm with: LPPHORE

Email ☒Call ☐

Payee 1:

\$53,890.95

Name 1: TONG LUCK AUTO PTE LTD

Payee 2 (Strike if N.A.):

\$5

Name 2:

Payee 3 (Strike if N.A.):

\$5

Name 3:

10/9/19

SENT

ASS. REC. BY:

REF: PWD /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

5 days

Res.: Yes or No

Lum Sum: _____

30 %

3 Val.: Yes or No

CA / REV WP REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: G80 3295BYr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Peugeot Partnerc.c. 1560Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 138586

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF37F9HF8EJ

735567

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front

Rear

R/Bal. 5 mmR/Bal. 6 mmL/Bal. 5 mmL/Bal. 6 mmD.O.A. 24/4/19D.O.I. 29/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to45: +5,050 (250: +2,113.90 39%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Fuel \$ _____

Others _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

*Not Authorized
C/Sig B?
Peugeot After Paint*

5-6 days

29/4/19 @ 1145 hrs

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		SG	SG

LIST PRICE

1 Rear door - RH	1	1,200.00	1,200.00
2 Rear door 'PARTNER' emblem - RH	1	122.00	122.00
3 Rear door 'e HDI' emblem - RH	1	102.00	102.00
4 Rear door trimboard - RH	1	355.00	355.00
5 Rear door inner trimboard clips - RH	10	6.00	60.00
6 Rear door - LH	1	1,320.00	1,320.00
7 Rear door 'PEUGEOT' emblem - LH	1	123.00	123.00
8 Rear door inner trimboard clips - LH	10	6.00	60.00
9 Rear-end-panel (outer)	1	380.00	380.00
10 Rear bumper	1	550.00	550.00
11 Rear bumper pad - RH	1	280.00	280.00
12 Rear bumper tow cover	1	39.00	39.00

Rear bumper reinforcement \$325 B1

Less 10%
4,871.10
4,383.90

SPECIAL NET

13 Rear door glass sealant - RH	1	50.00	50.00
14 Rear door glass sealant - LH	1	50.00	50.00
15 Rear bumper reverse sensor (set)	1	380.00	380.00
16 Rear door '70km/h' sticker - LH	1	25.00	25.00
17 Rear door '6pax' sticker - RH	1	15.00	15.00
18 Rear number plate	1	40.00	40.00

LABOUR

19 To check and rectify wiring system	1	80.00	80.00
20 To remove and refix both side door glass	1	200.00	200.00
21 To transfer both side rear door interior mechanism to new door	1	200.00	200.00
22 To panel beat rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
23 To putty and spray paint on affected areas	1	1,000.00	1,000.00
24 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00
25 To supply and paste sticker on both side rear door	1	680.00	680.00

3,280.00

1,960



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,223.90
		ADD GST @ 7%	575.67
		GRAND TOTAL	S\$ 8,799.57

SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED NINETY-NINE AND CENTS FIFTY-SEVEN ONLY

\$ 6,344.40
20% 1,268.88
\$ 5,075.52

Lump Sum \$ 5,050.00
7% 353.50
\$ 5,403.50

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



PRINTLAB
redefining print

PRINT LAB PTE LTD

25 Ubi Road 4 #01-01 Weltech Building Singapore 408621
Tel : 6749 0526 Fax : 6749 0683 Email: info@printlab.com.sg

Co. Reg No. 200711847C
GST No. 200711847-C

Sold To:

Tong Luck Auto Pte Ltd
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722

Attn: Terence Tan

Tel: 6250 0088

TAX INVOICE

Invoice No : IV-111804

Date : 06-May-19

Reference No.	Customer P.O. No.	Payment Terms	Due Date	Job Issue By
Q00023334		0	06/05/19	Terence
Quantity	Description	Unit Price	Total Amount	
1	RE: Peugeot_GBD3295B Peugeot_Back only_GBD3295B Subject : L_062G_070G_SCHNEIDER_1200x200MM_1PC Material : Block Out Sticker (MB) Finishing : Size: 1200mm (W) x 200mm (H)	400.00	400.00	

Subtotal	400.00
GST@7%	28.00
Total (SGD)	428.00

Please note that any overdue payment/s will be listed in the Singapore Commercial Credit Bureau (SCCB) records and this record may be assessed by financial institutions and other approving Credit companies.

* BANK Information

Name: PRINT LAB PTE LTD
Bank Name: Standard Chartered Bank, Singapore Branch
Bank Code: 7144
Branch Code: 001
Account No.: 0119156865
Swift code: SCBLSGSG
Address: 6 Battery Road Singapore 049909

Received, checked & accepted by

E. & O.E

This is a computer generated form.
No signature is required.

Cheques should be crossed and made payable to PRINT LAB PTE LTD
All goods sold are not refundable. Interest at 1.5% per month will charged on unpaid invoices.



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Not Authorized

LI Sup B?

Peugeot After Parts

5-6 days

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear door - RH	1	<i>As</i> 1,200.00	1,200.00 <i>✓</i>
2 Rear door 'PARTNER' emblem - RH	1	<i>m</i> 122.00	122.00 <i>✓</i>
3 Rear door 'e HDI' emblem - RH	1	<i>m</i> 102.00	102.00 <i>✓</i>
4 Rear door trimboard - RH	1	<i>CM</i> 355.00	355.00 <i>2</i>
5 Rear door inner trimboard clips - RH	10	<i>m</i> 6.00	60.00 <i>2</i>
6 Rear door - LH	1	<i>As</i> 1,320.00	1,320.00 <i>✓</i>
7 Rear door 'PEUGEOT' emblem - LH	1	123.00 <i>m</i>	123.00 <i>✓</i>
8 Rear door inner trimboard clips - LH	10	6.00	60.00 <i>?</i>
9 Rear end panel (outer)	1	380.00	380.00 <i>?</i>
10 Rear bumper	1	<i>Bu</i> 550.00	550.00 <i>✓</i>
11 Rear bumper pad - RH / LH	2	280.00	560.00 <i>✓</i>
12 Rear bumper tow cover	1	39.00	39.00 <i>✓</i>
			4,871.00
			Less 10%
			487.10
			4,383.90
SPECIAL NET			
13 Rear door glass sealant - RH	1	50.00 <i>m</i>	50.00 <i>40.50</i>
14 Rear door glass sealant - LH	1	50.00 <i>m</i>	50.00 <i>40.50</i>
15 Rear bumper reverse sensor (set)	1	380.00 <i>Bu</i>	380.00 <i>200.00</i>
16 Rear door '70km/h' sticker - LH	1	25.00 <i>m</i>	25.00 <i>15.50</i>
17 Rear door '6pax' sticker - RH	1	15.00 <i>m</i>	15.00 <i>✓</i>
18 Rear number plate	1	40.00 <i>Bu</i>	40.00 <i>X</i>
			560.00
LABOUR			
19 To check and rectify wiring system	1	80.00	80.00 <i>201</i>
20 To remove and refix both side door glass	1	200.00	200.00 <i>1601</i>
21 To transfer both side rear door interior mechanism to new door	1	200.00	200.00 <i>1201</i>
22 To panel beat rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 <i>?</i>
23 To putty and spray paint on affected areas	1	1,000.00	1,000.00 <i>6001</i>
24 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00 <i>601</i>
25 To supply and paste sticker on both side rear door	1	<i>B:11</i> 680.00	680.00 <i>?</i>
			3,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify both side door spray painting
- To rectify damaged part (during recovery)
- Part prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No single modification is allowed
- Supplementary work, without pre-approval and is subject to final approval from Insurance Company

Authorized by Repairer
Signature:
Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		TOTAL	S\$ 8,223.90
		ADD GST @ 7%	575.67
		GRAND TOTAL	<u>S\$ 8,799.57</u>

SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED NINETY-NINE AND CENTS FIFTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Saturday, 27 April 2019 3:42 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: AsherSng@lkkauto.com; motorclaims.sg@fwd.com
Subject: FW: ACCIDENT INVOLVING VEHICLE NO.: GBD3295B & SLL4878C ON 24/04/2019 ALONG FILTERING FROM PIE (TUAS) INTO UPPER JURONG ROAD Our Ref: 120190001089
Attachments: GBD3295B--NOA.PDF

12.31pm @ 27/4/19
vehicle in
condy
sur @ Kenneth.

Hi LKK team,

Please assist with the TP survey below and explore DS.

Thank you.

Regards,
Clara

From: Operation / Yu Ching [mailto:operation@tlauto.com.sg]
Sent: Saturday, 27 April, 2019 9:13 AM
To: Clara Li Zirong - SGUser
Cc: Motor Claims SG - SG Common
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: GBD3295B & SLL4878C ON 24/04/2019 ALONG FILTERING FROM PIE (TUAS) INTO UPPER JURONG ROAD Our Ref: 120190001089

Dear Clara,

We hereby confirm and agreed to nominate LKK Auto Consultants Pte Ltd to conduct the PRI survey of our client's vehicle.

Best regards,
Yu Ching

Tong Luck Auto Pte Ltd

From: clara.li@fwd.com [mailto:clara.li@fwd.com]
Sent: Friday, 26 April, 2019 6:31 PM
To: operation@tlauto.com.sg
Cc: motorclaims.sg@fwd.com
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: GBD3295B & SLL4878C ON 24/04/2019 ALONG FILTERING FROM PIE (TUAS) INTO UPPER JURONG ROAD Our Ref: 120190001089

WITHOUT PREJUDICE

Dear Sir/ Madam,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD

2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards,

Clara Li




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



From: Operation / Candy Ong [<mailto:operation@tlauto.com.sg>]

Sent: Friday, 26 April, 2019 5:30 PM

To: Motor Claims SG - SG Common

Subject: ACCIDENT INVOLVING VEHICLE NO.: GBD3295B & SLL4878C ON 24/04/2019 ALONG FILTERING FROM PIE (TUAS) INTO UPPER JURONG ROAD Our Ref: 1201900010894

Dear Clara,

We have our client's instruction to notify you the above accident.

Please find attached document for your information and necessary action

The vehicle is now garage at our workshop

Kindly let us have your surveyor list and arrange for the PRS of our client's vehicle at an earlier date

Best Regards,

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Print Received Message

This mail is associated with :

***GBD3295B (1201900010894)**
[SLL4878C]

TP

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD

Apr 24 2019 9:00AM

[CHAN CHUAN YONG KELVIN]

Tong Luck Auto Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 27/06/2019 12:34 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5890.95) - GBD3295B - Claim Handler: Clara Li Zi Rong

Approved:5890.95.



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : GBD3295B

Yours Ref : 120190001089

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD
SUNTEC TOWER 4 #18-01
SINGAPORE 038986

31 May 2019

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBD3295B & SLL4878C ON 24/04/2019 @ 09:20 HRS FILTERING FROM PIE (TUAS) INTO UPPER JURONG ROAD

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost of Repair	:	S\$5,403.50
Loss of Use (\$ 120.00 x 5 days)	:	S\$600.00
Additional Loss Of Use(\$120.00 x 2days) – Weekend / PH	:	S\$240.00
GIA / LTA Search	:	S\$7.45
		<u>S\$6,250.95</u>

Kindly revert within SEVEN days. Filing which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08 WESTGATE TOWER SINGAPORE 608531, owner of GBD3295B hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: GBD3295B that was damaged pursuant to the accident which occurred on 24/04/2019 FILTERING FROM PIE(TUAS) INTO UPPER JURONG ROAD involving vehicle nos: SLL4878C

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 26th day of April 2019



[Handwritten signature]

Signed by third party claimant



[Handwritten signature]

TONG LUCK AUTO PTE LTD

RELEASE

Claim Reference:	1201900010894
Surveyor's Reference:	CC4/FWD19007493/Keb3
TP Reference:	GBD 3295B

We, TONG LUCK AUTO PTE LTD ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle GBD 3295B ("Vehicle") to accept the sum of \$5,890.95, being the amount claimed for \$5,403.50 (repair costs), \$480.00 (loss of ~~rental~~ use), \$ - (loss of income), \$7.45 (disbursement) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 24/04/2019 (date of accident) at / along FILTERING FROM PIE (TUAS) INTO UPPER JURONG ROAD (location) involving vehicle no/s. GBD 3295B and SLL 4878C.



This is pursuant to the inspection conducted on 29/04/2019 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of SLL 4878C be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 8 day of July 2019

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]
For and on behalf of the "Claimant"



KSC

[FWD's appointed surveyor with Co. Stamp]
For and on behalf of FWD Singapore Pte. Ltd.



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

~~Tel: 6450 5104 Fax: 6450 2400~~

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email: operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : 120190001089

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 24/04/2019

TP VEHICLE NO : SLL4878C

NO : AR201905-0083

CLAIM NO : QUOT201904-000097(01)

DATE : 31/05/2019

POLICY NO : 999995580

VEH REG : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Final Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear door - RH	1	1,200.00	1,200.00
2 Rear door 'PARTNER' emblem - RH	1	122.00	122.00
3 Rear door 'e HDI' emblem - RH	1	102.00	102.00
4 Rear door trimboard - RH	1	355.00	355.00
5 Rear door - LH	1	1,320.00	1,320.00
6 Rear door 'PEUGEOT' emblem - LH	1	123.00	123.00
7 Rear bumper	1	550.00	550.00
8 Rear bumper reinforcement	1	325.00	325.00
9 Rear bumper pad - RH	1	280.00	280.00
10 Rear bumper tow cover	1	39.00	39.00
			4,416.00
		Less 10%	441.60
			3,974.40
SPECIAL NET			
11 Rear door inner trimboard clips - RH (set)	1	50.00	50.00
12 Rear door glass sealant - RH	1	40.00	40.00
13 Rear door glass sealant - LH	1	40.00	40.00
14 Rear door inner trimboard clips - LH (set)	1	50.00	50.00
15 Rear bumper reverse sensor (set)	1	200.00	200.00
16 Rear door '70km/h' sticker - LH	1	15.00	15.00
17 Rear door 'spax' sticker - RH	1	15.00	15.00
			410.00
LABOUR			
19 To check and rectify wiring system	1	20.00	20.00
20 To remove and refix both side door glass	1	160.00	160.00
21 To transfer both side rear door interior mechanism to new door	1	120.00	120.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

~~Tel: 6453 5104 Fax: 6453 2460~~

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email: operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : 120190001089

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 24/04/2019

TP VEHICLE NO : SLL4878C

TAX INVOICE

NO : AR201905-0083
CLAIM NO : QUOT201904-000097(01)
DATE : 31/05/2019
POLICY NO : 999995580
VEH REG : GBD3295B
MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB
CHASIS NO : VF37F9HF8EJ735567
ENGINE NO : 10JBFR0012800
REG. DATE : 2014

Final Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
22 To panel beat rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	600.00	600.00
23 To putty and spray paint on affected areas	1	600.00	600.00
24 To apply rust-proofing on repaired and replaced panels	1	60.00	60.00
25 To supply and paste sticker on both side rear door	1	400.00	400.00
			1,980.00

AMOUNT : S\$ 5,344.40

LUMP SUM DISCOUNT : S\$ -1,294.40

TOTAL : S\$ 5,050.00

ADD GST @ 7% : S\$ 353.50

GRAND TOTAL : S\$5,403.50

SINGAPORE DOLLARS FIVE THOUSAND FOUR HUNDRED AND THREE AND CENTS FIFTY ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 26 Apr 2019 / 11:25:02

Receipt Date/Time : 26 Apr 2019 / 11:25:02

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190426-001034

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLL4878C				
As at 24 Apr 2019/09:20:00				
Insurance Co: FWD SINGAPORE PTE. LTD.				
1	Insurance Enquiry - SLL4878C Enquiry Fee 20190426111725446297	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx2002	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[> Back to OneMotoring](#)**Vehicle Insurance Particulars Result**

Vehicle No.	Incident Date/Time	Insurance Company Name
SLL4878C	24 Apr 2019 / 09:20:00	FWD SINGAPORE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2019 Edit Reg		27 Apr 2019 00:00 Edit Adj Rpt	\$5,050.00 Edit Estimates	\$5,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CHAN CHUAN YONG KELVIN , ID: S8837676E									
Main Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD , Co. Reg. No.: 199803778Z									
Vehicle Reg. No.: GBD3295B		Date of Loss: 24/04/2019 09:00 - :59 [55 Months and 1 Days From LTA Reg Date (Man Yr)]	Policy/Cover Note No.: PNPV2018-0001679-01 (Comprehensive) Coverage: 28/02/2019 - 27/02/2020						
Claim Type: TP / 1201900010894		Policy No. (Claimant): 999995580	Excess:						
Vehicle Reg. No. (Insured): SLL4878C									
Repairer: Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (27/06/2019): Alert - Adj Mandate Approved (\$5890.95) - GBD3295B - Claim Handler: Clara Li Zi...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD3295B (1201900010894)
[SLL4878C]

TP

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD

Apr 24 2019 9:00AM

[CHAN CHUAN YONG KELVIN]

Tong Luck Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/04/19 15:44	Adjuster Immediate Advice	1	Load HTML	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	31/05/19 15:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	31/05/19 15:36	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
17	31/05/19 15:36	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/04/19 16:29	TP EST & GIA REPORT	1	Load PDF	
2	29/04/19 16:29	EMAIL FROM FWD DD 29042019	1	Load PDF	
3	29/04/19 16:35	FWD EMAIL TO OI DD 29042019	1	Load PDF	
4	02/05/19 09:02	TP ESTIMATE- MARKED	1	Load PDF	
5	21/06/19 14:08	WORKSHOP INVOICE	1	Load PDF	
6	21/06/19 14:08	LTA SEARCH	1	Load PDF	
7	21/06/19 14:08	LOD	1	Load PDF	
8	15/07/19 12:17	AUTHORISATION TO ACT FORM	1	Load PDF	
9	15/07/19 12:17	Release Voucher	1	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	06/05/19 11:04	E-filed GIA report	1	Load PDF	
2	06/06/19 21:58	Letter of Demand from Third Party	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>(note: Remarks are private unless you show it to other parties.)</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL4878C (Insd veh)	Model:	PEUGEOT PARTNER 1.6 D
	GBD3295B (TP veh)		HDI (M)
Date of Accident:	24/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	9,112.55
Final Repair Cost	:	\$	5,403.50
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,890.95

8.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tong Luck Auto Pte Ltd	:	\$ 5,890.95
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

15 Jul

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19007493/KEB3Q2

Date: 15/07/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-0001679-01

Claimant Vehicle No : GBD3295B **Insured Vehicle No :** SLL4878C

Date of Loss: 24/04/2019 Nature of Claim: TP Claim No: 1201900010894

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD3295B**
 Make & Model: PEUGEOT PARTNER, 1.6 D HDI (M) Engine No: 10JBFR0012800
 Reg. Date: 23/09/2014 (Man. Year: 2014) Chassis No: VF37F9HF8EJ735567
 Colour: White Odometer: 138586 km
 Engine Capacity: 1560 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Falken 5 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 5 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,236.40	4,384.40	852.00	16.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,960.00	1,320.00	40.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,516.40	6,344.40	2,172.00	25.50
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	8,516.40	5,050.00	3,466.40	40.70
+ GST 7.00/7.00% (S\$)	596.15	353.50	242.65	40.70
Nett Amount (S\$)	9,112.55	5,403.50	3,709.05	40.70
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,890.95		

INSPECTION

Date of Assignment: 27/04/2019

Date Inspected: 29/04/2019 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming

AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jun 2019)	
Parts:	N/A	PEUGEOT PARTNER 1.6 D HDI (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD3295B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -RH	Bent	1,200.00 FL	*1,200.00 FL
2	1		*REAR DOOR PARTNER EMBLEM -RH	Necessary	122.00 FL	*122.00 FL
3	1		*REAR DOOR E HDI EMBLEM -RH	Necessary	102.00 FL	*102.00 FL
4	1		*REAR DOOR TRIMBOARD -RH	Cracked	355.00 FL	*355.00 FL
5	10		*REAR DOOR INNER TRIMBOARD CLIPS -RH	Necessary	54.00 FS	*50.00 FS
6	1		*REAR DOOR -LH	Bent	1,320.00 FL	*1,320.00 FL
7	1		*REAR DOOR PEUGEOT EMBLEM -LH	Necessary	123.00 FL	*123.00 FL
8	10		*REAR DOOR INNER TRIMBOARD CLIPS -LH	Necessary	54.00 FS	*50.00 FS
9	1		*REAR END PANEL (OUTER)	Repair	380.00 FL	*- FL
10	1		*REAR BUMPER	Buckled	550.00 FL	*550.00 FL
11	1		*REAR BUMPER PAD-RH /LH	O/S Dented	560.00 FL	*280.00 FL
12	1		*REAR BUMPER TOW COVER	Dented	39.00 FL	*39.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	325.00 FL	*325.00 FL
14	1		*REAR DOOR GLASS SEALANT -RH	Necessary	50.00 FS	*40.00 FS
15	1		*REAR DOOR GLASS SEALANT -LH	Necessary	50.00 FS	*40.00 FS
16	1		*SET REAR BUMPER REVERSE SENSOR	Dented	380.00 FS	*200.00 FS
17	1		*REAR DOOR 70KM/H STICKER -LH	Necessary	25.00 FS	*15.00 FS
18	1		*REAR DOOR 6PAX STICKER -RH	Necessary	15.00 FS	*15.00 FS
19	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	5,744.00	4,826.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	507.60	441.60
Total Parts (\$\$)	5,236.40	4,384.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
2	TO REMOVE AND REFIX BOTH SIDE DOOR GLASS	New	200.00	160.00
3	TO TRANSFER BOTH SIDE REAR DOOR INTERIOR MECHANISM TO NEW DOOR	New	200.00	120.00
4	TO PANEL BEAT REAR FLOORBOARD PANEL, REAR CHASSIS FRAME, TO CUT AND WELD REAR END PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	600.00
5	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	600.00
6	TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PANELS	New	120.00	60.00
7	TO SUPPLY AND PASTE STICKER ON BOTH SIDE REAR DOOR	New	680.00	400.00
Gross Labour Cost (S\$)			3,280.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >